




- 1. Open the camera app
- Focus the camera on the QR code by gently tapping the code
- 3. Follow the instructions on the screen to view PDF file

# MINI-ME™ INSTALLATION MANUAL



# RD7CTS UNIVERSAL REMOTE DISPLAY

Revision 2213

Document No. DI00028 rev2213

OMNTEC Mfg., Inc. has been certified by DQS Inc. to ISO 9001:2015





### **RS-485 Installation and Setup**




Figure 1.0

### **IMPORTANT:**

Read all instructions prior to starting the installation process.

Do not apply power to the Mini-Me until the unit has been mounted and all wiring connections have been made.

All work must be performed by authorized installers in accordance with Local and National Electric Code®.

### **SUPPLIED HARDWARE**

- (1) OMNTEC 2.3mm flathead screwdriver
- (4) Wall anchors
- (1) Allen wrench
  - 1. Use the supplied Allen wrench to loosen the four Allen screws **(H)** that mount the display to the base (see Figure 2.0).
  - 2. Place the display face down on a flat surface to keep it from being damaged.

- 3. Disconnect the green wire **(A)** by loosening and removing the #10-32 nut and lock washer from the display shield.
- 4. Unplug connectors **(B)** and **(C)** to separate the display from the base.
- Measure base mounting dimensions and fasten the supplied wall anchors. Install screws for the top two mounting holes (D) leaving a minimum of ¼-inch of thread exposed.
- 6. Mount the base onto the top two screws **(D)** then tighten and secure.
- 7. Fasten the two bottom screws **(E)** to the base mounting holes and secure.
- Bring power wires (100-240 VAC) through the left preformed knockout (F) and secure on the terminal block as illustrated.





- Bring a low-voltage RS-485 cable (EC-4 or 4 conductor 22 AWG twisted pair with shield) through the right preformed knockout (G) and secure to the terminal block (see Figure 1.0).
- Secure the green wire (A) with #10-32 nut and lock washer.
- 11. Connect the data harness **(B)** making sure that the black wire is facing the bottom of the display as illustrated
- 12. Connect the low-voltage power supply harness **(C)** to the display.
- 13. Place the display back onto the base and secure with the four Allen screws **(H)** (see Figure 2.0).

#### **CAUTION!**

# \*\*DO NOT OVERTIGHTEN THE ALLEN SCREWS. DO NOT PINCH WIRES BETWEEN THE DISPLAY AND THE BASE.\*\*

- 14. Prepare the proper ATG connection for RS-485. The RS-485 connection is located on the Proteus® MCU on a small red board (see Figure 3.0).
- 15. Pin 1 \_\_\_\_\_\_ BLACK
  Pin 2 \_\_\_\_\_ WHITE
  Pin 3 \_\_\_\_\_ GREEN
  Pin 4 NO CONNECTION
- 16. Configure the RS-485 port in the system programming settings of the Proteus® ATG. Select the COMM TYPE to be RD7CTS (\*\*Must have ATG firmware version 6.0 or higher. Consult OMNTEC for help\*\*).
- 17. Power up the Mini-Me and view the programming guide to adjust system settings.
- \*\* Connecting via RS-485 is currently available for PROTEUS® K & X only.\*\*




Figure 2.0



Figure 3.0





### **RS-232 Installation and Setup**




Figure 4.0

#### **IMPORTANT:**

Read all instructions prior to starting the installation process.

Do not apply power to the Mini-Me until the unit has been mounted and all wiring connections have been made.

All work must be performed by authorized installers in accordance with Local and National Electric Code®.

#### SUPPLIED HARDWARE

- (1) OMNTEC 2.3mm flathead screwdriver
- (4) Wall anchors
- (1) Allen wrench
  - 1. Use the supplied Allen wrench to loosen the four Allen screws (H) that mount the display to the base (see Figure 2.0).
  - 2. Place the display face down on a flat surface to keep it from being damaged.

- Disconnect the green wire (A) by loosening and removing the #10-32 nut and lock washer from the display shield.
- 4. Unplug connectors (B) and (C) to separate the display from the base.
- 5. Measure base mounting dimensions and fasten the supplied wall anchors. Install screws for the top two mounting holes (D) leaving a minimum of 1/4-inch of thread exposed.
- 6. Mount the base onto the top two screws (D) then tighten and secure.
- 7. Fasten the two bottom screws (E) to the base mounting holes and secure.
- Bring power wires (100-240 VAC) through the left preformed knockout (F) and secure on the terminal block as illustrated.



PROTEUS®

INI-ME

Installation Instructions


- Bring a low-voltage RS-232 cable (Quabbin 7325 or 3-conductor 22 AWG with shield) through right preformed knockout (G) and secure to the terminal block (see Figure 4.0).
- 10. Secure the green wire (A) with #10-32 nut and lock washer.
- 11. Connect the data harness **(B)** making sure that the black wire is facing the bottom of the display as illustrated.
- 12. Connect the low-voltage power supply harness **(C)** to the display.
- 13. Place the display back onto the base and secure with the four Allen screws **(H)** (see Figure 2.0).

### **CAUTION!**

## \*\*DO NOT OVERTIGHTEN THE ALLEN SCREWS. DO NOT PINCH THE WIRES BETWEEN THE DISPLAY AND THE BASE.\*\*

- 14. Prepare the proper ATG connection for RS-232 (see Figure 5.0).
- 15. Configure the RS-232 port from the main ATG through the programming settings.
- 16. Power up the Mini-Me and view the programming guide to adjust system settings.

\*\*When using a RS-232 connection, the Mini-Me can be connected to any industry standard ATG.\*\*






Figure 5.0