

Company

Owner: GlobeAir AG
Operator: GlobeAir AG

Major Assemblies

Airframe	510 (Citation Mustang)	510-0065	14-Nov-2023	9,850.5 Hrs	7,900 Ldg	66.1 ACH
Eng 1	PW615F-A	PCE-LB0340	14-Nov-2023	4,277.5 Hrs	3,020 Enc	
Eng 2	PW615F-A	PCE-LB0337	14-Nov-2023	3,960.3 Hrs	3,480 Enc	

Additional Information

Program Type: Standard, General Categories: Extended TBO

Cost: 256,154.01+
Man Hrs: 511.2+

Analyst: Laurence Kirk lkirk@traxxall.com

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 3 - *Reserved for Airline Use										
CIL-03-01	Certification Requirements - Supplemental Type Certificate (STC)								T (A/R)	Informational
3 A/F										Mos
Eff: 03-Jun-2013 Not Applicable	Airline use									Hrs
(NOTE: 14th March 2019)										Ldg
SB510-03-01	Conversion from FAA (US) to EASA Certification								RE (-)	Optional
3 A/F										Mos
Eff: 15-May-2009 Not Applicable	Airline use									Hrs
(NOTE: 14th March 2019)										Ldg
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS										
05-12-01	Inspection Document 01 (Interval 1A items)								RE	≈17-Dec-2023
5 A/F										Mos
						07-Jun-2023				Hrs
(AVG MAN HRS: 12) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)							450	-/+25	9,921.8	71.3 Hrs (+25)
							7,591			Ldg
05-12-02	Inspection Document 02 (Interval 2A items)								RE	≈02-Apr-2024
5 A/F										Mos
						18-May-2022				Hrs
(AVG MAN HRS: 8) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)							900	-/+25	10,152.2	301.7 Hrs (+25)
							7,425			Ldg
05-12-03	Inspection Document 03 (Interval 3A items)								RE	≈10-Sep-2024
5 A/F										Mos
						17-Mar-2022				Hrs
(AVG MAN HRS: 7) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)							1,350	-/+25	10,496.2	645.7 Hrs (+25)
							7,338			Ldg
05-12-04	Inspection Document 04 (Interval 4A items)								RE	≈19-Apr-2024
5 A/F										Mos
						29-Oct-2020				Hrs
(AVG MAN HRS: 1) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)							1,800	-/+25	10,190.5	340 Hrs (+25)
							6,735			Ldg
05-12-05	Inspection Document 05 (Interval 7A items)								RE	≈01-Jan-2027
5 A/F										Mos
						17-Mar-2022				Hrs
(AVG MAN HRS: 1) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)							3,150	-/+25	12,296.2	2,445.7 Hrs (+25)
							7,338			Ldg
05-12-06	Inspection Document 06 (Interval 1C items)								RE	
5 A/F										Mos
						07-Jun-2023	12	-/+1m	30-Jun-2024	7.6 Months (+30 Days)
(AVG MAN HRS: 21) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)							9,471.8			Hrs
							7,591			Ldg

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-12-07	Inspection Document 07 (Interval 2C items)								RE	
5 A/F						Mos	18-May-2022	24	-/+1m	31-May-2024 6.6 Months (+30 Days)
	(AVG MAN HRS: 1) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,252.2			
						Ldg	7,425			
05-12-10	Inspection Document 10 (Interval 5C items)								RE	
5 A/F						Mos	07-Jun-2023	60	-/+1m	30-Jun-2028 4.6 Years (+30 Days)
	(AVG MAN HRS: 8) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8			
						Ldg	7,591			
05-12-11	Inspection Document 11 (Interval 6C items)								RE	
5 A/F						Mos	07-Jun-2023	72	-/+1m	30-Jun-2029 5.6 Years (+30 Days)
	(AVG MAN HRS: 30) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8			
						Ldg	7,591			
05-12-12	Inspection Document 12 (Interval 12C items)								RE	
5 A/F						Mos	08-May-2020	144	-/+1m	31-May-2032 8.5 Years (+30 Days)
	(AVG MAN HRS: 1) (SOURCE: Model 510 Maintenance Manual)					Hrs	7,976.4			
						Ldg	6,420			
05-12-13	Inspection Document 13 (Interval 1A/1C items)								RE	≈17-Dec-2023
5 A/F						Mos	07-Jun-2023	12	-/+1m	30-Jun-2024 7.6 Months (+30 Days)
	(AVG MAN HRS: 53) (APX COST: 875.56) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8	450	-/+25	9,921.8 71.3 Hrs (+25)
						Ldg	7,591			
05-12-14	Inspection Document 14 (Interval 2A/1C items)								RE	
5 A/F						Mos	07-Jun-2023	12	-/+1m	30-Jun-2024 7.6 Months (+30 Days)
	(AVG MAN HRS: 5) (APX COST: 124.44) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8	900	-/+25	10,371.8 521.3 Hrs (+25)
						Ldg	7,591			
05-12-15	Inspection Document 15 (Interval 3A/2C items)								RE	≈10-Feb-2025
5 A/F						Mos	07-Jun-2023	24	-/+1m	28-Feb-2025 1.3 Years (+28 Days)
	(AVG MAN HRS: 2) (APX COST: 0) (Tol. Adjustment: -124d) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8	1,350	-/+25	10,821.8 971.3 Hrs (+25)
						Ldg	7,591			
05-12-16	Inspection Document 16 (Interval 3A/3C items)								RE	≈10-Sep-2024
5 A/F						Mos	17-Mar-2022	36	-/+1m	31-Mar-2025 1.4 Years (+30 Days)
	(AVG MAN HRS: 65) (APX COST: 2,608.27) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,146.2	1,350	-/+25	10,496.2 645.7 Hrs (+25)
						Ldg	7,338			
05-12-17	Inspection Document 17 (Interval 4A/3C items)								RE	≈17-Dec-2025
5 A/F						Mos	04-Sep-2023	36	-/+1m	30-Sep-2026 2.9 Years (+30 Days)
	(AVG MAN HRS: 16) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,684.2	1,800	-/+25	11,484.2 1,633.7 Hrs (+25)
						Ldg	7,759			
05-12-18	Inspection Document 18 (Interval 5A/3C items)								RE	≈15-Jul-2026
5 A/F						Mos	04-Sep-2023	36	-/+1m	31-Jul-2026 2.7 Years (+31 Days)
	(AVG MAN HRS: 25) (APX COST: 0) (Tol. Adjustment: -51d) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,684.2	2,250	-/+25	11,934.2 2,083.7 Hrs (+25)
						Ldg	7,759			
05-12-20	Inspection Document 20 (Interval 6A/4C items)								RE	
5 A/F						Mos	22-Jan-2020	48	-/+1m	31-Jan-2024 76 Days (+29)
	(AVG MAN HRS: 7) (SOURCE: Model 510 Maintenance Manual)					Hrs	7,878.4	2,700	-/+25	10,578.4 727.9 Hrs (+25)
						Ldg	6,337			
05-12-21	Inspection Document 21								RE	
5 A/F						Mos	07-Jun-2023	12	-/+1m	30-Jun-2024 7.6 Months (+30 Days)
	(AVG MAN HRS: 4) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: Required 14 CFR 91.207)					Hrs	9,471.8			
						Ldg	7,591			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
05-12-22		Inspection Document 22								RE		
	5 A/F	(AVG MAN HRS: 12.5) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: Required 14 CFR 91.411, 91.413 and RVSM certification interval item)			Mos		18-May-2022	24	-/+1m	31-May-2024	6.6 Months (+30 Days)	
					Hrs		9,252.2					
					Ldg		7,425					
05-12-28		Inspection Document 28								RE (A/R)		
	5 A/F	(SOURCE: Model 510 Maintenance Manual) (NOTE: Refer to Goodrich Component Maintenance Manual)			Mos		19-Jul-2013					
					Hrs		3,391					
					Ldg		2,853					
05-12-30		Inspection Document 30 (Interval 4A/4C items)								RE		≈19-Apr-2024
	5 A/F	(AVG MAN HRS: 10) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)			Mos		29-Oct-2020	48	-/+1m	31-Oct-2024	11.7 Months (+30 Days)	
					Hrs		8,390.5	1,800	-/+25	10,190.5	340 Hrs (+25)	
					Ldg		6,735					
05-12-31		Inspection Document 31								RE		≈17-Dec-2023
	5 A/F	(AVG MAN HRS: 1) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: No grace period)			Mos		07-Jun-2023					
					Hrs		9,471.8	450	9,921.8		71.3 Hrs	
					Ldg		7,591					
05-12-32		Inspection Document 32								RE		≈25-May-2025
	5 A/F	(AVG MAN HRS: 22) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)			Mos		01-Jul-2021	72	-/+1m	31-Jul-2027	3.7 Years (+31 Days)	
					Hrs		8,733					
					Ldg		7,019	1,800	-/+25	8,819	919 Ldg (+25)	
05-12-34		Inspection Document 34								RE (N/A)		
	5 A/F	(AVG MAN HRS: 5) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)			Mos		26-Jun-2019					
					Hrs		7,476.1					
					Ldg		6,006					
05-12-35		Inspection Document 35								RE		
	5 A/F	(AVG MAN HRS: 10) (APX COST: 0.94) (SOURCE: Model 510 Maintenance Manual)			Mos		07-Jun-2023	6	-/+1m	31-Dec-2023	45 Days (+31)	
					Hrs		9,471.8					
					Ldg		7,591					
05-12-36		Inspection Document 36								RE (A/R)		
	5 A/F	(AVG MAN HRS: 5) (SOURCE: Model 510 Maintenance Manual) (NOTE: Inspection Document 5-12-36 gives a list of interval item(s), which are completed at the first 12 calendar months after Air Data Computer Part Number 011-01110-00 is installed.)			Mos		02-Jun-2015	-/+1m				
					Hrs		4,731.7					
					Ldg		3,868					
05-12-37		Inspection Document 37								RE		≈26-Dec-2028
	5 A/F	(SOURCE: Model 510 Maintenance Manual)			Mos		19-Apr-2018					
					Hrs		6,645.3	7,200	-/+25	13,845.3	3,994.8 Hrs (+25)	
					Ldg		5,345					
05-12-38		Inspection Document 38								T		
	5 A/F	(Manual Adjustment: 0d) (SOURCE: Model 510 Maintenance Manual)			Mos		07-Jun-2023	12	-/+1m	30-Jun-2024	7.6 Months (+30 Days)	
					Hrs		9,471.8					
					Ldg		7,591					
05-12-MA		Inspection Document MA								RE		≈10-Jan-2024
	5 A/F	(AVG MAN HRS: 7) (APX COST: 1.78) (SOURCE: Model 510 Maintenance Manual)			Mos		07-Jun-2023					
					Hrs		9,471.8	500	9,971.8		121.3 Hrs	
					Ldg		7,591					
05-12-MB		Inspection Document MB								RE		≈06-Aug-2024
	5 A/F	(AVG MAN HRS: 9.5) (APX COST: 318.28) (SOURCE: Model 510 Maintenance Manual)			Mos		07-Jun-2023					
					Hrs		9,471.8	950	10,421.8		571.3 Hrs	
					Ldg		7,591					

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-12-MC	Inspection Document MC						RE			≈13-Sep-2025
5 A/F					Mos	21-Mar-2019				
	(AVG MAN HRS: 16) (SOURCE: Model 510 Maintenance Manual)				Hrs	7,282.7	4,000		11,282.7	1,432.2 Hrs
					Ldg	5,847				
05-12-MD	Inspection Document MD						RE			
5 A/F					Mos	07-Jun-2023	12		02-Feb-2024	78 Days
	(AVG MAN HRS: 2) (APX COST: 0) (Tol. Adjustment: -124d) (SOURCE: Model 510 Maintenance Manual)				Hrs	9,471.8				
					Ldg	7,591				
05-12-ME	Inspection Document ME						RE			≈22-Nov-2024
5 A/F					Mos	18-May-2022	36		18-May-2025	1.5 Years
	(AVG MAN HRS: 5) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)				Hrs	9,252.2	1,400		10,652.2	801.7 Hrs
					Ldg	7,425				
05-12-MF	Inspection Document MF						T			≈15-Aug-2026
5 A/F					Mos					
	(SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		12,000	2,149.5 Hrs
					Ldg					
05-12-MG	Inspection Document MG						RE			≈10-Nov-2026
5 A/F					Mos	04-Sep-2023				
	(AVG MAN HRS: 10) (SOURCE: Model 510 Maintenance Manual)				Hrs	9,684.2	2,500		12,184.2	2,333.7 Hrs
					Ldg	7,759				
05-12-MH	Inspection Document MH						RE			≈28-Feb-2026
5 A/F					Mos	23-Aug-2020				
	(AVG MAN HRS: 30) (SOURCE: Model 510 Maintenance Manual)				Hrs	8,244.4	3,400		11,644.4	1,793.9 Hrs
					Ldg	6,617				
05-12-MI	Inspection Document MI						T			≈15-Aug-2026
5 A/F					Mos					
	(SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		12,000	2,149.5 Hrs
					Ldg					
05-12-MJ	Inspection Document MJ						T			≈29-Oct-2024
5 A/F					Mos					
	(SOURCE: Model 510 Maintenance Manual)				Hrs		10,600		10,600	749.5 Hrs
					Ldg					
05-12-MK	Inspection Document MK						T			≈27-Jul-2024
5 A/F					Mos					
	(SOURCE: Model 510 Maintenance Manual)				Hrs		10,400		10,400	549.5 Hrs
					Ldg					
053501	Inspect / Replace PBE Mask Inspection						RE		Custom Task	
5 A/F					Mos	22-Apr-2018	120		22-Apr-2028	4.4 Years
	(AVG MAN HRS: 1) (APX COST: 0)				Hrs	6,659.5				
					Ldg	5,358				
05-CUS-100	Airworthiness Review Full Renewal						RE		Custom Task	
5 A/F					Mos	01-Jul-2021	36		[09-Jun-2024]	6.9 Months
	(AVG MAN HRS: 0) (APX COST: 0)				Hrs	8,733				
					Ldg	7,019				
05-CUS-200	Airworthiness Review Extension						RE		Custom Task	
5 A/F					Mos	08-Jun-2023	12		[09-Jun-2024]	6.9 Months
	(AVG MAN HRS: 0) (APX COST: 0)				Hrs	9,471.8				
					Ldg	7,591				
05-CUS-301	Inspect LTH40A Item 4.1 Electronic on-board equipment (Avionics) Inspection						RE		National Requirement	
5 A/F					Mos	18-May-2022	24		18-May-2024	6.1 Months
	(AVG MAN HRS: 0) (APX COST: 0)				Hrs	9,252.2				
					Ldg	7,425				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-CUS-302-LH		Inspect LTH40A Item 4.2 Transponder system functional check (A/C/S) (Part of Document 22)									
	5 A/F	Left								RE	National Requirement
	011-00779-21						Mos	14-Aug-2023	24	14-Aug-2025	1.7 Years
	84805840						Hrs	9,639.6			
	(AVG MAN HRS: 0) (APX COST: 0)						Ldg	7,726			
05-CUS-302-RH		Inspect LTH40A Item 4.2 Transponder system functional check (A/C/S) (Part of Document 22)									
	5 A/F	Right								RE	National Requirement
	011-00779-21						Mos	18-May-2022	24	18-May-2024	6.1 Months
	84805361						Hrs	9,252.2			
	(AVG MAN HRS: 0) (APX COST: 0)						Ldg	7,425			
05-CUS-303		Inspect LTH40A Item 4.3(a) Pitot Static System Functional Check (Part of Document 22)									
	5 A/F									RE	National Requirement
							Mos	18-May-2022	24	18-May-2024	6.1 Months
							Hrs	9,252.2			
	(AVG MAN HRS: 0) (APX COST: 0)						Ldg	7,425			
05-CUS-304		Inspect LTH40A Item 4.3(b) Magnetic Compass Compensation									
	5 A/F									RE	National Requirement
	S2800-821						Mos	18-May-2022	24	18-May-2024	6.1 Months
	NSN						Hrs	9,252.2			
	MM:34-20-10 (AVG MAN HRS: 0) (APX COST: 0)						Ldg	7,425			
12-26-00-601		Discretionary Maintenance - 15 Day High Exposure Areas - Airplane Zone 1 Wash							RE (A/R)		5-19-00
	5 A/F										
		(SOURCE: Model 510 Maintenance Manual) (NOTE: NOTE 1: Aircraft washing is a key component of any CPCP. Washing removes corrosive agents from the surface of the airplane.					Mos				
		NOTE 2: These wash intervals are a baseline aircraft wash schedule. If an aircraft flies into any Severe Corrosion Areas during its operation route, it may be necessary to increase the frequency of the wash schedule.					Hrs				
		NOTE 3: Textron Aviation Inc. strongly recommends washing or rinsing the airplane as soon as possible, no later than three days, after any operation that exposes the airplane to Runway De-Icing (RDI) fluids. Any delay can result in the greater likelihood of corrosion.					Ldg				
12-26-00-602		Discretionary Maintenance - 45 Day Medium Exposure Areas - Airplane Zone 2 Wash							RE (A/R)		5-19-00
	5 A/F										
		(SOURCE: Model 510 Maintenance Manual) (NOTE: NOTE 1: Aircraft washing is a key component of any CPCP. Washing removes corrosive agents from the surface of the airplane.					Mos				
		NOTE 2: These wash intervals are a baseline aircraft wash schedule. If an aircraft flies into any Severe Corrosion Areas during its operation route, it may be necessary to increase the frequency of the wash schedule.					Hrs				
		NOTE 3: Textron Aviation Inc. strongly recommends washing or rinsing the airplane as soon as possible, no later than three days, after any operation that exposes the airplane to Runway De-Icing (RDI) fluids. Any delay can result in the greater likelihood of corrosion.					Ldg				
12-26-00-603		Discretionary Maintenance - 90 Day Low Exposure Areas - Airplane Zone 3 Wash							RE (A/R)		5-19-00
	5 A/F										
		(SOURCE: Model 510 Maintenance Manual) (NOTE: NOTE 1: Aircraft washing is a key component of any CPCP. Washing removes corrosive agents from the surface of the airplane.					Mos				
		NOTE 2: These wash intervals are a baseline aircraft wash schedule. If an aircraft flies into any Severe Corrosion Areas during its operation route, it may be necessary to increase the frequency of the wash schedule.					Hrs				
		NOTE 3: Textron Aviation Inc. strongly recommends washing or rinsing the airplane as soon as possible, no later than three days, after any operation that exposes the airplane to Runway De-Icing (RDI) fluids. Any delay can result in the greater likelihood of corrosion.					Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
5-50-00 (10)		Exposure to High Winds While the Aircraft is Parked Check						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											
5-50-00 (11)		Interior Cabin/Tailcone Fluid Spill						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											
5-50-00 (12)		Air Conditioner Operation on the Airplane During Periods when the System is not Typically Needed or Used						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											
5-50-00 (3)		Hard or Overweight Landing Check						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											
5-50-00 (4)		Overspeed Check						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											
5-50-00 (5)		Severe Turbulence and/or Maneuvers Checks						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											
5-50-00 (6)		Lightning Strike Check						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											
5-50-00 (7)		Foreign Object Damage Check						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											
5-50-00 (8)		Towing with Large Fuel Unbalance or High Drag/Side Loads Due to Ground Handling Check						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											
5-50-00 (9)		Nose Landing Gear Tow Limits Check						RE (A/R)		5-50-00, Unscheduled Maintenance Check	
	5 A/F										
(SOURCE: Model 510 Maintenance Manual)											

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
Pkg 450 Hour/12 Month 5 ENG1	Engine 450 Hour / 12 Month Inspection						RE			≈17-Dec-2023
					Mos	07-Jun-2023	12	-/+30d	07-Jun-2024	6.8 Months (+30 Days)
					Hrs	3,898.8	450	-/+10%	4,348.8	71.3 Hrs (+45)
					Enc	2,711				
Pkg 450 Hour/12 Month 5 ENG2	Engine 450 Hour / 12 Month Inspection						RE			≈17-Dec-2023
					Mos	07-Jun-2023	12	-/+30d	07-Jun-2024	6.8 Months (+30 Days)
					Hrs	3,581.6	450	-/+10%	4,031.6	71.3 Hrs (+45)
					Enc	3,171				
Pkg Pre-Flight 5 ENG1	Engine Pre-Flight Inspection						RE (PreFlight)			
					Mos					
					Hrs					
	(NOTE: These maintenance actions are performed by the flight crew as part of the pre-flight "walk around" inspection.)				Enc					
Pkg Pre-Flight 5 ENG2	Engine Pre-Flight Inspection						RE (PreFlight)			
					Mos					
					Hrs					
	(NOTE: These maintenance actions are performed by the flight crew as part of the pre-flight "walk around" inspection.)				Enc					
SL510-05-01 5 A/F Superseded	Landing Gear Life Limit Exemption SUPERSEDED BY REVISION 1						RE (-)		Informational	
					Mos					
					Hrs					
					Ldg					
SL510-05-01 R01 5 A/F Eff: 17-Mar-2011 Not Applicable	Landing Gear Life Limit Exemption BY SERIAL NUMBER NOT APPLICABLE						RE (-)		Informational	
					Mos					
					Hrs					
					Ldg					
▼ 8 - LEVELING AND WEIGHING.										
08-10-01-001 8 A/F	Aircraft Weighing and Balancing, +/- 30 days Tolerances acc LTH 36						RE		AMM	
					Mos	03-Feb-2022	48	-/+30d	28-Feb-2026	2.3 Years (+30 Days)
					Hrs	9,102.5				
	(AVG MAN HRS: 0) (APX COST: 0)				Ldg	7,303				
▼ 10 - PARKING, MOORING, STORAGE AND RETURN TO SERVICE										
Airframe Restoring 10 A/F	Perform restoring - cold soaked airplane return to service i.a.w. Model 510 Maintenance Manual Ch. 10-30-00						RE (-)			
					Mos					
					Hrs					
					Ldg					
Airframe Restoring 10 A/F	Perform restoring - ninety-one days and over i.a.w. Model 510 Maintenance Manual Ch. 10-30-00						RE (-)			
					Mos					
					Hrs					
					Ldg					
Airframe Restoring 10 A/F	Perform restoring - twenty-nine days to ninety days i.a.w. Model 510 Maintenance Manual Ch. 10-30-00						RE (-)			
					Mos					
					Hrs					
					Ldg					
Airframe Restoring 10 A/F	Perform restoring - zero to twenty-eight days i.a.w. Model 510 Maintenance Manual Ch. 10-30-00						RE (-)			
					Mos					
					Hrs					
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
Airframe Storage 10 A/F	Perform Cabin Upholstery and Carpet Storage for High Humidity Areas i.a.w. Model 510 Maintenance Manual Ch. 10-10-10					Mos 07-Jun-2023			RE (-)	
						Hrs 9,471.8				
						Ldg 7,591				
Airframe Storage 10 A/F	Perform Eight to Thirty Days Storage i.a.w. Model 510 Maintenance Manual Ch. 10-10-10					Mos			RE (-)	
						Hrs				
						Ldg				
Airframe Storage 10 A/F	Perform Ninety-One Days and Over Storage i.a.w. Model 510 Maintenance Manual Ch. 10-10-10					Mos			RE (-)	
						Hrs				
						Ldg				
Airframe Storage 10 A/F	Perform Thirty-One to Ninety Days Storage i.a.w. Model 510 Maintenance Manual Ch. 10-10-10					Mos 07-Jun-2023			RE (-)	
						Hrs 9,471.8				
						Ldg 7,591				
Airframe Storage 10 A/F	Perform Zero to Seven Days Storage i.a.w. Model 510 Maintenance Manual Ch. 10-10-10					Mos			RE (-)	
						Hrs				
						Ldg				
▼ 11 - PLACARDS AND MARKINGS										
SL510-11-01 11 A/F Eff: 06-Feb-2008 Not Applicable	Inspection of the Lower Speed Brake Placard BY SERIAL NUMBER NOT APPLICABLE					Mos			RE (-)	Recommended
						Hrs				
						Ldg				
SL510-11-02 11 A/F Eff: 31-Aug-2011 Complied With	Power J-Box Placard Inspection PERFORMED POWER J-BOX PLACARD INSPECTION SERVICE LETTER					Mos 26-Oct-2011			RE (-)	Recommended
						Hrs 2,660				
						Ldg 2,229				
SL510-11-03 11 A/F Eff: 27-Jun-2011 Not Applicable	Brake Accumulator Placard Inspection BY SERIAL NUMBER NOT APPLICABLE					Mos			RE (-)	Recommended
						Hrs				
						Ldg				
▼ 12 - SERVICING - ROUTINE MAINTENANCE										
12-CUS-001 12 A/F	Verify that the aircraft is clear by all tools and equipment's and that they have been properly re-stored					Mos			RE (A/R)	Custom Task
						Hrs				
						Ldg				
Reliability-12-001 12 A/F (AVG MAN HRS: 6)	Perform Electric Heated Glass Windshield Servicing i.a.w. Model 510 Maintenance Manual Ch. 12-16-00					Mos			RE (-)	
						Hrs				
						Ldg				
▼ 20 - STANDARD PRACTICES – AIRFRAME										
20-50-00-7 20 A/F Alias:20-50-00 (SOURCE: 20-50-00-7)	Perform Aircraft Polishing (Citation Standard Practices Manual)					Mos			RE (O/C)	
						Hrs				
						Ldg				

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
20-52-10-3  20 A/F Alias:20-52-10 (SOURCE: 20-52-10-3)	Perform Aircraft Interior Cleaning (Citation Standard Practices Manual)						RE (O/C)			
						Mos				
						Hrs				
						Ldg				
20-CUS-100  20 A/F	Report Part Numbers, Serial Numbers and Due Date of the Cockpit, Passenger and Infant Life Vest. Make sure no staples are present on life vest						RE (A/R)			
						Mos	16-Mar-2020			
						Hrs	7,941.9			
						Ldg	6,389			
CIL-20-01  20 A/F Eff: 09-Apr-2012 Superseded SUPERSEDED BY REVISION 1	Cessna Certification of Nondestructive Testing Facilities/Personnel						T (A/R)			
						Mos				
						Hrs				
						Ldg				
CIL-20-01 R3  20 A/F Eff: 30-May-2023	Standard Practices - Cessna Certification of Nondestructive Testing Facilities/Personnel (This SL has been Cancelled)						RE (-)		Service Letter	
						Mos				
						Hrs				
						Ldg				
CIL-20-01 Revision 1  20 A/F Superseded	Standard Practices - Cessna Certification Of Nondestructive Testing Facilities/Personnel SUPERSEDED BY REVISION 2						RE (-)		Informational	
						Mos				
						Hrs				
						Ldg				
CIL-20-01 Revision 2  20 A/F Eff: 18-Mar-2014 (NOTE: 14th March 2019)	Cessna Certification of Nondestructive Testing Facilities/Personnel NOTED						T (A/R)		Informational	
						Mos				
						Hrs				
						Ldg				
Reliability-20-001  20 A/F	Landing Gear Cleaning						RE (O/C)			
						Mos				
						Hrs				
						Ldg				
Reliability-20-001a  20 A/F	Clean Landing gear pistons i.a.w. Citation Standard Practices Manual Ch. 20-52-20 Reliability-20-001						RE (O/C)			
						Mos				
						Hrs				
						Ldg				
Reliability-20-001b  20 A/F	Clean landing gear doors, linkages and cylinder housing surfaces i.a.w. Citation Standard Practices Manual Ch. 20-52-20 Reliability-20-001						RE (O/C)			
						Mos				
						Hrs				
						Ldg				
Reliability-20-001c  20 A/F	Clean Landing gear trunnions and trailing link surfaces i.a.w. Citation Standard Practices Manual Ch. 20-52-20 Reliability-20-001						RE (O/C)			
						Mos				
						Hrs				
						Ldg				
Reliability-20-001d  20 A/F	Clean the wheels i.a.w. Citation Standard Practices Manual Ch. 20-52-20 Reliability-20-001						RE (O/C)			
						Mos				
						Hrs				
						Ldg				
SL510-20-01  20 A/F Superseded	Cessna Certification of Nondestructive Testing Facilities/Personnel SUPERSEDED BY REVISION 1						RE (-)		Informational	
						Mos				
						Hrs				
						Ldg				
SL510-20-01 R01  20 A/F Superseded	Cessna Certification of Nondestructive Testing Facilities/Personnel SUPERSEDED BY REVISION 2						RE (-)		Informational	
						Mos				
						Hrs				
						Ldg				

Task No		Description								Categories	Time					
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining					
SL510-20-01 R02		Cessna Certification of Nondestructive Testing Facilities/Personnel								RE (-)	Informational					
	20 A/F	SUPERSEDED BY REVISION 3					Mos									
	Superseded						Hrs									
							Ldg									
SL510-20-01 R03		Cessna Certification of Nondestructive Testing Facilities/Personnel								RE (-)	Informational					
	20 A/F	SUPERSEDED BY REVISION 4					Mos									
	Superseded						Hrs									
							Ldg									
SL510-20-01 R04		Cessna Certification of Nondestructive Testing Facilities/Personnel								RE (-)	Informational					
	20 A/F	SUPERSEDED BY REVISION 5					Mos									
	Superseded						Hrs									
							Ldg									
SL510-20-01 R05		Cessna Certification of Nondestructive Testing Facilities/Personnel								T (A/R)	Informational					
	20 A/F	NOTED Eff: 21-Sep-2012 (NOTE: 14th March 2019)					Mos									
							Hrs									
							Ldg									
SL510-20-02		Standard Practices - Cessna Standard Practices Manual								RE (-)	Service Letter					
	20 A/F	SUPERSEDED BY REVISION 1 Eff: 10-May-2017 Superseded					Mos									
							Hrs									
							Ldg									
SL510-20-02 R01		Standard Practices - Cessna Standard Practices Manual								T (A/R)	Service Letter					
	20 A/F	NOTED Eff: 20-Feb-2018 (NOTE: 19/09/2018)					Mos									
							Hrs									
							Ldg									
▼ 21 - AIR CONDITIONING AND PRESSURIZATION																
		(Brushless) Evaporator								RE (O/C)						
	21 A/F	No.1 New					Mos	20-Mar-2008								
	1133300-1						Hrs	0								
	248						Ldg	0								
			0				Ldg	0								
			0				ACH	0								
		(Brushless) Evaporator								RE (O/C)						
	21 A/F	No.2 New					Mos	20-Mar-2008								
	1133300-1						Hrs	0								
	259						Ldg	0								
			0				Ldg	0								
			0				ACH	0								
		Air Conditioning Compressor Module								RE (O/C)						
	21 A/F	Overhauled					Mos	14-Aug-2023								
	9912660-14						Hrs	9,639.6								
	429		0	0			Ldg	7,726								
	(APX COST: 5,903.97)		0	0			Ldg	7,726								
							Ldg	7,726								
		Condensor Assembly								RE (O/C)						
	21 A/F	New					Mos	20-Mar-2008								
	1134620-5						Hrs	0								
	114						Ldg	0								
			0				Ldg	0								
			0				ACH	0								
		KAPS II Controller								RE (O/C)						
	21 A/F	Overhauled					Mos	08-Feb-2019								
	9912661-6						Hrs	7,236.7								
	1362		7	13.8			Ldg	5,811								
	(APX COST: 3,788.31)		5				Ldg	5,811								
							Ldg	5,811								

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN	MOC	Note or Component	Condition					DUE	Remaining	
	21 A/F 52812-102 924	KAPS II Outflow Valve									
		No.1				Mos	20-Mar-2008				
		New				Hrs	0				
						Ldg	0				
	21 A/F 52812-102 919	KAPS II Outflow Valve									
		No.2				Mos	20-Mar-2008				
		New				Hrs	0				
						Ldg	0				
	21 A/F 1134275-1 1633	Receiver Dryer Assy									
		New				Mos	20-Mar-2008				
						Hrs	0				
						Ldg	0				
	21 A/F 74D235H6F251 NSN (AVG MAN HRS: 0) (APX COST: 179.01)	Thermal Actuator									
		Left				Mos	22-Nov-2018				
		New				Hrs	7,166.1				
						Ldg	5,742				
	21 A/F 0113-12 0404 (APX COST: 1,077.53)	Under Floor Blower Assy.									
		Overhauled				Mos	01-Jul-2021				
						Hrs	8,733				
						Ldg	7,019				
	21 A/F 1250435-5 2290	Vane Axial Blower Assy.									
		Overhauled				Mos	19-Jul-2013				
						Hrs	3,391				
						Ldg	2,853				
21-00-09		Vapor Cycle Cooling System - Compressor Drive Motor Brushes Discard - Replace every 800 compressor hours.					RE 05-11-00, Component Time Limits			≈07-May-2026	
	21 A/F (APX COST: 1,585.37) (SOURCE: Model 510 Maintenance Manual) (NOTE: Refer to the Enviro Systems, Inc., Operating, Servicing, and Component Maintenance Manual with Illustrated Parts List (21-00-09) for the maintenance procedures. Refer to the Introduction, Supplier Publication List. NOTE: An exchange compressor drive motor is an acceptable means of compliance. Contact Textron Aviation Parts Department (TAPD) at (316) 517-6002 for assistance with an exchange compressor drive motor.)					Mos	08-May-2020				
						Hrs	7,976.4				
						Ldg	6,420				
						ACH	160.3	800	960.3	894.2 ACH	
21-00-09-10-001		Compressor Drive Module Cleaning					RE			Custom Task	
	21 A/F	21-00-09-10-801				Mos	07-Jun-2023	12	+2m	(30-Jun-2024)	7.6 Months (+61 Days)
						Hrs	9,471.8				
						Ldg	7,591				
						ACH	476.7	250	+30	(726.7)	660.6 ACH (+30)
21-00-09-10-002		Condenser Blower Assembly Cleaning					RE			Custom Task	
	21 A/F	21-00-09-10-801				Mos	07-Jun-2023	12	+2m	(30-Jun-2024)	7.6 Months (+61 Days)
						Hrs	9,471.8				
						Ldg	7,591				
						ACH	476.7	250	+30	(726.7)	660.6 ACH (+30)

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
21-00-09-10-003  21 A/F		Evaporator Module Cleaning 21-00-09-10-801						RE		Custom Task	
						Mos	07-Jun-2023	12	+2m	(30-Jun-2024)	7.6 Months (+61 Days)
						Hrs	9,471.8				
						Ldg	7,591				
						ACH	476.7	250	+30	(726.7)	660.6 ACH (+30)
21-00-09-10-801  21 A/F		Air Condition Cleaning Operation (Main Task)						RE		Customer Operations Requirement	
						Mos	07-Jun-2023	12	+2m	30-Jun-2024	7.6 Months (+61 Days)
						Hrs	9,471.8				
						Ldg	7,591				
						ACH	476.7	250	+30	726.7	660.6 ACH (+30)
21-00-09-21-001  21 A/F		Compressor Drive Module and Condenser Blower Inspection 21-00-09-21-801						RE		Custom Task	
						Mos	07-Jun-2023	12	+2m	(30-Jun-2024)	7.6 Months (+61 Days)
						Hrs	9,471.8				
						Ldg	7,591				
						ACH	476.7	500	+30	(976.7)	910.6 ACH (+30)
21-00-09-21-801  21 A/F		Air Condition Inspection Operation (Main Task)						RE		Customer Operations Requirement	
						Mos	07-Jun-2023	12	-/+2m	30-Jun-2024	7.6 Months (+61 Days)
						Hrs	9,471.8				
						Ldg	7,591				
						ACH	476.7	500	-/+30	976.7	910.6 ACH (+30)
21-00-09-60-801  21 A/F		Air Condition Servicing						RE		Customer Operations Requirement	
						Mos	07-Jun-2023	12	+2m	30-Jun-2024	7.6 Months (+61 Days)
						Hrs	9,471.8				
						Ldg	7,591				
21-00-09-99F-016  21 A/F		Air Conditioning System Servicing Procedures 21-00-09-60-801						RE		Custom Task	
						Mos	07-Jun-2023	12	+2m	(30-Jun-2024)	7.6 Months (+61 Days)
						Hrs	9,471.8				
						Ldg	7,591				
A215000  21 A/F		Vapor Cycle Cooling System Hour Meter Inspection. 05-12-13 Task:21-50-00-210 (ZONE: 312) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						RE		Inspection Time Limits	≈17-Dec-2023
						Mos	07-Jun-2023	4	+1m	(30-Jun-2024)	7.6 Months (+30 Days)
						Hrs	9,471.8	200	+50	(9,921.8)	71.3 Hrs (+25)
						Ldg	7,591				
						ACH	576	200			
B213000  21 A/F		Pressurization System Functional Check 05-12-30 Task:21-30-00-720 (ZONE: 228, 241, 242, 311) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						RE		Inspection Time Limits	≈19-Apr-2024
						Mos	29-Oct-2020	48	-/+1m	(31-Oct-2024)	11.7 Months (+30 Days)
						Hrs	8,390.5	1,800	-/+25	(10,190.5)	340 Hrs (+25)
						Ldg	6,735				
D215000  21 A/F		Forward and Aft Evaporator Coil Cleaning 05-12-01 Task:21-50-00-160 (ZONE: 235, 241, 242) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						RE		Inspection Time Limits	≈17-Dec-2023
						Mos	07-Jun-2023				
						Hrs	9,471.8	450	-/+25	(9,921.8)	71.3 Hrs (+25)
						Ldg	7,591				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SI 21-2017 REV01 21 ENG1	INSP/REPAIR OF AGB HSG/COVER/PUMP HSG								RE (-)	
SI 21-2017 REV01 21 ENG2	INSP/REPAIR OF AGB HSG/COVER/PUMP HSG								RE (-)	
SL510-21-01 21 A/F Eff: 24-Jun-2008 Complied With	Compressor Isolator Mount Inspection								RE (-)	Recommended
SL510-21-02 21 A/F Complied With	Cabin Altitude Module Inspection								RE (-)	Mandatory
SL510-21-02 R01 21 A/F Eff: 09-Dec-2009 Complied With PREVIOUSLY SERVICE LETTER PREVIOUSLY ADDRESSED IN ORIGINAL ISSUE.	Cabin Altitude Module Inspection								RE (-)	Mandatory
SL510-21-04 21 A/F Eff: 09-Aug-2019 Not Applicable (AVG MAN HRS: 4) (NOTE: Reviewed by CAMO)	Air Conditioning - Cabin Pressurization Controller Improvement N/A by P/N Installed								T (A/R)	Recommended
SL510-21-05 21 A/F Eff: 16-Aug-2019	Air Conditioning - Air Conditioning Compressor Motor Fan Replacement								T (A/R)	Optional
▼ 22 - AUTOFLIGHT										
22 A/F 011-01020-10 22006182	GMC 710 AFCS Controller								RE (O/C)	
22 A/F 011-00877-00 66305130	GSA 80 Torque Servo Aileron New								RE (O/C)	
22 A/F 011-00877-00 66306014 (APX COST: 865.3)	GSA 80 Torque Servo Rudder Overhauled								RE (O/C)	
22 A/F 011-00878-10 71300123	GSA 81 Torque Servo Elevator Overhauled								RE (O/C)	



Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	22 A/F	GSM 85 Servo Mount						RE (O/C)				
	011-01436-A3	Rudder						Mos	20-Mar-2008			
	11005026	New	0					Hrs	0			
			0					Ldg	0			
	22 A/F	GSM 85A Servo Mount						RE (O/C)				
	011-01436-A2	Aileron						Mos	20-Mar-2008			
	10905029	New	0					Hrs	0			
			0					Ldg	0			
	22 A/F	GSM 85A Servo Mount						RE (O/C)				
	011-01436-A0	Elevator						Mos	20-Mar-2008			
	11205036	New	0					Hrs	0			
			0					Ldg	0			
	22 A/F	Trim GSM 85A Servo Mount						RE (O/C)				
	011-01436-A1	Elevator						Mos	24-Jun-2010			
	11300102	Overhauled	0					Hrs	1,375			
								Ldg	1,170			
	22 A/F	Trim Tab GSA 81 Torque Servo						RE (O/C)				
	Not Installed	Elevator						Mos	15-Jul-2017			
	Not Installed							Hrs	6,185.7			
(AVG MAN HRS: 0) (APX COST: 0)								Ldg	4,980			
B221000		Autopilot Servo Mount Functional Check							RE	Inspection Time Limits		≈17-Dec-2023
	22 A/F	05-12-13						Mos	07-Jun-2023	12	-/+ 1m (30-Jun-2024)	7.6 Months (+30 Days)
	Task:22-10-20-720 (RII ITEM) (ZONE: 311, 312,315, 322) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Hrs	9,471.8	450	-/+25 (9,921.8)	71.3 Hrs (+25)	
							Ldg	7,591				
C221000		Autopilot Servo Lubrication							RE	Inspection Time Limits		≈17-Dec-2023
	22 A/F	05-12-13						Mos	07-Jun-2023	12	-/+ 1m (30-Jun-2024)	7.6 Months (+30 Days)
	Task:22-10-20-640 (RII ITEM) (ZONE: 311, 312,315, 322) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Hrs	9,471.8	450	-/+25 (9,921.8)	71.3 Hrs (+25)	
							Ldg	7,591				
SL510-22-01A		Autopilot Servo Guard Pin Inspection							RE (-)	Mandatory		
	22 A/F							Mos				
	Eff: 19-Aug-2008 Not Applicable	BY SERIAL NUMBER NOT APPLICABLE						Hrs				
							Ldg					
▼ 23 - COMMUNICATIONS												
	23 A/F	Antenna :High Frequency Antenna						RE (O/C)				
	16390	New						Mos	20-Mar-2008			
	FEB/07		0					Hrs	0			
			0					Ldg	0			
	23 A/F	Antenna :Sat Phone Antenna						RE (O/C)				
	S67-1575-109	New						Mos	20-Mar-2008			
	7544		0					Hrs	0			
			0					Ldg	0			



Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	23 A/F	GMA 1347D Audio Panel									
	011-01257-00	No.1					Mos	10-Mar-2017			
	48405235	Overhauled					Hrs	5,845			
							Ldg	4,714			
	23 A/F	GMA 1347D Audio Panel									
	011-01257-00	No.2					Mos	02-Mar-2018			
	48405120	Tested/Inspected		4,346.7			Hrs	6,550			
	(AVG MAN HRS: 0) (APX COST: 0)						Ldg	5,271			
	23 A/F	High Frequency Controller									
	071-01605-0201	New					Mos	20-Mar-2008			
	777			0			Hrs	0			
				0			Ldg	0			
	23 A/F	High Frequency Power Amplifer									
	064-01072-0101	New					Mos	20-Mar-2008			
	2548			0			Hrs	0			
				0			Ldg	0			
	23 A/F	High Frequency Receiver/ Exciter									
	064-01073-0102	New					Mos	20-Mar-2008			
	2352			0			Hrs	0			
				0			Ldg	0			
	23 A/F	VHF Comm Antenna									
	VHF10-829	No.1		32			Mos	03-Feb-2022			
	3226	New		0			Hrs	9,102.5			
	(APX COST: 1,697.99)			0			Ldg	7,303			
	23 A/F	VHF Comm Antenna									
	VHF10-829	No.2					Mos	07-Jun-2023			
	4351	New					Hrs	9,471.8			
	(APX COST: 1,906.02)						Ldg	7,591			
23-0A-02-970-801-01	Radio Station License							RE			
	23 A/F						Mos	13-Aug-2018	117	+3m	13-May-2028 4.5 Years (+92 Days)
							Hrs				
	(AVG MAN HRS: 0) (APX COST: 0)						Ldg				
B236000	Static Discharge System Functional Check							RE		Inspection Time Limits	≈10-Sep-2024
	23 A/F	05-12-16					Mos	17-Mar-2022	36	-/+1m	(31-Mar-2025) 1.4 Years (+30 Days)
							Hrs	9,146.2	1,350	-/+25	(10,496.2) 645.7 Hrs (+25)
	Task:23-60-00-720 (ZONE: 330, 340,351, 352,532, 632) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Ldg	7,338			
SB510-23-02	Enable XM Radio in the Cockpit							T (A/R)			Optional
	23 A/F						Mos				
	Eff: 20-Apr-2011 Declined	NOT OF INTEREST					Hrs				
							Ldg				
SL510-23-01	Lightning Related Anomalies of the Garmin GMA 1347(D) Audio Panel							T (A/R)			Informational
	23 A/F						Mos				
	Eff: 18-Sep-2008	NOTED					Hrs				
							Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 24 - ELECTRICAL POWER											
		Switch Panel							RE (-)		
	24 A/F	Tested/Inspected					Mos	02-Mar-2018			
	7018111-11						Hrs	6,550			
	AS26537						Ldg	5,271			
(APX COST: 0)											
		AVN Bus #1 Sensor							RE (O/C)		
	24 A/F	Right					Mos	20-Mar-2008			
	10747P03E25	New	0				Hrs	0			
	07092486	0				Ldg	0				
		AVN Bus #2 Sensor							RE (O/C)		
	24 A/F	Right					Mos	20-Mar-2008			
	10747P03E25	New	0				Hrs	0			
	07092485	0				Ldg	0				
		AVN Emerg Sensor							RE (O/C)		
	24 A/F	New					Mos	20-Mar-2008			
	10747P03E25		0				Hrs	0			
	07092484		0				Ldg	0			
		AVN Sensor							RE (O/C)		
	24 A/F	Left					Mos	20-Mar-2008			
	10747P03E25	New	0				Hrs	0			
	07092490	0				Ldg	0				
		Battery Power Relay							RE (O/C)		
	24 A/F	Tested/Inspected					Mos	02-Mar-2018			
	k-400B3C-05						Hrs	6,550			
	CR16461						Ldg	5,271			
(APX COST: 0)											
		Boost Pump Sensor							RE (O/C)		
	24 A/F	Left					Mos	20-Mar-2008			
	10747P03E25	New	0				Hrs	0			
	07092496	0				Ldg	0				
		Boost Pump Sensor							RE (O/C)		
	24 A/F	Right					Mos	20-Mar-2008			
	10747P03E25	New	0				Hrs	0			
	07092513	0				Ldg	0				
		Cabin Altitude Module							RE (O/C)		
	24 A/F	Left					Mos	20-Mar-2008			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Cabin Altitude Module							RE (O/C)		
	24 A/F	Right					Mos	20-Mar-2008			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	24 A/F 10747P03E25 07092480	Cabin Fan Sensor						RE (O/C)				
		New						Mos	20-Mar-2008			
			0						Hrs	0		
			0						Ldg	0		
	24 A/F 10747P03E25 07092505	Cockpit Fan Sensor						RE (O/C)				
		New						Mos	20-Mar-2008			
			0						Hrs	0		
			0						Ldg	0		
	24 A/F 7018919-9 0241	Cockpit/Cabin Enviromental Control PCB						RE (O/C)				
		Left New						Mos	20-Mar-2008			
			0						Hrs	0		
			0						Ldg	0		
	24 A/F 7018919-9 0242	Cockpit/Cabin Enviromental Control PCB						RE (O/C)				
		Right New						Mos	20-Mar-2008			
			0						Hrs	0		
			0						Ldg	0		
	24 A/F 10747P03E25 07092514	Condenser Fan Sensor						RE (O/C)				
		New						Mos	20-Mar-2008			
			0						Hrs	0		
			0						Ldg	0		
	24 A/F 10747P03E10 07082381	DC-DC Converter Relay						RE (O/C)				
		New						Mos	20-Mar-2008			
			0						Hrs	0		
			0						Ldg	0		
	24 A/F 7018927-7 0196	Diagnostic Unit						RE (O/C)				
		New						Mos	20-Mar-2008			
			0						Hrs	0		
			0						Ldg	0		
	24 A/F 51525-001F P5060	Digital GCU						RE (O/C)				
		Left New						Mos	10-Jul-2010			
			0						Hrs	1,439		
									Ldg	1,210		
	24 A/F 51525-001F P4772	Digital GCU						RE (O/C)				
		Right New						Mos	10-Jul-2010			
			0						Hrs	1,439		
									Ldg	1,210		
	24 A/F 7018921-8 0133	Door Monitor						RE (O/C)				
		New						Mos	20-Mar-2008			
			0						Hrs	0		
			0						Ldg	0		
	24 A/F CBS24 00418M (APX COST: 2,166.63)	Emergency Inst Battery						RE (O/C)				
		Tested/Inspected						Mos	07-Jun-2023			
									Hrs	9,471.8		
									Ldg	7,591		

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	24 A/F 7018916-9 0362 (APX COST: 0)	Flap Control Module						RE (O/C)			
		Tested/Inspected					Mos	07-Jun-2023			
			7,538.7				Hrs	9,471.8			
			6,151				Ldg	7,591			
	24 A/F 7018925-11 0337 (APX COST: 0)	Flap Monitor						RE (O/C)			
		Tested/Inspected					Mos	07-Jun-2023			
			7,538.7				Hrs	9,471.8			
			6,151				Ldg	7,591			
	24 A/F 7018920-5 0270	Fuel Control Assembly (PCB)						RE (O/C)			
		Left					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
	24 A/F 7018920-5 0269	Fuel Control Assembly (PCB)						RE (O/C)			
		Right					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
	24 A/F 85-230-2 0729-639M2	Fuel Flow Signal PCB Unit						RE (O/C)			
		New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
	24 A/F 7018917-9 0174	Ice Protection Control						RE (O/C)			
		Left					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
	24 A/F Not Installed Not Installed	Ice Protection Control						RE (O/C)			
		Right					Mos	12-Feb-2019			
							Hrs				
							Ldg				
	24 A/F 10747P03E10 07082377	Ignition #1 Sensor Relay						RE (O/C)			
		Left					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
	24 A/F 10747P03E10 07072224	Ignition #1 Sensor Relay						RE (O/C)			
		Right					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
	24 A/F 10747P03E10 07082367	Ignition #2 Sensor Relay						RE (O/C)			
		Left					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
	24 A/F 10747P03E10 07082369	Ignition #2 Sensor Relay						RE (O/C)			
		Right					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	24 A/F	New					Mos	RE (O/C)				
	7018923-12						Hrs	20-Mar-2008				
	0109A						Ldg	0				
			0									
			0									
	24 A/F	New					Mos	RE (O/C)				
	RG-390E/30						Hrs	07-Jun-2023				
	41256300						Ldg	9,471.8				
(AVG MAN HRS: 0) (APX COST: 3,042.61)								7,591				
	24 A/F	New					Mos	RE (O/C)				
	10747P03E25						Hrs	20-Mar-2008				
	07092483						Ldg	0				
			0									
			0									
	24 A/F	New					Mos	RE (O/C)				
	A-931F						Hrs	20-Mar-2008				
	CP-55021						Ldg	0				
			0									
			0									
	24 A/F	Left					Mos	RE (O/C)				
	7018926-1						Hrs	20-Mar-2008				
	0281						Ldg	0				
			0									
			0									
	24 A/F	Right					Mos	RE (O/C)				
	7018926-1						Hrs	20-Mar-2008				
	0282						Ldg	0				
			0									
			0									
	24 A/F	Left					Mos	RE (O/C)				
	7018924-12						Hrs	10-Jul-2010				
	189						Ldg	1,439				
			0						1,210			
			0									
	24 A/F	Right					Mos	RE (O/C)				
	7018924-12						Hrs	10-Jul-2010				
	185						Ldg	1,439				
			0						1,210			
			0									
24-STC-SA02653LA		STC - Concorde Battery (RG-390E/30) STC Installtion						RE (A/R)		STC-Supplemental Type Certificate		
	24 A/F					Mos	30-Oct-2018					
					Hrs	7,125						
	(AVG MAN HRS: 0) (APX COST: 0) (SOURCE: STC SA02653LA)				Ldg	5,711						
B243000		Concorde (RG-390E) Lead-Acid Battery Functional Check (Capacity Check)						T		Inspection Time Limits		
	24 A/F					Mos	07-Jun-2023	12	-/+1m	30-Jun-2024	7.6 Months (+30 Days)	
	RG-390E/30					Hrs	9,471.8					
	41256300					Ldg	7,591					
Task:24-30-10-720 (ZONE: 312) (SOURCE: Model 510 Maintenance Manual) (NOTE: (Refer to the Concorde RG Series Component Maintenance Manual). The inspection interval may need to be reduced based on the battery capacity check results.)												

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
B243000	ICA - Concorde (RG-390E/30) Battery Capacity Check "iaw STC No SA02653LA"						RE (N/A)		Supplemental - ICA	
 24 A/F										Mos
RG-390E/30										Hrs
41158538										Ldg
(AVG MAN HRS: 0) (APX COST: 0) (SOURCE: ICA 5-0171)										
B243002	Standby Instrument Battery Functional Check (Capacity Check)						RE		Inspection Time Limits	≈17-Dec-2023
 24 A/F	05-12-13									
Task:24-30-30-720 (ZONE: 110) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)										
B243003	Teledyne Gill (S1473 or S4324-1) Lead-Acid Battery Functional Check (Capacity Check)						RE (N/A)		Inspection Time Limits	
 24 A/F										Mos
RG-390E/30										Hrs
41158538										Ldg
Task:24-30-10-720 (ZONE: 312) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)										
B244000	External Power Relay Operational Check						RE		Inspection Time Limits	≈01-Jan-2027
 24 A/F	05-12-05									
Task:24-40-00-710 (ZONE: 311, 312) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)										
B246000	Solid State Relay Functional Check						RE		Inspection Time Limits	≈10-Sep-2024
 24 A/F	05-12-03									
Task:24-60-00-720 (ZONE: 311, 312) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)										
Reliability-24-001	Emergency Power Relay (KZ007) Replacement						RE			
 24 A/F										
FCA-325-BY3	New	0								
Form# 1403106										
(AVG MAN HRS: 2) (APX COST: 0)										
SL510-24-01A	Electrical Terminal Hardware Torque Check						RE (-)		Mandatory	
 24 A/F										
Eff: 25-Feb-2008 Not	BY SERIAL NUMBER NOT APPLICABLE									
Applicable										
SL510-24-02	Aft Pressure Bulkhead Connector Inspection						RE (-)		Recommended	
 24 A/F										
Eff: 25-Feb-2008 Not	BY SERIAL NUMBER NOT APPLICABLE									
Applicable										
SL510-24-03	Crew Alerting System (CAS) Electrical Wiring Inspection						RE (-)		Mandatory	
 24 A/F										
Eff: 05-Jun-2008 Not	BY SERIAL NUMBER NOT APPLICABLE									
Applicable										
SL510-24-04	Left Circuit Breaker Panel Pins Inspection/Replacement						RE (-)		Mandatory	
 24 A/F										
Superseded	SUPERSEDED BY REVISION 1									
(NOTE: August 2018)										
SL510-24-04 R01	Left Circuit Breaker Panel Pins Inspection/Replacement						RE (-)		Mandatory	
 24 A/F										
Eff: 24-Sep-2010 Not	BY SERIAL NUMBER NOT APPLICABLE									
Applicable										
(NOTE: evaluated at August 2018)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL510-24-05A	Fuel Control, Start Control and Landing Gear Monitor Printed Circuit Board Replacement						RE (-)		Mandatory	
 24 A/F						Mos				
Eff: 17-Jun-2009 Not Applicable	BY SERIAL NUMBER NOT APPLICABLE					Hrs				
(NOTE: evaluated at August 2018)						Ldg				
SL510-24-06	Fuse Limiter Inspection						RE (-)		Mandatory	
 24 A/F						Mos	14-Sep-2009			
Eff: 16-Jul-2009 Complied With						Hrs	725			
						Ldg				
SL510-24-07	Printed Circuit Board Inpsection						RE (-)		Mandatory	
 24 A/F						Mos				
Eff: 30-Nov-2009 Not Applicable	BY SERIAL NUMBER NOT APPLICABLE					Hrs				
(NOTE: 19/09/2018)						Ldg				
SL510-24-08	Starter/Generator Inspection						RE (-)		Mandatory	
 24 A/F						Mos	11-Feb-2010			
Complied With						Hrs	954.1			
						Ldg	806			
SL510-24-08 R01	Starter/Generator Inspection						RE (-)		Mandatory	
 24 A/F						Mos	11-Feb-2010			
Eff: 10-Mar-2010 Complied With	R1 OF 24-08 COMPLIED WITH BY APPLICATION OF 24-08 ORIGINAL RELEASE.					Hrs	954			
						Ldg	806			
SL510-24-10	Control Wheel Electrical Connector Inspection						RE (-)		Mandatory	
 24 A/F						Mos				
Eff: 29-Jul-2010 Not Applicable	BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0226 THRU 510-0256 ONLY.					Hrs				
						Ldg				
SL510-24-11	Right Circuit Breaker Panel Bus Bar Inspection						RE (-)		Mandatory	
 24 A/F						Mos				
Not Applicable	BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0153 THRU 51-0279, -0281 THRU -0285, -0291 THRU -0294, AND -0296 ONLY.					Hrs				
						Ldg				
SL510-24-11 R01	Right Circuit Breaker Panel Bus Bar Inspection						RE (-)		Mandatory	
 24 A/F						Mos				
Eff: 28-Oct-2010 Not Applicable	BY SERIAL NUMBER -					Hrs				
						Ldg				
SL510-24-12	Control Column Tie Strap Inspection						RE (-)		Mandatory	
 24 A/F						Mos				
Eff: 29-Jul-2010 Not Applicable	BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0253 THRU 510-0323 ONLY.					Hrs				
						Ldg				
SL510-24-13	Throttle Quadrant Wire Bundle Inspection						RE (-)		Mandatory	
 24 A/F						Mos	22-Aug-2011			
Eff: 30-Jun-2011 Complied With	PERFORMED THROTTLE QUADRANT WIRE BUNDLE INSPECTION SERVICE LETTER					Hrs	2,513			
						Ldg	2,113			
SL510-24-14	Electrical Power - Printed Circuit Board Verification						RE (-)		Mandatory	
 24 A/F						Mos	30-Sep-2016			
Eff: 13-Sep-2016 Complied With						Hrs	5,764.8			
(AVG MAN HRS: 3)						Ldg	4,639			

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL510-24-14 R01		Electrical Power - Printed Circuit Board Verification								RE (-)	Mandatory
	24 A/F						Mos	30-Sep-2016			
	Eff: 28-Sep-2016 Complied With						Hrs	5,764.8			
	(AVG MAN HRS: 3)						Ldg	4,639			
▼ 25 - EQUIPMENT/FURNISHINGS											
		Life Vest (Infant)								RE (O/C)	
	25 A/F	No.1					Mos	31-May-2016			
	A316101A	New					Hrs	0			
	34069-045						Ldg	0			
		Life Vest (Infant)								RE (O/C)	
	25 A/F	No.2					Mos	31-May-2016			
	A316101A	New					Hrs	0			
	34609-038						Ldg	0			
		ELT Antenna								RE (O/C)	
	25 A/F						Mos	22-Aug-2018			
	110-340	New					Hrs	7,007.8			
	5034718						Ldg	5,616			
		(AVG MAN HRS: 0) (APX COST: 1,178.73)									
		Emergency Locator Transmitter (ELT)								RE (O/C)	
	25 A/F						Mos	20-Mar-2008			
	453-5060	New	0				Hrs	0			
	03962		0				Ldg	0			
		Emergency Locator Transmitter (ELT) Battery Pack								RE	Component Time Limits
	25 A/F						Yrs	07-Jun-2023	5	02-Nov-2027	4 Years
	452-0133	New					Hrs	9,471.8			
	396414-029						Ldg	7,591			
		Manufactured Date 02-Nov-2022									
		MM:5-11-00, Task:25-60-20-960 (AVG MAN HRS: 0) (APX COST: 590.09) (SOURCE: Model 510 Maintenance Manual)									
		Glareshield Assembly								RE (O/C)	
	25 A/F						Mos	20-Mar-2008			
	4319027-13	New	0				Hrs	0			
	106103-3		0				Ldg	0			
		Life Vest								RE (O/C)	
	25 A/F	Copilot	11				Mos	20-Mar-2019			
	P01074-207	New	0				Hrs				
	19031760086		0				Ldg				
		Life Vest								RE (O/C)	
	25 A/F	No.1	2				Mos	16-Jan-2019			
	P01074-207	New	0				Hrs	7,198.5			
	18081520400		0				Ldg	5,773			
		(APX COST: 73.57)									
		Life Vest								RE (O/C)	
	25 A/F	No.2	2				Mos	16-Jan-2019			
	P01074-207	New	0				Hrs	7,198.5			
	18081520396		0				Ldg	5,773			
		(APX COST: 73.57)									

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
25 A/F P01074-207 18081770332 (APX COST: 73.57)	Life Vest No.3 New						RE (O/C)			
		2			Mos	16-Jan-2019				
		0			Hrs	7,198.5				
		0			Ldg	5,773				
25 A/F P01074-207 18081770335 (APX COST: 73.57)	Life Vest No.4 New						RE (O/C)			
		2			Mos	16-Jan-2019				
		0			Hrs	7,198.5				
		0			Ldg	5,773				
25 A/F P01074-207 19100510025	Life Vest Pilot New						RE (O/C)			
					Mos	10-Apr-2019				
					Hrs	0				
					Ldg	0				
2007-0256-CN	CANCELLED: Equipment / Furnishings - Seat Restraint System Plastic Rotary Buckle Handle - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 11-May-2021 Not Applicable (NOTE: NOTE: This Notice cancels EASA AD 2007-0256 dated 19 September 2007.)	N/A AD cancelled				Mos	08-Nov-2022				
					Hrs	9,471.8				
					Ldg	7,591				
2013-0020	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Feb-2013 Not Applicable					Mos	10-Jun-2013				
					Hrs	3,391				
					Ldg	2,853				
2013-0020 Paragraph (1)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Feb-2013 Not Applicable					Mos	10-Jun-2013				
					Hrs	3,391				
					Ldg	2,853				
2013-0020 Paragraph (2)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - verify if the organisation is listed among the authorized maintenance or repair organisation						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Feb-2013 Not Applicable					Mos	10-Jun-2013				
					Hrs	3,391				
					Ldg	2,853				
2013-0020 Paragraph (3)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Feb-2013 Not Applicable					Mos	10-Jun-2013				
					Hrs	3,391				
					Ldg	2,853				
2013-0020R1	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 12-Mar-2013 Not Applicable					Mos					
					Hrs					
					Ldg					
2013-0020R1 Paragraph (1)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 12-Mar-2013 Not Applicable					Mos					
					Hrs					
					Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
2013-0020R1 Paragraph (2)		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - verify if the organisation is listed among the authorized maintenance or repair organisation						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos					
	Eff: 12-Mar-2013					Hrs					
						Ldg					
2013-0020R1 Paragraph (3)		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Replacement						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos					
	Eff: 12-Mar-2013 Not Applicable					Hrs					
						Ldg					
2013-0020R2		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos	28-Jul-2013				
	Eff: 14-Feb-2013 Not Applicable					Hrs	3,408.4				
						Ldg	2,871				
2013-0020R2 Paragraph (1)		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos	28-Jul-2013				
	Eff: 14-Feb-2013 Not Applicable					Hrs	3,408.4				
						Ldg	2,871				
2013-0020R2 Paragraph (2)		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - verify if the organisation is listed among the authorized maintenance or repair organisation						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos	28-Jul-2013				
	Eff: 14-Feb-2013 Not Applicable					Hrs	3,408.4				
						Ldg	2,871				
2013-0020R2 Paragraph (3)		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Replacement						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos	28-Jul-2013				
	Eff: 14-Feb-2013 Not Applicable					Hrs	3,408.4				
						Ldg	2,871				
2013-0020R3		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos					
	Eff: 28-Mar-2014 Not Applicable					Hrs					
						Ldg					
2013-0020R3 Paragraph (1)		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos					
	Eff: 28-Mar-2014 Not Applicable					Hrs					
						Ldg					
2013-0020R3 Paragraph (2)		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - verify if the organisation is listed among the authorized maintenance or repair organisation						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos					
	Eff: 28-Mar-2014					Hrs					
						Ldg					
2013-0020R3 Paragraph (3)		AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Replacement						RE (-)		Mandatory (Appliance AD)	
	25 A/F					Mos					
	Eff: 28-Mar-2014					Hrs					
						Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2013-0020R4	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos	04-Jul-2014				
Eff: 11-Jul-2014 Not Applicable					Hrs	4,041.5				
					Ldg	3,378				
2013-0020R4 Paragraph (1)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection						RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos	04-Jul-2014				
Eff: 11-Jul-2014 Not Applicable					Hrs	4,041.5				
					Ldg	3,378				
2013-0020R4 Paragraph (2)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - verify if the organisation is listed among the authorized maintenance or repair organisation						T (A/R)		Mandatory (Appliance AD)	
25 A/F					Mos					
Eff: 11-Jul-2014 Not Applicable					Hrs					
					Ldg					
2013-0020R4 Paragraph (3)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos					
Eff: 14-Feb-2013 Not Applicable					Hrs					
					Ldg					
2019-0235	ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Inspection / Modification / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos					
Eff: 04-Oct-2019 Not Applicable	Original ELT installed				Hrs					
					Ldg					
2019-0235 Par. (1)(2)	ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Inspection / Testing						RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos					
Not Applicable	Original ELT installed				Hrs					
					Ldg					
2019-0235 Par. (3)(4)	ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Repetitive Test Interval Reduction						RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos					
Eff: 04-Oct-2019 Not Applicable	Original ELT installed				Hrs					
(NOTE: COMPLIANCE: Within 30 days after the effective date of this AD, reduce the interval of the G-switch testing, as required by paragraph (1.1) of this AD, to the applicable value as specified in section 8 of the SB.)					Ldg					
2019-0235 Par. (5)(6)	ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Modification / Replacement (Terminating Action)						RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos					
Eff: 04-Oct-2019 Not Applicable	Original ELT installed				Hrs					
					Ldg					
2021-0137	Equipment/Furnishings - Pilot and Co-Pilot Seats/Longitudinal Locking System Pins - Measurement/Adjustment						RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos	15-Nov-2021				
Eff: 22-Jun-2021 Not Applicable					Hrs	9,014.2				
(NOTE: APPLICABILITY: 191 series pilot seats, having Part Number (P/N) 19101-00-00, and 191 series co-pilot seats, having P/N 19102-00-00.					Ldg	7,227				
COMPLIANCE: Within 750 flight hours after the effective date of this AD, measure the length of the LH and RH locking pin installed in the longitudinal seat locking system in accordance with the instructions of the SB.)										
25-05-0215	Interior Configuration Change IAW Leat Modification EO No 25-05-0215						RE (A/R)		Custom Task	
25 A/F					Mos	15-Jan-2016				
					Hrs					
					Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
256001	25 A/F P01074-207 19031760086 Restored Date 20-Mar-2019	Life Vest - Restoration Copilot								RE	
										120	20-Mar-2029 5.3 Years
256001	25 A/F P01074-207 18081520400 Restored Date 15-Aug-2018	Life Vest - Restoration No.1								RE	
										120	15-Aug-2028 4.8 Years
256001	25 A/F P01074-207 18081520396 Restored Date 15-Aug-2018	Life Vest - Restoration No.2								RE	
										120	15-Aug-2028 4.8 Years
256001	25 A/F P01074-207 18081770332 Restored Date 17-Aug-2018	Life Vest - Restoration No.3								RE	
										120	17-Aug-2028 4.8 Years
256001	25 A/F P01074-207 18081770335 Restored Date 17-Aug-2018	Life Vest - Restoration No.4								RE	
										120	17-Aug-2028 4.8 Years
256001	25 A/F P01074-207 19100510025 Restored Date 10-Apr-2019	Life Vest - Restoration Pilot								RE	
										120	10-Apr-2029 5.4 Years
256001	25 A/F A316101A 34069-045 Restored Date 31-May-2016	Life Vest (Infant) - Restoration No.1								RE	
										120	31-May-2026 2.5 Years
256001	25 A/F A316101A 34609-038 Restored Date 31-May-2016	Life Vest (Infant) - Restoration No.2								RE	
										120	31-May-2026 2.5 Years
A252000	25 A/F Task:25-20-10-220 (ZONE: 241, 242) (SOURCE: Model 510 Maintenance Manual)	Cabin Seats and Restraint System Detailed Inspection 05-12-20								RE	Inspection Time Limits
										48	-/+1m (31-Jan-2024) 76 Days (+29)
										2,700	-/+25 (10,578.4) 727.9 Hrs (+25)
										6,337	

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
A256000		First Aid Kit Detailed Inspection								RE	Inspection Time Limits	
	25 A/F	05-12-06					Mos	07-Jun-2023	6	-/+ 1m	31-Dec-2023	45 Days (+31)
		Task:25-60-00-220 (ZONE: 241, 242) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8				
							Ldg	7,591				
A256001		Overwater Passenger Life Jacket Detailed Inspection								RE	Inspection Time Limits	
	25 A/F	05-12-06					Mos	07-Jun-2023	12	-/+ 1m	(30-Jun-2024)	7.6 Months (+30 Days)
		Task:25-60-00-221 (ZONE: 241, 242) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8				
							Ldg	7,591				
A256002		Smoke Goggles Detailed Inspection								RE	Inspection Time Limits	
	25 A/F	05-12-06					Mos	07-Jun-2023	12	-/+ 1m	(30-Jun-2024)	7.6 Months (+30 Days)
		Task:25-60-00-222 (ZONE: 231, 232) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8				
							Ldg	7,591				
A256003		ELT System Detailed Inspection								RE	Inspection Time Limits	
	25 A/F	05-12-21					Mos	07-Jun-2023	12	-/+ 1m	(30-Jun-2024)	7.6 Months (+30 Days)
		Task:25-60-20-220 (ZONE: 311, 312) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8				
							Ldg	7,591				
B251000		Crew Seats and Restraint System Detailed Inspection								RE	Inspection Time Limits	
	25 A/F	05-12-20					Mos	22-Jan-2020	48	-/+ 1m	(31-Jan-2024)	76 Days (+29)
		Task:25-10-00-220 (ZONE: 231, 232) (SOURCE: Model 510 Maintenance Manual)					Hrs	7,878.4	2,700	-/+25	(10,578.4)	727.9 Hrs (+25)
							Ldg	6,337				
B256000		ELT System Operational Check								RE	Inspection Time Limits	
	25 A/F	05-12-21					Mos	07-Jun-2023	12	-/+ 1m	(30-Jun-2024)	7.6 Months (+30 Days)
		Task:25-60-20-720 (ZONE: 228, 311,312) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8				
							Ldg	7,591				
Reliability-25-001		Check Flight Crew Seat movement by operating forward and aft control, tilt control, and up or down control i.a.w. Ch. 25-10-00 and check for correct installation of the Seat Belt to the Seat Frame i.a.w. Ch. 25-10-10.								RE		
	25 A/F						Mos	07-Jun-2023	12	-/+ 1m	07-Jun-2024	6.8 Months (+30 Days)
		(AVG MAN HRS: 4)					Hrs	9,471.8				
							Ldg	7,591				
SB510-25-02		Aft Cabin Curtain Improvement								T (A/R)	Optional	
	25 A/F						Mos					
		Eff: 14-Jul-2011 Declined NOT OF INTEREST					Hrs					
		(NOTE: 19/09/2018)					Ldg					
SB510-25-03		Removal of the Cabin Sidewall Air Diffuser								RE (-)	Discretionary	
	25 A/F						Mos	12-Jun-2012				
		Eff: 03-Nov-2011 Complied PERFORMED REMOVAL OF THE CABIN SIDEWALL AIR DIFFUSER SERVICE BULLETIN					Hrs	2,965				
		With					Ldg	2,498				
SB510-25-04		Equipment/Furnishings - Cabin Comfort Improvements								T (A/R)	Optional	
	25 A/F						Mos					
		Eff: 14-Apr-2018 Declined Not of interest.					Hrs					
		(NOTE: 14th March 2019)					Ldg					
SL510-25-02		Crew Seat Control Assembly Screw Inspection								RE (-)	Mandatory	
	25 A/F						Mos	25-Jun-2010				
		Eff: 12-May-2010 Complied APPLIED SL25-02					Hrs	1,379				
		With					Ldg	1,154				

Task No		Description								Categories		Time				
SEQ	PN/SN	MOC Note or Component Condition					TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
SL510-25-03		Crew Seat Inspection Revision 1										RE (-)		Mandatory		
	25 A/F											Mos				
	Superseded	SUPERSEDED BY REVISION 1										Hrs				
	(NOTE: 19/09/2018)											Ldg				
SL510-25-03 R01		Crew Seat Inspection Revision 1										RE (-)		Mandatory		
	25 A/F											Mos				
	Eff: 06-Jan-2012 Not Applicable	BY SERIAL NUMBER NOT APPLICABLE										Hrs				
	(NOTE: 19/09/2018)											Ldg				
▼ 26 - FIRE PROTECTION																
		Engine Fire Bottle removal										RE (-)				
	26 A/F											Mos		02-Apr-2018		
	Not Installed											Hrs		6,643		
	Not Installed											Ldg		5,343		
		(AVG MAN HRS: 0) (APX COST: 0)														
		Engine Fire Extinguisher										RE (O/C)				
	26 A/F											Mos		07-Jun-2023		
	9912048-6	Overhauled						6,662.9		0	Hrs		9,471.8			
	57131B1							5,389		0	Ldg		7,591			
		(AVG MAN HRS: 0) (APX COST: 1,005.16)														
		Engine fire extinguisher cartridge										RE		Component Time Limits		
	26 A/F	Left								Yrs		07-Jun-2023		6	31-Oct-2028	5 Years
	AE13083-5	New								Hrs		9,471.8				
	A1341									Ldg		7,591				
		Manufactured Date 31-Oct-2022														
		MM:5-11-00, Task:26-20-00-960 (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)														
		Engine fire extinguisher cartridge										RE		Component Time Limits		
	26 A/F	Right								Yrs		07-Jun-2023		6	31-Oct-2028	5 Years
	AE13083-5	New								Hrs		9,471.8				
	A1343									Ldg		7,591				
		Manufactured Date 31-Oct-2022														
		MM:5-11-00, Task:26-20-00-960 (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)														
		Fire -Engine Loop Detector										RE (O/C)				
	26 A/F	No.1								Mos		20-Mar-2008				
	3001-212-1004/455-9	New						0		Hrs		0				
	208317							0		Ldg		0				
		Fire -Engine Loop Detector										RE (O/C)				
	26 A/F	No.2								Mos		07-Jun-2023				
	3001-212-1004/455-9	Tested/Inspected						7,587.3		Hrs		9,471.8				
	209288							6,140		Ldg		7,591				
		(APX COST: 0)														
		Portable Fire Extinguisher										RE (O/C)				
	26 A/F	05-12-12						4		Mos		08-May-2020		(31-May-2032)	8.5 Years (+30 Days)	
	C352CS	New						0		Hrs		7,976.4				
	F-75061875							0		Ldg		6,420				
		(APX COST: 517.96)														
2009-0251-E		Fire Fighting Enterprises Ltd - Fire Protection - Portable Fire Extinguishers - Identification / Replacement										RE (-)		Mandatory (Appliance AD)		
	26 A/F											Mos		21-Nov-2012		
	Eff: 26-Nov-2009 Not Applicable	ALL FIRE EXTINGUISHERS INSTALLED ARE PRODUCED BY AMEREX										Hrs		3,220.3		
												Ldg		2,716		

Task No	Description									Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
2009-0278	SICLI - Fire Protection - Portable Halon 1211 Fire Extinguishers - Identification / Replacement										RE (-)	Mandatory (Appliance AD)
26 A/F						Mos	21-Nov-2012					
Eff: 05-Jan-2010 Not Applicable		ALL FIRE EXTINGUISHERS INSTALLED ARE PRODUCED BY AMEREX				Hrs	3,220.3					
						Ldg	2,716					
2010-01-03	Fire Fighting Enterprises Limited - Fire Protection										RE (-)	Mandatory (Appliance AD)
26 A/F						Mos	21-Nov-2012					
Eff: 20-Jan-2010 Not Applicable		ALL FIRE EXTINGUISHERS INSTALLED ARE PRODUCED BY AMEREX				Hrs	3,220.3					
Brand A:9990-2010-01-03						Ldg	2,716					
2010-04-16	SICLI - Identification & Removal of Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers										RE (-)	Mandatory (Appliance AD)
26 A/F						Mos	21-Nov-2012					
Eff: 08-Mar-2010 Not Applicable		ALL FIRE EXTINGUISHERS INSTALLED ARE PRODUCED BY AMEREX				Hrs	3,220.3					
Brand A:9990-2010-04-16 (NOTE: Within 90 days after the effective date of this AD, replace all Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers manufactured by SICLI, having P/N 1708337B4 and having any serial number listed in Table 1 of this AD, with serviceable fire extinguishers)						Ldg	2,716					
2016-0024	Fire Protection - Optical and Ambient Smoke Detectors - Identification / Replacement										RE (-)	Mandatory (Appliance AD)
26 A/F						Mos	09-Mar-2016					
Eff: 01-Feb-2016 Not Applicable						Hrs						
						Ldg						
2016-0024 Paragraph (1)	Fire Protection - Optical and Ambient Smoke Detectors - Identification										RE (-)	Mandatory (Appliance AD)
26 A/F						Days	09-Mar-2016					
Eff: 01-Feb-2016 Not Applicable						Hrs						
(NOTE: Part Number (P/N) PMC1102-02, P/N PMC3100-00 and P/N GMC1102-02 smoke detectors, having a date of manufacture (DMF, in digits as 'MMYYYY', e.g. 072010, see Appendix 2 of this AD) between November 2010 to January 2013 inclusive, and certain repaired units, as identified by P/N and serial number (s/n) in Appendix 1 of this AD)						Ldg						
2016-0024 Paragraph (2)	Fire Protection - Optical and Ambient Smoke Detectors - Replacement										RE (-)	Mandatory (Appliance AD)
26 A/F						Mos	09-Mar-2016					
Eff: 01-Feb-2016 Not Applicable						Hrs						
(NOTE: P/N PMC1102-02 Detectors (Cargo Compartments) Manufacturing Date (month/year) 122010 to 112011 inclusive and P/N PMC3100-00 Detectors (Cargo Compartments) Manufacturing Date (month/year) 032011 to 012012 inclusive)						Ldg						
2021-0185	Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement										RE (-)	Mandatory (Appliance AD)
26 A/F						Mos	08-Nov-2022					
Eff: 19-Aug-2021 Not Applicable		N/A by PN				Hrs	9,471.8					
(NOTE: APPLICABILITY: For Group 1 aircraft with HAFEX (Halon-free) hand-held fire extinguishers, having Part Number (P/N) P3APP003010A, P/N P3APP003010B or P/N P3APP003010C, all serial numbers (s/n). COMPLIANCE: Within 30 days after the effective date of this AD, and, thereafter, at intervals not to exceed 6 months, inspect each affected fire extinguisher in accordance with the instructions of paragraph 3.2.C of the VSB, or equivalent maintenance instructions issued by the design (change) approval holder (see Note 1 of this AD).)						Ldg	7,591					
2021-0185R1	Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement										RE (-)	Mandatory (Appliance AD)
26 A/F						Mos	08-Nov-2022					
Eff: 19-Aug-2021 Not Applicable		N/A by PN				Hrs	9,471.8					
(NOTE: APPLICABILITY: For aircraft with HAFEX (Halon-free) hand-held fire extinguishers, having Part Number (P/N) P3APP003010A, P/N P3APP003010B or P/N P3APP003010C, all serial numbers (s/n). COMPLIANCE: Within 30 days after the effective date of this AD, and, thereafter, at intervals not to exceed 6 months, inspect each affected fire extinguisher installed on any aircraft, in accordance with the instructions of paragraph 3.2.C of the VSB, or in accordance with equivalent maintenance instructions issued by the aircraft design (change) approval holder (see Note 1 of this AD).)						Ldg	7,591					

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
2021-0185R2	Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement						RE		Mandatory (Appliance AD)	
26 A/F					Mos	05-Nov-2023	12		05-Nov-2024	11.8 Months
Eff: 14-Sep-2022 Not Applicable	N/A by P/N Installed				Hrs	9,837.4				
	(NOTE: APPLICABILITY: HAFEX (Halon-free) hand-held fire extinguishers, having Part Number (P/N) P3APP003010A, P/N P3APP003010B or P/N P3APP003010C, all serial numbers (s/n). COMPLIANCE: Within 30 days after the effective date of this AD, or within 12 months after the last inspection, as applicable, and, thereafter, at intervals not to exceed 12 months, inspect each affected fire extinguisher installed on any aircraft, in accordance with the instructions of paragraph 3.2.C of the VSB, or in accordance with equivalent maintenance instructions issued by the aircraft design (change) approval holder (see Note 1 of this AD).)				Ldg	7,886				
26-20-00-960	Engine fire extinguisher cartridge - Service Life						RE		Component Time Limits	
26 A/F	Left				Yrs	07-Jun-2023	6		07-Jun-2029	5.6 Years
AE13083-5					Hrs	9,471.8				
A1341					Ldg	7,591				
	MM:5-11-00 (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: Service life is the amount of time the explosive cartridge is installed in a fire extinguisher. Service life of any particular explosive cartridge can not be extended.)									
26-20-00-960	Engine fire extinguisher cartridge - Service Life						RE		Component Time Limits	
26 A/F	Right				Yrs	07-Jun-2023	6		07-Jun-2029	5.6 Years
AE13083-5					Hrs	9,471.8				
A1343					Ldg	7,591				
	MM:5-11-00 (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: Service life is the amount of time the explosive cartridge is installed in a fire extinguisher. Service life of any particular explosive cartridge can not be extended.)									
A261000	Engine Fire Detection System General Visual Inspection						RE		Inspection Time Limits	≈10-Sep-2024
26 A/F	05-12-16				Mos	17-Mar-2022	36	-/+1m	(31-Mar-2025)	1.4 Years (+30 Days)
					Hrs	9,146.2	1,350	-/+25	(10,496.2)	645.7 Hrs (+25)
	Task:26-10-00-210 (ZONE: 410, 420) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)				Ldg	7,338				
A262100	Portable Fire Extinguisher Restoration (Internal Inspection)						RE		Inspection Time Limits	
26 A/F	05-12-11				Mos	07-Jun-2023	72	-/+1m	31-Jan-2026	2.2 Years (+28 Days)
C352CS					Hrs	9,471.8				
F-75061875					Ldg	7,591				
	Restored Date 03-Jan-2020 Task:26-21-00-280 (ZONE: 241, 242) (SOURCE: Model 510 Maintenance Manual)									
B262000	Firewall Shutoff Valve Operational Check						RE		Inspection Time Limits	≈17-Dec-2023
26 A/F	05-12-01				Mos	07-Jun-2023				
					Hrs	9,471.8	450	-/+25	(9,921.8)	71.3 Hrs (+25)
	Task:26-20-00-710 (ZONE: 224, 315,316) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)				Ldg	7,591				
B262002	Engine Fire Extinguishing System Functional Check						RE		Inspection Time Limits	≈10-Sep-2024
26 A/F	05-12-16				Mos	17-Mar-2022	36	-/+1m	(31-Mar-2025)	1.4 Years (+30 Days)
					Hrs	9,146.2	1,350	-/+25	(10,496.2)	645.7 Hrs (+25)
	Task:26-20-00-721 (ZONE: 224, 315,316) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)				Ldg	7,338				
B262004	Engine Fire Extinguisher Bottle Restoration (Hydrostatic Test)						RE		Inspection Time Limits	
26 A/F					Mos	07-Jun-2023	60	-/+1m	31-Mar-2028	4.4 Years (+30 Days)
9912048-6					Hrs	9,471.8				
57131B1					Ldg	7,591				
	Hydrostatic Tested Date 30-Mar-2023 Task:26-20-00-961 (ZONE: 311, 312) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									
B262100	Portable Fire Extinguisher Functional check (Weight Check)						RE		Inspection Time Limits	
26 A/F	05-12-06				Mos	07-Jun-2023	6	-/+1m	30-Nov-2023	14 Days (+30)
C352CS					Hrs	9,471.8				
F-75061875					Ldg	7,591				
	07-Jun-2023 Task:26-21-00-700 (ZONE: 241, 242) (AVG MAN HRS: 0) (APX COST: 0) (Tol. Adjustment: -29d) (SOURCE: Model 510 Maintenance Manual)									

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
B262101		Portable Fire Extinguisher Restoration (Hydrostatic Test)								RE	Inspection Time Limits	
	26 A/F	05-12-12					Mos	08-May-2020	144	-/+1m	31-Jan-2032	8.2 Years (+29 Days)
	C352CS						Hrs	7,976.4				
	F-75061875						Ldg	6,420				
	Hydrostatic Tested Date 03-Jan-2020											
	Task:26-21-00-960 (ZONE: 241, 242) (SOURCE: Model 510 Maintenance Manual)											
▼ 27 - FLIGHT CONTROLS												
		Aileron Trim Actuator								RE (O/C)		
	27 A/F	New					Mos	20-Mar-2008				
	SYLC-53361-1		0				Hrs	0				
	0155		0				Ldg	0				
		Control Wheel Assy								RE (O/C)		
	27 A/F	Left New					Mos	20-Mar-2008				
	4319065-1		0				Hrs	0				
	1187		0				Ldg	0				
		Control Wheel Assy								RE (O/C)		
	27 A/F	Right New					Mos	20-Mar-2008				
	4319065-2		0				Hrs	0				
	1178		0				Ldg	0				
		Elevator Trim Tab Actuator								RE (O/C)		
	27 A/F	Left					Mos	20-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Elevator Trim Tab Actuator								RE (O/C)		
	27 A/F	Right					Mos	20-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Flap Actuator								RE (O/C)		
	27 A/F	Left Repaired			44	Mos	03-Feb-2022					
	9912640-1				0	Hrs	9,102.5					
	0678				0	Ldg	7,303					
		(APX COST: 10,775.84)										
		Flap Actuator								RE (O/C)		
	27 A/F	Right Repaired			14	Mos	03-Feb-2022					
	9912640-2				0	Hrs	9,102.5					
	0712				0	Ldg	7,303					
		(APX COST: 10,984.23)										
		Flap Flex Shaft Assembly								RE (O/C)		
	27 A/F	Left New					Mos	20-Mar-2008				
	140527-5200		0				Hrs	0				
	0193		0				Ldg	0				
		Flap Flex Shaft Assembly								RE (O/C)		
	27 A/F	Right New	0				Mos	26-Oct-2011				
	140527-5900		0				Hrs	2,660				
	0131		0				Ldg	2,229				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
Flap PDU (Power Drive Unit)								RE (O/C)			
	27 A/F	Overhauled					Mos	21-Mar-2019			
	9912642-1						Hrs	7,282.7			
	0104AC						Ldg	5,847			
	(APX COST: 2,987.56)										
Rudder Trim Actuator								RE (O/C)			
	27 A/F	New					Mos	20-Mar-2008			
	SYLC-53361-1		0				Hrs	0			
	0159		0				Ldg	0			
Speed Brake Actuator								RE (O/C)			
	27 A/F	Left					Mos	10-Feb-2012			
	41014070-104	Overhauled	0				Hrs	2,810.2			
	0099		0				Ldg	2,349			
Speed Brake Actuator								RE (O/C)			
	27 A/F	Right	0				Mos	11-Nov-2011			
	41014070-104	Overhauled	0				Hrs	2,658			
	0346		0				Ldg	2,227			
A270000		Flight Control Hinges General Visual Inspection						RE		Inspection Time Limits	
	27 A/F	05-12-MD					Mos	07-Jun-2023	12	(02-Feb-2024) 78 Days	
							Hrs	9,471.8			
							Ldg	7,591			
	MM:5-10-01, MM:4-10-00, Task:27-00-00-210 (ZONE: 341, 351, 352, 532, 632) (AVG MAN HRS: 0) (APX COST: 0) (Tol. Adjustment: -124d) (SOURCE: Model 510 Maintenance Manual)										
A270001		Flight Control Cable Guide, Fairlead, and Aileron Sector General Visual Inspection						RE		Inspection Time Limits ≈17-Dec-2023	
	27 A/F	05-12-01					Mos	07-Jun-2023			
							Hrs	9,471.8	450	-/+25	(9,921.8) 71.3 Hrs (+25)
	Task:27-00-00-211 (ZONE: 312, 522, 622, 532, 632) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Ldg	7,591			
A271000		Aileron System Detailed Inspection						RE		Inspection Time Limits ≈10-Sep-2024	
	27 A/F	05-12-16					Mos	17-Mar-2022	36	-/+1m	(31-Mar-2025) 1.4 Years (+30 Days)
							Hrs	9,146.2	1,350	-/+25	(10,496.2) 645.7 Hrs (+25)
	Task:27-10-00-220 (ZONE: 131, 132, 141, 142, 231, 232, 241, 242, 315, 316) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 512, 522, 532, 612, 622, 632)						Ldg	7,338			
A272000		Rudder System Detailed Inspection						RE		Inspection Time Limits ≈10-Sep-2024	
	27 A/F	05-12-16					Mos	17-Mar-2022	36	-/+1m	(31-Mar-2025) 1.4 Years (+30 Days)
							Hrs	9,146.2	1,350	-/+25	(10,496.2) 645.7 Hrs (+25)
	Task:27-20-00-220 (ZONE: 131, 132, 141, 142, 221, 222, 231, 232, 241, 242) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 311, 312, 313, 314, 321, 322, 340)						Ldg	7,338			
A273000		Elevator System Detailed Inspection						RE		Inspection Time Limits ≈10-Sep-2024	
	27 A/F	05-12-16					Mos	17-Mar-2022	36	-/+1m	(31-Mar-2025) 1.4 Years (+30 Days)
							Hrs	9,146.2	1,350	-/+25	(10,496.2) 645.7 Hrs (+25)
	Task:27-30-00-220 (ZONE: 131, 132, 141, 142, 221, 222, 231, 232, 241, 242) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 311, 312, 313, 314, 321, 322, 340, 351, 352)						Ldg	7,338			
A275000		Flap System Detailed Inspection						RE		Inspection Time Limits	
	27 A/F	05-12-14					Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024) 7.6 Months (+30 Days)
							Hrs	9,471.8	900	-/+25	(10,371.8) 521.3 Hrs (+25)
	Task:27-50-00-220 (ZONE: 315, 316) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Ldg	7,591			
A276000		Speed Brake System Detailed Inspection (Airplanes -0001 thru -0314)						RE		Inspection Time Limits ≈17-Dec-2023	
	27 A/F	05-12-13					Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024) 7.6 Months (+30 Days)
							Hrs	9,471.8	450	-/+25	(9,921.8) 71.3 Hrs (+25)
	Task:27-60-00-220 (ZONE: 522, 622) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Ldg	7,591			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
A276001		Rotary Speed Brake System Detailed Inspection (Airplanes -0315 and On)						RE (N/A)		Inspection Time Limits	
	27 A/F	Task:27-60-10-220 (ZONE: 522, 622) (SOURCE: Model 510 Maintenance Manual)									
B271000		Aileron Control Cable Functional Test						RE		Inspection Time Limits ≈10-Sep-2024	
	27 A/F	05-12-16 Task:27-10-00-720 (ZONE: 131, 132, 141, 142, 231, 232, 241, 242, 315, 316) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 512, 522, 532, 612, 622, 632)									
B271001		Aileron Trim Tab Free Play Functional Check						RE		Inspection Time Limits ≈10-Sep-2024	
	27 A/F	05-12-16 Task:27-10-00-721 (RII ITEM) (ZONE: 540) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									
B272000		Rudder Control Cable Functional Test						RE		Inspection Time Limits ≈10-Sep-2024	
	27 A/F	05-12-16 Task:27-20-00-720 (ZONE: 131, 132, 141, 142, 221, 222, 231, 232, 241, 242) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 311, 312, 313, 314, 321, 322, 340)									
B272001		Rudder Trim Tab Free Play Functional Check						RE		Inspection Time Limits ≈10-Sep-2024	
	27 A/F	05-12-16 Task:27-20-00-721 (RII ITEM) (ZONE: 341) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									
B273000		Elevator Control Cable Functional Test						RE		Inspection Time Limits ≈10-Sep-2024	
	27 A/F	05-12-16 Task:27-30-00-720 (ZONE: 131, 132, 141, 142, 221, 222, 231, 232, 241, 242) (AVG MAN HRS: 0) (APX COST: 559.83) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 311, 312, 313, 314, 321, 322, 340, 351, 352)									
B273001		Elevator Trim Tab Free Play Functional Check						RE		Inspection Time Limits ≈10-Sep-2024	
	27 A/F	05-12-16 Task:27-30-00-721 (RII ITEM) (ZONE: 351, 352) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									
B275000		Flap Cable Functional Test						RE		Inspection Time Limits	
	27 A/F	05-12-14 Task:27-50-00-720 (ZONE: 315, 316,512, 612) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									
C272000		Rudder Pedal Torque Tube Lubrication						RE		Inspection Time Limits ≈17-Dec-2023	
	27 A/F	05-12-13 Task:27-20-00-640 (ZONE: 131, 132) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									
C273000		Elevator Trim Tab Actuator Lubrication						RE		Inspection Time Limits ≈17-Dec-2023	
	27 A/F	05-12-13 Task:27-30-00-640 (ZONE: 351, 352) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									
C275000		Flap Flexible Drive Shaft Lubrication						RE		Inspection Time Limits ≈17-Dec-2023	
	27 A/F	05-12-13 Task:27-50-00-640 (RII ITEM) (ZONE: 315, 316,512, 612) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
C275001		Flap Actuator Lubrication								RE	Inspection Time Limits	
	27 A/F	05-12-06					Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)
		Task:27-50-00-641 (ZONE: 522, 622) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8				
							Ldg	7,591				
C276000		Speed Brake Actuator Lubrication (Airplanes -0001 thru -0314)								RE	Inspection Time Limits	≈17-Dec-2023
	27 A/F	05-12-13					Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)
		Task:27-60-00-640 (ZONE: 522, 622) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8	450	-/+25	(9,921.8)	71.3 Hrs (+25)
							Ldg	7,591				
SB510-27-01		Aileron Shield Sealant Revision								RE (-)	Mandatory	
	27 A/F						Mos	11-Feb-2010				
		Eff: 05-Jun-2009 Complied With					Hrs	954.1				
							Ldg	806				
SB510-27-02		Speed Brake Mechanical Switch Conversion								RE (-)	Recommended	
	27 A/F						Mos	19-Jul-2013				
		Eff: 27-Feb-2013 Complied With					Hrs	3,391				
		PERFORMED SB510-27-02					Ldg	2,853				
SL510-27-01		Flap Actuator Installation Setscrew Inspection								RE (-)	Recommended	
	27 A/F						Mos					
		Eff: 19-Mar-2008 Not Applicable					Hrs					
		BY SERIAL NUMBER NOT APPLICABLE					Ldg					
		(NOTE: 19/09/2018)										
SL510-27-01A		Elevator Autopilot Cable Inspection								RE (-)	Mandatory	
	27 A/F						Mos					
		Eff: 10-Sep-2007 Not Applicable					Hrs					
		BY SERIAL NUMBER NOT APPLICABLE					Ldg					
		(NOTE: 19/09/2018)										
SL510-27-02		Control Yoke Assembly Tie Strap Inspection								RE (-)	Mandatory	
	27 A/F						Mos	04-Nov-2008				
		Eff: 28-Aug-2008 Complied With					Hrs	143				
							Ldg					
SL510-27-05		Flap Actuator Inspection								RE (-)	Mandatory	
	27 A/F						Mos	14-Sep-2009				
		Eff: 10-Jun-2009 Complied With					Hrs	725				
							Ldg					
SL510-27-06		Rudder Pushrod Inspection								RE (-)	Mandatory	
	27 A/F						Mos					
		Superseded					Hrs					
		SUPERSEDED BY REVISION 1					Ldg					
		(NOTE: 19/09/2018)										
SL510-27-06 R01		Rudder Pushrod Inspection								RE (-)	Mandatory	
	27 A/F						Mos	13-Oct-2009				
		Eff: 18-Aug-2009 Complied With					Hrs	783				
							Ldg					
SL510-27-08		Elevator Trim Chain Inspection								RE (-)	Mandatory	
	27 A/F						Mos					
		Eff: 08-Dec-2011 Not Applicable					Hrs					
		BY SERIAL NUMBER NOT APPLICABLE					Ldg					
		(NOTE: 19/09/2018)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 28 - FUEL											
✖	28 A/F 1C7-23 10BC256	DC Fuel Pump Left New						RE (O/C)			
							Mos	20-Mar-2008			
			0				Hrs	0			
							Ldg	0			
								RE (O/C)			
							Mos	20-Mar-2008			
✖	28 A/F 1C7-23 10BC254	DC Fuel Pump Right New					Hrs	0			
			0				Ldg	0			
								RE (O/C)			
✖	28 A/F 020-251-001 0305	Fuel Probe Left No.1 New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
✖	28 A/F 020-251-002 0279	Fuel Probe Left No.2 New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
✖	28 A/F 020-251-003 0307	Fuel Probe Left No.3 New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
✖	28 A/F 020-251-004 0302	Fuel Probe Left No.4 New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
✖	28 A/F 020-251-005 0298	Fuel Probe Left No.5 New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
✖	28 A/F 020-251-001 0306	Fuel Probe Right No.1 New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
✖	28 A/F 020-251-002 0275	Fuel Probe Right No.2 New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
✖	28 A/F 020-251-003 0302	Fuel Probe Right No.3 New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	28 A/F 020-251-004 0307	Fuel Probe Right No.4 New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F 020-251-005 0299	Fuel Probe Right No.5 New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F LR45300A C1309	Primary Ejector Left New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F LR45300A C1350	Primary Ejector Right New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F RG45310 C633	Scavenge Ejector Left No.1 New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F RG45310 C567	Scavenge Ejector Left No.2 New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F RG45310 C642	Scavenge Ejector Right No.1 New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F RG45310 C598	Scavenge Ejector Right No.2 New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F 367-350-001 1110	Signal Conditioner New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F ZSV57 07-1024492	Transfer Valve New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			
	28 A/F AV24B1507 AA122191	Valve-Fuel Motor Left New					Mos	20-Mar-2008	RE (O/C)		
			0				Hrs	0			
			0				Ldg	0			

Task No	Description									Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	28 A/F AV24B1507 AA109322	Valve-Fuel Motor						RE (O/C)				
		Right				Mos	20-Mar-2008					
		New		0		Hrs	0					
				0		Ldg	0					
28-00-02-220	Discretionary Maintenance - Microbiological Contamination Inspection (Airplanes Not Using the Biocidal Preventative Treatment)							RE (A/R)		5-19-00		
	28 A/F	(SOURCE: Model 510 Maintenance Manual) (NOTE: NOTE 5: The recommended test interval is considered a baseline interval. Based on the history of the airplane and other risk factors, it may be necessary to increase the frequency of the treatment. Refer to Chapter 28, Fuel Contamination - Description and Operation for a list of risk factors.)				Mos						
						Hrs						
						Ldg						
28-00-02-221	Discretionary Maintenance - Microbiological Contamination Inspection (Airplanes Using the Biocidal Preventative Treatment)							RE (A/R)		5-19-00		
	28 A/F	(SOURCE: Model 510 Maintenance Manual) (NOTE: NOTE 5: The recommended test interval is considered a baseline interval. Based on the history of the airplane and other risk factors, it may be necessary to increase the frequency of the treatment. Refer to Chapter 28, Fuel Contamination - Description and Operation for a list of risk factors.)				Mos						
						Hrs						
						Ldg						
A281000	Fuel Storage System Detailed Inspection							RE	Inspection Time Limits	≈15-Jul-2026		
	28 A/F	05-12-18 Task:28-10-00-220 (ZONE: 147, 148, 511, 512, 521, 522, 531, 532) (AVG MAN HRS: 0) (APX COST: 0) (Tol. Adjustment: -51d) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 611, 612, 621, 622, 631, 632)				Mos	04-Sep-2023	36	-/+1m	(31-Jul-2026)	2.7 Years (+31 Days)	
						Hrs	9,684.2	2,250	-/+25	(11,934.2)	2,083.7 Hrs (+25)	
						Ldg	7,759					
B284000	Fuel Filter Bypass Annunciator Circuit Operational Check							RE	Inspection Time Limits	≈10-Sep-2024		
	28 A/F	05-12-03 Task:28-40-00-710 (ZONE: 224, 410,420) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)				Mos	17-Mar-2022					
						Hrs	9,146.2	1,350	-/+25	(10,496.2)	645.7 Hrs (+25)	
						Ldg	7,338					
CIL-28-01	Fuel - Microbiological Contamination in Aircraft Fuel Tanks and Fuel Systems							T (A/R)	Informational			
	28 A/F Eff: 24-Feb-2023					Mos						
						Hrs						
						Ldg						
D282000	Fuel System Filter Elements Discard (Replace) (Left Engine)							RE	Inspection Time Limits			
	28 A/F	05-12-14 Task:28-20-00-960 (RII ITEM) (ZONE: 410, 420) (AVG MAN HRS: 0) (APX COST: 61.26) (SOURCE: Model 510 Maintenance Manual)				Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)	
						Hrs	9,471.8	900	-/+25	(10,371.8)	521.3 Hrs (+25)	
						Ldg	7,591					
D282000	Fuel System Filter Elements Discard (Replace) (Right Engine)							RE	Inspection Time Limits			
	28 A/F	05-12-14 Task:28-20-00-960 (RII ITEM) (ZONE: 410, 420) (AVG MAN HRS: 0) (APX COST: 66.22) (SOURCE: Model 510 Maintenance Manual)				Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)	
						Hrs	9,471.8	900	-/+25	(10,371.8)	521.3 Hrs (+25)	
						Ldg	7,591					
SB510-28-02	Locking Fuel Cap Installation							T (A/R)	Optional			
	28 A/F Eff: 27-May-2008 Deferred (NOTE: 03/10/12018)	NOT OF INTEREST				Mos						
						Hrs						
						Ldg						
SL510-28-01	Left and Right Fuel Probe Wire Bundle Inspection							RE (-)	Mandatory			
	28 A/F Eff: 19-Feb-2009 Complied With					Mos	13-Oct-2009					
						Hrs	783					
						Ldg						
▼ 29 - HYDRAULIC POWER												
Hydraulic "extend" pressure switch (SN013)												
	29 A/F 9912657-4 0179 (APX COST: 7,794.65)	Tested/Inspected				Mos	15-Jul-2021					
						Hrs	8,752.1					
						Ldg	7,035					

Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
 29 A/F 9912657-13 0193 (APX COST: 7,794.65)	Tested/Inspected	Hydraulic "retract" pressure switch (SN005)						RE (-)			
								Mos	15-Jul-2021		
								Hrs	8,752.1		
								Ldg	7,035		
 29 A/F 9912657-3 0546 (APX COST: 6,389.54)	New	Pressure Switch (SN006)	1				Mos	26-Nov-2021			
			0				Hrs	9,014.2			
			0				Ldg	7,227			
 29 A/F 80665 NSN	New	Hyd Power Pack Pressure Switch						RE (O/C)			
								Mos	20-Mar-2008		
			0				Hrs	0			
			0				Ldg	0			
 29 A/F 4251 NSN	New	Hyd Solenoid Extraction Control Valve						RE (O/C)			
								Mos	20-Mar-2008		
			0				Hrs	0			
			0				Ldg	0			
 29 A/F 4252 NSN	New	Hyd Solenoid Retraction Control Valve						RE (O/C)			
								Mos	20-Mar-2008		
			0				Hrs	0			
			0				Ldg	0			
 29 A/F 7550-2 0116	New	Hydraulic Accumulator Assembly						RE (O/C)			
								Mos	20-Mar-2008		
			0				Hrs	0			
			0				Ldg	0			
 29 A/F CV02-267 NSN	New	Hydraulic Check Valve						RE (O/C)			
								Mos	20-Mar-2008		
			0				Hrs	0			
			0				Ldg	0			
 29 A/F 9625-1 NSN	New	Hydraulic Dump Valve						RE (O/C)			
								Mos	20-Mar-2008		
			0				Hrs	0			
			0				Ldg	0			
 29 A/F 8257-3 0019	New	Hydraulic Manifold						RE (O/C)			
								Mos	20-Mar-2008		
			0				Hrs	0			
			0				Ldg	0			
 29 A/F HM50C-3 079B (AVG MAN HRS: 0) (APX COST: 7,317.27)	Overhauled	Hydraulic Power - Hydraulic Pack Assembly						RE (O/C)			
								Mos	09-Aug-2018		
			0				Hrs	6,999.3			
								Ldg	5,609		
 29 A/F 2672 NSN	New	Hydraulic Relief Valve						RE (O/C)			
								Mos	20-Mar-2008		
			0				Hrs	0			
			0				Ldg	0			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
		Hydraulic Reservoir Assembly						RE (O/C)				
	29 A/F 7017005-24 AT54619	New					Mos	20-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
		Hydraulic Sys Pressure Gauge						RE (O/C)				
	29 A/F 19940933-1 025101	New					Mos	20-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
B291001		Hydraulic Pack Assembly (Leak) Functional Check Task 29-10-00-720						RE	Inspection Time Limits		≈10-Sep-2024	
	29 A/F HM50C-3 079B Task:29-10-00-720 (ZONE: 212) (SOURCE: Model 510 Maintenance Manual)	05-12-16					Mos	36	-/+1m	(31-Mar-2025)	1.4 Years (+30 Days)	
							Hrs	1,350	-/+25	(10,496.2)	645.7 Hrs (+25)	
							Ldg					
D291000		Hydraulic System Filter Elements Discard (Replace)						RE	Inspection Time Limits		≈10-Sep-2024	
	29 A/F Task:29-10-00-960 (RII ITEM) (ZONE: 211) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)	05-12-16					Mos	17-Mar-2022	36	-/+1m	(31-Mar-2025)	1.4 Years (+30 Days)
							Hrs	9,146.2	1,350	-/+25	(10,496.2)	645.7 Hrs (+25)
							Ldg	7,338				
SB510-29-01		Hydraulic System Noise Reduction						RE (-)	Optional			
	29 A/F Eff: 25-Jul-2007 Not Applicable (NOTE: 03/10/2018)	BY SERIAL NUMBER NOT APPLICABLE					Mos					
							Hrs					
							Ldg					
SB510-29-02		Replacement of the Hydraulic Pack Assembly						RE (-)	Recommended			
	29 A/F Eff: 12-Dec-2007 Not Applicable (NOTE: 03/10/2018)	BY SERIAL NUMBER NOT APPLICABLE					Mos					
							Hrs					
							Ldg					
▼ 30 - ICE AND RAIN PROTECTION												
		De-Ice Pressure Switch - LH Horizontal Stabilizer						RE (O/C)				
	30 A/F 1106P55-1 4864A	New					Mos	20-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
		De-Ice Pressure Switch - LH Wing						RE (O/C)				
	30 A/F 1106P55-1 6351A (APX COST: 0)	Lower Serviceable					Mos	24-Jan-2014				
							Hrs	3,749.4				
							Ldg	3,133				
		De-Ice Pressure Switch - LH Wing						RE (O/C)				
	30 A/F 1106P55-1 6483A (APX COST: 0)	Upper Serviceable					Mos	24-Jan-2014				
							Hrs	3,749.4				
							Ldg	3,133				
		De-Ice Pressure Switch - RH Horizontal Stabilizer						RE (O/C)				
	30 A/F 1106P55-1 5026A	New					Mos	20-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	30 A/F 1106P55-1 6260A (APX COST: 0)	De-Ice Pressure Switch - RH Wing								RE (O/C)	
		Lower					Mos	24-Jan-2014			
		Serviceable					Hrs	3,749.4			
							Ldg	3,133			
✖	30 A/F 1106P55-1 6331A (APX COST: 0)	De-Ice Pressure Switch - RH Wing								RE (O/C)	
		Upper					Mos	24-Jan-2014			
		Serviceable					Hrs	3,749.4			
							Ldg	3,133			
✖	30 A/F 3D2353-06 N073680	De-Ice Valve								RE (O/C)	
		Left No.1					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
✖	30 A/F 3D2353-06 N074206	De-Ice Valve								RE (O/C)	
		Left No.2					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
✖	30 A/F 3D2353-06 N073625	De-Ice Valve								RE (O/C)	
		Right No.1					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
✖	30 A/F 3D2353-06 N073624	De-Ice Valve								RE (O/C)	
		Right No.2					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			
✖	30 A/F P29S4D5317-05 NCR2940	Horizontal Stab De-Ice Boot								RE (O/C)	
		Left	0				Mos	13-Nov-2015			
		New	0				Hrs	5,151.3			
			0				Ldg	4,170			
							ACH	650			
✖	30 A/F 9912662-4 NFR8990 (APX COST: 2,513.18)	Horizontal Stab De-Ice Boot								RE (O/C)	
		Right	5				Mos	01-Jul-2021			
		New	0				Hrs	8,733			
			0				Ldg	7,019			
✖	30 A/F 5285-00-3 2152 (APX COST: 0)	Press Reg/Shutoff Valve Assy								RE (O/C)	
		Left					Mos	05-Sep-2019			
		Serviceable	5,884.9				Hrs	7,635.4			
			4,750				Ldg	6,141			
✖	30 A/F 5285-00-3 1483	Press Reg/Shutoff Valve Assy								RE (O/C)	
		Right					Mos	20-Mar-2008			
		New	0				Hrs	0			
			0				Ldg	0			

Task No	Description								Categories	Time			
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
	30 A/F 1173T0759 4346	Temp Switch						RE (O/C)					
		Left						Mos	20-Mar-2008				
		New						Hrs	0				
								Ldg	0				
	30 A/F 1173T0759 4317	Temp Switch						RE (O/C)					
		Right						Mos	20-Mar-2008				
		New						Hrs	0				
								Ldg	0				
	30 A/F 9912662-13 NEG3890 (APX COST: 2,589.13)	Vert De-Ice Boot						RE (O/C)					
		New						Mos	26-Jun-2019				
								Hrs	7,476.1				
								Ldg	6,006				
	30 A/F 7018108-30 223	Windshield Controller						RE (O/C)					
		Left						Mos	10-Mar-2017				
		New						Hrs	5,845				
								Ldg	4,714				
	30 A/F 7018108-30 0300	Windshield Controller						RE (O/C)					
		Right						Mos	10-Mar-2017				
		New						Hrs	5,845				
								Ldg	4,714				
	30 A/F 9912662-17 NDO9530 (AVG MAN HRS: 0) (APX COST: 0)	Wing De-Ice Boot						RE (O/C)					
		Left						Mos	06-Oct-2017				
		New						Hrs	6,390				
								Ldg	5,136				
	30 A/F 9912662-18 NEE9260 (APX COST: 7,187.64)	Wing De-Ice Boot						RE (O/C)					
		Right						Mos	01-Jul-2021				
		New						Hrs	8,733				
								Ldg	7,019				
B301000	De-Ice System Functional Test							RE	Inspection Time Limits		≈10-Feb-2025		
	30 A/F	05-12-15						Mos	07-Jun-2023	24	-/+1m	(28-Feb-2025)	1.3 Years (+28 Days)
Task:30-10-00-700 (ZONE: 340, 351,352, 511,521, 531,611, 621,631) (AVG MAN HRS: 0) (APX COST: 0) (Tol. Adjustment: -124d) (SOURCE: Model 510 Maintenance Manual)								Hrs	9,471.8	1,350	-/+25	(10,821.8)	971.3 Hrs (+25)
								Ldg	7,591				
CIL-30-01	Ice and Rain Protection - Approved Deicing Program Updates							RE (-)		Informational			
	30 A/F							Mos					
Superseded		SUPERSEDED BY REVISION 1						Hrs					
(NOTE: 03/10/2018)								Ldg					
CIL-30-01 Revision 1	Approved Deicing Program Updates							T (A/R)		Informational			
	30 A/F							Mos					
Eff: 13-Sep-2013		NOTED						Hrs					
(NOTE: 03/10/2018)								Ldg					
Reliability-30-001	Inspection and Treatment of LH Wing De-Ice Boot							RE					
	30 A/F							Mos	07-Jun-2023	4	-/+1m	31-Oct-2023	0 Days (+14)
								Hrs	9,471.8				
(SOURCE: 30-10-00-2 (REV 12))								Ldg	7,591				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
Reliability-30-002	Inspection and Treatment of RH Wing De-Ice Boot								RE	
 30 A/F					Mos	07-Jun-2023	4	-/+1m	31-Oct-2023	0 Days (+14)
					Hrs	9,471.8				
	(SOURCE: 30-10-00-2 (REV 12))				Ldg	7,591				
Reliability-30-003	Inspection and Treatment of LH Horizontal Stab De-Ice Boot								RE	
 30 A/F					Mos	07-Jun-2023	4	-/+1m	31-Oct-2023	0 Days (+14)
					Hrs	9,471.8				
	(SOURCE: 30-10-00-2 (REV 12))				Ldg	7,591				
Reliability-30-004	Inspection and Treatment of RH Horizontal Stab De-Ice Boot								RE	
 30 A/F					Mos	07-Jun-2023	4	-/+1m	31-Oct-2023	0 Days (+14)
					Hrs	9,471.8				
	(SOURCE: 30-10-00-2 (REV 12))				Ldg	7,591				
Reliability-30-005	Inspection and Treatment of Vertical Stab De-Ice Boot								RE	
 30 A/F					Mos	07-Jun-2023	4	-/+1m	31-Oct-2023	0 Days (+14)
					Hrs	9,471.8				
					Ldg	7,591				
SB510-30-01	Windshield Controller Wiring Harness Installation								RE (-)	Optional
 30 A/F					Mos					
Eff: 08-Sep-2009 Not Applicable	BY SERIAL NUMBER NOT APPLICABLE				Hrs					
(NOTE: 03/10/2018)					Ldg					
SB510-30-02	PPG Windshield Anti-Ice System Improvement								RE (-)	Discretionary
 30 A/F					Mos					
Superseded	SUPERSEDED BY REVISION 1				Hrs					
(NOTE: 03/10/2018)					Ldg					
SB510-30-02 R01	PPG Windshield Anti-Ice System Improvement								T (A/R)	Discretionary
 30 A/F					Mos					
Eff: 02-Jun-2015 Declined	NOT OF INTEREST				Hrs					
(NOTE: 03/10/2018)					Ldg					
SB510-30-03	Windshield Connector Clip Assembly Improvement								RE (-)	Discretionary
 30 A/F					Mos					
Superseded	SUPERSEDED BY REVISION 1				Hrs					
(NOTE: 03/10/2018)					Ldg					
SB510-30-03 R01	Windshield Connector Clip Assembly Improvement								T (A/R)	Discretionary
 30 A/F					Mos					
Eff: 24-Oct-2011 Declined	NOT OF INTEREST				Hrs					
(NOTE: 03/10/2018)					Ldg					
SB510-30-04	Windshield Controller Contact Replacement								RE (-)	Mandatory
 30 A/F					Mos					
Eff: 20-Oct-2010 Not Applicable	Not applicable by SN				Hrs					
					Ldg					
SB510-30-05	Windshield Temperature Control Unit Modification								RE (-)	Mandatory
 30 A/F					Mos	01-Oct-2012				
Eff: 04-Apr-2012 Complied With	PERFORMED SB510-30-05				Hrs	3,194.1				
					Ldg	2,679				
SB510-30-06	Ice and Rain Protection - Windshield Temperature Controller Enhancement								RE (-)	Recommended
 30 A/F					Mos	10-Mar-2017				
Eff: 16-Nov-2015 Complied With					Hrs	5,845				
(AVG MAN HRS: 4) (NOTE: Note: This service bulletin should be accomplished at a scheduled maintenance period or inspection.)					Ldg	4,714				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SB510-30-06 R01	Ice and Rain Protection - Windshield Temperature Controller Enhancement						T (A/R)		Recommended	
30 A/F										
Eff: 03-Aug-2016 Complied	ALREADY C/W									
With										
(AVG MAN HRS: 4) (NOTE: 03/10/2018)										
SL510-30-01	Approved Deicing Program Updates						RE (-)		Informational	
30 A/F										
Superseded	SUPERSEDED BY REVISION 1									
(NOTE: 10/03/2018)										
SL510-30-01 R01	Approved Deicing Program Updates						RE (-)		Informational	
30 A/F										
Superseded	SUPERSEDED BY REVISION 2									
(NOTE: 10/03/2018)										
SL510-30-01 R02	Approved Deicing Program Updates						RE (-)		Informational	
30 A/F										
Superseded	SUPERSEDED BY REVISION 3									
(NOTE: 10/03/2018)										
SL510-30-01 R03	Approved Deicing Program Updates						RE (-)		Informational	
30 A/F										
Superseded	SUPERSEDED BY REVISION 4									
(NOTE: 10/03/2018)										
SL510-30-01 R04	Approved Deicing Program Updates						RE (-)		Informational	
30 A/F										
Superseded	SUPERSEDED BY REVISION 5									
(NOTE: 10/03/2018)										
SL510-30-01 R05	Approved Deicing Program Updates						RE (-)		Informational	
30 A/F										
Superseded	SUPERSEDED BY REVISION 6									
(NOTE: 10/03/2018)										
SL510-30-01 R06	Approved Deicing Program Updates						T (A/R)		Informational	
30 A/F										
Eff: 08-Oct-2012	NOTED									
(NOTE: 10/03/2018)										
SL510-30-02A	Water Separator Drain Cap						RE (-)		Mandatory	
30 A/F										
Eff: 26-Mar-2008 Not	BY SERIAL NUMBER NOT APPLICABLE									
Applicable										
(NOTE: 04/10/2018)										
▼ 31 - INDICATING / RECORDING SYSTEM										
CIL-31-01	Indicating/Recording Systems - CVR, FDR, and CVDR 90-Day Battery Underwater Locator Beacon (ULB) Installation						T (A/R)		Informational, Service Letter	
31 A/F										
Eff: 02-Feb-2018	NOTED									
(NOTE: 04/10/2018)										
SB510-31-01	Master Caution Warning Light Wiring Modification						RE (-)		Discretionary	
31 A/F										
Eff: 14-Jul-2008 Complied With							08-Oct-2008			
							136			
SL510-31-02	Cockpit Switch Inspection						RE (-)		Mandatory	
31 A/F										
Eff: 29-Nov-2007 Not	BY SERIAL NUMBER NOT APPLICABLE									
Applicable										
(NOTE: 01/10/2018)										



OE-FFB STATUS REPORT
Owner/Operator: GlobeAir AG GlobeAir AG

CESSNA
510 (Citation Mustang) OE-FFB,SN 510-0065

Task No	Description						Categories			Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
SL510-31-03		Cockpit Switch Wire Bundle Assembly (WBA) Inspection						RE (-)			Mandatory	
	31 A/F	Eff: 14-Dec-2009 Not Applicable BY SERIAL NUMBER APPLICABLE TO AIRCRAFT SERIAL NUMBERS -0156 THRU -0164, -0167 THRU -0191, -0193 THRU -0215, -0218 THRU -0220, -0223, -0225 THRU -0227.					Mos					
					Hrs							
					Ldg							
▼ 32 - LANDING GEAR												
		Antiskid Control Unit							RE (O/C)			
	32 A/F	Overhauled					Mos	19-Jul-2013				
	556-3						Hrs	3,391				
	302829417						Ldg	2,853				
		Antiskid Control Valve							RE (O/C)			
	32 A/F	Tested/Inspected (APX COST: 20,000)					Mos	07-Jun-2023				
	9912650-6 0078		3,484.24				Hrs	9,471.8				
	3,047				Ldg	7,591						
		Brake Metering Valve							RE (O/C)			
	32 A/F	Tested/Inspected (APX COST: 0)					Mos	07-Jun-2023				
	9912650-9 0263		7,587.3				Hrs	9,471.8				
	6,140				Ldg	7,591						
		Bunge Assembly							RE (O/C)			
	32 A/F	7042072-9 NSN					Mos	20-Mar-2008				
					Hrs	0						
	1				Ldg	0						
		Emergency Blow Down BTL Pressure Gauge							RE (O/C)			
	32 A/F	New					Mos	20-Mar-2008				
	19940931-1		0				Hrs	0				
	024753		0				Ldg	0				
		Emergency Brake Bottle Pressure Gauge							RE (O/C)			
	32 A/F	New					Mos	20-Mar-2008				
	19940931-1		0				Hrs	0				
	024862		0				Ldg	0				
		Emergency Brake Pneumatic Bottle							RE	Component Time Limits		
	32 A/F	Overhauled Manufactured Date 01-Jul-2008 MM:5-11-00, Task:32-40-00-961 (APX COST: 193.81) (SOURCE: Model 510 Maintenance Manual)					Yrs	18-May-2022	24	01-Jul-2032	8.6 Years	
	9914678-4 6283		0				Hrs	9,252.2				
	0				Ldg	7,425						
		Emergency Brake Valve							RE (O/C)			
	32 A/F	New					Mos	20-Mar-2008				
	72298		0				Hrs	0				
	0091		0				Ldg	0				
		Landing Gear Assembly							RE (O/C)			
	32 A/F	Left					Mos	20-Mar-2008				
	7041010-5	New	0				Hrs	0				
	61		0				Ldg	0				

Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	32 A/F 7041010-6 62	Landing Gear Assembly						RE (O/C)			
		Right				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0				
✖	32 A/F 40005369-2 6826 Manufactured Date 01-Apr-2009 MM:5-11-00, Task:32-30-40-961 (APX COST: 318.25) (SOURCE: Model 510 Maintenance Manual)	Landing Gear Emergency Pneumatic Bottle						RE	Component Time Limits		
		Tested/Inspected				Yrs	29-Jul-2022	24		01-Apr-2033	9.4 Years
						Hrs	9,418.9				
						Ldg	7,552				
✖	32 A/F 6327504-6 1942	Main Gear Actuator Uplock						RE (O/C)			
		Left				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0				
✖	32 A/F 6327504-6 1941	Main Gear Actuator Uplock						RE (O/C)			
		Right				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0				
✖	32 A/F FA100104-001 FA100104-1-0087 MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)	Main Landing Gear Hydraulic Actuator						RE	Replacement Schedule	≈11-Sep-2030	
		Left				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0	12,000	12,000	4,100 Ldg	
✖	32 A/F FA100105-001 FA100105-1-0173 MM:4-11-00, MM:5-11-00 (SOURCE: Model 510 Maintenance Manual)	Main Landing Gear Hydraulic Actuator						RE	Replacement Schedule	≈25-May-2035	
		Right				Mos	21-Aug-2015				
		Serviceable				Hrs	4,985.3				
			1,232			Ldg	4,055	12,000	14,823	6,923 Ldg	
✖	32 A/F 7041050-5 26081549A MM:5-11-00, MM:4-11-00 (AVG MAN HRS: 0) (APX COST: 15,520.38) (SOURCE: Model 510 Maintenance Manual)	Main Landing Gear Oleo Assembly						RE	Replacement Schedule	≈20-May-2042	
		Left	0			Mos	01-Jul-2021				
		New	0			Hrs	8,733				
			0			Ldg	7,019	12,000	19,019	11,119 Ldg	
✖	32 A/F 7041050-5 24874531C MM:5-11-00, MM:4-11-00 (APX COST: 8,923.13) (SOURCE: Model 510 Maintenance Manual)	Main Landing Gear Oleo Assembly						RE	Replacement Schedule	≈21-Nov-2039	
		Right				Mos	17-Mar-2022				
		Repaired			0	Hrs	9,146.2				
			1,818		0	Ldg	7,338	12,000	17,520	9,620 Ldg	
✖	32 A/F 7041030-1 68 MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)	Main Landing Gear Trailing Link Assembly						RE	Replacement Schedule	≈08-Jan-2044	
		Left				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0	20,000	20,000	12,100 Ldg	
✖	32 A/F 7041030-2 64 MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)	Main Landing Gear Trailing Link Assembly						RE	Replacement Schedule	≈08-Jan-2044	
		Right				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0	20,000	20,000	12,100 Ldg	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	Main Landing Gear Trunnion Assembly							RE	Replacement Schedule		≈08-Jan-2044
	32 A/F	Left					Mos	20-Mar-2008			
	7041020-5	New					Hrs	0			
	62						Ldg	0	20,000	20,000	12,100 Ldg
MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)											
	Main Landing Gear Trunnion Assembly							RE	Replacement Schedule		≈08-Jan-2044
	32 A/F	Right					Mos	20-Mar-2008			
	7041020-6	New					Hrs	0			
	63						Ldg	0	20,000	20,000	12,100 Ldg
MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)											
	Main Landing Gear Wheel							RE (O/C)			
	32 A/F	Left					Mos	14-Aug-2023			
	3-1640	Repaired					Hrs	9,639.6			
	0339						Ldg	7,726			
(AVG MAN HRS: 0) (APX COST: 0.01)											
	Main Landing Gear Wheel							RE (O/C)			
	32 A/F	Right					Mos	14-Aug-2023			
	3-1640		7,889.5	3,302.5	1,216.1	Hrs	9,639.6				
	0558		6,468	2,693	1,003	Ldg	7,726				
(AVG MAN HRS: 0) (APX COST: 0)											
	Nose Gear Fork & Piston Assembly							RE (O/C)			
	32 A/F						Mos	20-Mar-2008			
	7042040-1						Hrs	0			
	NSN		1				Ldg	0			
	Nose Gear Uplock Actuator							RE (O/C)			
	32 A/F						Mos	20-Mar-2008			
	6327504-7	New					Hrs	0			
	806						Ldg	0			
	Nose Landing Gear Actuator							RE	Replacement Schedule		≈11-Sep-2030
	32 A/F						Mos	20-Mar-2008			
	FA100087-001	New					Hrs	0			
	FA100087-1-0103		0				Ldg	0	12,000	12,000	4,100 Ldg
MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)											
	Nose Landing Gear Downlock Release Actuator							RE	Replacement Schedule		≈11-Sep-2030
	32 A/F						Mos	20-Mar-2008			
	FA100036-001	New					Hrs	0			
	FA100036-1-0080		0				Ldg	0	12,000	12,000	4,100 Ldg
MM:4-11-00, MM:5-11-00 (SOURCE: Model 510 Maintenance Manual)											
	Nose Landing Gear Drag Brace Assembly (Except Nose Landing Gear Downlock Release Actuator)							RE	Replacement Schedule		≈08-Jan-2044
	32 A/F						Mos	20-Mar-2008			
	7042120-1	New					Hrs	0			
	NSN		0				Ldg	0	20,000	20,000	12,100 Ldg
MM:4-11-00, MM:5-11-00 (SOURCE: Model 510 Maintenance Manual)											
	Nose Landing Gear Strut Assembly							RE	Replacement Schedule		≈08-Jan-2044
	32 A/F						Mos	07-Mar-2011			
	7042010-4						Hrs	2,069			
	60		1,745					Ldg	1,745	20,000	20,000
MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)											

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining	
	32 A/F 7042020-1 59	Nose Landing Gear Trunnion New							RE (O/C)			
							Mos	20-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
	32 A/F 3-1642 0068 (APX COST: 0.01)	Nose Landing Gear Wheel Repaired					Mos	14-Aug-2023				
			466.1				466.1	Hrs	9,639.6			
			386				386	Ldg	7,726			
	32 A/F 98433-1 0085	Parking Brake Valve New					Mos	20-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
	32 A/F 7042030-2 NSN	Shimmy Damper					Mos	20-Mar-2008				
							Hrs	0				
			1				Ldg	0				
	32 A/F 5145-1 0696 (APX COST: 0)	Shuttle Valve Left Overhauled	13				Mos	16-Mar-2020				
			0				0	Hrs	7,941.9			
			0				0	Ldg	6,389			
	32 A/F 5145-1 0008	Shuttle Valve Right New					Mos	20-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
	32 A/F 466-23-1 0238	Wheel Speed Sensor Left New					Mos	20-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
	32 A/F 466-23-1 ukn	Wheel Speed Sensor Right New					Mos	27-Nov-2009				
			0				Hrs	855				
			0				Ldg					
2018-07-13		Brake Pad Wear Indicator Pins - Inspection/ Replacement						RE (-)		Mandatory		
	32 A/F Eff: 15-May-2018 Complied With	PCW IAW SL510-32-08					Days	01-Aug-2017				
							Hrs	6,232				
							Ldg	5,017				
32-30-40-960		Landing Gear Emergency Pneumatic Bottle - Hydrostatic Test						RE 05-11-00, Component Time Limits				
	32 A/F 40005369-2 6826 Hydrostatic Tested Date 14-Dec-2021 (ZONE: 212) (SOURCE: Model 510 Maintenance Manual)		7				Mos	29-Jul-2022		36	31-Dec-2024	1.1 Years
			0				Hrs	9,418.9				
			0				Ldg	7,552				

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
32-40-00-960		Emergency Brake Pneumatic Storage Bottle - Hydrostatic Test								RE 05-11-00, Component Time Limits		
	32 A/F						Mos	18-May-2022	36	31-Aug-2024	9.6 Months	
	9914678-4						Hrs	9,252.2				
	6283						Ldg	7,425				
	Hydrostatic Tested Date 30-Aug-2021											
	(ZONE: 212) (SOURCE: Model 510 Maintenance Manual)											
A320000		Landing Gear Wheel Well Zonal Inspection								RE	Inspection Time Limits	
	32 A/F	05-12-11					Mos	07-Jun-2023	72	-/+1m (30-Jun-2029)	5.6 Years (+30 Days)	
							Hrs	9,471.8				
	Task:32-00-00-210 (RII ITEM) (ZONE: 710, 720,730) (SOURCE: Model 510 Maintenance Manual)											
							Ldg	7,591				
A320001		Landing Gear Corrosion Detailed Inspection								RE	Inspection Time Limits	≈25-May-2025
	32 A/F	05-12-32					Mos	01-Jul-2021	72	-/+1m (31-Jul-2027)	3.7 Years (+31 Days)	
							Hrs	8,733				
	Task:32-00-00-220 (RII ITEM) (ZONE: 710, 720,730) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)											
							Ldg	7,019	1,800	-/+25 (8,819)	919 Ldg (+25)	
A320002		Landing Gear General Visual Inspection (Corrosion Inspection)								RE	Inspection Time Limits	
	32 A/F	05-12-35					Mos	07-Jun-2023	6	-/+1m (31-Dec-2023)	45 Days (+31)	
							Hrs	9,471.8				
	Task:32-00-00-211 (ZONE: 111, 112) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: For airplanes that operate in moderate or severe corrosion environments)											
							Ldg	7,591				
A320003		Landing Gear General Visual Inspection (Corrosion Inspection)								RE	Inspection Time Limits	
	32 A/F	05-12-06					Mos	07-Jun-2023	12	-/+1m (30-Jun-2024)	7.6 Months (+30 Days)	
							Hrs	9,471.8				
	Task:32-00-00-211 (ZONE: 111, 112) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)											
							Ldg	7,591				
A321000		Main Landing Gear - General Visual Inspection								RE	Inspection Time Limits	≈10-Sep-2024
	32 A/F	05-12-16					Mos	17-Mar-2022	36	-/+1m (31-Mar-2025)	1.4 Years (+30 Days)	
							Hrs	9,146.2	1,350	-/+25 (10,496.2)	645.7 Hrs (+25)	
	Task:32-10-00-210 (ZONE: 720, 730) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)											
							Ldg	7,338				
A322000		Nose Landing Gear - General Visual Inspection								RE	Inspection Time Limits	≈10-Sep-2024
	32 A/F	05-12-16					Mos	17-Mar-2022	36	-/+1m (31-Mar-2025)	1.4 Years (+30 Days)	
							Hrs	9,146.2	1,350	-/+25 (10,496.2)	645.7 Hrs (+25)	
	Task:32-20-00-210 (ZONE: 710) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)											
							Ldg	7,338				
A323000		Landing Gear Manual Release Cable Assemblies Detailed Inspection								RE	Inspection Time Limits	≈10-Sep-2024
	32 A/F	05-12-16					Mos	17-Mar-2022	36	-/+1m (31-Mar-2025)	1.4 Years (+30 Days)	
							Hrs	9,146.2	1,350	-/+25 (10,496.2)	645.7 Hrs (+25)	
	Task:32-30-40-220 (ZONE: 131, 141, 143, 145, 147, 148, 221, 231, 241) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 710, 720, 730)											
							Ldg	7,338				
A325000		Nosewheel Steering System Detailed Inspection								RE	Inspection Time Limits	≈10-Sep-2024
	32 A/F	05-12-16					Mos	17-Mar-2022	36	-/+1m (31-Mar-2025)	1.4 Years (+30 Days)	
							Hrs	9,146.2	1,350	-/+25 (10,496.2)	645.7 Hrs (+25)	
	Task:32-50-00-220 (ZONE: 111, 112, 221, 222,710) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)											
							Ldg	7,338				
B320000		Landing Gear Uplock and Downlock Switches Operational Check								RE	Inspection Time Limits	≈06-Aug-2024
	32 A/F	05-12-MB					Mos	07-Jun-2023				
							Hrs	9,471.8	950	(10,421.8)	571.3 Hrs	
	MM:5-10-01, MM:4-10-00, Task:32-00-00-710 (ZONE: 710, 720, 730) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)											
							Ldg	7,591				
B320001		Landing Gear System Functional Check								RE	Inspection Time Limits	≈06-Aug-2024
	32 A/F	05-12-MB					Mos	07-Jun-2023				
							Hrs	9,471.8	950	(10,421.8)	571.3 Hrs	
	MM:5-10-01, MM:4-10-00, Task:32-00-00-720 (ZONE: 710, 720, 730) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)											
							Ldg	7,591				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
B323000		Landing Gear Manual Release and Pneumatic Extension System Functional Check						RE		Inspection Time Limits	≈02-Apr-2024
	32 A/F	05-12-02				Mos	18-May-2022				
		Task:32-30-40-720 (ZONE: 131, 141, 143, 145, 147, 148, 212, 221, 231, 241) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 710, 720, 730)				Hrs	9,252.2	900	-/+25	(10,152.2)	301.7 Hrs (+25)
						Ldg	7,425				
B324000		Main Landing Gear Wheels Special Detailed Inspection (NDI)						RE (A/R)		Inspection Time Limits	
	32 A/F	Left05-12-28				Mos	29-Oct-2020				
	3-1640					Hrs	8,390.5				
	0918					Ldg	6,735				
		Task:32-40-00-280 (ZONE: 710, 720, 730) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									
B324000		Main Landing Gear Wheels Special Detailed Inspection (NDI)						RE (A/R)		Inspection Time Limits	
	32 A/F	Right05-12-28				Mos	26-Nov-2021				
	3-1640					Hrs	9,014.2				
	0562					Ldg	7,227				
		Task:32-40-00-280 (ZONE: 710, 720, 730) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)									
B324000		Nose Landing Gear Wheels Special Detailed Inspection (NDI) - Inspection Document 28						RE (A/R)		Inspection Time Limits	
	32 A/F	05-12-28				Mos	29-Oct-2020				
	3-1642					Hrs	8,390.5				
	0363					Ldg	6,735				
		Task:32-40-00-280 (ZONE: 710, 720,730) (SOURCE: Model 510 Maintenance Manual)									
B324001		Landing Gear Pneumatic Brake System Functional Check						RE		Inspection Time Limits	≈10-Jan-2024
	32 A/F	05-12-MA				Mos	07-Jun-2023				
		MM:5-10-01, MM:4-10-00, Task:32-40-00-720 (ZONE: 221, 720, 730) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)				Hrs	9,471.8	500		(9,971.8)	121.3 Hrs
						Ldg	7,591				
B326000		Main Landing Gear Squat Switch Functional Test						RE		Inspection Time Limits	≈02-Apr-2024
	32 A/F	05-12-02				Mos	18-May-2022				
		Task:32-60-00-720 (ZONE: 720, 730) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)				Hrs	9,252.2	900	-/+25	(10,152.2)	301.7 Hrs (+25)
						Ldg	7,425				
C320000		Landing Gear Lubrication						RE		Inspection Time Limits	≈17-Dec-2023
	32 A/F	05-12-13				Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)
		Task:32-00-00-640 (ZONE: 710, 720,730) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)				Hrs	9,471.8	450	-/+25	(9,921.8)	71.3 Hrs (+25)
						Ldg	7,591				
CIL-32-04		Landing Gear - Wireless Tire Pressure Monitoring System Installation						RE (-)		Informational	
	32 A/F					Mos					
	Eff: 25-Sep-2014	NOTED				Hrs					
	(NOTE: 5/Oct/2018)					Ldg					
CIL-32-06		Landing Gear - Wireless Tire Pressure Sensor Fill Valve Torque Verification						T (A/R)		Informational	
	32 A/F					Mos					
	Eff: 09-Mar-2020					Hrs					
						Ldg					
Reliability-32-001		Perform Visual Inspection of emergency extension mechanism and replace Pin, washer and cotter Pin						RE		Custom Task	
	32 A/F					Mos	07-Jun-2023	12	-/+1m	30-Jun-2024	7.6 Months (+30 Days)
						Hrs	9,471.8				
						Ldg	7,591				
Reliability-32-002		LH Main Landing gear axle 7041040-1 and 7041040-3 cleaning and treatment i.a.w. Model 510 Structural Repair manual Ch 32-10-01.						RE			≈28-Dec-2024
	32 A/F					Mos	30-Oct-2023				
						Hrs	9,825.4				
	(ZONE: Main Landing Gear) (AVG MAN HRS: 3)					Ldg	7,875	700	-/+50	8,575	675 Ldg (+50)

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
Reliability-32-003	RH Main Landing gear axle 7041040-1 and 7041040-3 cleaning and treatment i.a.w. Model 510 Structural Repair manual Ch 32-10-01.						RE			≈28-May-2024
32 A/F						Mos 18-May-2022				
						Hrs 9,252.2				
	(ZONE: Main Landing Gear) (AVG MAN HRS: 3) (Manual Adjustment: 100 Ldg)					Ldg 7,425	700	-/+50	8,225	325 Ldg (+50)
Reliability-32-004	Main Landing Gear Tire Replacement						RE			≈29-Jan-2024
32 A/F	Left					Mos 14-Aug-2023				
021-523-0	New					Hrs 9,639.6				
2161T00319		0				Ldg 7,726	300	-/+50	8,025	125 Ldg (+50)
	(ZONE: Main Landing Gear) (AVG MAN HRS: 2) (APX COST: 565.7) (Tol. Adjustment: -1 Ldg)									
Reliability-32-005	Main Landing Gear Tire Replacement						RE			≈29-Jan-2024
32 A/F	Right					Mos 14-Aug-2023				
021-523-0						Hrs 9,639.6				
2161T00312		0				Ldg 7,726	300	-/+50	8,025	125 Ldg (+50)
	(ZONE: Main Landing Gear) (AVG MAN HRS: 2) (APX COST: 565.7) (Tol. Adjustment: -1 Ldg)									
Reliability-32-006	Nose Landing Gear Tire Replacement						RE			≈29-Mar-2024
32 A/F						Mos 14-Aug-2023				
079-606-0	New					Hrs 9,639.6				
1202T00180		0				Ldg 7,726	400	-/+50	8,126	226 Ldg (+50)
	(AVG MAN HRS: 0) (APX COST: 485.6)									
Reliability-32-007	Main Landing Gear Brake Assy Replacement						RE			≈28-Dec-2024
32 A/F	Left					Mos 30-Oct-2023				
2-1706-1	Overhauled		0	0		Hrs 9,825.4				
0172A		0	0	0		Ldg 7,875	700	-/+50	8,575	675 Ldg (+50)
	(AVG MAN HRS: 0) (APX COST: 5,180.79)									
Reliability-32-008	Main Landing Gear Brake Assy Replacement						RE			≈30-Nov-2023
32 A/F	Right					Mos 26-Nov-2021				
2-1706-1	Overhauled	0				Hrs 9,014.2				
0610		0				Ldg 7,227	700	-/+50	7,927	27 Ldg (+50)
	(AVG MAN HRS: 0) (APX COST: 4,412.85)									
SL510-32-01	Main Landing Gear (MLG) Identification Placard Replacement						RE (-)		Recommended	
32 A/F						Mos				
Eff: 30-Oct-2007	NOTED					Hrs				
(NOTE: 5/Oct/2018)						Ldg				
SL510-32-02	Emergency Gear Release Inspection						RE (-)		Mandatory	
32 A/F						Mos				
Superseded	SUPERSEDED BY REVISION 1					Hrs				
(NOTE: 5/Oct/2018)						Ldg				
SL510-32-02 R01	Emergency Gear Release Inspection						T (A/R)		Mandatory	
32 A/F						Mos 11-Feb-2010				
Eff: 13-Nov-2009 Complied With						Hrs 954.1				
						Ldg 806				
SL510-32-03	Right Brake Stop Bracket Inspection						RE (-)		Mandatory	
32 A/F						Mos 11-Feb-2010				
Eff: 02-Sep-2009 Complied With						Hrs 954.1				
						Ldg 806				
SL510-32-04	Nose Landing Gear (NLG) Uplock Bracket Corrosion Repair						T (A/R)		Informational	
32 A/F						Mos				
Eff: 04-Aug-2010	NOTED					Hrs				
(NOTE: 5/Oct/2018)						Ldg				

Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL510-32-05	Nose Landing Gear Downlock Switch Wiring Inspection							RE (-)	Recommended		
	32 A/F					Mos	01-Oct-2012				
	Eff: 20-Apr-2012 Complied With	PERFORMED SB510-32-05				Hrs	3,194.1				
						Ldg	2,679				
SL510-32-07	Landing Gear - Main Landing Gear Brake Verification							RE (-)	Mandatory		
	32 A/F					Days	22-Feb-2017				
	Eff: 17-Feb-2017 Complied With					Hrs	5,845				
	(AVG MAN HRS: 3.2)					Ldg	4,714				
SL510-32-08	Transmit Goodrich Service Bulletin 2-1706-1-32-1 Landing Gear - Main Brake Assembly, - Introduction of an Inspection Procedure to Make Sure The Wear Indicator Pins Were Set Correctly							RE (-)	Mandatory, Service Letter		
	32 A/F					Days	01-Aug-2017				
	Eff: 21-Jul-2017 Complied With					Hrs	6,232				
	(AVG MAN HRS: 0) (APX COST: 0)					Ldg	5,017				
▼ 33 - LIGHTS											
	Ground Recognition Light							RE (O/C)			
	33 A/F					Mos	31-Jan-2013				
	84003-2	New				Hrs	3,329.9				
	0095					Ldg	2,803				
	Landing/Taxi Light							RE (O/C)			
	33 A/F	Left				Mos	09-Sep-2020				
	9912677-1	New				Hrs	8,287.1				
	000814					Ldg	6,654				
	(APX COST: 4,107.67)										
	Landing/Taxi Light							RE (O/C)			
	33 A/F	Right				Mos	20-Mar-2008				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
	Position/Anticollision Light Assembly							RE	Component Time Limits	≈19-Sep-2031	
	33 A/F	Left				Mos	08-May-2020				
	9912679-7	New				Hrs	7,976.4	8,000	15,976.4	6,125.9 Hrs	
	001317					Ldg	6,420				
	MM:5-11-00, Task:33-40-00-2 (APX COST: 5,167.47) (SOURCE: Model 510 Maintenance Manual)										
	Position/Anticollision Light Assembly							RE	Component Time Limits	≈18-Aug-2033	
	33 A/F	Right				Mos	07-Jun-2023				
	9912679-8	New				Hrs	9,471.8	8,000	17,471.8	7,621.3 Hrs	
	001050					Ldg	7,591				
	MM:5-11-00, Task:33-40-00-2 (APX COST: 4,052.34) (SOURCE: Model 510 Maintenance Manual)										
	Power Supply							RE (O/C)			
	33 A/F	Left				Mos	09-Sep-2020				
	9912677-3					Hrs	8,287.1				
	001116					Ldg	6,654				
	(APX COST: 0)										
	Power Supply							RE (O/C)			
	33 A/F	Right				Mos	27-Jun-2023				
	9912677-3	New				Hrs	9,504.4				
	001244					Ldg	7,617				
	(APX COST: 1,794.17)										

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
A334000		Ground Recognition Light Sealant Inspection						RE		Inspection Time Limits	≈17-Dec-2023	
	33 A/F	05-12-13					Mos	07-Jun-2023	12	-/+1m (30-Jun-2024)	7.6 Months (+30 Days)	
	Task:33-40-00-210 (ZONE: 341) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Hrs	9,471.8	450	-/+25 (9,921.8)	71.3 Hrs (+25)	
							Ldg	7,591				
B334000		Position and Anticollision Lights Operational Check						RE		Inspection Time Limits	≈19-Apr-2024	
	33 A/F	05-12-04					Mos	29-Oct-2020				
	Task:33-40-00-710 (ZONE: 540, 640) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Hrs	8,390.5	1,800	-/+25 (10,190.5)	340 Hrs (+25)	
							Ldg	6,735				
B335000		Emergency Lighting System Operational Check						RE		Inspection Time Limits	≈17-Dec-2023	
	33 A/F	05-12-13					Mos	07-Jun-2023	12	-/+1m (30-Jun-2024)	7.6 Months (+30 Days)	
	Task:33-50-00-710 (ZONE: 142, 242) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Hrs	9,471.8	450	-/+25 (9,921.8)	71.3 Hrs (+25)	
							Ldg	7,591				
Reliability-33-001		Inspect for Proper Sealant in Tail Section, Around Beacon Light Area per MM Ch. 33-40-00 section 6/B/(3)						RE				
	33 A/F						Mos	07-Jun-2023	12	-/+1m 30-Jun-2024	7.6 Months (+30 Days)	
	(SOURCE: 20-40-20-2 (REV 2))						Hrs	9,471.8				
							Ldg	7,591				
SB510-33-01		Lights - Landing/Taxi Light Improvement						T (A/R)		Optional		
	33 A/F						Mos					
	Eff: 10-Nov-2017 Declined	NOT OF INTEREST					Hrs					
	(NOTE: 05/Oct/2018)						Ldg					
▼ 34 - NAVIGATION												
		VHF/NAV/VOR/LOC Antenna						RE (O/C)				
	34 A/F	Left					Mos	20-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		VHF/NAV/VOR/LOC Antenna						RE (O/C)				
	34 A/F	Right					Mos	20-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		VHF/NAV/VOR/LOC Antenna (Kit)						RE (O/C)				
	34 A/F						Mos	20-Mar-2008				
	VT10-767-3	New	0				Hrs	0				
	0328		0				Ldg	0				
		ADF Antenna						RE (O/C)				
	34 A/F		8				Mos	04-Feb-2020				
	013-00165-00	New	0				Hrs	7,901.3				
	4808		0				Ldg	6,354				
	(APX COST: 2,372.48)											
		ADF Receiver						RE (O/C)				
	34 A/F						Mos	10-Mar-2017				
	013-00166-00	Overhauled					Hrs	5,845				
	3107						Ldg	4,714				
		Airspeed Indicator						RE (O/C)				
	34 A/F			6			Mos	10-Sep-2015				
	261440-1143	Overhauled		0			Hrs	5,017.1				
	294294A			0			Ldg	4,068				

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
		Attitude Indicator	RE (O/C)								
✱	34 A/F	New					Mos	22-Nov-2018			
	4200-21						Hrs	7,166.1			
	A10-10257						Ldg	5,742			
	(AVG MAN HRS: 0) (APX COST: 0)										
		Configuration Module	RE (O/C)								
✱	34 A/F	New					Mos	20-Mar-2008			
	071-00112-0200		0				Hrs	0			
	14207		0				Ldg	0			
		DME Antenna	RE (O/C)								
✱	34 A/F	New	5				Mos	22-Jan-2020			
	L10-611-14		0				Hrs	7,878.4			
	12830		0				Ldg	6,337			
		(APX COST: 475.71)									
		GCU 475 Flight Mgmt Control Unit	RE (O/C)								
✱	34 A/F	Overhauled					Mos	07-Jun-2023			
	011-01054-10		0				Hrs	9,471.8			
	21805281		0				Ldg	7,591			
		(APX COST: 547.92)									
		GDC 74B Air Data System	RE (O/C)								
✱	34 A/F	No.1					Mos	20-Mar-2008			
	011-01110-00	New	0				Hrs	0			
	43800485		0				Ldg	0			
		GDC 74B Air Data System	RE (O/C)								
✱	34 A/F	No.2					Mos	20-Mar-2008			
	011-01110-00	New	0				Hrs	0			
	43800497		0				Ldg	0			
		GDL 69 Weather Data Link	RE (O/C)								
✱	34 A/F	New					Mos	20-Mar-2008			
	011-00987-00		0				Hrs	0			
	47759215		0				Ldg	0			
		GDU 1040A Display	RE (O/C)								
✱	34 A/F	No.1					Mos	18-May-2016			
	011-00916-00	New	0				Hrs	5,434.2			
	86805798		0				Ldg	4,387			
		GDU 1040A Display	RE (O/C)								
✱	34 A/F	No.2					Mos	20-Mar-2008			
	011-00916-00	New	0				Hrs	0			
	86800580		0				Ldg	0			
		GDU 1500 Mfd Unit	RE (O/C)								
✱	34 A/F	Overhauled					Mos	07-Jun-2023			
	011-01108-00		0				Hrs	9,471.8			
	43201132		0				Ldg	7,591			
		(APX COST: 1,630.3)									
		Gea 71 Eng/Airframe Interface	RE (O/C)								
✱	34 A/F	No.1	12				Mos	25-Aug-2020			
	011-00831-00	Overhauled	0				Hrs	8,245.4			
	46702901		0				Ldg	6,618			
		(AVG MAN HRS: 0) (APX COST: 0) (NOTE: Previously : 46708211)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
Gea 71 Eng/Airframe Interface											RE (O/C)
34 A/F		No.2					Mos	07-Jun-2023			
011-00831-00		Tested/Inspected	7,538.4				Hrs	9,471.8			
46710057			6,150				Ldg	7,591			
(AVG MAN HRS: 0) (APX COST: 0) (NOTE: Previously: 46701682)											
Gia 63W Nav/Comm/Ls/Gps Unit											RE (O/C)
34 A/F		No.1					Mos	20-Mar-2008			
011-01105-01		New	0				Hrs	0			
15W005206			0				Ldg	0			
Gia 63W Nav/Comm/Ls/Gps Unit											RE (O/C)
34 A/F		No.2					Mos	20-Mar-2008			
011-01105-01		New	0				Hrs	0			
15W005217			0				Ldg	0			
GMU 44 Magnetometer											RE (O/C)
34 A/F		No.1					Mos	20-Mar-2008			
011-00870-00		New	0				Hrs	0			
47509620			0				Ldg	0			
GMU 44 Magnetometer											RE (O/C)
34 A/F		No.2		20			Mos	26-Jul-2022			
011-00870-00		Overhauled	0	0			Hrs	9,417.9			
47517726			0	0			Ldg	7,551			
(APX COST: 0.01)											
GPS/WAAS/ Antenna											RE (O/C)
34 A/F							Mos	20-Mar-2008			
013-00244-00		New	0				Hrs	0			
5124			0				Ldg	0			
GPS/WAAS/Xm Antenna											RE (O/C)
34 A/F							Mos	20-Mar-2008			
013-00245-00		New	0				Hrs	0			
5197			0				Ldg	0			
GRS 77 AHRS Unit											RE (O/C)
34 A/F		No.1					Mos	20-Mar-2008			
011-00868-10		New	0				Hrs	0			
42007667			0				Ldg	0			
GRS 77 AHRS Unit											RE (O/C)
34 A/F		No.2					Mos	12-Jun-2023			
011-00868-10		Overhauled	0	0			Hrs	9,472.4			
42027237			0	0			Ldg	7,592			
(APX COST: 922.39)											
GTP 59 Oat Probe System											RE (O/C)
34 A/F		No.1					Mos	20-Mar-2008			
011-00978-00		New	0				Hrs	0			
47909447			0				Ldg	0			
GTP 59 Oat Probe System											RE (O/C)
34 A/F		No.2					Mos	20-Mar-2008			
011-00978-00		New	0				Hrs	0			
47909451			0				Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
GWX 68 Weather Radar											RE (O/C)
34 A/F	011-00883-20 47204561 (APX COST: 3,134.5)	Overhauled					Mos	30-Oct-2023			
				0	0		Hrs	9,825.4			
				0	0		Ldg	7,875			
KN63 DME Transceiver											RE (O/C)
34 A/F	066-01070-0001 31319	Overhauled		0			Mos	31-Jan-2013			
				0			Hrs	3,329.9			
				0			Ldg	2,803			
L-Band Transponder Antenna											RE (O/C)
34 A/F	L10-611-14 0726	Left New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
L-Band Transponder Antenna											RE (O/C)
34 A/F	L10-611-14 0473	No.1 (Upper) New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
L-Band Transponder Antenna											RE (O/C)
34 A/F	L10-611-14 0475	No.2 (Upper) New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
L-Band Transponder Antenna											RE (O/C)
34 A/F	L10-611-14 0728	Right New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
Magnetic Compass											RE (O/C)
34 A/F	S2800-821 NSN	New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
Marker Beacon Antenna											RE (O/C)
34 A/F	MB10-754-2 0108	New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
Pitot Probe											RE (O/C)
34 A/F	0851LN 257115	Left New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
Pitot Probe											RE (O/C)
34 A/F	0851LN 257402	Right New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			
RMI Converter											RE (O/C)
34 A/F	013-00167-00 0513	New					Mos	20-Mar-2008			
			0				Hrs	0			
			0				Ldg	0			

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
Standby Altimeter											
	34 A/F	New					Mos	RE (O/C)			
	162350-1161						Hrs	20-Mar-2008			
	177446B		0				Ldg	0			
Swaat Unit											
	34 A/F	New					Mos	RE (O/C)			
	0863B2						Hrs	20-Mar-2008			
	136		0				Ldg	0			
TAS Antenna											
	34 A/F	Bottom					Mos	RE (O/C)			
	L10-611-14	New					Hrs	20-Mar-2008			
	0730		0				Ldg	0			
TAS Antenna											
	34 A/F	Top					Mos	RE (O/C)			
	071-01599-0100	New					Hrs	13-Jan-2022			
	31171						Ldg	9,092.5			
(APX COST: 2,248.65)											
TAS Processor											
	34 A/F	New					Mos	RE (O/C)			
	066-01152-0101						Hrs	20-Mar-2008			
	1656		0				Ldg	0			
Transponder											
	34 A/F	Left					Mos	RE (O/C)			
	011-00779-21	Tested/Inspected					Hrs	14-Aug-2023			
	84805840						Ldg	9,639.6			
(APX COST: 1,052.12)											
Transponder											
	34 A/F	Right					Mos	RE (O/C)			
	011-00779-21	Tested/Inspected					Hrs	04-Feb-2020			
	84805361		6,433.1				Ldg	7,901.3			
(APX COST: 847.68)											
2005-01-19		GARMIN International Inc. - Mode S Transponders						RE (-)		Mandatory (Appliance AD)	
	34 A/F	Not Applicable by software version					Mos				
	Eff: 23-Feb-2005 Not Applicable						Hrs				
	Brand A:9990-2005-01-19						Ldg				
2010-0003		Rockwell Collins - Navigation - Mode S Transponder Aircraft Type Mode Strapping - Check / Modification						RE (-)		Mandatory (Appliance AD)	
	34 A/F	SUPERSEDED BY REVISION 1					Mos				
	Eff: 05-Jan-2010 Superseded						Hrs				
							Ldg				
2010-0003R1		Rockwell Collins - Navigation - Mode S Transponder Aircraft Type Mode Strapping - Check / Modification						RE (-)		Mandatory (Appliance AD)	
	34 A/F	SUPERSEDED BY REVISION 2					Mos				
	Eff: 19-Jan-2010 Superseded						Hrs				
							Ldg				
2010-0003R2		Rockwell Collins - Navigation - Mode S Transponder Aircraft Type Mode Strapping - Check / Modification						T (A/R)		Mandatory (Appliance AD)	
	34 A/F	BY AIRCRAFT MODEL					Mos				
	Eff: 14-Oct-2014 Not Applicable						Hrs				
							Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2014-18-01	Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02.						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos				
Eff: 14-Oct-2014 Not Applicable	BY AIRCRAFT MODEL					Hrs				
Brand A:9990-2014-18-01 (AVG MAN HRS: 4) (APX COST: 75.85)						Ldg				
2015-0093	NORTHROP GRUMMAN LITEF GmbH - Navigation - Attitude Heading Reference System - Modification / Replacement						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos				
Eff: 10-Jun-2015 Not Applicable	BY AIRCRAFT MODEL					Hrs				
						Ldg				
2015-0093 Paragraph (1)	NORTHROP GRUMMAN LITEF GmbH- Navigation - Attitude Heading Reference System - AFM Amendment						RE (-)		Mandatory (Appliance AD)	
34 A/F						Days				
Eff: 10-Jun-2015 Not Applicable	BY AIRCRAFT MODEL					Hrs				
						Ldg				
2015-0093 Paragraph (2)	NORTHROP GRUMMAN LITEF GmbH - Navigation - Attitude Heading Reference System - Modification / Replacement						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos				
Eff: 10-Jun-2015 Not Applicable	BY AIRCRAFT MODEL					Hrs				
						Ldg				
2015-0093 Paragraph (3)	NORTHROP GRUMMAN LITEF GmbH - Navigation - Attitude Heading Reference System - Concurrent with modification of an aircraft as required by paragraph (2) of this AD, the AFM change, if required by paragraph (1) of this AD (see Note 1 of this AD), can be removed from that aircraft.						T (A/R)		Mandatory (Appliance AD)	
34 A/F						Mos				
Eff: 10-Jun-2015 Not Applicable	BY AIRCRAFT MODEL					Hrs				
						Ldg				
2015-10-51	Avidyne Integrated Flight Display (IFD) - Navigation - Incorporate Operational Limitations into Airplane Flight Manual (AFM) or Airplane Flight Manual Supplement (AFMS) Limitation.						T (A/R)		Mandatory (Appliance AD)	
34 A/F						Mos				
Not Applicable	BY AIRCRAFT MODEL					Hrs				
Brand A:9990-2015-10-51						Ldg				
2015-10-51-E	EMERGENCY AD - Avidyne Integrated Flight Display (IFD) - Navigation - Incorporate Operational Limitations into Airplane Flight Manual (AFM) or Airplane Flight Manual Supplement (AFMS) Limitation						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos				
Eff: 18-May-2015 Not Applicable	BY AIRCRAFT MODEL					Hrs				
						Ldg				
2022-0024	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	08-Nov-2022			
Eff: 18-Feb-2022 Not Applicable	N/A by PN					Hrs	9,471.8			
(NOTE: APPLICABILITY: Thales Flight Management Computer (FMC) 2 Navigation Modules (NAVM), identified by Part Number C13084CA03. These FMC2 NAVM are known to be installed on, but not limited to, Dassault (formerly Br��guet) Br.1150 Atlantique 2 (ATL2) maritime patrol aeroplanes.)						Ldg	7,591			
2022-0024 Par. (1)	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment: Operational Limitation(s)						RE (-)		Mandatory (Appliance AD)	
34 A/F						Days	08-Nov-2022			
Eff: 18-Feb-2022 Not Applicable	N/A by PN					Hrs	9,471.8			
(NOTE: COMPLIANCE: Within 30 days after the effective date of this AD, amend the applicable AFM to refer to Thales FMS User Manual J68952AA-01, containing the limitations specified in Table 1 of this AD, inform all flight crew and, thereafter, operate the Flight Management System (FMS) in accordance with Table 2 of this AD.)						Ldg	7,591			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2022-0024 Par. (2)	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment: Use of Navigation Database						RE (-)		Mandatory (Appliance AD)	
34 A/F						Days	08-Nov-2022			
Eff: 18-Feb-2022 Not Applicable	N/A by PN					Hrs	9,471.8			
	(NOTE: COMPLIANCE: Within 30 days after the effective date of this AD, update the navigation database delivered to installers and operators to remove some navigation procedures as defined in the SIL, and, thereafter, use only a regularly updated navigation database where the above-mentioned procedures have been removed.)					Ldg	7,591			
340080	Glide Slope Antenna						RE (O/C)			
34 A/F						Mos	20-Mar-2008			
RGS10-48	New	0				Hrs	0			
12611		0				Ldg	0			
34AD-01	Transponder Gilham Code Inspection						RE (-)			
34 A/F						Mos				
Not Applicable	GILHAM CODE DOES NOT APPLY TO GARMIN					Hrs				
						Ldg				
34-CUS-100	Download Flight Log Data from Upper MFD card						RE		Custom Task, Recommended	≈17-Dec-2023
34 A/F	05-12-01					Mos	07-Jun-2023			
						Hrs	9,471.8	450	(9,921.8)	71.3 Hrs (+25)
						Ldg	7,591			
B341000	Pitot-Static System Functional Check (Airplanes with Air Data Computer P/N 011- 01110-00 only)						RE (A/R)		Inspection Time Limits	
34 A/F	05-12-36					Mos	02-Jun-2015		-/+1m	
	Task:34-10-00-720 (ZONE: 221, 222,231, 232) (SOURCE: Model 510 Maintenance Manual) (NOTE: Inspection Document 5-12-36 gives a list of interval item(s), which are completed at the first 12 calendar months after Air Data Computer Part Number 011-01110-00 is installed.)					Hrs	4,731.7			
						Ldg	3,868			
B341001	Airspeed Indicator - Certification per 14 CFR Part 91.411						RE		Inspection Time Limits	
34 A/F	05-12-22					Mos	18-May-2022	24	-/+1m (31-May-2024)	6.6 Months (+30 Days)
261440-1143						Hrs	9,252.2			
294294A	Task:34-10-00-720 (ZONE: 221, 222, 231, 232) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Ldg	7,425			
B341001	GDC 74B Air Data System - Certification per 14 CFR Part 91.411						RE		Inspection Time Limits	
34 A/F	No.105-12-22					Mos	18-May-2022	24	-/+1m (31-May-2024)	6.6 Months (+30 Days)
011-01110-00						Hrs	9,252.2			
43800485	Task:34-10-00-720 (ZONE: 221, 222, 231, 232) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Ldg	7,425			
B341001	GDC 74B Air Data System - Certification per 14 CFR Part 91.411						RE		Inspection Time Limits	
34 A/F	No.205-12-22					Mos	18-May-2022	24	-/+1m (31-May-2024)	6.6 Months (+30 Days)
011-01110-00						Hrs	9,252.2			
43800497	Task:34-10-00-720 (ZONE: 221, 222, 231, 232) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Ldg	7,425			
B341001	Pitot-Static System Functional Check (Airplanes with Air Data Computer P/N 011-01110-00 or 011-01110-01)						RE		Inspection Time Limits	
34 A/F	05-12-22					Mos	18-May-2022	24	-/+1m (31-May-2024)	6.6 Months (+30 Days)
	Task:34-10-00-720 (ZONE: 221, 222,231, 232) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,252.2			
						Ldg	7,425			
B341001	Standby Altimeter - Certification per 14 CFR Part 91.411						RE		Inspection Time Limits	
34 A/F	05-12-22					Mos	18-May-2022	24	-/+1m (31-May-2024)	6.6 Months (+30 Days)
162350-1161						Hrs	9,252.2			
177446B	Task:34-10-00-720 (ZONE: 221, 222, 231, 232) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Ldg	7,425			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
B342000 	34 A/F	Stall Warning/Angle-of-Attack System (SWAAT) Operational Check 05-12-01						RE	Inspection Time Limits		≈17-Dec-2023	
							Mos	07-Jun-2023				
							Hrs	9,471.8	450	-/+25	(9,921.8)	71.3 Hrs (+25)
							Ldg	7,591				
Task:34-20-00-710 (ZONE: 222, 224,232) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)												
B345000 	34 A/F	Transponder System Functional Check - Certification per 14 CFR Part 91.413 Left05-12-22						RE	Inspection Time Limits			
							Mos	14-Aug-2023	24	-/+1m	(31-May-2024)	6.6 Months (+30 Days)
							Hrs	9,639.6				
							Ldg	7,726				
Task:34-50-40-720 (ZONE: 221, 222,224) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)												
B345000 	34 A/F	Transponder System Functional Check - Certification per 14 CFR Part 91.413 Right05-12-22						RE	Inspection Time Limits			
							Mos	18-May-2022	24	-/+1m	(31-May-2024)	6.6 Months (+30 Days)
							Hrs	9,252.2				
							Ldg	7,425				
Task:34-50-40-720 (ZONE: 221, 222,224) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)												
B346000 	34 A/F	Fault Log Data Deletion 05-12-06						RE	Inspection Time Limits			
							Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)
							Hrs	9,471.8				
							Ldg	7,591				
Task:34-60-00-070 (ZONE: 221, 222) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)												
CIL-34-07 	34 A/F	Navigation - Transmittal of Garmin Service Advisory 1604 Worldwide Navigation Database Eff: 23-Mar-2016 Complied With						T (A/R)	Informational			
							Mos	10-Mar-2017				
							Hrs	5,845				
							Ldg	4,714				
SB510-34-01 	34 A/F	Traffic Advisory System Installation BY SERIAL NUMBER NOT APPLICABLE						RE (-)	Optional			
							Mos					
							Hrs					
							Ldg					
SB510-34-02 	34 A/F	Hardware and Software Update for Garmin G1000 Avionics Eff: 14-Apr-2008 Complied With						RE (-)	Mandatory			
							Mos	03-Jul-2008				
							Hrs	84				
							Ldg					
SB510-34-05 	34 A/F	Dual Diversity Transponder Installation BY SERIAL NUMBER NOT APPLICABLE						RE (-)	Optional			
							Mos					
							Hrs					
							Ldg					
SB510-34-08 	34 A/F	Garmin Transponder Hardware Improvement BY SERIAL NUMBER NOT APPLICABLE						RE (-)	Mandatory			
							Mos					
							Hrs					
							Ldg					
SB510-34-09 	34 A/F	Garmin G1000 Software Version 010-00435-16 Upgrade Eff: 26-Mar-2009 Complied With						RE (-)	Recommended			
							Mos	16-May-2009				
							Hrs	378				
							Ldg					
SB510-34-10 	34 A/F	Garmin Synthetic Vision Technology Installation SB34-10 APPLIED. With						RE (-)	Optional			
							Mos	25-Jun-2010				
							Hrs	1,379				
							Ldg	1,154				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SB510-34-11		Garmin G1000 Software Version 010-00435-21 Upgrade									
	34 A/F						Mos	03-May-2011		RE (-)	Mandatory
	Complied With	PERFORMED GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE SERVICE BULLETIN					Hrs	2,198			
							Ldg	1,848			
SB510-34-11 R01		Garmin G1000 Software Version 010-00435-21 Upgrade									
	34 A/F						Mos	22-Aug-2011		RE (-)	Mandatory
	Eff: 13-Jul-2011 Complied With	PERFORMED GARMIN G1000 SOFTWARE VERSION 010-00435-21 R1 UPGRADE SERVICE BULLETIN					Hrs	2,513			
							Ldg	2,113			
SB510-34-12		Garmin Display Improvement Revision 1									
	34 A/F						Mos	12-Jun-2012		RE (-)	Mandatory
	Complied With	PERFORMED GARMIN DISPLAY IMPROVEMENT SERVICE BULLETIN					Hrs	2,965			
							Ldg	2,498			
SB510-34-12 R01		Garmin Display Improvement Revision 1									
	34 A/F						Mos	12-Jun-2012		RE (-)	Mandatory
	Eff: 13-Feb-2012 Complied With	PERFORMED GARMIN DISPLAY IMPROVEMENT SERVICE BULLETIN					Hrs	2,965			
							Ldg	2,498			
SB510-34-14		Garmin G1000 Software Version 010-00435-24 Upgrade									
	34 A/F						Mos	12-Jun-2012		RE (-)	Mandatory
	Eff: 04-May-2012 Complied With	PERFORMED GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE SERVICE BULLETIN					Hrs	2,965			
							Ldg	2,498			
SB510-34-16		Navigation - Garmin GRS-77 AHRS Software Update									
	34 A/F						Mos			RE (-)	Mandatory
	Eff: 16-Sep-2016 Superseded	SUPERSEDED BY REVISION 1					Hrs				
	(AVG MAN HRS: 2)						Ldg				
SB510-34-16 R01		Navigation - Garmin GRS-77 AHRS Software Update									
	34 A/F						Mos	10-Mar-2017		RE (-)	Mandatory
	Eff: 30-Sep-2016 Complied With						Hrs	5,845			
	(AVG MAN HRS: 2) (NOTE: NOTE: This service bulletin supersedes SB510-34-14 Navigation - Garmin G1000 Software Version 010-00435-24 Upgrade. SB510-34-14 must be completed before this service bulletin can be accomplished.)						Ldg	4,714			
	Optional service bulletin SB510-34-17 Navigation – Garmin G1000 ADS-B Out Installation with Software Upgrade includes the GRS77 software upgrade in this service bulletin and will supersede this service bulletin if it is accomplished.)										
SB510-34-17		Navigation - Garmin G1000 ADS-B Out Installation with Software Upgrade									
	34 A/F						Mos			T (-)	Optional
	Eff: 16-Sep-2016 Superseded	SUPERSEDED BY REVISION 1					Hrs				
							Ldg				
SB510-34-17 R01		Navigation - Garmin G1000 ADS-B Out Installation with Software Upgrade									
	34 A/F						Mos	10-Mar-2017		RE (-)	Optional
	Eff: 28-Sep-2016 Complied With						Hrs	5,845			
	(NOTE: EFFECTIVITY: Aircraft with Garmin GTX-33D transponders.)						Ldg	4,714			
SB510-34-17 R02		Navigation - Garmin G1000 ADS-B Out Installation with Software Upgrade									
	34 A/F						Mos			T (-)	Optional
	Eff: 26-Apr-2017 Complied With	ALREADY C/W					Hrs				
	(NOTE: EFFECTIVITY: Aircraft with Garmin GTX-33D transponders.)						Ldg				
SB510-34-17 R03		Navigation - Garmin G1000 ADS-B Out Installation with Software Upgrade									
	34 A/F						Mos	07-Nov-2019		RE (-)	Optional
	Eff: 18-Feb-2019 Complied With	SB510-34-18					Hrs	7,783.12			
	(NOTE: 15th March 2019)						Ldg	6,260			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SB510-34-18		Navigation - Garmin G1000 ADS-B Out Software Update						RE (-)		Recommended	
	34 A/F					Mos	07-Nov-2019				
	Eff: 18-Feb-2019 Complied With	SB510-34-18				Hrs	7,783.12				
	(AVG MAN HRS: 3) (NOTE: 15th March 2019)					Ldg	6,260				
SL510-34-01		Transmittal of Garmin Service Alert 070424-00						T (A/R)		Informational	
	34 A/F					Mos					
	Eff: 31-May-2007	NOTED				Hrs					
						Ldg					
SL510-34-02		Garmin GRS 77 Attitude Heading Reference System (AHRS)						RE (-)		Informational	
	34 A/F					Mos					
	Eff: 03-Aug-2007 Not Applicable	BY SERIAL NUMBER NOT APPLICABLE				Hrs					
						Ldg					
SL510-34-03		Transmittal of Garmin Service Advisory Number 0745 Revision A, G1000 WAAS GPS CDI Scaling						RE (-)		Informational	
	34 A/F					Mos	15-Jun-2008				
	Eff: 14-Apr-2008 Complied With					Hrs	63				
						Ldg					
SL510-34-04		Transmittal of Garmin Service Alert No. 0816						RE (-)		Mandatory	
	34 A/F					Mos	30-Nov-2008				
	Eff: 11-Sep-2008 Complied With					Hrs	184				
						Ldg					
SL510-34-05		Garmin G1000 Transponder Operation Change						T (A/R)		Informational	
	34 A/F					Mos					
	Eff: 05-Jun-2008	NOTED				Hrs					
						Ldg					
SL510-34-06		Transmittal of Garmin Service Alert No. 0811, G1000 Series Flight Plan Sequencing Issue						T (A/R)		Informational	
	34 A/F					Mos					
	Eff: 25-Nov-2008	NOTED				Hrs					
						Ldg					
SL510-34-07		Transmittal of Garmin Service Advisory No. 0825 LPV and LNAV/VNAV Approaches with Three-Character Airport Identifiers						T (A/R)		Informational	
	34 A/F					Mos					
	Eff: 19-Nov-2008	NOTED				Hrs					
						Ldg					
SL510-34-08		GPS/WAAS Loss of Reception in Alaska, Northwest Canada, and Eastern Russia						T (A/R)		Informational	
	34 A/F					Mos					
	Eff: 08-Jan-2009	NOTED				Hrs					
						Ldg					
SL510-34-09		Grounding Strip Inspection						RE (-)		Mandatory	
	34 A/F					Mos	11-Feb-2010				
	Eff: 05-Aug-2009 Complied With					Hrs	954.1				
						Ldg	806				
SL510-34-10		Transmittal of Garmin Service Advisory No. 0915 Revision A, G1000 Series Navigation Suspended During Non-Precision Approaches						T (A/R)		Informational	
	34 A/F					Mos					
	Eff: 09-Sep-2009	NOTED				Hrs					
						Ldg					
SL510-34-11		Stored Flight Plan Deletion per Garmin Service Advisory 0929 Rev A						T (A/R)		Informational	
	34 A/F					Mos					
	Eff: 25-Jan-2010	NOTED				Hrs					
						Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL510-34-12	Transmittal of Garmin Service Advisory No. 0933 Revision A, System May Select Nav2 as a Navigation Source During Approach						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 01-Oct-2009	NOTED					Hrs				
						Ldg				
SL510-34-13	Transmittal of Garmin Service Advisory No. 0922 Revision A, VOR or LOC/ILS Approaches						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 30-Sep-2009	NOTED					Hrs				
						Ldg				
SL510-34-14	Transmittal of Garmin Service Advisory No. 0941 Revision A Erroneous GWX Service Message May Be Displayed						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 26-Feb-2010	NOTED					Hrs				
						Ldg				
SL510-34-15	Transmittal of Garmin Service Bulletin 1017 GWX 68 Weather Radar Mod 1						RE (-)		Recommended	
 34 A/F						Mos	05-Nov-2010			
Eff: 28-Oct-2010 Complied With	SL34-15 APPLIED, RADAR REPLACED WITH MOD 1 RADAR.					Hrs	1,821			
						Ldg	1,518			
SL510-34-16	Transmittal of Garmin Service Advisory No. 1041 - GDL 69/69A NEXRAD Weather Reporting Issue						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 17-Jun-2011	NOTED					Hrs				
						Ldg				
SL510-34-17	Transmittal of Garmin Service Advisory No. 1101 - GDL 69/69A TFR (Temporary Flight Restrictions) Reporting Issue						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 17-Jun-2011	NOTED					Hrs				
						Ldg				
SL510-34-18	Transmittal of Garmin Service Advisory No. 1107 - Anomalies in Greenland Terrain Data May Inhibit Operational Capability and Garmin Terrain Data Alert - Anomalies in Greenland Terrain Data						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 17-Jun-2011	NOTED					Hrs				
						Ldg				
SL510-34-19	Transmittal of Garmin Service Advisory No. 1118 - Momentary Failure Indications (Red X) Can Occur When Sorting Stored Flight Plans						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 17-Jun-2011	NOTED					Hrs				
						Ldg				
SL510-34-20	Transmittal of Garmin Service Advisory No. 1129 - Momentary Loss of GRS 77/77H and GDC 74A/74B/74H Functions						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 28-Jun-2011	NOTED					Hrs				
						Ldg				
SL510-34-21	Garmin G1000 GRS77 AHRS Heading Drift Condition						T (A/R)		Informational	
 34 A/F						Mos	10-Mar-2017			
Eff: 08-May-2013 Complied With	SB510-34-17					Hrs	5,845			
						Ldg	4,714			
SL510-34-22	Navigation - Transmittal of Garmin Service Advisory No 1612 2015 IGRF (International Geomagnetic Reference Field) Magnetic Field Model						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 13-Jul-2016	NOTED					Hrs				
						Ldg				
SL510-34-23	Navigation - Garmin G1000 Database Card Replacement						T (A/R)	Recommended, Service Letter		
 34 A/F						Mos				
Eff: 04-May-2017 Complied With	Standard SD card installed					Hrs				
(NOTE: 13th March 2019)						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL510-34-24	Navigation - Transmittal of Garmin Service Advisory 1729 (Rev A) Locked Waypoints						T (A/R)		Service Letter	
 34 A/F						Mos				
Eff: 19-Oct-2017	NOTED					Hrs				
(NOTE: EFFECTIVITY: Aircraft that have SB510-34-17 installed.)						Ldg				
SL510-34-25	Navigation - Transmittal of Garmin Service Advisory 1838 Emergency Descent Mode (EDM)						T (A/R)		Informational, Service Letter	
 34 A/F						Mos				
Eff: 01-Aug-2018	NOTED					Hrs				
(NOTE: 15th March 2019)						Ldg				
SL510-34-26	Navigation - Transmittal of Garmin Service Advisory 1802 Incorrect Direct-To Navigation Following Intercept (Intrcpt) Leg						T (A/R)		Informational, Service Letter	
 34 A/F						Mos				
Eff: 12-Jul-2018	NOTED					Hrs				
(NOTE: 15th March 2019)						Ldg				
SL510-34-27	Navigation - Transmittal of Garmin SB 2046, GRS 77 Software Version 3.04 - Pitch/Roll Offset Calibration Procedure (G1000 With Dual GRS and Three Displays)						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 09-Jun-2020						Hrs				
(NOTE: EFFECTIVITY: Aircraft that have incorporated SB510-34-16, SB510-34-17R1, R2, R3 or SB510-34-18.)						Ldg				
▼ 35 - OXYGEN										
	Indicator - Blowout Disc						RE (O/C)			
 35 A/F						Mos	06-May-2021			
CM3578-1	New	0	0	0		Hrs	8,682.2			
9453		0	0	0		Ldg	6,980			
(AVG MAN HRS: 4) (APX COST: 303.01) (SOURCE: 35-10-00)										
	Crew Oxygen Mask						RE (O/C)			
 35 A/F	Left					Mos	01-Jul-2021			
9914067-41	Overhauled		0	0		Hrs	8,733			
122720			0	0		Ldg	7,019			
(APX COST: 2,563.62)										
	Crew Oxygen Mask						RE (O/C)			
 35 A/F	Right		4			Mos	03-Feb-2021			
9914067-41	Overhauled		0	0		Hrs	8,536.5			
122435			0	0		Ldg	6,858			
(APX COST: 3,060.26)										
	Oxygen Cylinder						RE	Component Time Limits		
 35 A/F		2				Yrs	06-May-2021	15	-/+1m [28-Feb-2034]	10.3 Years (+28 Days)
4441073-040	Overhauled		0	0		Hrs	8,682.2			
0848-312			0	0		Ldg	6,980			
28-Feb-2019										
MM:5-11-00, Task:35-00-00-961 (APX COST: 1,800.33) (SOURCE: Model 510 Maintenance Manual)										
	Oxygen Pressure Gauge						RE (O/C)			
 35 A/F						Mos	20-Mar-2008			
MD97-1	New	0				Hrs	0			
NSN		0				Ldg	0			
	Portable Pbe						RE (O/C)			
 35 A/F						Mos	22-Apr-2018			
MR-10035N	New	0	0	0		Hrs	6,659.5			
E1704341		0	0	0		Ldg	5,358			
(AVG MAN HRS: 0) (APX COST: 791.1)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
174080-35-04	Oxygen - Passenger Oxygen System Mask In-Line Flow Indicator Replacement						T (A/R)		Mandatory	
35 A/F										
Eff: 06-Sep-2010 Not Applicable	Part numbers referred in the SB are not used in the aircraft									
(NOTE: 11th March 2019)										
2011-0090	Intertechnique Aircraft Systems - Oxygen - Oxygen Mask Regulator Inflatable Harness - Identification / Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F										
Eff: 18-May-2011 Complied With	PERFORMED AD 2011-0090R1									
2011-0090 R1	Intertechnique Aircraft Systems - Oxygen - Oxygen Mask Regulator Inflatable Harness - Identification / Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F										
Eff: 27-Jul-2011 Complied With	PERFORMED AD2011-0090R1									
2011-01-09	B/E Aerospace - Oxygen - PBE units having PN 119003-11						T (A/R)		Mandatory (Appliance AD)	
35 A/F										
Eff: 09-Feb-2011 Not Applicable	N/A by P/N and manufacturer									
Brand A:9990-2011-01-09 (AVG MAN HRS: 1) (APX COST: 75.85) (NOTE: This AD applies to B/E Aerospace protective breathing equipment (PBE) units having part number (P/N) 119003-11. Ref: BE SB 119003-35-5.)										
2012-0254	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Flight Crew Oxygen Mask Regulator - Identification / Operational Procedure / Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F										
Eff: 29-Nov-2012 Not Applicable	BY PN & SN									
2012-0254 Paragraph (1)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Flight Crew Oxygen Mask Regulator - Identification						RE (-)		Mandatory (Appliance AD)	
35 A/F										
Eff: 29-Nov-2012 Not Applicable	BY PN & SN									
2012-0254 Paragraph (2.1)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Replace each affected flight crew oxygen mask regulator with a serviceable part, not having a P/N and s/n as listed in Appendix 1 of this AD, or with a part that has passed the test in accordance with the instructions of paragraph 3.A.(4) of intertechnique SB MCF-SBU-35-001.						RE (-)		Mandatory (Appliance AD)	
35 A/F										
Eff: 29-Nov-2012 Not Applicable	BY PN & SN									
2012-0254 Paragraph (2.2)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Amend the Aircraft Flight Manual (AFM) and install a placard						RE (-)		Mandatory (Appliance AD)	
35 A/F										
Eff: 29-Nov-2012 Not Applicable	BY PN & SN									
2012-0254 Paragraph (3)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - replace each affected flight crew oxygen mask regulator with a serviceable part, not having a P/N and s/n as listed in Appendix 1 of this AD, or with a part that has passed the test in accordance with the instructions of paragraph 3.A.(4) of Intertechnique SB MCF-SBU-35-001						RE (-)		Mandatory (Appliance AD)	
35 A/F										
Eff: 29-Nov-2012 Not Applicable	BY PN & SN									

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
2012-0254R1	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Flight Crew Oxygen Mask Regulator - Identification / Operational Procedure / Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F	BY PN & SN				Mos	10-Jun-2013				
Eff: 21-Dec-2012 Not Applicable					Hrs	3,391				
					Ldg	2,853				
2012-0254R1 Paragraph (1)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Flight Crew Oxygen Mask Regulator - Identification						RE (-)		Mandatory (Appliance AD)	
35 A/F	BY PN & SN				Mos	10-Jun-2013				
Eff: 21-Dec-2012 Not Applicable					Hrs	3,391				
					Ldg	2,853				
2012-0254R1 Paragraph (2.1)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Replace each affected flight crew oxygen mask regulator with a serviceable part, not having a P/N and s/n as listed in Appendix 1 of this AD, or with a part that has passed the test in accordance with the instructions of paragraph 3.A.(4) of intertechnique SB MCF-SBU-35-001.						RE (-)		Mandatory (Appliance AD)	
35 A/F	BY PN & SN				Mos	10-Jun-2013				
Eff: 21-Dec-2012 Not Applicable					Hrs	3,391				
					Ldg	2,853				
2012-0254R1 Paragraph (2.2)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Amend the Aircraft Flight Manual (AFM) and install a placard						RE (-)		Mandatory (Appliance AD)	
35 A/F	BY PN & SN				Mos	10-Jun-2013				
Eff: 21-Dec-2012 Not Applicable					Hrs	3,391				
					Ldg	2,853				
2012-0254R1 Paragraph (3)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - replace each affected flight crew oxygen mask regulator with a serviceable part, not having a P/N and s/n as listed in Appendix 1 of this AD, or with a part that has passed the test in accordance with the instructions of paragraph 3.A.(4) of Intertechnique SB MCF-SBU-35-001						RE (-)		Mandatory (Appliance AD)	
35 A/F	BY PN & SN				Mos	10-Jun-2013				
Eff: 21-Dec-2012 Not Applicable					Hrs	3,391				
					Ldg	2,853				
2014-0142	Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification / Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F	N/A as our masks PN MC10-16-101 are not part of Zodiac Aerospace SB MC10-35-274.				Mos					
Eff: 04-Jun-2014 Not Applicable					Hrs					
					Ldg					
2014-0142 Paragraph (1)	Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification						RE (-)		Mandatory (Appliance AD)	
35 A/F	N/A as our masks PN MC10-16-101 are not part of Zodiac Aerospace SB MC10-35-274.				Mos					
Eff: 04-Jun-2014 Not Applicable					Hrs					
					Ldg					
2014-0142 Paragraph (2)	Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F	N/A as our masks PN MC10-16-101 are not part of Zodiac Aerospace SB MC10-35-274.				Mos					
Eff: 04-Jun-2014 Not Applicable					Hrs					
					Ldg					
2014-0142R1	Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification / Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F	N/A as our masks PN MC10-16-101 are not part of Zodiac Aerospace SB MC10-35-274.				Mos	12-May-2016				
Eff: 18-Jun-2014 Not Applicable					Hrs					
					Ldg					
2014-0142R1 Paragraph (1)	Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification						RE (-)		Mandatory (Appliance AD)	
35 A/F	N/A as our masks PN MC10-16-101 are not part of Zodiac Aerospace SB MC10-35-274.				Mos	12-May-2016				
Eff: 18-Jun-2014 Not Applicable					Hrs					
					Ldg					

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
2014-0142R1 Paragraph (2)	Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	12-May-2016			
Eff: 18-Jun-2014 Not Applicable	N/A as our masks PN MC10-16-101 are not part of Zodiac Aerospace SB MC10-35-274.					Hrs				
						Ldg				
35-00-00-960	Crew oxygen masks - Overhaul						RE		Component Time Limits	
35 A/F	Left					Yrs	01-Jul-2021	6	31-Mar-2027	3.4 Years
9914067-41					0	Hrs	8,733			
122720					0	Ldg	7,019			
Overhaul Date 31-Mar-2021										
MM:5-11-00 (SOURCE: Model 510 Maintenance Manual)										
35-00-00-960	Crew oxygen masks - Overhaul						RE		Component Time Limits	
35 A/F	Right					Yrs	03-Feb-2021	6	31-Oct-2026	3 Years
9914067-41					0	Hrs	8,536.5			
122435					0	Ldg	6,858			
Overhaul Date 01-Oct-2020										
MM:5-11-00 (SOURCE: Model 510 Maintenance Manual)										
35-00-00-960	Oxygen Cylinder - Hydrostatic Test						RE		Component Time Limits	
35 A/F						Yrs	06-May-2021	5	02-Aug-2025	1.7 Years
4441073-040					0	Hrs	8,682.2			
0848-312					0	Ldg	6,980			
Hydrostatic Tested Date 02-Aug-2020										
MM:5-11-00 (SOURCE: Model 510 Maintenance Manual)										
A351000	Crew Oxygen Masks and Stowage Boxes Detailed Inspection						RE		Inspection Time Limits	≈15-Jul-2026
35 A/F	05-12-18					Mos	04-Sep-2023	36	-/+1m (31-Jul-2026)	2.7 Years (+31 Days)
						Hrs	9,684.2	2,250	-/+25 (11,934.2)	2,083.7 Hrs (+25)
Task:35-00-00-220 (ZONE: 231, 232) (AVG MAN HRS: 0) (APX COST: 0) (Tol. Adjustment: -51d) (SOURCE: Model 510 Maintenance Manual)						Ldg	7,759			
B351000	Oxygen Bottle and Pressure Gage Functional Check						RE		Inspection Time Limits	≈22-Nov-2024
35 A/F	05-12-ME					Mos	18-May-2022	36	(18-May-2025)	1.5 Years
						Hrs	9,252.2	1,400	(10,652.2)	801.7 Hrs
MM:5-10-01, MM:4-10-00, Task:35-10-00-720 (ZONE: 212, 224) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Ldg	7,425			
B352000	Passenger Oxygen Masks and Passenger Mask Dropout Boxes Operational Check						RE		Inspection Time Limits	
35 A/F	05-12-06					Mos	07-Jun-2023	12	-/+1m (30-Jun-2024)	7.6 Months (+30 Days)
Task:35-20-00-710 (ZONE: 241, 242) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Hrs	9,471.8			
						Ldg	7,591			
B352001	Passenger Oxygen System Functional Check						RE		Inspection Time Limits	≈22-Nov-2024
35 A/F	05-12-ME					Mos	18-May-2022	36	(18-May-2025)	1.5 Years
						Hrs	9,252.2	1,400	(10,652.2)	801.7 Hrs
MM:5-10-01, MM:4-10-00, Task:35-20-00-720 (ZONE: 241, 242, 311, 312) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Ldg	7,425			
CIL-35-05	Oxygen - Transmittal of Zodiac Aerospace Service Bulletin MCF-35-001						RE (-)		Mandatory	
35 A/F						Days				
Eff: 08-Jan-2016 Not Applicable	oxygen mask part numbers are not part of the SL.					Hrs				
(AVG MAN HRS: 3) (NOTE: All Citation Models with flight crew oxygen mask regulators, having P/N MC10, MF10, MF20 series with S?N as listed in Zodiac Aerospace SB MCF-SBU-35-001)						Ldg				
SL510-35-01	Transmittal Of Intertechnique Service Bulletin MXH-35-240 Revision 2						RE (-)		Mandatory	
35 A/F						Mos	19-Jul-2013			
Complied With	PERFORMED SL510-35-01					Hrs	3,391			
						Ldg	2,853			

Task No		Description					Categories		Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL510-35-01 R01		Transmittal Of Intertechnique Service Bulletin MXH-35-240 Revision 2					RE (-)		Mandatory		
	35 A/F						Mos	19-Jul-2013			
	Complied With	PERFORMED SL510-35-01					Hrs	3,391			
							Ldg	2,853			
SL510-35-01 R02		Transmittal Of Intertechnique Service Bulletin MXH-35-240 Revision 2					RE (-)		Mandatory		
	35 A/F						Mos	19-Jul-2013			
	Eff: 25-Oct-2012 Complied With	PERFORMED SL510-35-01					Hrs	3,391			
							Ldg	2,853			
▼ 36 - PNEUMATIC											
		B/A Shutoff Valve					RE (O/C)				
	36 A/F	Left					Mos	04-Sep-2019			
	2601-34	Tested/Inspected	19				Hrs	7,635.4			
	0947A		0				Ldg	6,141			
		(APX COST: 1,674.03)									
		B/A Shutoff Valve					RE (O/C)				
	36 A/F	Right					Mos	20-Mar-2008			
	5253-00-1	New	0				Hrs	0			
	0178A		0				Ldg	0			
		Precooler					RE (O/C)				
	36 A/F	Left					Mos	07-Jun-2023			
	9914402-7	New					Hrs	9,471.8			
	HX-00204						Ldg	7,591			
		(AVG MAN HRS: 0) (APX COST: 9,199.07)									
		Precooler					RE (O/C)				
	36 A/F	Right					Mos	07-Jun-2023			
	9914402-7	New					Hrs	9,471.8			
	T1282						Ldg	7,591			
		(APX COST: 8,588.42)									
		Service Air Regulator Assy					RE (O/C)				
	36 A/F						Mos	20-Mar-2008			
	9912510-2	New	0				Hrs	0			
	7BC038		0				Ldg	0			
		Variable Venturi Valve Assy					RE (O/C)				
	36 A/F	Left					Mos	20-Mar-2008			
	5253-00-1	New	0				Hrs	0			
	1946		0				Ldg	0			
		Variable Venturi Valve Assy					RE (O/C)				
	36 A/F	Right					Mos	20-Mar-2008			
	2601-34		0				Hrs	0			
	1918		0				Ldg	0			
		(APX COST: 0)									
▼ 46 - INFORMATION SYSTEMS											
		EFB Charging Cable					RE (O/C)				
	46 A/F	Left					Mos	20-Mar-2008			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	46 A/F Unknown Unknown	EFB Charging Cable						RE (O/C)				
		Right						Mos	20-Mar-2008			
								Hrs	0			
								Ldg	0			
	46 A/F Apple iPad11,2 MUXC2FD DMPF907ZLMTG Manufactured Date 01-Mar-2021	EFB Device						RE (O/C)				
		Left						Mos	30-Apr-2021			
								Hrs	0			
								Ldg	0			
	46 A/F Apple iPad11,2 MUXC2FD DMPF903SLMTG Manufactured Date 01-Mar-2021	EFB Device						RE (O/C)				
		Right						Mos	30-Apr-2021			
								Hrs	0			
								Ldg	0			
	46 A/F Unknown Unknown	EFB Mount						RE (O/C)				
		Left						Mos	20-Mar-2008			
								Hrs	0			
								Ldg	0			
	46 A/F Unknown Unknown	EFB Mount						RE (O/C)				
		Right						Mos	20-Mar-2008			
								Hrs	0			
								Ldg	0			
	46 A/F	EFB Mount Suction Cup cleaning and inspection (LH)						RE				
								Mos	07-Jun-2023			
								Hrs	9,471.8			
								Ldg	7,591			
	46 A/F	EFB Mount Suction Cup cleaning and inspection (RH)						RE				
								Mos	07-Jun-2023			
								Hrs	9,471.8			
								Ldg	7,591			
	46 A/F Unknown Unknown	EFB Protection Case						RE (O/C)				
		Left						Mos	20-Mar-2008			
								Hrs	0			
								Ldg	0			
	46 A/F Unknown Unknown	EFB Protection Case						RE (O/C)				
		Right						Mos	20-Mar-2008			
								Hrs	0			
								Ldg	0			
▼ 52 - DOORS												
	52 A/F S-22560-3 104	Cabin Door Seal						RE (O/C)				
								Mos	20-Mar-2008			
								Hrs	0			
								Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
 52 A/F S-22561 109	New						RE (O/C)			
							Mos	20-Mar-2008		
							Hrs	0		
							Ldg	0		
 52 A/F	Inspect Door Switches for proper operation and adjustment per MM Ch 52-70-00						RE (A/R)			
							Mos	08-May-2020		
							Hrs	7,976.4		
							Ldg	6,420		
 52 A/F	Emergency Door Sealant Lubrication						RE (A/R)			
							Mos	01-Jul-2021		
							Hrs	8,733		
							Ldg	7,019		
 52 A/F	Cabin Door Seal General Visual Inspection 05-12-13						RE			
							Mos	07-Jun-2023		
							Hrs	9,471.8		
							Ldg	7,591		
 52 A/F	Cabin Door and Step Assembly Detailed Inspection 05-12-16						RE			
							Mos	17-Mar-2022		
							Hrs	9,146.2		
							Ldg	7,338		
 52 A/F	Escape Hatch Detailed Inspection 05-12-16						RE			
							Mos	17-Mar-2022		
							Hrs	9,146.2		
							Ldg	7,338		
 52 A/F	Cabin and Baggage Compartment Door Switches Operational Check 05-12-01						RE			
							Mos	07-Jun-2023		
							Hrs	9,471.8		
							Ldg	7,591		
 52 A/F	Key Lock Lubrication 05-12-06						RE			
							Mos	07-Jun-2023		
							Hrs	9,471.8		
							Ldg	7,591		
 52 A/F	Doors - Cessna 510 - Entry Upper Step Repair i.a.w. EAR521229-1 Reliability-52-001						RE (-)			
							Mos			
							Hrs			
							Ldg			
 52 A/F	Doors - Cessna 510 - Entry Upper Step Repair. General Inspection General Visual Inspect the Repair Area for Signs of Crack Propagation and Overall Condition of the Repair and Step. Reliability-52-001						T (N/A)			
							Mos			
							Hrs			
							Ldg			
 52 A/F	Inspection of the Main Entry Door Step (AVG MAN HRS: 1)						RE			
							Mos	12		
							Hrs	-/+1m		
							Ldg	[30-Jun-2024]		



OE-FFB STATUS REPORT

Owner/Operator: GlobeAir AG GlobeAir AG

CESSNA

510 (Citation Mustang) OE-FFB,SN 510-0065

Task No		Description									Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
Reliability-52-001a		Perform Inspection of Main Entry Door Step						RE					
52	A/F	Reliability-52-001						12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)		
(NOTE: Perform inspection of main entry door step due to possible crack. If crack is observed, evaluate possibility for a repair per EAR521229-1. If repair is already performed, perform inspection per ICA521229-1. If no crack is observed, no further action till next inspection)													
SB510-52-01		Improvement to the Door Frame Proximity Switch						RE (-)		Recommended			
52	A/F							Mos					
Eff: 29-Apr-2008 Not Applicable		BY SERIAL NUMBER NOT APPLICABLE						Hrs					
(NOTE: 11/Oct/2018)								Ldg					
SB510-52-03		Nose Baggage Door Hinge Improvement						RE (-)		Recommended			
52	A/F							Mos					
Eff: 13-Feb-2008 Not Applicable		BY SERIAL NUMBER NOT APPLICABLE						Hrs					
(NOTE: 11/Oct/2018)								Ldg					
SB510-52-05SDA		Aft Baggage Door Modification - Supplemental Data Sheet Revision A						RE (-)		Discretionary			
52	A/F							Mos	07-Mar-2011				
Eff: 11-Oct-2010 Complied With		COMPLETED SB510-52-05						Hrs	2,069				
								Ldg	1,745				
SB510-52-06		Doors - Emergency Escape Hatch Inner Handle Hardware Replacement						RE (-)		Mandatory, Service Bulletin			
52	A/F							Days	08-May-2020				
Eff: 16-Jan-2020 Complied With								Hrs	7,976.4				
(AVG MAN HRS: 1) (APX COST: 400.6) (NOTE: COMPLIANCE: This service document must be accomplished within 90 days from the date of receipt.)								Ldg	6,420				
SL510-52-01		Cabin Entry Door Hinge Fastener Inspection						RE (-)		Mandatory			
52	A/F							Mos	13-Oct-2009				
Complied With								Hrs	783				
								Ldg					
SL510-52-01 R01		Cabin Entry Door Hinge Fastener Inspection						RE (-)		Mandatory			
52	A/F							Mos	05-Oct-2010				
Eff: 14-Oct-2009 Complied With		PERFORMED SL510.52.01 R1 NO MISSING RIVETS						Hrs	1,734				
								Ldg	1,449				
SL510-52-02		Cabin Door Fairing Fastener Inspection						RE (-)		Mandatory			
52	A/F							Mos					
Eff: 03-Aug-2009 Not Applicable		BY SERIAL NUMBER NOT APPLICABLE						Hrs					
(NOTE: 11/Oct/2018)								Ldg					
SL510-52-03		Door Frame Corner Fastener Inspection						RE (-)		Mandatory			
52	A/F							Mos	11-Feb-2010				
Eff: 29-Sep-2009 Complied With								Hrs	954.1				
								Ldg	806				
SL510-52-04		Cabin Entry Door Pin Repair						T (A/R)		Informational			
52	A/F							Mos					
Eff: 17-Oct-2011		NOTED						Hrs					
(NOTE: 11/Oct/2018)								Ldg					
SL510-52-05		Cabin Entry Door Hinge Shield Inspection						RE (-)		Recommended			
52	A/F							Mos					
Eff: 04-Jan-2013 Not Applicable		BY SERIAL NUMBER NOT APPLICABLE						Hrs					
(NOTE: 11/Oct/2018)								Ldg					

Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL510-52-06	Doors - Inspect and Torque the Inner Escape Hatch Handle Bolt and Nut							RE (-)	Mandatory, Service Letter		
	52 A/F						Days	22-Jan-2020			
	Eff: 18-Nov-2019 Complied	SL510-52-06					Hrs	7,878.4			
	With						Ldg	6,337			
	(AVG MAN HRS: 1)										
▼ 53 - FUSELAGE											
		Fwd Engine Beam						RE (O/C)			
	53 A/F						Mos	20-Mar-2008			
	7012061-3	New					Hrs	0			
	0065						Ldg	0			
		Nose Landing Gear Attach Fitting Assembly						RE	Replacement Schedule	≈08-Jan-2044	
	53 A/F	Left					Mos	20-Mar-2008			
	7013022-3	New					Hrs	0			
	NSN						Ldg	0	20,000	20,000	12,100 Ldg
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)										
		Nose Landing Gear Attach Fitting Assembly						RE	Replacement Schedule	≈08-Jan-2044	
	53 A/F	Right					Mos	20-Mar-2008			
	7013022-4	New					Hrs	0			
	NSN						Ldg	0	20,000	20,000	12,100 Ldg
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)										
		Nose Landing Gear Drag Brace Fitting Assembly						RE	Replacement Schedule	≈08-Jan-2044	
	53 A/F	Left					Mos	20-Mar-2008			
	7013022-11	New					Hrs	0			
	NSN						Ldg	0	20,000	20,000	12,100 Ldg
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)										
		Nose Landing Gear Drag Brace Fitting Assembly						RE	Replacement Schedule	≈08-Jan-2044	
	53 A/F	Right					Mos	20-Mar-2008			
	7013022-10	New					Hrs	0			
	NSN						Ldg	0	20,000	20,000	12,100 Ldg
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)										
		Nose Radome						RE (O/C)			
	53 A/F						Mos	20-Mar-2008			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
A522001	Escape Hatch Skin Special Detailed Inspection							T	Inspection Time Limits	≈15-Aug-2026	
	53 A/F	05-12-MF					Mos				
							Hrs	12,000	(12,000)	2,149.5 Hrs	
	MM:5-10-01, MM:4-10-00, Task:52-20-20-250 (ZONE: 820) (SOURCE: Model 510 Maintenance Manual)						Ldg				
A530000	Fuselage Internal Zonal Inspection							RE	Inspection Time Limits		
	53 A/F	05-12-11					Mos	07-Jun-2023	72	-/+1m (30-Jun-2029)	5.6 Years (+30 Days)
							Hrs	9,471.8			
	Task:53-00-00-210 (ZONE: 110, 111, 112, 131, 132, 141, 142, 211, 212, 221) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 222, 231, 232, 241, 242)						Ldg	7,591			
A530001	Fuselage External Zonal Inspection							RE	Inspection Time Limits		
	53 A/F	05-12-11					Mos	07-Jun-2023	72	-/+1m (30-Jun-2029)	5.6 Years (+30 Days)
							Hrs	9,471.8			
	Task:53-00-00-211 (ZONE: 110, 111, 112, 131, 132, 133, 134, 141, 142, 143) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 145, 147, 148, 211, 212, 221, 222, 231, 232, 241, 242, 311, 312, 313, 314, 315, 317, 321, 322, 330, 340, 341, 351, 352, 410, 411, 412, 420, 511, 512, 521, 522, 531, 532, 540, 611, 612)						Ldg	7,591			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
A530002 	53 A/F	Fuselage Fairing Zonal Inspection 05-12-11 Task:53-00-00-212 (ZONE: 133, 134, 143, 144, 145, 146, 148, 315, 316, 318) (SOURCE: Model 510 Maintenance Manual) (NOTE: Zones Continued: 147, 317)						RE		Inspection Time Limits	
						Mos	07-Jun-2023	72	-/+1m	(30-Jun-2029)	5.6 Years (+30 Days)
						Hrs	9,471.8				
						Ldg	7,591				
A530003 	53 A/F	Forward Pressure Bulkhead Special Detailed Inspection 05-12-MF MM:5-10-01, MM:4-10-00, task:53-00-00-250 (ZONE: 221, 222) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits ≈15-Aug-2026	
						Mos					
						Hrs	12,000		(12,000)	2,149.5 Hrs	
						Ldg					
A530004 	53 A/F	Aft Pressure Bulkhead Special Detailed Inspection 05-12-MF MM:5-10-01, MM:4-10-00, Task:53-00-00-251 (ZONE: 241, 242) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits ≈15-Aug-2026	
						Mos					
						Hrs	12,000		(12,000)	2,149.5 Hrs	
						Ldg					
A530005 	53 A/F	Environmental Corrosion Exterior (All Pressure Vessel Skins and Splices Detailed) Inspection 05-12-MG MM:4-10-00, MM:5-10-01, Task:51-10-10-211 (ZONE: 100, 200) (SOURCE: Model 510 Maintenance Manual)						RE		Inspection Time Limits ≈10-Nov-2026	
						Mos	04-Sep-2023				
						Hrs	9,684.2	2,500	(12,184.2)	2,333.7 Hrs	
						Ldg	7,759				
A530006 	53 A/F	Nose Landing Gear Wheel Well General Visual Inspection (Corrosion Inspection) 05-12-06 Task:53-00-00-213 (ZONE: 111, 112) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						RE		Inspection Time Limits	
						Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)
						Hrs	9,471.8				
						Ldg	7,591				
A530007 	53 A/F	Nose Landing Gear Wheel Well General Visual Inspection (Corrosion Inspection) 05-12-35 Task:53-00-00-213 (ZONE: 111, 112) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: For airplanes that operate in moderate or severe corrosion environments)						RE		Inspection Time Limits	
						Mos	07-Jun-2023	6	-/+1m	(31-Dec-2023)	45 Days (+31)
						Hrs	9,471.8				
						Ldg	7,591				
A531001 	53 A/F	Windshield Lower Sill Special Detailed Inspection 05-12-MH MM:5-10-01, MM:4-10-00, Task:53-10-20-250 (ZONE: 231, 232) (SOURCE: Model 510 Maintenance Manual)						RE		Inspection Time Limits ≈28-Feb-2026	
						Mos	23-Aug-2020				
						Hrs	8,244.4	3,400	(11,644.4)	1,793.9 Hrs	
						Ldg	6,617				
A532000 	53 A/F	Cabin Door Frame Special Detailed Inspection 05-12-MJ MM:5-10-01, MM:4-10-00, Task:53-20-10-250 (ZONE: 810) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits ≈29-Oct-2024	
						Mos					
						Hrs	10,600		(10,600)	749.5 Hrs	
						Ldg					
A532001 	53 A/F	Cabin Door Threshold Special Detailed Inspection 05-12-MF MM:5-10-01, MM:4-10-00, Task:53-20-10-251 (ZONE: 810) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits ≈15-Aug-2026	
						Mos					
						Hrs	12,000		(12,000)	2,149.5 Hrs	
						Ldg					
A532002 	53 A/F	Cabin Door Lintel Special Detailed Inspection 05-12-MI MM:5-10-01, MM:4-10-00, Task:53-20-10-252 (ZONE: 810) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits ≈15-Aug-2026	
						Mos					
						Hrs	12,000		(12,000)	2,149.5 Hrs	
						Ldg					
A532020 	53 A/F	Escape Hatch Opening Special Detailed Inspection 05-12-MK MM:5-10-01, MM:4-10-00, Task:53-20-20-250 (ZONE: 820) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits ≈27-Jul-2024	
						Mos					
						Hrs	10,400		(10,400)	549.5 Hrs	
						Ldg					
A534000 	53 A/F	Empennage External Zonal Inspection 05-12-11 Task:53-40-00-210 (ZONE: 311, 312, 313, 314, 321, 322, 330, 340) (SOURCE: Model 510 Maintenance Manual) (NOTE: Zones Continued: 341, 351, 352)						RE		Inspection Time Limits	
						Mos	07-Jun-2023	72	-/+1m	(30-Jun-2029)	5.6 Years (+30 Days)
						Hrs	9,471.8				
						Ldg	7,591				

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
A534001	Empennage Internal Zonal Inspection						RE		Inspection Time Limits	
 53 A/F	05-12-11				Mos	07-Jun-2023	72	-/+1m	(30-Jun-2029)	5.6 Years (+30 Days)
	Task:53-40-00-211 (ZONE: 311, 312, 313, 314, 321, 322, 330, 340) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 341, 351, 352)				Hrs	9,471.8				
					Ldg	7,591				
A534003	Aft Tailcone Skin and Splices Detailed Inspection						T		Inspection Time Limits	≈15-Aug-2026
 53 A/F	05-12-MF				Mos					
	MM:5-10-01, MM:4-10-00 (ZONE: 321, 322) (SOURCE: Model 510 Maintenance Manual)				Hrs	12,000			(12,000)	2,149.5 Hrs
					Ldg					
B533000	Skin Joint Special Detailed Inspection (Eddy Current)						RE		Inspection Time Limits	≈26-Dec-2028
 53 A/F	05-12-37				Mos	22-Apr-2018				
	Task:53-30-10-250 (ZONE: 110, 111, 112, 131, 132, 133, 134, 141, 142, 143) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: more zone: 144, 145, 146, 147, 148, 211, 212, 221, 222, 231, 232, 241, 242, 311, 312, 313, 314, 315, 316, 317, 318, 321, 322, 330, 340, 341, 351, 352, 410, 411, 412, 420, 511, 512, 521, 522, 531, 532, 540, 611, 612)				Hrs	6,659.5	7,200	-/+25	(13,845.3)	3,994.8 Hrs (+25)
					Ldg	5,358				
Reliability-53-001	Inspect Antennas and top section of Fuselage for proper sealing per Citation Standard Practices Manual Ch. 20-40-20.						RE			
 53 A/F					Mos	07-Jun-2023	12	-/+1m	30-Jun-2024	7.6 Months (+30 Days)
	(SOURCE: 20-40-20-2 (REV 2))				Hrs	9,471.8				
					Ldg	7,591				
SB510-53-01	Aft Cabin Structure Inspection						RE (-)		Mandatory	
 53 A/F					Mos	11-Feb-2010				
	Eff: 13-Mar-2009 Complied With				Hrs	954.1				
					Ldg	806				
SL510-53-01	Forward Pressure Bulkhead Inspection						RE (-)		Recommended	
 53 A/F					Mos					
	Eff: 24-Mar-2008 Not Applicable				Hrs					
	(NOTE: 11/Oct/2018)				Ldg					
SL510-53-02A	Tailcone Sealant Inspection						RE (-)		Mandatory	
 53 A/F					Mos	14-Nov-2008				
	Complied With				Hrs	158				
					Ldg					
SL510-53-02A R01	Tailcone Sealant Inspection						RE (-)		Mandatory	
 53 A/F					Mos					
	Complied With				Hrs					
	(NOTE: 11/Oct/2018)				Ldg					
SL510-53-02A R02	Tailcone Sealant Inspection						T (A/R)		Mandatory	
 53 A/F					Mos					
	Eff: 02-Mar-2009 Complied With				Hrs					
	(NOTE: 11/Oct/2018)				Ldg					
SL510-53-03	Drain Hole Inspection						RE (-)		Mandatory	
 53 A/F					Mos	28-May-2010				
	Eff: 05-Mar-2010 Complied With				Hrs	1,291				
	PERFORMED SL510-53-03. DRAIN HOLE AS EXPECTED.				Ldg	1,085				
▼ 54 - NACELLES/PYLONS										
A545001	Forward Engine Mount Lug Special Detailed Inspection						T		Inspection Time Limits	≈15-Aug-2026
 54 A/F	05-12-MF				Mos					
	MM:5-10-01, MM:4-10-00, Task:54-50-00-250 (ZONE: 411, 412) (SOURCE: Model 510 Maintenance Manual)				Hrs	12,000			(12,000)	2,149.5 Hrs
					Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
A545002	54 A/F	Forward Engine Mount-To-Engine Beam Interface Special Detailed Inspection 05-12-MF MM:5-10-01, MM:4-10-00, Task:54-50-00-251 (ZONE: 411, 412) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545003	54 A/F	Upper and Lower Fire Shield Special Detailed Inspection 05-12-MF MM:5-10-01, MM:4-10-00, Task:54-50-00-252 (ZONE: 411, 412) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545004	54 A/F	Forward Engine Mount Upper Arm Radius Special Detailed Inspection 05-12-MF MM:5-10-01, MM:4-10-00, Task:54-50-00-253 (ZONE: 411, 412) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545005	54 A/F	Forward Engine Mount Outboard Fire Shield Special Detailed Inspection 05-12-MF MM:5-10-01, MM:4-10-00, Task:54-50-00-254 (ZONE: 411, 412) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545006	54 A/F	Forward Engine Beam Upper Cap (BL 24.86 - Outboard End) Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 411, 412) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545007	54 A/F	Aft Engine Beam Upper Cap (BL 23.72 - Outboard End) Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 311, 312, 321, 322) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545008	54 A/F	Forward Engine Beam to Tailcone Frame Interfaces (TCS132.25 and TCS 135.25) Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 311, 312, 321, 322) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545009	54 A/F	Aft Engine Beam and Tailcone Frame Interfaces (TCS 150.35 and TCS 152.35) Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 311, 312, 321, 322) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545010	54 A/F	Aft engine Mount Tees Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 411, 412) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545011	54 A/F	Aft Engine Mount to Aft Engine Beam Interfaces Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 411, 412) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
A545012	54 A/F	Aft Engine Beam to Pylon Upper Interfaces Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 411, 412) (SOURCE: Model 510 Maintenance Manual)						T		Inspection Time Limits	≈15-Aug-2026
Reliability-54-001	54 A/F	Inspect for Proper Sealant in Tail Section - Engine Pylon - fuselage section						RE			
SB510-54-01	54 A/F Superseded (NOTE: SB510-54-01)	Pylon Skin Improvements SUPERSEDED BY REVISION 1						RE (-)		Discretionary	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SB510-54-01 R01		Pylon Skin Improvements								RE (-)	Discretionary
	54 A/F						Mos	16-Mar-2020			
	Eff: 05-Jun-2012 Complied With						Hrs	7,941.9			
	(NOTE: 16/Oct/2018)						Ldg	6,389			
SL510-54-01A		Pylon Ram Air Duct Visual Inspection								RE (-)	Mandatory
	54 A/F						Mos				
	Eff: 14-Feb-2008 Not Applicable	BY SERIAL NUMBER NOT APPLICABLE					Hrs				
	(NOTE: 16/Oct/2018)						Ldg				
▼ 55 - STABILIZERS											
		HORIZONTAL STABILIZER SEALANT INSPECTION IAW SL510-55-02 REV.2								RE (-)	
	55 A/F						Mos	16-Jan-2019			
							Hrs	7,198.5			
							Ldg	5,773			
		HORIZONTAL STABILIZER SEALANT INSPECTION IAW SL510-55-02 REV.2								RE (-)	
	55 A/F						Mos	16-Jan-2019			
							Hrs	7,198.5			
							Ldg	5,773			
		Elevator Assembly								RE (O/C)	
	55 A/F	Left					Mos	20-Mar-2008			
	7034001-7	New	0				Hrs	0			
	44		0				Ldg	0			
		Elevator Assembly								RE (O/C)	
	55 A/F	Right					Mos	20-Mar-2008			
	7034001-8	New	0				Hrs	0			
	48		0				Ldg	0			
		Horizontal Stabilizer								RE (O/C)	
	55 A/F						Mos	20-Mar-2008			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Vertical Stabilizer Assy								RE (O/C)	
	55 A/F						Mos	20-Mar-2008			
	7031001-1	New	0				Hrs	0			
	22		0				Ldg	0			
A551001		Horizontal Stabilizer - Front Spar Upper Flange and Splice Straps (BL 0.00 - BL 6.00) Special Detailed Inspection								T	Inspection Time Limits ≈15-Aug-2026
	55 A/F	05-12-MF					Mos				
							Hrs	12,000	(12,000)	2,149.5 Hrs	
	MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 351, 352) (SOURCE: Model 510 Maintenance Manual)						Ldg				
A551002		Horizontal Stabilizer - Front Spar Upper Flange (BL 6.00 - HSS 120.67) Special Detailed Inspection								T	Inspection Time Limits ≈15-Aug-2026
	55 A/F	05-12-MF					Mos				
							Hrs	12,000	(12,000)	2,149.5 Hrs	
	MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 351, 352) (SOURCE: Model 510 Maintenance Manual)						Ldg				
A551003		Horizontal Stabilizer - Center Spar Upper Flange and Splice Straps (BL 0.00 - BL 6.00) Special Detailed Inspection								T	Inspection Time Limits ≈15-Aug-2026
	55 A/F	05-12-MF					Mos				
							Hrs	12,000	(12,000)	2,149.5 Hrs	
	MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 351, 352) (SOURCE: Model 510 Maintenance Manual)						Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
A551004		Horizontal Stabilizer - Center Spar Upper Flange (BL 6.00 - HSS 120.67) Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 351, 352) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					
A551005		Horizontal Stabilizer - Rear Spar Upper Flange and Splice Straps (BL 0.00 - BL 6.00) Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 351, 352) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					
A551006		Horizontal Stabilizer - Rear Spar Upper Flange (BL 6.00 - HSS 120.67) Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 351, 352) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					
A551007		Horizontal Stabilizer - Front Horizontal Tail Attach Fittings Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:55-10-10-250 (ZONE: 351, 352) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					
A551008		Horizontal Stabilizer - Rear Horizontal Tail Attach Fittings Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:55-10-10-250 (ZONE: 351, 352) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					
A551009		Horizontal Stabilizer Aft Spar Area General Visual Inspection (Corrosion Inspection)									
	55 A/F	05-12-35				Mos	07-Jun-2023	RE 6	-/+1m	Inspection Time Limits (31-Dec-2023)	45 Days (+31)
		Task:55-10-00-210 (ZONE: 351, 352) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: For airplanes that operate in moderate or severe corrosion environments)				Hrs	9,471.8				
						Ldg	7,591				
A551010		Horizontal Stabilizer Aft Spar Area General Visual Inspection (Corrosion Inspection)									
	55 A/F	05-12-06				Mos	07-Jun-2023	RE 12	-/+1m	Inspection Time Limits (30-Jun-2024)	7.6 Months (+30 Days)
		Task:55-10-00-210 (ZONE: 351, 352) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)				Hrs	9,471.8				
						Ldg	7,591				
A553001		Vertical Stabilizer - Front Spar Outer Flanges (Lower Closeout Rib - VFS 135.02) Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 340) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					
A553002		Vertical Stabilizer - Forward, Center, and Rear Spar Attachment Holes Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:55-30-00-250 (ZONE: 340) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					
A553003		Vertical Stabilizer - Rear Spar Outer Flanges and Sideplates (VFS 140.69 - WL 179.30) Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 340) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					
A553004		Vertical Stabilizer - Front Horizontal Tail Attach Fitting Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 340) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					
A553005		Rear Spar Integral Horizontal Tail Attach Lugs Special Detailed Inspection									
	55 A/F	05-12-MF				Mos				Inspection Time Limits	≈15-Aug-2026
		MM:4-10-00, MM:5-10-01, Task:51-00-00-250 (ZONE: 340) (SOURCE: Model 510 Maintenance Manual)				Hrs		12,000		(12,000)	2,149.5 Hrs
						Ldg					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
A553006		Vertical Stabilizer Aft Spar Assembly General Visual Inspection (Corrosion Inspection)								RE	Inspection Time Limits	
	55 A/F	05-12-35					Mos	07-Jun-2023	6	-/+1m	(31-Dec-2023)	45 Days (+31)
		Task:55-30-00-210 (ZONE: 340) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: For airplanes that operate in moderate or severe corrosion environments)					Hrs	9,471.8				
							Ldg	7,591				
A553007		Vertical Stabilizer Aft Spar Assembly General Visual Inspection (Corrosion Inspection)								RE	Inspection Time Limits	
	55 A/F	05-12-06					Mos	07-Jun-2023	12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)
		Task:55-30-00-210 (ZONE: 340) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,471.8				
							Ldg	7,591				
B551001		Horizontal Stabilizer Ribs Detailed Inspection								RE	Inspection Time Limits	≈10-Sep-2024
	55 A/F	05-12-16					Mos	17-Mar-2022	36	-/+1m	(31-Mar-2025)	1.4 Years (+30 Days)
		Task:55-10-00-290 (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)					Hrs	9,146.2	1,350	-/+25	(10,496.2)	645.7 Hrs (+25)
							Ldg	7,338				
SL510-55-01		Horizontal Stabilizer Rib Inspection								RE (-)	Mandatory	
	55 A/F						Mos	23-Feb-2009				
		Eff: 04-Nov-2008 Complied With					Hrs	293				
							Ldg					
SL510-55-02		Horizontal Stabilizer Sealant Inspection								RE (-)	Mandatory	
	55 A/F						Mos	07-Mar-2011				
		Complied With					Hrs	2,069				
		ORIGINALLY PERFORMED IN NOVEMBER 2011 AT CESSNA SERVICE CENTER IN PARIS.					Ldg	1,745				
SL510-55-02 R01		Horizontal Stabilizer Sealant Inspection								RE (-)	Mandatory	
	55 A/F						Mos					
		Complied With					Hrs					
		(NOTE: 24/Oct/2018)					Ldg					
SL510-55-02 R02		Horizontal Stabilizer Sealant Inspection								T (A/R)	Mandatory	
	55 A/F						Mos	16-Jan-2019				
		Eff: 31-Aug-2011 Complied With					Hrs	7,198.5				
		(NOTE: 24/Oct/2018)					Ldg	5,773				
▼ 56 - WINDOWS												
		Cabin (Escape Hatch) Window								RE (O/C)		
	56 A/F	Right No.2					Mos	20-Mar-2008				
		93320-10					Hrs	0				
		1370					Ldg	0				
		New										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	56 A/F 93320-10 1120	Cabin Window						RE (O/C)			
		Right No.1				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0				
	56 A/F 93320-10 1150	Cabin Window						RE (O/C)			
		Right No.3				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0				
	56 A/F 93310-1 1251	Flight Compartment Side Window						RE (O/C)			
		Left				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0				
	56 A/F 93310-2 1228	Flight Compartment Side Window						RE (O/C)			
		Right				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0				
	56 A/F P03100-7 00311	Windshield						RE (O/C)			
		Left				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0				
	56 A/F P03100-8 00307	Windshield						RE (O/C)			
		Right				Mos	20-Mar-2008				
		New	0			Hrs	0				
			0			Ldg	0				
A561000		Cockpit Windshield Detailed Inspection						RE	Inspection Time Limits		
	56 A/F	05-12-07					Mos	18-May-2022	24	-/+1m (31-May-2024)	6.6 Months (+30 Days)
	Task:56-10-00-210 (ZONE: 231, 232) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Hrs	9,252.2			
							Ldg	7,425			
A561001		Electrically Heated Windshield Detailed Inspection						RE	Inspection Time Limits		≈17-Dec-2023
	56 A/F	05-12-13					Mos	07-Jun-2023	12	-/+1m (30-Jun-2024)	7.6 Months (+30 Days)
	Task:56-10-00-220 (ZONE: 231, 232) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Hrs	9,471.8	450	-/+25 (9,921.8)	71.3 Hrs (+25)
							Ldg	7,591			
A561003		Windshield Detailed Inspection						T	Inspection Time Limits		≈15-Aug-2026
	56 A/F	05-12-MF					Mos				
	MM:4-10-00, MM:5-10-01 (ZONE: 231, 232) (SOURCE: Model 510 Maintenance Manual)						Hrs	12,000	(12,000)		2,149.5 Hrs
							Ldg				
A561005		Cockpit Side Window Detailed Inspection						T	Inspection Time Limits		≈15-Aug-2026
	56 A/F	05-12-MF					Mos				
	MM:4-10-00, MM:5-10-01 (ZONE: 231, 232) (SOURCE: Model 510 Maintenance Manual)						Hrs	12,000	(12,000)		2,149.5 Hrs
							Ldg				
A562001		Cabin Windows Detailed Inspection						T	Inspection Time Limits		≈15-Aug-2026
	56 A/F	05-12-MF					Mos				
	MM:4-10-00, MM:5-10-01 (ZONE: 241, 242) (SOURCE: Model 510 Maintenance Manual)						Hrs	12,000	(12,000)		2,149.5 Hrs
							Ldg				

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
SB510-56-01		Windshield Screw Sealing Improvement								RE (-)	Mandatory	
	56 A/F						Mos					
	Eff: 31-Jan-2008 Not Applicable	BY SERIAL NUMBER NOT APPLICABLE					Hrs					
	(NOTE: 24/Oct/2018)						Ldg					
SB510-56-02		Cabin Window Frost Pane Modification								RE (-)	Discretionary	
	56 A/F						Mos	11-Feb-2010				
	Eff: 13-Apr-2009 Complied With						Hrs	954.1				
							Ldg	806				
SL510-56-01		Windshield Wire Bundle Assembly Inspection								RE (-)	Mandatory	
	56 A/F						Mos	13-Oct-2009				
	Eff: 19-Feb-2009 Complied With						Hrs	783				
							Ldg					
▼ 57 - WINGS												
		Aileron Assembly								RE (O/C)		
	57 A/F	Left					Mos	20-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Aileron Assembly								RE (O/C)		
	57 A/F	Right					Mos	20-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Main Landing Gear Attach Fitting Assembly - Trunnion Fitting Assembly								RE	Replacement Schedule	≈08-Jan-2044
	57 A/F	Aft - Left					Mos	20-Mar-2008				
	7041165-5	New					Hrs	0				
	39						Ldg	0	20,000	20,000	12,100 Ldg	
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)											
		Main Landing Gear Attach Fitting Assembly - Trunnion Fitting Assembly								RE	Replacement Schedule	≈08-Jan-2044
	57 A/F	Aft - Right					Mos	20-Mar-2008				
	7041165-6	New					Hrs	0				
	62						Ldg	0	20,000	20,000	12,100 Ldg	
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)											
		Main Landing Gear Attach Fitting Assembly - Trunnion Fitting Assembly								RE	Replacement Schedule	≈08-Jan-2044
	57 A/F	Fwd - Left					Mos	20-Mar-2008				
	7041155-9	New					Hrs	0				
	47						Ldg	0	20,000	20,000	12,100 Ldg	
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)											
		Main Landing Gear Attach Fitting Assembly - Trunnion Fitting Assembly								RE	Replacement Schedule	≈08-Jan-2044
	57 A/F	Fwd - Right					Mos	20-Mar-2008				
	7041155-10	New					Hrs	0				
	35						Ldg	0	20,000	20,000	12,100 Ldg	
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)											
		Main Landing Gear Side Brace Fitting Assembly								RE	Replacement Schedule	≈08-Jan-2044
	57 A/F	Left					Mos	20-Mar-2008				
	7041175-5	New					Hrs	0				
	58						Ldg	0	20,000	20,000	12,100 Ldg	
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)											



OE-FFB STATUS REPORT
Owner/Operator: GlobeAir AG GlobeAir AG

CESSNA
510 (Citation Mustang) OE-FFB,SN 510-0065

Task No		Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
	57 A/F	Main Landing Gear Side Brace Fitting Assembly						RE	Replacement Schedule		≈08-Jan-2044		
	7041175-6	Right					Mos	20-Mar-2008					
	69	New	0				Hrs	0					
	MM:5-11-00, MM:4-11-00 (SOURCE: Model 510 Maintenance Manual)						Ldg	0	20,000	20,000	12,100 Ldg		
	57 A/F	Wing Flap					RE (O/C)						
	7025001-13	Left					Mos	07-Jun-2023					
	0000205	Repaired	5,871.5				Hrs	9,471.8					
	(APX COST: 14,664.16)						Ldg	7,591					
	57 A/F	Wing Flap					RE (O/C)						
	7025001-14	Right					Mos	07-Jun-2023					
	0000209	Tested/Inspected					Hrs	9,471.8					
	(APX COST: 0)						Ldg	7,591					
	57 A/F	Wing Fwd Spar					RE (O/C)						
	7022022-1	Left					Mos	20-Mar-2008					
	59217-2	New	0				Hrs	0					
							Ldg	0					
	57 A/F	Wing Fwd Spar					RE (O/C)						
	7022022-2	Right					Mos	20-Mar-2008					
	61229	New	0				Hrs	0					
							Ldg	0					
	57 A/F	Wing Main Spar					RE (O/C)						
	7022027-1	Left					Mos	20-Mar-2008					
	45621	New	0				Hrs	0					
							Ldg	0					
	57 A/F	Wing Main Spar					RE (O/C)						
	7022027-2	Right					Mos	20-Mar-2008					
	45622	New	0				Hrs	0					
							Ldg	0					
	57 A/F	Wing Rear Spar					RE (O/C)						
	7022032-3	Left					Mos	20-Mar-2008					
	63100	New	0				Hrs	0					
							Ldg	0					
	57 A/F	Wing Rear Spar					RE (O/C)						
	7022032-4	Right					Mos	20-Mar-2008					
	45678	New	0				Hrs	0					
							Ldg	0					
A570000		Wing Zonal Inspection					RE					Inspection Time Limits	≈17-Dec-2025
57 A/F	05-12-17					Mos	04-Sep-2023	36	-/+1m	(30-Sep-2026)	2.9 Years (+30 Days)		
Task:57-00-00-210 (ZONE: 511, 512, 521, 522, 531, 532, 540) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						Hrs	9,684.2	1,800	-/+25	(11,484.2)	1,633.7 Hrs (+25)		
(NOTE: more zone: 611, 612, 621, 622, 631, 632, 640)						Ldg	7,759						
A570001		Wing Attach Fittings and Frames Special Detailed Inspection					T					Inspection Time Limits	≈15-Aug-2026
57 A/F	05-12-MF					Mos							
						Hrs	12,000				(12,000)	2,149.5 Hrs	
MM:4-10-00, MM:5-10-01, Task:57-00-00-250 (ZONE: 145, 146, 147, 148, 315, 316) (SOURCE: Model 510 Maintenance Manual)						Ldg							

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
A570002	57 A/F	Main Landing Gear Wheel Well General Visual Inspection (Corrosion Inspection) 05-12-35 Task:57-00-00-211 (ZONE: 512, 612) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: For airplanes that operate in moderate or severe corrosion environments)						6	-/+1m	(31-Dec-2023)	45 Days (+31)
A570003	57 A/F	Aft Wing Spar Area General Visual Inspection (Corrosion Inspection) 05-12-35 Task:57-00-00-212 (ZONE: 512, 522,532, 612,622, 632) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual) (NOTE: For airplanes that operate in moderate or severe corrosion environments)						6	-/+1m	(31-Dec-2023)	45 Days (+31)
A570004	57 A/F	Main Landing Gear Wheel Well General Visual Inspection (Corrosion Inspection) 05-12-06 Task:57-00-00-211 (ZONE: 512, 612) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)
A570005	57 A/F	Aft Wing Spar Area General Visual Inspection (Corrosion Inspection) 05-12-06 Task:57-00-00-212 (ZONE: 512, 522,532, 612,622, 632) (AVG MAN HRS: 0) (APX COST: 0) (SOURCE: Model 510 Maintenance Manual)						12	-/+1m	(30-Jun-2024)	7.6 Months (+30 Days)
A572001	57 A/F	Wing Rear Spar Fasteners Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:57-20-20-250 (ZONE: 500, 600) (SOURCE: Model 510 Maintenance Manual)						12,000		(12,000)	2,149.5 Hrs
A572002	57 A/F	Wing Main Spar Fasteners Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:57-20-20-251 (ZONE: 500, 600) (SOURCE: Model 510 Maintenance Manual)						12,000		(12,000)	2,149.5 Hrs
A572003	57 A/F	Flap Hinge Fastener Hole Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:57-20-20-252 (ZONE: 500, 600) (SOURCE: Model 510 Maintenance Manual)						12,000		(12,000)	2,149.5 Hrs
A572004	57 A/F	Wing Forward Spar Fasteners Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:57-20-20-253 (ZONE: 500, 600) (SOURCE: Model 510 Maintenance Manual)						12,000		(12,000)	2,149.5 Hrs
A572005	57 A/F	Wing Rear Spar Fasteners (LBL 14.00 To RBL 14.00) Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:57-20-20-254 (ZONE: 500, 600) (SOURCE: Model 510 Maintenance Manual)						12,000		(12,000)	2,149.5 Hrs
A572006	57 A/F	Wing Main Spar Fasteners (LBL 14.00 to RBL 14.00) Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:57-20-20-255 (ZONE: 500, 600) (SOURCE: Model 510 Maintenance Manual)						12,000		(12,000)	2,149.5 Hrs
A572007	57 A/F	Wing Forward Spar Fasteners (LBL 14.00 to RBL 14.00) Special Detailed Inspection 05-12-MF MM:4-10-00, MM:5-10-01, Task:57-20-20-256 (ZONE: 500, 600) (SOURCE: Model 510 Maintenance Manual)						12,000		(12,000)	2,149.5 Hrs
SL510-57-01	57 A/F	Flap Hinge Inspection Superseded (NOTE: 15th March 2019)									

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL510-57-01 R01	Flap Hinge Inspection							RE (-)		Mandatory	
	57 A/F					Mos	14-Sep-2009				
	Eff: 24-Jun-2009 Complied With					Hrs	725				
						Ldg					
SL510-57-02	Wings - Flap Actuator Bolt Replacement							RE (-)		Mandatory	
	57 A/F					Mos					
	Eff: 25-Aug-2015 Not Applicable	BY SERIAL NUMBER NOT APPLICABLE				Hrs					
	(NOTE: 25/Oct/2018)					Ldg					
▼ 70 - STANDARD PRACTICES - ENGINES											
70-PW615F-001	Engine - Tubing - Examine for evidence of wear, chafing, cracks and corrosion.							RE		EMM - Requirement	≈17-Dec-2023
	70 ENG1	Pkg 450 Hour/12 Month				Mos	07-Jun-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
	Task:70-00-00-200-801 (SOURCE: EMM 05-20-00) (NOTE: Damage limits and repair instruction for tubing are given in Chapter 70-00-00, INSPECTION)					Hrs	3,898.8	450	-/+10%	(4,348.8)	71.3 Hrs (+45)
						Enc	2,711				
70-PW615F-001	Engine - Tubing - Examine for evidence of wear, chafing, cracks and corrosion.							RE		EMM - Requirement	≈17-Dec-2023
	70 ENG2	Pkg 450 Hour/12 Month				Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
	Task:70-00-00-200-801 (SOURCE: EMM 05-20-00) (NOTE: Damage limits and repair instruction for tubing are given in Chapter 70-00-00, INSPECTION)					Hrs	3,581.6	450	-/+10%	(4,031.6)	71.3 Hrs (+45)
						Enc	3,171				
70-PW615F-002	Oil System - LP Compressor Case Nos. 1,2,3 Bearings Oil Tube - Do a visual inspection of the LP compressor case Nos. 1,2,3 bearings oil tube at the 12 o'clock location where the Nos. 1,2,3 bearings pressure oil transfer tube is installed.							RE (N/A)		EMM - Requirement	
	70 ENG1					Mos	18-May-2023				
	Ref:70-00-00, Task:70-00-00-200-801 (SOURCE: EMM 05-20-00) (NOTE: N/A as this inspection is only applicable to PRE-SB63012 engines and LB0340 is post SB63012)					Hrs	3,898.8				
						Enc	2,711				
70-PW615F-002	Oil System - LP Compressor Case Nos. 1,2,3 Bearings Oil Tube - Do a visual inspection of the LP compressor case Nos. 1,2,3 bearings oil tube at the 12 o'clock location where the Nos. 1,2,3 bearings pressure oil transfer tube is installed.							RE (N/A)		EMM - Requirement	
	70 ENG2					Mos					
	Ref.:70-00-00, Task:70-00-00-200-801 (SOURCE: EMM 05-20-00)					Hrs					
						Enc					
▼ 71 - POWER PLANT											
	Aft Engine Isolator Assembly							RE		Replacement Schedule	≈19-Sep-2031
71 A/F	Left					Mos	08-May-2020				
9912647-3	New		3			Hrs	7,976.4	8,000		15,976.4	6,125.9 Hrs
LK2773			0			Ldg	6,420				
MM:5-11-00, MM:4-11-00, Task:71-20-00-960 (APX COST: 3,912.58) (SOURCE: Model 510 Maintenance Manual) (NOTE: This interval is to be completed when the engine is removed for overhaul.)											
	Aft Engine Isolator Assembly							RE		Replacement Schedule	≈19-Sep-2031
71 A/F	Right					Mos	08-May-2020				
9912647-3	New		3			Hrs	7,976.4	8,000		15,976.4	6,125.9 Hrs
LK2772			0			Ldg	6,420				
MM:5-11-00, MM:4-11-00, Task:71-20-00-960 (APX COST: 3,912.58) (SOURCE: Model 510 Maintenance Manual) (NOTE: This interval is to be completed when the engine is removed for overhaul.)											
	Aft Engine Mount Channel							RE (O/C)			
71 A/F	Left					Mos	20-Mar-2008				
7051001-3	New		0			Hrs	0				
00100			0			Ldg	0				
	Aft Engine Mount Channel							RE (O/C)			
71 A/F	Right					Mos	20-Mar-2008				
7051001-4	New		0			Hrs	0				
00168			0			Ldq	0				

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	71 A/F 7012066-2 0065	Engine Beam							RE (O/C)			
		Aft							Mos	20-Mar-2008		
		New							Hrs	0		
								Ldg	0			
	71 A/F 9912647-1 2424	Forward Engine Isolator Assembly							RE			
		Left Bottom							21-Mar-2019	Replacement Schedule		
		New							Hrs	4,000	11,282.7	1,432.2 Hrs
								Ldg	5,847			
MM:5-11-00, MM:4-11-00 (APX COST: 3,788.49) (SOURCE: Model 510 Maintenance Manual) (NOTE: This interval is to be completed when the engine is removed for overhaul. The LM-471-SA11 isolator is included in the LM-471-SA12 isolator kit.)												
	71 A/F 9912647-1 2421	Forward Engine Isolator Assembly							RE			
		Left Top							21-Mar-2019	Replacement Schedule		
		New							Hrs	4,000	11,282.7	1,432.2 Hrs
								Ldg	5,847			
MM:5-11-00, MM:4-11-00 (APX COST: 3,788.49) (SOURCE: Model 510 Maintenance Manual) (NOTE: This interval is to be completed when the engine is removed for overhaul. The LM-471-SA11 isolator is included in the LM-471-SA12 isolator kit.)												
	71 A/F 9912647-1 2413	Forward Engine Isolator Assembly							RE			
		Right Bottom							21-Mar-2019	Replacement Schedule		
		New							Hrs	4,000	11,282.7	1,432.2 Hrs
								Ldg	5,847			
MM:5-11-00, MM:4-11-00 (APX COST: 3,788.49) (SOURCE: Model 510 Maintenance Manual) (NOTE: This interval is to be completed when the engine is removed for overhaul. The LM-471-SA11 isolator is included in the LM-471-SA12 isolator kit.)												
	71 A/F 9912647-1 2357	Forward Engine Isolator Assembly							RE			
		Right Top							21-Mar-2019	Replacement Schedule		
		New							Hrs	4,000	11,282.7	1,432.2 Hrs
								Ldg	5,847			
MM:5-11-00, MM:4-11-00 (APX COST: 3,788.49) (SOURCE: Model 510 Maintenance Manual) (NOTE: This interval is to be completed when the engine is removed for overhaul. The LM-471-SA11 isolator is included in the LM-471-SA12 isolator kit.)												
	71 A/F 7051001-1 00105	Fwd Engine Mount Channel							RE (O/C)			
		Left							Mos	20-Mar-2008		
		New							Hrs	0		
								Ldg	0			
	71 A/F 7051001-2 00110	Fwd Engine Mount Channel							RE (O/C)			
		Right							Mos	20-Mar-2008		
		New							Hrs	0		
								Ldg	0			
71-CUS-100		Compressor Wash - Performance Recovery (For operations in Salt Environment)							RE			
	71 ENG1	Pkg 450 Hour/12 Month							12	EMM - Requirement		
							Mos	04-Sep-2023	-/+30d	(07-Jun-2024)	≈17-Dec-2023	
Alias2:71-00-00-160-008 (SOURCE: LMM Part No. 3072691)							Hrs	4,111.2	450	-/+10%	(4,348.8)	
							Enc	2,879	71.3 Hrs (+45)			
71-CUS-100		Compressor Wash - Performance Recovery (For operations in Salt Environment)							RE			
	71 ENG2	Pkg 450 Hour/12 Month							12	EMM - Requirement		
							Mos	04-Sep-2023	-/+30d	(07-Jun-2024)	≈17-Dec-2023	
Alias2:71-00-00-160-008 (SOURCE: LMM Part No. 3072691)							Hrs	3,794	450	-/+10%	(4,031.6)	
							Enc	3,339	71.3 Hrs (+45)			

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
71-CUS-200 71 ENG1	ECTM download if the aircraft is in MXX							RE (A/R)		Custom Task	
						Mos					
						Hrs					
						Enc					
71-CUS-200 71 ENG2	ECTM download if the aircraft is in MXX							RE (A/R)		Custom Task	
						Mos					
						Hrs					
						Enc					
71-PW615F-001 71 ENG1	Compressor Wash Schedule - Desalination Wash							RE (A/R)		EMM - Requirement	
						Mos	04-Sep-2023				
						Hrs	4,111.2				
						Enc	2,879				
		Task:71-00-00-160-807 (SOURCE: EMM 05-20-00) (NOTE: Continually Operated or Based in. Extreme Environment (Salt-Laden) - Daily or as general observations warrant. Severe Environment (Salt-Laden) - Every two months or as general observations warrant. Moderate Environment - Aircraft yearly inspection or as general observations warrant. Mild Environment - As general observations warrant. Frequently Operated or Based in. Extreme Environment (Salt-Laden) - Every two months or as general observations warrant. Severe Environment (Salt-Laden) - Aircraft yearly inspection or as general observations warrant. Moderate Environment - Aircraft yearly inspection or as general observations warrant. Mild Environment - As general observations warrant. Occasionally Operated or Based in. Extreme Environment (Salt-Laden) - Aircraft yearly inspection or as general observations warrant. Severe Environment (Salt-Laden) - Aircraft yearly inspection or as general observations warrant. Moderate Environment - As general observations warrant. Mild Environment - As general observations warrant.)									
71-PW615F-001 71 ENG2	Compressor Wash Schedule - Desalination Wash							RE (A/R)		EMM - Requirement	
						Mos	04-Sep-2023				
						Hrs	3,794				
						Enc	3,339				
Task:71-00-00-160-807 (SOURCE: EMM 05-20-00) (NOTE: Continually Operated or Based in. Extreme Environment (Salt-Laden) - Daily or as general observations warrant. Severe Environment (Salt-Laden) - Every two months or as general observations warrant. Moderate Environment - Aircraft yearly inspection or as general observations warrant. Mild Environment - As general observations warrant. Frequently Operated or Based in. Extreme Environment (Salt-Laden) - Every two months or as general observations warrant. Severe Environment (Salt-Laden) - Aircraft yearly inspection or as general observations warrant. Moderate Environment - Aircraft yearly inspection or as general observations warrant. Mild Environment - As general observations warrant. Occasionally Operated or Based in. Extreme Environment (Salt-Laden) - Aircraft yearly inspection or as general observations warrant. Severe Environment (Salt-Laden) - Aircraft yearly inspection or as general observations warrant. Moderate Environment - As general observations warrant. Mild Environment - As general observations warrant.)											
71-PW615F-002 71 ENG1	Compressor Wash Schedule - Performance Recovery Wash							RE		EMM - Requirement	
						Mos	04-Sep-2023	3	+1m	04-Dec-2023	18 Days (+31)
						Hrs	4,111.2				
						Enc	2,879				
Task:71-00-00-160-808 (SOURCE: EMM 05-20-00)											
71-PW615F-002 71 ENG2	Compressor Wash Schedule - Performance Recovery Wash							RE		EMM - Requirement	
						Mos	04-Sep-2023	3	+1m	04-Dec-2023	18 Days (+31)
						Hrs	3,794				
						Enc	3,339				
Task:71-00-00-160-808 (SOURCE: EMM 05-20-00)											

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
71-PW615F-003		Engine Prestart Check (Check No.1)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG1						Mos	18-May-2023			
							Hrs	3,898.8			
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691)						Enc	2,711			
71-PW615F-003		Engine Prestart Check (Check No.1)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG2						Mos				
							Hrs				
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691) (NOTE: Ground Checks Required After Major Component Repair/Replacement or Engine Installation)						Enc				
71-PW615F-004		Engine Start (Check No.2)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG1						Mos	18-May-2023			
							Hrs	3,898.8			
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691)						Enc	2,711			
71-PW615F-004		Engine Start (Check No.2)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG2						Mos				
							Hrs				
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691) (NOTE: Ground Checks Required After Major Component Repair/Replacement or Engine Installation)						Enc				
71-PW615F-005		Engine Shutdown (Check No.3)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG1						Mos	18-May-2023			
							Hrs	3,898.8			
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691)						Enc	2,711			
71-PW615F-005		Engine Shutdown (Check No.3)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG2						Mos				
							Hrs				
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691) (NOTE: Ground Checks Required After Major Component Repair/Replacement or Engine Installation)						Enc				
71-PW615F-006		Engine Calibration (Check No.4)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG1						Mos	07-Jun-2023			
							Hrs	3,898.8			
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691)						Enc	2,711			
71-PW615F-006		Engine Calibration (Check No.4)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG2						Mos	07-Jun-2023			
							Hrs	3,581.6			
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691) (NOTE: Ground Checks Required After Major Component Repair/Replacement or Engine Installation)						Enc	3,171			
71-PW615F-007		Power Assurance Check (Check No.5)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG1						Mos	04-Sep-2023			
							Hrs	4,111.2			
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691)						Enc	2,879			
71-PW615F-007		Power Assurance Check (Check No.5)						RE (A/R)	05-10-00, EMM - Requirement,	Table 501	
	71 ENG2						Mos	04-Sep-2023			
							Hrs	3,794			
	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691) (NOTE: Ground Checks Required After Major Component Repair/Replacement or Engine Installation)						Enc	3,339			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
71-PW615F-008		Main Oil Pressure (MOP) Check						RE (A/R)	05-10-00, EMM - Requirement, Table 501		
	71 ENG1	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691) (NOTE: Ground Checks Required After Major Component Repair/Replacement or Engine Installation)					Mos	18-May-2023			
							Hrs	3,898.8			
							Enc	2,711			
71-PW615F-008		Main Oil Pressure (MOP) Check						RE (A/R)	05-10-00, EMM - Requirement, Table 501		
	71 ENG2	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691) (NOTE: Ground Checks Required After Major Component Repair/Replacement or Engine Installation)					Mos				
							Hrs				
							Enc				
71-PW615F-009		Engine Fan Trim Balancing						RE (A/R)	05-10-00, EMM - Requirement, Table 501		
	71 ENG1	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691) (NOTE: Ground Checks Required After Major Component Repair/Replacement or Engine Installation)					Mos	18-May-2023			
							Hrs	3,898.8			
							Enc	2,711			
71-PW615F-009		Engine Fan Trim Balancing						RE (A/R)	05-10-00, EMM - Requirement, Table 501		
	71 ENG2	Task:71-00-00-760-804 (SOURCE: Manual Part No.3072691) (NOTE: Ground Checks Required After Major Component Repair/Replacement or Engine Installation)					Mos				
							Hrs				
							Enc				
A710000		Engine Zonal Inspection						RE	Inspection Time Limits		
	71 A/F	05-12-11 Task:71-00-10-210 (ZONE: 410, 420) (SOURCE: Model 510 Maintenance Manual)					Mos	07-Jun-2023	72	-/+1m	(30-Jun-2029) 5.6 Years (+30 Days)
							Hrs	9,471.8			
							Ldg	7,591			
A712000		Aft Engine Isolator Inspection						RE	Inspection Time Limits ≈13-Sep-2025		
	71 A/F	05-12-MC MM:5-10-01, MM:4-10-00, Task:71-20-00-220 (RII ITEM) (ZONE: 410, 411,412, 420) (SOURCE: Model 510 Maintenance Manual)					Mos	21-Mar-2019			
							Hrs	7,282.7	4,000	(11,282.7)	1,432.2 Hrs
							Ldg	5,847			
Reliability-71-001		Perform Hand Wash of LP Compressor (Fan) per EMM Task: 71-00-00-160-806						RE (-)			
	71 ENG1	(AVG MAN HRS: 1) (NOTE: Hand Wash of LP Compressor (Fan) ENG1 performed IAW C510 AMM 71-00-00-160-806 Rev. 16)					Mos				
							Hrs				
							Enc				
Reliability-71-001		Perform Hand Wash of LP Compressor (Fan) per EMM Task: 71-00-00-160-806						RE (-)			
	71 ENG2	(AVG MAN HRS: 1) (NOTE: Hand Wash of LP Compressor (Fan) ENG1 performed IAW C510 AMM 71-00-00-160-806 Rev. 16)					Mos				
							Hrs				
							Enc				
▼ 72 - ENGINE											
		Vane Ring HP Assembly						RE (O/C)			
	72 ENG2 35C2581CL01 HLA01C203	New					Mos	17-May-2023			
							Hrs	3,581.6			
							Enc	3,171			
		AGB Starter Magnetic Seal						RE (O/C)			
	72 ENG2 Unknown Unknown						Mos				
							Hrs				
							Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2 Unknown Unknown	Ball Bearing						RE (O/C)			
								Mos			
								Hrs			
								Enc			
	72 ENG2 Unknown Unknown	Ball Bearing						RE (O/C)			
								Mos			
								Hrs			
								Enc			
	72 ENG2 Unknown Unknown	Ball Bearing						RE (O/C)			
								Mos			
								Hrs			
								Enc			
	72 ENG2 Unknown Unknown	Ball Bearing						RE (O/C)			
								Mos			
								Hrs			
								Enc			
	72 ENG2 Unknown Unknown	Bearing-Rolller No.1						RE (O/C)			
								Mos			
								Hrs			
								Enc			
	72 ENG2 Unknown Unknown	Bearing-Rolller No.2						RE (O/C)			
								Mos			
								Hrs			
								Enc			
	72 ENG2 35C4412-01 RWA91B162	Case - Compressor, ASSY of Overhauled						RE (O/C)			
								Mos			
								17-May-2023			
								Hrs			
	72 ENG2 Unknown Unknown	Case - High Pressure Diffuse, Assy of						RE (O/C)			
								Mos			
								Hrs			
								Enc			
	72 ENG2 Unknown Unknown	Case - Support, HP Turbine Assy of						RE (O/C)			
								Mos			
								Hrs			
								Enc			
	72 ENG2 Unknown Unknown	Case -Fan						RE (O/C)			
								Mos			
								Hrs			
								Enc			
	72 ENG2 Unknown Unknown	Case- Turbine Exhaust, Assy of						RE (O/C)			
								Mos			
								Hrs			
								Enc			

Task No	Description								Categories	Time			
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
	72 ENG2 35C4881-01 KUA011774	Case-Fan, Assy of Overhauled					RE (O/C)						
							Mos	17-May-2023					
							Hrs	3,581.6					
							Enc	3,171					
	72 ENG1 35C4281-01 A002FH74	Combustion Liner Assembly New					RE (O/C)						
							Mos	14-Nov-2008					
							Hrs	0					
							Enc	0					
	72 ENG2 35C4281-01 A0057CBD	Combustion Liner Assembly New					RE (O/C)						
							Mos	17-May-2023					
			0				Hrs	3,581.6					
			0				Enc	3,171					
	72 ENG1 35C4888-01 A002DT4E (SOURCE: AWL Manual Part No. 3072698)	Compressor Impeller and Shaft Assy					RE					EMM - Life Limit	≈27-Apr-2036
							Mos	18-May-2023					
			3,898.8				Hrs	3,898.8					
			2,711				Enc	2,711	10,500	10,500	7,480	Enc	
	72 ENG2 35C4888-01 AAPPHZVU2012 (SOURCE: AWL Manual Part No. 3072698)	Compressor Impeller and Shaft Assy					RE					EMM - Life Limit	≈23-Jul-2035
							Mos	17-May-2023					
							Hrs	3,581.6					
			3,171				Enc	3,171	10,500	10,500	7,020	Enc	
	72 ENG1 35C2311-01 FRAEUAEW50 (SOURCE: AWL Manual Part No. 3072698) (NOTE: NOTE: 1. Service Life is only valid for the disk when operated as an element of the disk balancing assembly 35C3921-01.)	Disk - HP Turbine New					RE					EMM - Life Limit	≈06-Feb-2032
							Mos	18-May-2023					
			0				Hrs	3,898.8					
			0				Enc	2,711	5,250	7,961	4,941	Enc	
	72 ENG2 35C2311-01 FRAEUATL38 (SOURCE: AWL Manual Part No. 3072698) (NOTE: NOTE: 1. Service Life is only valid for the disk when operated as an element of the disk balancing assembly 35C3921-01.)	Disk - HP Turbine New					RE					EMM - Life Limit	≈06-Feb-2032
							Mos	17-May-2023					
							Hrs	3,581.6					
			0				Enc	3,171	5,250	8,421	4,941	Enc	
	72 ENG1 35C2372-01 A002F51Y (SOURCE: AWL Manual Part No. 3072698) (NOTE: NOTE: 2. Service Life is only valid for the disk when operated as an element of the disk balancing assemblies 35C2382-01, 35C4232-01 and 35C4432-01.)	Disk - LP Turbine					RE					EMM - Life Limit	≈27-Apr-2036
							Mos	18-May-2023					
			3,898.8				Hrs	3,898.8					
			2,711				Enc	2,711	10,500	10,500	7,480	Enc	
	72 ENG2 35C2372-01 A002F9MM (SOURCE: AWL Manual Part No. 3072698) (NOTE: NOTE: 2. Service Life is only valid for the disk when operated as an element of the disk balancing assemblies 35C2382-01, 35C4232-01 and 35C4432-01.)	Disk - LP Turbine Overhauled					RE					EMM - Life Limit	≈23-Jul-2035
							Mos	17-May-2023					
							Hrs	3,581.6					
			3,171				Enc	3,171	10,500	10,500	7,020	Enc	
	72 ENG2 Unknown Unknown	Drive Gearshaft Assembly					RE (O/C)						
							Mos						
							Hrs						
							Enc						

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2 Unknown Unknown	Duct - Bypass, Rear outer, Assy of								RE (O/C)	
	72 ENG2 Unknown Unknown	Duct-Bypass, Front, Outer , Assy of								RE (O/C)	
	72 ENG2 Unknown Unknown	Duplex Bearing								RE (O/C)	
	72 ENG2 Unknown Unknown	Housing Assy - Accessory Gearbox								RE (O/C)	
	72 ENG1 Unknown Unknown	HP Turbine Disk Balancing Assembly								RE (O/C)	
	72 ENG2 Unknown Unknown	HP Turbine Disk Balancing Assembly								RE (O/C)	
	72 ENG2 35C5648-01 RWA56H834	Impeller Housing Assembly New								RE (O/C)	
	72 ENG1 Unknown Unknown	LP Turbine Disk Balancing Assembly								RE (O/C)	
	72 ENG2 Unknown Unknown	LP Turbine Disk Balancing Assembly								RE (O/C)	
	72 ENG2 Unknown Unknown	Roller Bearing								RE (O/C)	
	72 ENG2 Unknown Unknown	Roller Bearing								RE (O/C)	



Task No		Description								Categories	Time										
SEQ	PN/SN	MOC Note or Component Condition					TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining						
	72 ENG2	Roller Bearing										RE (O/C)									
	Unknown											Mos									
	Unknown											Hrs									
												Enc									
	72 ENG1	Rotor - Fan										RE			EMM - Life Limit		≈27-Apr-2036				
	35C1940-01						Overhauled										18-May-2023				
	TXA1B7813											3,898.8					Hrs			3,898.8	
	(SOURCE: AWL Manual Part No. 3072698)											2,711					Enc			2,711 10,500 10,500 7,480 Enc	
	72 ENG2	Rotor - Fan										RE			EMM - Life Limit		≈23-Jul-2035				
	35C1940-01						Overhauled										17-May-2023				
	TXA1B7458											3,581.6					Hrs			3,581.6	
	(SOURCE: AWL Manual Part No. 3072698)											3,171					Enc			3,171 10,500 10,500 7,020 Enc	
	72 ENG1	Rotor - High Compressor										RE			EMM - Life Limit		≈27-Apr-2036				
	35C3661-01																18-May-2023				
	TXA1B6523											3,898.8					Hrs			3,898.8	
	(SOURCE: AWL Manual Part No. 3072698)											2,711					Enc			2,711 10,500 10,500 7,480 Enc	
	72 ENG2	Rotor - High Compressor										RE			EMM - Life Limit		≈23-Jul-2035				
	35C3661-01						Overhauled										17-May-2023				
	TXA1B7908											3,581.6					Hrs			3,581.6	
	(SOURCE: AWL Manual Part No. 3072698)											3,171					Enc			3,171 10,500 10,500 7,020 Enc	
	72 ENG2	Shaft- Tie, High Pressure Turbine										RE (O/C)									
	Unknown											Mos									
	Unknown											Hrs									
												Enc									
	72 ENG2	Shaft-Low Pressure Compressor										RE (O/C)									
	35C5461-01						New										17-May-2023				
	PKAAA961415											3,581.6					Hrs			3,581.6	
												3,171			Enc						
	72 ENG2	Spiral Bevel Gearshaft										RE (O/C)									
	Unknown											Mos									
	Unknown											Hrs									
												Enc									
	72 ENG2	Stator - Compressor, ASSY of										RE (O/C)									
	Unknown											Mos									
	Unknown											Hrs									
												Enc									
	72 ENG2	Vane Ring - Turbine, Lp, Assy of										RE (O/C)									
	Unknown											Mos									
	Unknown											Hrs									
												Enc									
2010-17-06		Fuel Oil Heat Exchanger (FOHE)										RE (-)			Mandatory						
	72 ENG1	Eff: 27-Sep-2010 Complied With Complied during OH										18-May-2023									
							3,898.8					Hrs			3,898.8						
							2,711					Enc			2,711						

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2010-17-06	Fuel Oil Heat Exchanger (FOHE)						RE (-)		Mandatory	
72 ENG2					Mos	17-May-2023				
Eff: 27-Sep-2010 Complied With					Hrs	3,581.6				
					Enc	3,171				
63108 Rev 1	Replacement of No. 3 Flanged Ball Bearing						T (A/R)		Category 7	
72 ENG2					Mos	17-May-2023				
Eff: 30-Mar-2021 Complied With					Hrs	3,581.6				
					Enc	3,171				
63113	Replacement of Turbofan Engine Accessory-Gearbox (AGB) Plain Seal						RE (-)		Category 3, Category 7	
72 ENG2					Mos	17-May-2023				
Eff: 02-Feb-2022 Complied With					Hrs	3,581.6				
(AVG MAN HRS: 1.5) (NOTE: COMPLIANCE: P&WC recommends to do this service bulletin by February 03, 2022.					Enc	3,171				
NOTE: For Post-SB63062 and Pre-SB 63112 engines that replaced the AGB Seal with P/N 35C5539-01 between January 01, 2018 and February 01, 2021.)										
63114	Replacement of No. 4 Bearing Carbon Seal						T (-)		Category 7	
72 ENG1					Mos					
Eff: 09-Aug-2023					Hrs					
(AVG MAN HRS: 1.5)					Enc					
63114	Replacement of No. 4 Bearing Carbon Seal						T (-)		Category 7	
72 ENG2					Mos					
Eff: 09-Aug-2023					Hrs					
(AVG MAN HRS: 1.5)					Enc					
63114 Rev 1	Replacement of No. 4 Bearing Carbon Seal						T (A/R)		Category 5	
72 ENG1					Mos					
Eff: 08-Nov-2023					Hrs					
(AVG MAN HRS: 1.5)					Enc					
63114 Rev 1	Replacement of No. 4 Bearing Carbon Seal						T (A/R)		Category 5	
72 ENG2					Mos					
Eff: 08-Nov-2023					Hrs					
(AVG MAN HRS: 1.5)					Enc					
72-CUS-100	Fuel Manifold Pressure Check (1750 hours after Fuel Manifold replacement) IAW SI No. 48-2016 and a Calibration test IAW Task 71-00-00-760-812 and send the result to PWC for review. Recommendations for the fuel manifold will be based on the data provided and reviewed by P&WC customer engineering.						T		Custom Task	≈16-Aug-2025
72 ENG1					Mos	18-May-2023				
					Hrs	3,898.8	1,750	+50	5,648.8	1,371.3 Hrs (+50)
(NOTE: Extended until next HSI - needs to be reviewed.)					Enc	2,711				
72-CUS-100	Fuel Manifold Pressure Check (One time at 1750 hours since manifold replacement with no repetitive inspection till the H.S.I.)IAW SI No. 48-2016 and a Calibration test IAW Task 71-00-00-760-812 and send the result to PWC for review.						T		Custom Task	≈16-Aug-2025
72 ENG2					Mos	17-May-2023				
					Hrs	3,581.6	1,750	+50	5,331.6	1,371.3 Hrs (+50)
(NOTE: Extended until next HSI - needs to be reviewed.)					Enc	3,171				
72-PW615F-001	Engine - Externals - Examine for external evidence of fuel or oil leaks.						RE		EMM - Requirement	≈17-Dec-2023
72 ENG1	Pkg 450 Hour/12 Month,...				Mos	07-Jun-2023	12	-/+30d	≈07-Jun-2024	
					Hrs	3,898.8	450	-/+10%	≈4,348.8	
(SOURCE: EMM 05-20-00)					Enc	2,711				
72-PW615F-001	Engine - Externals - Examine for external evidence of fuel or oil leaks.						RE		EMM - Requirement	≈17-Dec-2023
72 ENG2	Pkg 450 Hour/12 Month,...				Mos	17-May-2023	12	-/+30d	≈17-May-2024	
					Hrs	3,581.6	450	-/+10%	≈4,031.6	
(SOURCE: EMM 05-20-00)					Enc	3,171				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-PW615F-002	72 ENG1	Engine - Externals - Make sure all connections, clamps, ties and brackets are properly attached. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-002	72 ENG2	Engine - Externals - Make sure all connections, clamps, ties and brackets are properly attached. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-003	72 ENG1	Engine - Engine Mounts - Make sure they are properly attached. Examine general condition. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-003	72 ENG2	Engine - Engine Mounts - Make sure they are properly attached. Examine general condition. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-004	72 ENG1	Engine - Compressor Inlet - Examine compressor inlet area for cleanliness. Pkg 450 Hour/12 Month,.... Task:71-00-00-160-807 (SOURCE: EMM 05-20-00) (NOTE: If excessive dirt accumulation is visible on inlet or fan blades do a compressor desalination wash . Refer to 71-00-00, POWERPLANT CLEANING, Task 71-00-00-160-807)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-004	72 ENG2	Engine - Compressor Inlet - Examine compressor inlet area for cleanliness. Pkg 450 Hour/12 Month,.... Task:71-00-00-160-807 (SOURCE: EMM 05-20-00) (NOTE: If excessive dirt accumulation is visible on inlet or fan blades do a compressor desalination wash . Refer to 71-00-00, POWERPLANT CLEANING, Task 71-00-00-160-807)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-005	72 ENG1	Engine - Compressor Inlet - Examine inlet and fan blades for FOD. Pkg 450 Hour/12 Month,.... (SOURCE: EMM 05-20-00) (NOTE: If FOD is suspected, refer to 05-50-00, UNSCHEDULED MAINTENANCE CHECKS, Task 05-50-00-210-805.)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-005	72 ENG2	Engine - Compressor Inlet - Examine inlet and fan blades for FOD. Pkg 450 Hour/12 Month,.... (SOURCE: EMM 05-20-00) (NOTE: If FOD is suspected, refer to 05-50-00, UNSCHEDULED MAINTENANCE CHECKS, Task 05-50-00-210-805.)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-006	72 ENG1	Engine - Compressor Inlet - Examine inlet and fan blades for erosion. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-006	72 ENG2	Engine - Compressor Inlet - Examine inlet and fan blades for erosion. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-PW615F-007	72 ENG1	Engine - Fan Case Stator Vanes - Make sure the retaining clamp is properly attached. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-007	72 ENG2	Engine - Fan Case Stator Vanes - Make sure the retaining clamp is properly attached. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-008	72 ENG1	Engine - Bypass Ducts and Fairings - Examine for FOD and cleanliness. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-008	72 ENG2	Engine - Bypass Ducts and Fairings - Examine for FOD and cleanliness. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-009	72 ENG1	Engine - Bypass Ducts and Fairings - Examine for cracks in outer bypass duct, rear bypass duct, struts and fairing. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-009	72 ENG2	Engine - Bypass Ducts and Fairings - Examine for cracks in outer bypass duct, rear bypass duct, struts and fairing. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-010	72 ENG1	Engine - Turbine Exhaust Cowl Case - Do a visual inspection for cracks. Pkg 450 Hour/12 Month Ref.:72-50-07, Task:72-50-07-220-801 (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-010	72 ENG2	Engine - Turbine Exhaust Cowl Case - Do a visual inspection for cracks. Pkg 450 Hour/12 Month Ref.:72-50-07, Task:72-50-07-220-801 (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
72-PW615F-011	72 ENG1	Engine - Exhaust and Mixer - Examine for obvious signs of damage or loose debris. Pkg Pre-Flight (SOURCE: EMM 05-20-00) (NOTE: These maintenance actions are performed by the flight crew as part of the pre-flight "walk around" inspection.)						RE (PreFlight)		EMM - Requirement	
72-PW615F-011	72 ENG2	Engine - Exhaust and Mixer - Examine for obvious signs of damage or loose debris. Pkg Pre-Flight (SOURCE: EMM 05-20-00) (NOTE: These maintenance actions are performed by the flight crew as part of the pre-flight "walk around" inspection.)						RE (PreFlight)		EMM - Requirement	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-PW615F-012	72 ENG1	Engine - Accessories - Make sure they are properly attached. Examine their general condition. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement (07-Jun-2024)	≈17-Dec-2023
											6.8 Months (+30 Days)
											71.3 Hrs (+45)
72-PW615F-012	72 ENG2	Engine - Accessories - Make sure they are properly attached. Examine their general condition. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement (07-Jun-2024)	≈17-Dec-2023
											6.8 Months (+30 Days)
											71.3 Hrs (+45)
72-PW615F-013	72 ENG1	Oil System - AGB Plain Seals - Examine accessory pad plain-seals for oil leaks. Pkg 450 Hour/12 Month Task:72-60-04-400-804, Task:72-60-01-000-804 (SOURCE: EMM 05-20-00) (NOTE: Leak rates up to 0.1 cc/hour from any pad plain-seal is acceptable. If the this rate is exceeded, replace the plain-seal. Refer to Task 72-60-01-000-804 and Task 72-60-04-400-804)						RE		EMM - Requirement (07-Jun-2024)	≈17-Dec-2023
											6.8 Months (+30 Days)
											71.3 Hrs (+45)
72-PW615F-013	72 ENG2	Oil System - AGB Plain Seals - Examine accessory pad plain-seals for oil leaks. Pkg 450 Hour/12 Month Task:72-60-04-400-804, Task:72-60-01-000-804 (SOURCE: EMM 05-20-00) (NOTE: Leak rates up to 0.1 cc/hour from any pad plain-seal is acceptable. If the this rate is exceeded, replace the plain-seal. Refer to Task 72-60-01-000-804 and Task 72-60-04-400-804)						RE		EMM - Requirement (07-Jun-2024)	≈17-Dec-2023
											6.8 Months (+30 Days)
											71.3 Hrs (+45)
72-PW615F-014	72 ENG1	Oil System - AGB Starter Magnetic Seal - Replace seal. Task:72-60-01-400-802, Task:72-60-01-000-802 (SOURCE: EMM 05-20-00) (NOTE: At scheduled HSI interval - Engine following the Extended TBO program)						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
											1,871.3 Hrs (+50)
72-PW615F-014	72 ENG2 Unknown Unknown	Oil System - AGB Starter Magnetic Seal - Replace seal. Task:72-60-01-400-802, Task:72-60-01-000-802 (SOURCE: EMM 05-20-00) (NOTE: At scheduled HSI interval - Engine following the Extended TBO program)						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
											1,871.3 Hrs (+50)
72-PW615F-015	72 ENG1	Oil System - Starter Generator Gear-shaft Spline Adapter - Replace the spline adapter. Task:72-60-01-400-805, Task:72-60-01-000-805 (SOURCE: EMM 05-20-00) (NOTE: At scheduled HSI interval - Engine following the Extended TBO program)						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
											1,871.3 Hrs (+50)
72-PW615F-015	72 ENG2	Oil System - Starter Generator Gear-shaft Spline Adapter - Replace the spline adapter. Task:72-60-01-400-805, Task:72-60-01-000-805 (SOURCE: EMM 05-20-00) (NOTE: At scheduled HSI interval - Engine following the Extended TBO program)						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
											1,871.3 Hrs (+50)
72-PW615F-016	72 ENG1	Oil System - LP Compressor Case Nos. 1,2,3 Bearings Oil Tube - Do a visual inspection of the LP compressor case Nos. 1,2,3 bearings oil tube for paint loss. Pkg 450 Hour/12 Month Task:72-30-03-220-802 (SOURCE: EMM 05-20-00) (NOTE: If paint is found to have flaked off the tube, do a 5-minute ground run at takeoff power and make sure the tube does not leak. If leak is found, send the engine to a P&WC approved overhaul facility. If no leak is found, no further action is required.)						RE		EMM - Requirement (07-Jun-2024)	≈17-Dec-2023
											6.8 Months (+30 Days)
											71.3 Hrs (+45)

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
72-PW615F-016	Oil System - LP Compressor Case Nos. 1,2,3 Bearings Oil Tube - Do a visual inspection of the LP compressor case Nos. 1,2,3 bearings oil tube for paint loss.						RE		EMM - Requirement	≈17-Dec-2023
72 ENG2	Pkg 450 Hour/12 Month				Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
	Task:72-30-03-220-802 (SOURCE: EMM 05-20-00) (NOTE: If paint is found to have flaked off the tube, do a 5-minute ground run at takeoff power and make sure the tube does not leak. If leak is found, send the engine to a P&WC approved overhaul facility. If no leak is found, no further action is required.)				Hrs	3,581.6	450	-/+10%	(4,031.6)	71.3 Hrs (+45)
					Enc	3,171				
72-PW615F-017	HP Turbine Retaining Nut Keywasher - Remove, discard and replace keywasher.						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
72 ENG1					Mos	18-May-2023				
	(SOURCE: EMM 05-20-00 Part No.3059712) (NOTE: Interval :Every HSI and overhaul. Engine following the Extended TBO program)				Hrs	3,898.8	2,250	+50	6,148.8	1,871.3 Hrs (+50)
					Enc	2,711				
72-PW615F-017	HP Turbine Retaining Nut Keywasher - Remove, discard and replace keywasher.						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
72 ENG2					Mos	17-May-2023				
	(SOURCE: EMM 05-20-00 Part No.3059712) (NOTE: Interval :Every HSI and overhaul. Engine following the Extended TBO program)				Hrs	3,581.6	2,250	+50	5,831.6	1,871.3 Hrs (+50)
					Enc	3,171				
72-PW615F-63109	Replacement of No. 4 Bearing Carbon Seals and Impeller Baffle						RE (-)		Category 5	
72 ENG2					Mos	17-May-2023				
	Eff: 22-Jun-2018 Complied With				Hrs	3,581.6				
	(AVG MAN HRS: 1.5)				Enc	3,171				
72-PW615F-63110	Validation of No. 3 Bearing Assembly Procedure						T (A/R)		Category 5	
72 ENG2					Mos					
	Eff: 07-May-2018				Hrs					
					Enc					
72-PW615F-HSI	Engine Hot Section Inspection (HSI)						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
72 ENG1					Mos	18-May-2023				
	(SOURCE: EMM 05-20-00) (NOTE: Engine following the Extended TBO program)				Hrs	3,898.8	2,250	+50	6,148.8	1,871.3 Hrs (+50)
					Enc	2,711				
72-PW615F-HSI	Engine Hot Section Inspection (HSI)						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
72 ENG2					Mos	17-May-2023				
	(SOURCE: EMM 05-20-00) (NOTE: Engine following the Extended TBO program)				Hrs	3,581.6	2,250	+50	5,831.6	1,871.3 Hrs (+50)
					Enc	3,171				
72-PW615F-LUI	On-Wing Low Utilization Engine Inspection						T		EMM - Requirement	
72 ENG1					Mos	18-May-2023	144		18-May-2035	11.5 Years
	Task:72-00-00-290-818 (SOURCE: PW615F-A LMM (P/N 3072691)) (NOTE: An additional one month or ten flying hours, whichever comes first, is permitted for scheduling purposes for the initial LUI inspection and for the 24-month Low Utilization Inspection intervals.)				Hrs	3,898.8				
					Enc	2,711				
72-PW615F-LUI	On-Wing Low Utilization Engine Inspection						T		EMM - Requirement	
72 ENG2					Mos	17-May-2023	144		17-May-2035	11.5 Years
	Task:72-00-00-290-818 (SOURCE: PW615F-A LMM (P/N 3072691)) (NOTE: An additional one month or ten flying hours, whichever comes first, is permitted for scheduling purposes for the initial LUI inspection and for the 24-month Low Utilization Inspection intervals.)				Hrs	3,581.6				
					Enc	3,171				
72-PW615F-TBO	Engine Overhaul						RE		EMM - Requirement, Extended TBO	≈22-Feb-2029
72 ENG1					Mos	18-May-2023				
	(SOURCE: EMM 05-20-00) (NOTE: Engine following the Extended TBO program)				Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
					Enc	2,711				
72-PW615F-TBO	Engine Overhaul						RE		EMM - Requirement, Extended TBO	≈22-Feb-2029
72 ENG2					Mos	17-May-2023				
	(SOURCE: EMM 05-20-00) (NOTE: Engine following the Extended TBO program)				Hrs	3,581.6	4,500	+100	8,081.6	4,121.3 Hrs (+100)
					Enc	3,171				

Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
CF-2010-03 Fuel Oil Heat Exchanger (FOHE) Fuel Filter Bypass Valve Wear												
	72 ENG1						Mos	18-May-2023				
	Eff: 25-Jan-2010 Complied With	Complied during OH					Hrs	3,898.8				
							Enc	2,711				
CF-2010-03 Fuel Oil Heat Exchanger (FOHE) Fuel Filter Bypass Valve Wear												
	72 ENG2						Mos	17-May-2023				
	Eff: 25-Jan-2010 Complied With						Hrs	3,581.6				
							Enc	3,171				
Engine 1 Pratt & Whitney of Canada - PW615F-A												
	72 A/F						Mos	07-Jun-2023				
	35C0510-01	Time at install: 3898.8 Hrs, 2711 Enc, TSO: 0 Hrs, 0 Enc					Hrs	9,471.8				
	PCE-LB0340						Ldg	7,591				
(AVG MAN HRS: 0) (APX COST: 0)												
Engine 2 Pratt & Whitney of Canada - PW615F-A												
	72 A/F						Mos	07-Jun-2023				
	35C0510	Time at install: 3581.6 Hrs, 3171 Enc, TSO: 0 Hrs, 0 Enc					Hrs	9,471.8				
	PCE-LB0337						Ldg	7,591				
PW600-72-63002 Replacement of Turbine Exhaust Case (TEC) Cowl Brackets												
	72 ENG1						Mos	14-Nov-2008				
	Eff: 17-Oct-2006 Complied With	Complied with during Manufacturing					Hrs	0				
							Enc	0				
PW600-72-63002 Replacement of Turbine Exhaust Case (TEC) Cowl Brackets												
	72 ENG2						Mos	23-Nov-2008				
	Eff: 17-Oct-2006 Complied With	at Manufacture					Hrs	0				
							Enc	0				
PW600-72-63003 Introduction of Additional Balancing Weights For The Fan Trim Balance												
	72 ENG1						Mos	14-Nov-2008				
	Eff: 14-Nov-2006 Complied With	Complied with during Manufacturing					Hrs	0				
							Enc	0				
PW600-72-63003 Introduction of Additional Balancing Weights For The Fan Trim Balance												
	72 ENG2						Mos	23-Nov-2008				
	Eff: 14-Nov-2006 Complied With	C/W in Production					Hrs	0				
							Enc	0				
PW600-72-63005 Replacement of Bleed-Valve-Assembly Ball Bearing												
	72 ENG1						Mos	14-Nov-2008				
	Eff: 22-Nov-2006 Complied With	Complied with during Manufacturing					Hrs	0				
							Enc	0				
PW600-72-63005 Replacement of Bleed-Valve-Assembly Ball Bearing												
	72 ENG2						Mos	23-Nov-2008				
	Eff: 22-Nov-2006 Complied With	at Manufacture					Hrs	0				
							Enc	0				
PW600-72-63006 Replacement of Shipping Container Hardware												
	72 ENG1						Mos	14-Nov-2008				
	Eff: 22-Feb-2007 Complied With	Complied with during Manufacturing					Hrs	0				
							Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-72-63006		Replacement of Shipping Container Hardware								Category 9	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 22-Feb-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63007		Replacement of Turbine Exhaust Case Cowl Assembly								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 16-Jan-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63007		Replacement of Turbine Exhaust Case Cowl Assembly								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 16-Jan-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63010		Replacement of Turbine Exhaust Case Assembly								Category 8	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 07-Feb-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63010		Replacement of Turbine Exhaust Case Assembly								Category 8	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 07-Feb-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63012		Replacement of Compressor Case Assembly								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 29-Mar-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63012		Replacement of Compressor Case Assembly								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 29-Mar-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63013		Replacement of Compressor Impeller And Shaft Assembly								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 02-Apr-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63013		Replacement of Compressor Impeller And Shaft Assembly								Category 7	
	72 ENG2						Mos	17-May-2023			
	Eff: 02-Apr-2007 Complied With	at Manufacture					Hrs	3,581.5			
							Enc	3,171			
PW600-72-63016		Replacement of Combustion Chamber Liner Assembly- Replacement Of								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 02-May-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63016		Replacement of Combustion Chamber Liner Assembly- Replacement Of								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 02-May-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-72-63017		Introduction of Classified Spacers								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 15-Jun-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63017		Introduction of Classified Spacers								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 15-Jun-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63019		Introduction of Shipping Bracket Assembly								Category 9	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 11-Jul-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63019		Introduction of Shipping Bracket Assembly								Category 9	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 11-Jul-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63022		Replacement of Compressor Impeller And Shaft Assembly								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 11-Jul-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63022		Replacement of Compressor Impeller And Shaft Assembly								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 11-Jul-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63024		Replacement of No. 4 Roller Bearing								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 05-Jul-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63024		Replacement of No. 4 Roller Bearing								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 05-Jul-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63025		Replacement of Seal Runner								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 27-Aug-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63025		Replacement of Seal Runner								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 27-Aug-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63026		Replacement of Shipping Container Assembly								Category 9	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 09-Aug-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-72-63026		Replacement of Shipping Container Assembly								Category 9	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 09-Aug-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63027		Inspection of No.1-Bearing Air-Seal-Runner Assembly								Category 8	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 25-Jul-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63027		Inspection of No.1-Bearing Air-Seal-Runner Assembly								Category 8	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 25-Jul-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63028		Replacement of No.1-Bearing Air-Seal-Runner Assembly								Category 5	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 27-Aug-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63028		Replacement of No.1-Bearing Air-Seal-Runner Assembly								Category 5	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 27-Aug-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63031		Replacement of Impeller Housing Assembly								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 16-Nov-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63031		Replacement of Impeller Housing Assembly								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 16-Nov-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63032		Replacement of High-Pressure-Compressor (HPc) Rotor Balancing Ring								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 18-Sep-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63032		Replacement of High-Pressure-Compressor (HPc) Rotor Balancing Ring								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 18-Sep-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63034		Replacement of Oil Pump Plate								Category 8	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 01-Oct-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63034		Replacement of Oil Pump Plate								Category 8	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 01-Oct-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-72-63035		No. 1 Bearing Support Assembly Replacement								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 28-Apr-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63035		No. 1 Bearing Support Assembly Replacement								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 28-Apr-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63037		Replacement of Engine Mount Bracket Assembly								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 13-Dec-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63037		Replacement of Engine Mount Bracket Assembly								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 13-Dec-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63039		Replacement of LPT Vane Ring Assembly								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 05-Dec-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63039		Replacement of LPT Vane Ring Assembly								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 05-Dec-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63040		Replacement of Front Outer Bypass Duct Assembly - Modification/Replacement Of								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 30-Jan-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63040		Replacement of Front Outer Bypass Duct Assembly - Modification/Replacement Of								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 30-Jan-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63041		Replacement of Turbine Exhaust Case Assembly								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 14-Dec-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63041		Replacement of Turbine Exhaust Case Assembly								Category 7	
	72 ENG2						Mos	23-Nov-2008			
	Eff: 14-Dec-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63042		Replacement of Impeller Housing Assembly								Category 7	
	72 ENG1						Mos	14-Nov-2008			
	Eff: 13-Feb-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-72-63042		Replacement of Impeller Housing Assembly								RE (-)	Category 7
	72 ENG2						Mos	23-Nov-2008			
	Eff: 13-Feb-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63043		Replacement/Modification of Fan Case Assembly Stick-On Studs								RE (-)	Category 6
	72 ENG1						Mos	14-Nov-2008			
	Eff: 16-Jan-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63043		Replacement/Modification of Fan Case Assembly Stick-On Studs								RE (-)	Category 6
	72 ENG2						Mos	23-Nov-2008			
	Eff: 16-Jan-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63045		Replacement of Oil Nozzle Housing Assembly								RE (-)	Category 7
	72 ENG1						Mos	14-Nov-2008			
	Eff: 19-Dec-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63045		Replacement of Oil Nozzle Housing Assembly								RE (-)	Category 7
	72 ENG2						Mos	23-Nov-2008			
	Eff: 19-Dec-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63051		Replacement of Diffuser Case Assembly No. 4 Bearing Oil Pressure And Scavenge Tube Assemblies								RE (-)	Category 6
	72 ENG1						Mos	14-Nov-2008			
	Eff: 03-Jul-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63051		Replacement of Diffuser Case Assembly No. 4 Bearing Oil Pressure And Scavenge Tube Assemblies								RE (-)	Category 6
	72 ENG2						Mos	23-Nov-2008			
	Eff: 03-Jul-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63052		Replacement of Compressor Case Assembly And No. 1 To No. 3 Bearing Oil-Pressure Tube-Assembly								RE (-)	Category 7
	72 ENG1						Mos	14-Nov-2008			
	Eff: 12-Sep-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63052		Replacement of Compressor Case Assembly And No. 1 To No. 3 Bearing Oil-Pressure Tube-Assembly								RE (-)	Category 7
	72 ENG2						Mos	23-Nov-2008			
	Eff: 12-Sep-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63053		Replacement of No.4-Bearing Front And Rear Seal Runners								RE (-)	Category 7
	72 ENG1						Mos	11-Nov-2008			
	Eff: 03-Jul-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63053		Replacement of No.4-Bearing Front And Rear Seal Runners								RE (-)	Category 7
	72 ENG2						Mos	23-Nov-2008			
	Eff: 03-Jul-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-72-63055		Replacement/Modification of Air Cooled Oil Cooler								RE (-)	Category 7
	72 ENG1						Mos	25-Jul-2023			
	Eff: 02-Dec-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63055		Replacement/Modification of Air Cooled Oil Cooler								RE (-)	Category 7
	72 ENG2						Mos	23-Nov-2008			
	Eff: 02-Dec-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63057		Replacement of No. 5 Bearing Seal Runner								RE (-)	Category 7
	72 ENG1						Mos	14-Nov-2008			
	Eff: 08-Sep-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63057		Replacement of No. 5 Bearing Seal Runner								RE (-)	Category 7
	72 ENG2						Mos	23-Nov-2008			
	Eff: 08-Sep-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63059		Replacement of HP Diffuser Case Assembly - Modification/Replacement Of								RE (-)	Category 6
	72 ENG1						Mos	14-Nov-2008			
	Eff: 16-Feb-2009 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-72-63059		Replacement of HP Diffuser Case Assembly - Modification/Replacement Of								RE (-)	Category 6
	72 ENG2						Mos	23-Nov-2008			
	Eff: 16-Feb-2009 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-72-63060		Replacement of Bleed-Valve-Actuator (Bva) Bracket Bolts								RE (-)	Category 6
	72 ENG1						Mos	18-May-2023			
	Eff: 12-Dec-2008 Complied With	Complied during OH					Hrs	3,898.8			
							Enc	2,711			
PW600-72-63060		Replacement of Bleed-Valve-Actuator (Bva) Bracket Bolts								RE (-)	Category 6
	72 ENG2						Mos	17-May-2023			
	Eff: 12-Dec-2008 Complied With						Hrs	3,581.5			
							Enc	3,171			
PW600-72-63062 R1		Replacement of Accessory-Gearbox (Agb) Plain Seal								RE (-)	Category 7
	72 ENG2						Mos	17-May-2023			
	Eff: 26-Nov-2010 Complied With						Hrs	3,581.5			
							Enc	3,171			
PW600-72-63064 R2		Replacement/Modification of N0. 4 Bearing Oil Pressure Tube Assembly								RE (-)	Category 6
	72 ENG1						Mos	18-May-2023			
	Eff: 05-Feb-2014 Complied With	Complied during OH					Hrs	3,898.8			
							Enc	2,711			
PW600-72-63064 R2		Replacement/Modification of N0. 4 Bearing Oil Pressure Tube Assembly								RE (-)	Category 6
	72 ENG2						Mos	17-May-2023			
	Eff: 05-Feb-2014 Complied With						Hrs	3,581.5			
							Enc	3,171			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-72-63068 R1		Replacement/Modification of Oil Filler And Indicator Assembly						RE (-)		Category 6	
	72 ENG1						Mos	18-May-2023			
	Eff: 05-Nov-2010 Complied With	Complied during OH					Hrs	3,898.8			
							Enc	2,711			
PW600-72-63068 R1		Replacement/Modification of Oil Filler And Indicator Assembly						RE (-)		Category 6	
	72 ENG2						Mos	17-May-2023			
	Eff: 05-Nov-2010 Complied With						Hrs	3,581.5			
							Enc	3,171			
PW600-72-63070		Deletion of Fire-Insulation Blanket Assembly						RE (-)			
	72 ENG1						Mos	11-Jun-2015			
	Eff: 30-Oct-2009 Complied With	Complied during H.S.I.					Hrs	1,743.6			
							Enc	1,441			
PW600-72-63070		Deletion of Fire-Insulation Blanket Assembly						T (A/R)		Category 6	
	72 ENG2						Mos	17-May-2023			
	Eff: 30-Oct-2009 Complied With						Hrs	3,581.5			
							Enc	3,171			
PW600-72-63072 R1		Replacement of No. 3 Flanged Ball Bearing						RE (-)		Category 7	
	72 ENG2						Mos	17-May-2023			
	Eff: 13-Feb-2012 Complied With						Hrs	3,581.5			
							Enc	3,171			
PW600-72-63073		Replacement Of The Fuel-Shut-Off-Lever Cotter Pin By A Safety Wire						RE (-)		Category 6	
	72 ENG1						Mos	18-May-2023			
	Eff: 19-Feb-2010 Complied With	Complied during OH					Hrs	3,898.8			
							Enc	2,711			
PW600-72-63073		Replacement Of The Fuel-Shut-Off-Lever Cotter Pin By A Safety Wire						RE (-)		Category 6	
	72 ENG2						Mos	17-May-2023			
	Eff: 19-Feb-2010 Complied With						Hrs	3,581.5			
							Enc	3,171			
PW600-72-63074 Rev 1		Replacement of Impeller Housing Assembly						RE (-)		Category 6	
	72 ENG1						Mos	18-May-2023			
	Eff: 12-Dec-2019 Complied With	Complied during OH					Hrs	3,898.8			
							Enc	2,711			
PW600-72-63074 Rev 1		Replacement of Impeller Housing Assembly						RE (-)		Category 6	
	72 ENG2						Mos	17-May-2023			
	Eff: 12-Dec-2019 Complied With						Hrs	3,581.5			
							Enc	3,171			
PW600-72-63075		Replacement/Modification of Fuel Oil/Heater Exchanger (FOHE)						RE (-)		Category 7	
	72 ENG1						Mos	18-May-2023			
	Eff: 16-Mar-2010 Complied With	Complied during OH					Hrs	3,898.8			
							Enc	2,711			
PW600-72-63075		Replacement/Modification of Fuel Oil/Heater Exchanger (FOHE)						RE (-)		Category 7	
	72 ENG2						Mos	17-May-2023			
	Eff: 16-Mar-2010 Complied With						Hrs	3,581.5			
							Enc	3,171			
PW600-72-63077 R2		Replacement of Accessory Drive Gearshaft and Spiral Bevel Gear						RE (-)		Category 6	
	72 ENG1						Mos	18-May-2023			
	Eff: 10-Jul-2018 Complied With	Complied during OH					Hrs	3,898.8			
							Enc	2,711			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-72-63077 R2		Replacement of Accessory Drive Gearshaft and Spiral Bevel Gear						RE (-)		Category 6	
	72 ENG2					Mos	17-May-2023				
	Eff: 10-Jul-2018 Complied With					Hrs	3,581.5				
						Enc	3,171				
PW600-72-63079		Replacement of Fuel Shut-Off Cable Assembly						T (A/R)		Category 7	
	72 ENG2					Mos	17-May-2023				
	Eff: 23-Mar-2010 Complied With					Hrs	3,581.5				
						Enc	3,171				
PW600-72-63080 R2		Modification/Replacement of Electrical Wiring Harness (TT0 Sensor)						RE (-)		Category 6	
	72 ENG1					Mos	18-May-2023				
	Eff: 11-Jan-2017 Complied With	Complied during OH				Hrs	3,898.8				
	(AVG MAN HRS: 2.5)					Enc	2,711				
PW600-72-63080 R2		Modification/Replacement of Electrical Wiring Harness (TT0 Sensor)						RE (-)		Category 6	
	72 ENG2					Mos	17-May-2023				
	Eff: 11-Jan-2017 Complied With					Hrs	3,581.5				
	(AVG MAN HRS: 2.5)					Enc	3,171				
PW600-72-63084		Replacement of Flange Duplex Bearing (Ic)						RE (-)		Category 7	
	72 ENG1					Mos	18-May-2023				
	Eff: 13-Aug-2010 Complied With	Complied during OH				Hrs	3,898.8				
						Enc	2,711				
PW600-72-63084		Replacement of Flange Duplex Bearing (Ic)						RE (-)		Category 7	
	72 ENG2					Mos	17-May-2023				
	Eff: 13-Aug-2010 Complied With					Hrs	3,581.5				
						Enc	3,171				
PW600-72-63086		Replacement of Diffuser Exit Duct Assembly						RE (-)		Category 7	
	72 ENG2					Mos	17-May-2023				
	Eff: 10-Jan-2011 Complied With					Hrs	3,581.5				
						Enc	3,171				
PW600-72-63089 R2		Replacement/Modification of Fuel Metering Unit						RE (-)		Category 6	
	72 ENG1					Mos	18-May-2023				
	Eff: 06-Feb-2012 Complied With	Complied during OH				Hrs	3,898.8				
						Enc	2,711				
PW600-72-63089 R2		Replacement/Modification of Fuel Metering Unit						RE (-)		Category 6	
	72 ENG2					Mos	17-May-2023				
	Eff: 06-Feb-2012 Complied With					Hrs	3,581.5				
						Enc	3,171				
PW600-72-63091 R2		Inspection of Primary and Secondary Fuel Fairing Reducers						RE (-)		Category 6	
	72 ENG1					Mos	18-May-2023				
	Eff: 08-Feb-2017 Complied With	Complied during OH				Hrs	3,898.8				
	(AVG MAN HRS: 1.5)					Enc	2,711				
PW600-72-63091 R2		Inspection of Primary and Secondary Fuel Fairing Reducers						RE (-)		Category 6	
	72 ENG2					Mos	17-May-2023				
	Eff: 08-Feb-2017 Complied With					Hrs	3,581.5				
	(AVG MAN HRS: 1.5)					Enc	3,171				
PW600-72-63092		Replacement of Low Pressure Compressor Shaft						RE (-)		Category 7	
	72 ENG2					Mos	17-May-2023				
	Eff: 17-May-2012 Complied With					Hrs	3,581.5				
						Enc	3,171				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
PW600-72-63093	Inspection of Oil Filler Cap Assembly Bracket - Repositioning Of						RE (-)		Category 6	
 72 ENG1						Mos	18-May-2023			
Eff: 30-Sep-2011 Complied With	Complied during OH					Hrs	3,898.8			
						Enc	2,711			
PW600-72-63093	Inspection of Oil Filler Cap Assembly Bracket - Repositioning Of						RE (-)		Category 6	
 72 ENG2						Mos	17-May-2023			
Eff: 30-Sep-2011 Complied With						Hrs	3,581.5			
						Enc	3,171			
PW600-72-63098 Rev 1	Inspection of High Pressure Diffuser Case Assembly						RE (-)		Category 3	
 72 ENG1						Mos	18-May-2023			
Eff: 07-May-2020 Complied With	Complied during OH					Hrs	3,898.8			
(AVG MAN HRS: 2.5)						Enc	2,711			
PW600-72-63098 Rev 1	Inspection of High Pressure Diffuser Case Assembly						RE (-)		Category 3	
 72 ENG2						Mos	17-May-2023			
Eff: 07-May-2020 Complied With						Hrs	3,581.5			
(AVG MAN HRS: 2.5)						Enc	3,171			
PW600-72-63102	Replacement of No.4 - Bearing Front and Rear Carbon Seal						RE (-)			
 72 ENG1						Mos				
Eff: 12-Apr-2013 Superseded With	Superseded by Revision 1					Hrs				
						Enc				
PW600-72-63102 R1	Replacement of No.4 - Bearing Front And Rear Carbon Seal						RE (-)			
 72 ENG1						Mos	11-Jun-2015			
Eff: 17-Apr-2013 Complied With	Complied during H.S.I.					Hrs	1,743.6			
						Enc	1,441			
PW600-72-63106 R1	Re-Identification of AGB Housing and Cover						RE (-)		Category 5	
 72 ENG1						Mos	18-May-2023			
Eff: 02-Apr-2018 Complied With	Complied during OH					Hrs	3,898.9			
(NOTE: EFFECTIVITY: PW615F-A Engines which have incorporated CIR Task 72-61-50-220-802-A on the AGB housing and Task 7261-51-220-802-A on the AGB cover.)						Enc	2,711			
PW600-72-63106 R1	Re-Identification of AGB Housing and Cover						RE (-)		Category 5	
 72 ENG2						Mos	17-May-2023			
Eff: 02-Apr-2018 Complied With						Hrs	3,581.5			
(NOTE: EFFECTIVITY: PW615F-A Engines which have incorporated CIR Task 72-61-50-220-802-A on the AGB housing and Task 7261-51-220-802-A on the AGB cover.)						Enc	3,171			
PW600-72-63108 Rev 1	Replacement of No. 3 Flanged Ball Bearing						RE (-)		Category 7	
 72 ENG1						Mos	18-May-2023			
Eff: 30-Mar-2021 Complied With	Complied during OH					Hrs	3,898.8			
						Enc	2,711			
PW600-72-63109	Replacement of No. 4 Bearing Carbon Seals and Impeller Baffle						RE (-)		Category 5	
 72 ENG1						Mos	18-May-2023			
Eff: 22-Jun-2018 Complied With	Complied during OH					Hrs	3,898.8			
(AVG MAN HRS: 1.5)						Enc	2,711			
PW600-72-63110	Validation of No. 3 Bearing Assembly Procedure						T (A/R)		Category 5	
 72 ENG1						Mos				
Eff: 07-May-2018						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-72-63113		Replacement of Turbofan Engine Accessory-Gearbox (AGB) Plain Seal						RE (-)		Category 3, Category 7	
	72 ENG1					Mos	18-May-2023				
	Eff: 02-Feb-2022	Complied With				Hrs	3,898.8				
		(AVG MAN HRS: 1.5) (NOTE: COMPLIANCE: P&WC recommends to do this service bulletin by February 03, 2022.				Enc	2,711				
		NOTE: For Post-SB63062 and Pre-SB 63112 engines that replaced the AGB Seal with P/N 35C5539-01 between January 01, 2018 and February 01, 2021.)									
SIL-GEN-020 Rev 5		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 15-Jul-2015					Hrs					
						Enc					
SIL-GEN-020 Rev 6		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 27-Sep-2021					Hrs					
						Enc					
SIL-GEN-020 Rev 7		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 09-Jan-2023					Hrs					
						Enc					
SIL-GEN-038 R4		Use of Non-Pratt and Whitney Canada (PWC) Supported Parts or Non-PWC Approved Repair Schemes						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
SIL-GEN-038 R4		Use of Non-Pratt and Whitney Canada (PWC) Supported Parts or Non-PWC Approved Repair Schemes						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
SIL-GEN-044 Rev 2		Material Returned to PWC						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 03-Aug-2023					Hrs					
						Enc					
SIL-GEN-044 Rev 2		Material Returned to PWC						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 03-Aug-2023					Hrs					
						Enc					
SIL-GEN-065 Rev 1		Information Required to Process New Engine Accessory Warranty Claims						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 29-Jun-2023					Hrs					
						Enc					
SIL-GEN-065 Rev 1		Information Required to Process New Engine Accessory Warranty Claims						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 29-Jun-2023					Hrs					
						Enc					
SIL-GEN-123 Rev 11		Qualified Engine Oil Analysis Laboratory List						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 12-Sep-2023					Hrs					
						Enc					
SIL-GEN-123 Rev 11		Qualified Engine Oil Analysis Laboratory List						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 12-Sep-2023					Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 73 - ENGINE - FUEL AND CONTROL											
	73 A/F 1103P0448 8024	Engine Fuel Pressure Switch						RE (O/C)			
		Left						Mos	20-Mar-2008		
		New	0					Hrs	0		
			0					Ldg	0		
	73 A/F 1103P0448 8001	Engine Fuel Pressure Switch						RE (O/C)			
		Right						Mos	20-Mar-2008		
		New	0					Hrs	0		
			0					Ldg	0		
	73 ENG1 35C3943-02 WDAAL000349	Engine Harness						RE (O/C)			
		Repaired						Mos	18-May-2023		
			3,898.8					Hrs	3,898.8		
			2,711					Enc	2,711		
	73 ENG2 35C3943-02 WDAAL000347	Engine Harness						RE (O/C)			
		Tested/Inspected						Mos	17-May-2023		
								Hrs	3,581.6		
								Enc	3,171		
	73 ENG1 35C3388-01 WDA103643	Fuel Filter Impending Bypass Switch						RE (O/C)			
		Tested/Inspected						Mos	18-May-2023		
			3,898.8					Hrs	3,898.8		
			2,711					Enc	2,711		
	73 ENG2 35C3388-01 WDA103569	Fuel Filter Impending Bypass Switch						RE (O/C)			
		Tested/Inspected						Mos	17-May-2023		
								Hrs	3,581.5		
								Enc	3,171		
	73 A/F 9912417-1 0495 (APX COST: 1,698.37)	Fuel Flow Transmitter						RE (O/C)			
		Left						Mos	07-Jun-2023		
		Overhauled	0					Hrs	9,471.8		
			0					Ldg	7,591		
	73 A/F 9912417-1 0490 (APX COST: 1,698.37)	Fuel Flow Transmitter						RE (O/C)			
		Right						Mos	07-Jun-2023		
		Overhauled	0					Hrs	9,471.8		
			0					Ldg	7,591		
	73 ENG1 35C6160-01 DEAAAAA88896	Fuel Manifold						RE (Srv)			
		New						Mos	11-Jun-2015		
			0					Hrs	1,743.6		
			0					Enc	1,441		
	73 ENG2 35C6160-01 DEAAAA88896	Fuel Manifold						RE (Srv)			
		New						Mos	17-May-2023		
								Hrs	3,581.5		
								Enc	3,171		

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	73 ENG1	Overhauled					Mos	RE (O/C)			
	8062-1109						Hrs	18-May-2023			
	16311350							3,898.8			
							Enc	2,711			
	73 ENG2	Overhauled					Mos	RE (O/C)			
	8062-1109						Hrs	17-May-2023			
	16307844							3,581.5			
							Enc	3,171			
	73 ENG1	Tested/Inspected					Mos	RE (O/C)			
	35C0374-01						Hrs	17-May-2023			
	WDAAD001568										
							Enc				
	73 ENG2	Tested/Inspected					Mos	RE (O/C)			
	35C-0374-01						Hrs	17-May-2023			
	WDAAD001568							3,581.5			
							Enc	3,171			
73-PW615F-001	Engine - EEC - Make sure it is properly attached. Examine general condition.							RE	EMM - Requirement		≈17-Dec-2023
	73 ENG1	Pkg 450 Hour/12 Month					Mos	07-Jun-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)
	(SOURCE: EMM 05-20-00)						Hrs	3,898.8	450	-/+10% (4,348.8)	71.3 Hrs (+45)
							Enc	2,711			
73-PW615F-001	Engine - EEC - Make sure it is properly attached. Examine general condition.							RE	EMM - Requirement		≈17-Dec-2023
	73 ENG2	Pkg 450 Hour/12 Month					Mos	17-May-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)
	(SOURCE: EMM 05-20-00)						Hrs	3,581.5	450	-/+10% (4,031.6)	71.3 Hrs (+45)
							Enc	3,171			
73-PW615F-002	Engine - Wiring Harness - Make sure all the clamps and brackets are properly attached. Examine cables for evidence of wear, fraying, chafing and cracks.							RE	EMM - Requirement		≈17-Dec-2023
	73 ENG1	Pkg 450 Hour/12 Month					Mos	07-Jun-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)
	(SOURCE: EMM 05-20-00)						Hrs	3,898.8	450	-/+10% (4,348.8)	71.3 Hrs (+45)
							Enc	2,711			
73-PW615F-002	Engine - Wiring Harness - Make sure all the clamps and brackets are properly attached. Examine cables for evidence of wear, fraying, chafing and cracks.							RE	EMM - Requirement		≈17-Dec-2023
	73 ENG2	Pkg 450 Hour/12 Month					Mos	17-May-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)
	(SOURCE: EMM 05-20-00)						Hrs	3,581.5	450	-/+10% (4,031.6)	71.3 Hrs (+45)
							Enc	3,171			
73-PW615F-003	Engine - Wiring Harness - Make sure all the wiring harness connectors are properly attached. Examine outer surfaces for cracks and corrosion.							RE	EMM - Requirement		≈17-Dec-2023
	73 ENG1	Pkg 450 Hour/12 Month					Mos	07-Jun-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)
	(SOURCE: EMM 05-20-00)						Hrs	3,898.8	450	-/+10% (4,348.8)	71.3 Hrs (+45)
							Enc	2,711			
73-PW615F-003	Engine - Wiring Harness - Make sure all the wiring harness connectors are properly attached. Examine outer surfaces for cracks and corrosion.							RE	EMM - Requirement		≈17-Dec-2023
	73 ENG2	Pkg 450 Hour/12 Month					Mos	17-May-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)
	(SOURCE: EMM 05-20-00)						Hrs	3,581.5	450	-/+10% (4,031.6)	71.3 Hrs (+45)
							Enc	3,171			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-PW615F-004	73 ENG1	Fuel System - FMU - Make sure it is properly attached. Examine general condition. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
73-PW615F-004	73 ENG2	Fuel System - FMU - Make sure it is properly attached. Examine general condition. Pkg 450 Hour/12 Month (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
73-PW615F-005	73 ENG1 10940J WA34494 (SOURCE: EMM 05-20-00)	Fuel System - Fuel/Oil Heat Exchanger - make sure it is properly attached. Examine general condition. Pkg 450 Hour/12 Month						RE		EMM - Requirement	≈17-Dec-2023
73-PW615F-005	73 ENG2 10940J WA34522 (SOURCE: EMM 05-20-00)	Fuel System - Fuel/Oil Heat Exchanger - make sure it is properly attached. Examine general condition. Pkg 450 Hour/12 Month						RE		EMM - Requirement	≈17-Dec-2023
73-PW615F-006	73 ENG1 Ref.:73-10-05, Task:73-10-05-400-801, Task:73-10-05-290-801, Task:73-10-05-000-801 (SOURCE: EMM 05-20-00)	Fuel System - Fuel Filter Element - Remove old filter element and check it for foreign matter. Replace the filter element. Pkg 450 Hour/12 Month						RE		EMM - Requirement	≈17-Dec-2023
73-PW615F-006	73 ENG2 Ref.:73-10-05, Task:73-10-05-400-801, Task:73-10-05-290-801, Task:73-10-05-000-801 (SOURCE: EMM 05-20-00)	Fuel System - Fuel Filter Element - Remove old filter element and check it for foreign matter. Replace the filter element.						RE		EMM - Requirement	≈17-Dec-2023
73-PW615F-007	73 ENG1 35C6160-01 DEAAAAA88896 Ref.:73-10-04, Task:73-10-04-400-801, Task:73-10-04-000-801 (SOURCE: EMM 05-20-00)	Fuel System - Fuel Manifold - Replace the Fuel Manifold with a new or Overhauled Assembly						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
73-PW615F-007	73 ENG2 35C6160-01 DEAAAAA88896 Ref.:73-10-04, Task:73-10-04-400-801, Task:73-10-04-000-801 (SOURCE: EMM 05-20-00) (NOTE: At scheduled HSI interval - Engine following the Extended TBO program)	Fuel System - Fuel Manifold - Replace the Fuel Manifold with a new or Overhauled Assembly						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
73-PW615F-008	73 ENG1 (SOURCE: EMM 05-20-00)	Fuel System - Emergency Fuel Shutoff Cable at the FMU - Make sure the cable to the FMU is properly attached. Pkg 450 Hour/12 Month						RE		EMM - Requirement	≈17-Dec-2023
73-PW615F-008	73 ENG2 (SOURCE: EMM 05-20-00)	Fuel System - Emergency Fuel Shutoff Cable at the FMU - Make sure the cable to the FMU is properly attached. Pkg 450 Hour/12 Month						RE		EMM - Requirement	≈17-Dec-2023

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-PW615F-009	Fuel System - Emergency Fuel Shutoff Lever and Cable in the Exhaust Case - Inspect through hole in exhaust cone and: make sure the control lever is properly attached / make sure the cable to control lever is properly attached / examine for evidence of oil leaks or carbon at No.5 Bearing area.						RE		EMM - Requirement	≈17-Dec-2023
73 ENG1	Pkg 450 Hour/12 Month				Mos	07-Jun-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
(SOURCE: EMM 05-20-00)					Hrs	3,898.8	450	-/+10%	(4,348.8)	71.3 Hrs (+45)
					Enc	2,711				
73-PW615F-009	Fuel System - Emergency Fuel Shutoff Lever and Cable in the Exhaust Case - Inspect through hole in exhaust cone and: make sure the control lever is properly attached / make sure the cable to control lever is properly attached / examine for evidence of oil leaks or carbon at No.5 Bearing area.						RE		EMM - Requirement	≈17-Dec-2023
73 ENG2	Pkg 450 Hour/12 Month				Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
(SOURCE: EMM 05-20-00)					Hrs	3,581.5	450	-/+10%	(4,031.6)	71.3 Hrs (+45)
					Enc	3,171				
73-PW615F-010	Fuel System - Emergency Fuel Shutoff Lever and Cable in the Exhaust Case - Do a borescope inspection of the fuel shutoff cable wire core for broken strands where the wire core exits the cable.						RE		EMM - Requirement	≈17-Dec-2023
73 ENG1	Pkg 450 Hour/12 Month				Mos	07-Jun-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
Task:73-10-07-400-801, Task:73-10-07-000-801 (SOURCE: EMM 05-20-00) (NOTE: Insert the borescope between the exhaust mixer and the bypass duct service fairing and move the borescope downward to locate the cable attachment point. Replace the cable if there any broken strands.)					Hrs	3,898.8	450	-/+10%	(4,348.8)	71.3 Hrs (+45)
					Enc	2,711				
73-PW615F-010	Fuel System - Emergency Fuel Shutoff Lever and Cable in the Exhaust Case - Do a borescope inspection of the fuel shutoff cable wire core for broken strands where the wire core exits the cable.						RE		EMM - Requirement	≈17-Dec-2023
73 ENG2	Pkg 450 Hour/12 Month				Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
Task:73-10-07-400-801, Task:73-10-07-000-801 (SOURCE: EMM 05-20-00) (NOTE: Insert the borescope between the exhaust mixer and the bypass duct service fairing and move the borescope downward to locate the cable attachment point. Replace the cable if there any broken strands.)					Hrs	3,581.5	450	-/+10%	(4,031.6)	71.3 Hrs (+45)
					Enc	3,171				
73-PW615F-011	Fuel System - Fuel Filter Impending Bypass Switch - Do a functional test.						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
73 ENG1					Mos	18-May-2023				
Task:73-30-01-720-801 (SOURCE: EMM 05-20-00) (NOTE: At scheduled HSI interval - Engine following the Extended TBO program)					Hrs	3,898.8	2,250	+50	6,148.8	1,871.3 Hrs (+50)
					Enc	2,711				
73-PW615F-011	Fuel System - Fuel Filter Impending Bypass Switch - Do a functional test.						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
73 ENG2					Mos	17-May-2023				
Task:73-30-01-720-801 (SOURCE: EMM 05-20-00) (NOTE: At scheduled HSI interval - Engine following the Extended TBO program)					Hrs	3,581.5	2,250	+50	5,831.5	1,871.2 Hrs (+50)
					Enc	3,171				
73-PW615F-012	Engine Electronic Control (E.E.C.) - Send to Supplier to do a Test as Received and a Recertification (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
73 ENG1					Mos	07-Jun-2023				
35C4035-03					Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
08-505					Enc	2,711				
73-PW615F-012	Engine Electronic Control (E.E.C.) - Send to Supplier to do a Test as Received and a Recertification (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
73 ENG2					Mos	17-May-2023				
8237-1217-1					Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
09-613					Enc	3,171				
73-PW615F-013	Engine Electrical Wiring Harness - Inspection (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
73 ENG1					Mos	18-May-2023				
					Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
					Enc	2,711				
73-PW615F-013	Engine Electrical Wiring Harness - Inspection (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
73 ENG2					Mos	17-May-2023				
					Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
					Enc	3,171				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-PW615F-014		Fuel Filter Impending Bypass Switch - Do a Visual Inspection and a Functional Test (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	73 ENG1					Mos	18-May-2023				
	35C3388-01					Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
	WDA103643					Enc	2,711				
	Ref:73-30-01-210-801										
73-PW615F-014		Fuel Filter Impending Bypass Switch - Do a Visual Inspection and a Functional Test (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	73 ENG2					Mos	17-May-2023				
	35C3388-01					Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
	WDA103569					Enc	3,171				
	Ref:73-30-01-210-801										
73-PW615F-015		Fuel Metering Unit (F.M.U.) - Send To Supplier For Overhaul (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	73 ENG1					Mos	18-May-2023				
	8062-1109					Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
	16311350					Enc	2,711				
73-PW615F-015		Fuel Metering Unit (F.M.U.) - Send To Supplier For Overhaul (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	73 ENG2					Mos	17-May-2023				
	8062-1109					Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
	16307844					Enc	3,171				
PW600-73-63004		Replacement of Fuel-Shut-Off-Valve Pin						RE (-)		Category 7	
	73 ENG1					Mos	14-Nov-2008				
	Eff: 01-Feb-2007 Complied With	Complied with during Manufacturing				Hrs	0				
						Enc	0				
PW600-73-63004		Replacement of Fuel-Shut-Off-Valve Pin						RE (-)		Category 7	
	73 ENG2					Mos	23-Nov-2008				
	Eff: 01-Feb-2007 Complied With	at Manufacture				Hrs	0				
						Enc	0				
PW600-73-63009		Replacement of Fuel Shut-Off Cable Assembly						RE (-)		Category 8	
	73 ENG1					Mos	14-Nov-2008				
	Eff: 15-Mar-2007 Complied With	Complied with during Manufacturing				Hrs	0				
						Enc	0				
PW600-73-63009		Replacement of Fuel Shut-Off Cable Assembly						RE (-)		Category 8	
	73 ENG2					Mos	23-Nov-2008				
	Eff: 15-Mar-2007 Complied With	at Manufacture				Hrs	0				
						Enc	0				
PW600-73-63011		Replacement of Electronic Engine Control (EEC) - Reprogramming/Replacement Of						RE (-)		Category 8	
	73 ENG1					Mos	14-Nov-2008				
	Eff: 05-Jan-2007 Complied With	Complied with during Manufacturing				Hrs	0				
						Enc	0				
PW600-73-63011		Replacement of Electronic Engine Control (EEC) - Reprogramming/Replacement Of						RE (-)		Category 8	
	73 ENG2					Mos	23-Nov-2008				
	Eff: 05-Jan-2007 Complied With	at Manufacture				Hrs	0				
						Enc	0				
PW600-73-63014		Replacement of Fuel Manifold Assembly						RE (-)		Category 7	
	73 ENG1					Mos	14-Nov-2008				
	Eff: 16-Mar-2007 Complied With	Complied with during Manufacturing				Hrs	0				
						Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-73-63014		Replacement of Fuel Manifold Assembly								Category 7	
	73 ENG2						Mos	23-Nov-2008			
	Eff: 16-Mar-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-73-63020		Replacement/Modification of Fuel Metering Unit								Category 8	
	73 ENG1						Mos	14-Nov-2008			
	Eff: 27-Aug-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-73-63020		Replacement/Modification of Fuel Metering Unit								Category 8	
	73 ENG2						Mos	23-Nov-2008			
	Eff: 27-Aug-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-73-63023		Replacement of Fuel Shut-Off Cable Assembly								Category 7	
	73 ENG1						Mos	14-Nov-2008			
	Eff: 05-Jul-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-73-63023		Replacement of Fuel Shut-Off Cable Assembly								Category 7	
	73 ENG2						Mos	23-Nov-2008			
	Eff: 05-Jul-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-73-63029		Replacement of Fuel Manifold Assembly								Category 7	
	73 ENG1						Mos	14-Nov-2008			
	Eff: 01-Oct-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-73-63029		Replacement of Fuel Manifold Assembly								Category 7	
	73 ENG2						Mos	23-Nov-2008			
	Eff: 01-Oct-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-73-63030		Modification/Replacement Of Electrical Wiring Harness -								Category 7	
	73 ENG1						Mos	14-Nov-2008			
	Eff: 16-Nov-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-73-63030		Modification/Replacement Of Electrical Wiring Harness -								Category 7	
	73 ENG2						Mos	23-Nov-2008			
	Eff: 16-Nov-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-73-63036		Replacement of Fuel Drain Valve Adapter								Category 7	
	73 ENG1						Mos	14-Nov-2008			
	Eff: 14-Dec-2007 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-73-63036		Replacement of Fuel Drain Valve Adapter								Category 7	
	73 ENG2						Mos	23-Nov-2008			
	Eff: 14-Dec-2007 Complied With	at Manufacture					Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-73-63038		Replacement of Fuel Oil Heat Exchanger (FOHE)								Category 7	
	73 ENG1						Mos	14-Nov-2008			
	Eff: 03-Apr-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-73-63038		Replacement of Fuel Oil Heat Exchanger (FOHE)								Category 7	
	73 ENG2						Mos	23-Nov-2008			
	Eff: 03-Apr-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-73-63048		Replacement/Modification of Fuel Metering Unit								Category 7	
	73 ENG1						Mos	14-Nov-2008			
	Eff: 06-Mar-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-73-63048		Replacement/Modification of Fuel Metering Unit								Category 7	
	73 ENG2						Mos	23-Nov-2008			
	Eff: 06-Mar-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
PW600-73-63049		Replacement of Fuel-Shut-Off Lever Support								Category 7	
	73 ENG1						Mos	14-Nov-2008			
	Eff: 04-Mar-2008 Complied With	Complied with during Manufacturing					Hrs	0			
							Enc	0			
PW600-73-63049		Replacement of Fuel-Shut-Off Lever Support								Category 7	
	73 ENG2						Mos	23-Nov-2008			
	Eff: 04-Mar-2008 Complied With	at Manufacture					Hrs	0			
							Enc	0			
SL510-73-01A		Transmittal of Pratt & Whitney Canada Alert Service Bulletin A63069 Titled, Turbofan Engine Fuel Oil Heat Exchanger (FOHE) Fuel-Filter Bypass Valve								Mandatory	
	73 A/F						Mos	21-Oct-2009			
	Eff: 30-Nov-2009 Complied With	ASL510-73-01 COMPLIED WITH VIA APPLICATION OF SB63069					Hrs	788			
							Ldg	656			
SL510-73-02A		Transmittal of Pratt & Whitney Canada Service Bulletin A63071 - Turbofan Engine Fuel Oil Heat Exchanger (FOHE) Fuel-Filter Bypass Valve - Replacement								Mandatory	
	73 A/F						Mos	11-Feb-2010			
	Eff: 09-Feb-2010 Complied With	ASL510-73-02 COMPLIED WITH VIA APPLICATION OF PWC SB63071 R1.					Hrs	954			
							Ldg	806			
▼ 74 - IGNITION											
		Igniter Cable								RE (O/C)	
	74 ENG1	Left					Mos				
	Unknown						Hrs				
	Unknown						Enc				
		Igniter Cable								RE (O/C)	
	74 ENG2	Left					Mos	17-May-2023			
	35C0844-01	Tested/Inspected					Hrs	3,581.5			
	WDA107744						Enc	3,171			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	74 ENG1 Unknown Unknown	Igniter Cable Right								RE (O/C)		
							Mos					
							Hrs					
							Enc					
	74 ENG2 35C0799-01 WDA107684	Igniter Cable Right Tested/Inspected								RE (O/C)		
							Mos	17-May-2023				
							Hrs	3,581.5				
							Enc	3,171				
	74 ENG1 35C5472-01 WDA107469	Ignition Exciter Tested/Inspected								RE (O/C)		
							Mos	18-May-2023				
			3,898.8	0	0		Hrs	3,898.8				
			2,711	0	0		Enc	2,711				
	74 ENG2 35C5472-01 WDA107453	Ignition Exciter Tested/Inspected								RE (O/C)		
							Mos	17-May-2023				
							Hrs	3,581.5				
							Enc	3,171				
	74 ENG1 Unknown Unknown	Spark Igniter Inboard New								RE (O/C)		
							Mos	18-May-2023				
							Hrs	3,898.8				
							Enc	2,711				
	74 ENG2 35C2353-02	Spark Igniter Inboard New								RE (O/C)		
							Mos	17-May-2023				
							Hrs	3,581.5				
							Enc	3,171				
	74 ENG1 Unknown Unknown	Spark Igniter Outboard New								RE (O/C)		
							Mos	18-May-2023				
							Hrs	3,898.8				
							Enc	2,711				
	74 ENG2 Unknown Unknown	Spark Igniter Outboard New								RE (O/C)		
							Mos	17-May-2023				
							Hrs	3,581.5				
							Enc	3,171				
	74-PW615F-001	Ignition System - Ignition Exciter - Make sure it is properly attached. Examine general condition.								RE	EMM - Requirement	≈17-Dec-2023
	74 ENG1 35C5472-01 WDA107469 (SOURCE: EMM 05-20-00)	Pkg 450 Hour/12 Month					Mos	07-Jun-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)	
							Hrs	3,898.8	450	-/+10% (4,348.8)	71.3 Hrs (+45)	
							Enc	2,711				
	74-PW615F-001	Ignition System - Ignition Exciter - Make sure it is properly attached. Examine general condition.								RE	EMM - Requirement	≈17-Dec-2023
	74 ENG2 35C5472-01 WDA107453 (SOURCE: EMM 05-20-00)	Pkg 450 Hour/12 Month					Mos	17-May-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)	
							Hrs	3,581.5	450	-/+10% (4,031.6)	71.3 Hrs (+45)	
							Enc	3,171				
	74-PW615F-002	Ignition System - Ignition Cables - Make sure they are properly attached. Examine for chafing, wear and security.								RE	EMM - Requirement	≈17-Dec-2023
	74 ENG1 Ref.:74-20-01, Task:74-20-01-210-801 (SOURCE: EMM 05-20-00)	Pkg 450 Hour/12 Month					Mos	18-May-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)	
							Hrs	3,898.8	450	-/+10% (4,348.8)	71.3 Hrs (+45)	
							Enc	2,711				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
74-PW615F-002	 74 ENG2	Ignition System - Ignition Cables - Make sure they are properly attached. Examine for chafing, wear and security. Pkg 450 Hour/12 Month Ref.:74-20-01, Task:74-20-01-210-801 (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
						Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
						Hrs	3,581.5	450	-/+10%	(4,031.6)	71.3 Hrs (+45)
						Enc	3,171				
74-PW615F-003	 74 ENG1	Ignition System - Spark Igniters - Examine for cleanliness and erosion. Pkg 450 Hour/12 Month Ref.:74-20-02, Task:74-20-02-220-801 (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
						Mos	18-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
						Hrs	3,898.8	450	-/+10%	(4,348.8)	71.3 Hrs (+45)
						Enc	2,711				
74-PW615F-003	 74 ENG2	Ignition System - Spark Igniters - Examine for cleanliness and erosion. Pkg 450 Hour/12 Month Ref.:74-20-02, Task:74-20-02-220-801 (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
						Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
						Hrs	3,581.5	450	-/+10%	(4,031.6)	71.3 Hrs (+45)
						Enc	3,171				
74-PW615F-004	 74 ENG1	Ignition System - Spark Igniters - Do an operational test. Pkg 450 Hour/12 Month Ref.:74-20-01, Task:74-00-01-720-801 (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
						Mos	18-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
						Hrs	3,898.8	450	-/+10%	(4,348.8)	71.3 Hrs (+45)
						Enc	2,711				
74-PW615F-004	 74 ENG2	Ignition System - Spark Igniters - Do an operational test. Pkg 450 Hour/12 Month Ref.:74-20-01, Task:74-00-01-720-801 (SOURCE: EMM 05-20-00)						RE		EMM - Requirement	≈17-Dec-2023
						Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
						Hrs	3,581.5	450	-/+10%	(4,031.6)	71.3 Hrs (+45)
						Enc	3,171				
74-PW615F-005	 74 ENG1 35C5472-01 WDA107469	Ignition Exciter - Do a General Visual Inspection and send it to Vendor for Overhaul if needed (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
						Mos	18-May-2023				
						Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
						Enc	2,711				
74-PW615F-005	 74 ENG2 35C5472-01 WDA107453	Ignition Exciter - Do a General Visual Inspection and send it to Vendor for Overhaul if needed (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
						Mos	17-May-2023				
						Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
						Enc	3,171				
74-PW615F-006	 74 ENG1 Unknown Unknown Ref:74-20-01-720-801, Ref:74-20-01-210-801	Ignition Cables - Do a Visual Inspection and Functional Test (at Engine Overhaul) Left						RE		LMM - Requirement	≈22-Feb-2029
						Mos	18-May-2023				
						Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
						Enc	2,711				
74-PW615F-006	 74 ENG2 35C0844-01 WDA107744 Ref:74-20-01-720-801, Ref:74-20-01-210-801	Ignition Cables - Do a Visual Inspection and Functional Test (at Engine Overhaul) Left						RE		LMM - Requirement	≈22-Feb-2029
						Mos	17-May-2023				
						Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
						Enc	3,171				
74-PW615F-007	 74 ENG1 Unknown Unknown Ref:74-20-01-210-801, Ref:74-20-01-720-801	Ignition Cables - Do a Visual Inspection and Functional Test (at Engine Overhaul) Right						RE		LMM - Requirement	≈22-Feb-2029
						Mos	18-May-2023				
						Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
						Enc	2,711				

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
74-PW615F-007		Ignition Cables - Do a Visual Inspection and Functional Test (at Engine Overhaul)								RE	LMM - Requirement	≈22-Feb-2029
	74 ENG2	Right					Mos	17-May-2023				
	35C0799-01						Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
	WDA107684						Enc	3,171				
	Ref:74-20-01-210-801, Ref:74-20-01-720-801											
74-PW615F-008		Spark Igniter - Visual Inspection (at Engine Overhaul)								RE	LMM - Requirement	≈22-Feb-2029
	74 ENG1	Inboard					Mos	18-May-2023				
	Unknown						Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
	Unknown						Enc	2,711				
	Ref:74-20-02-220-801											
74-PW615F-008		Spark Igniter - Visual Inspection (at Engine Overhaul)								RE	LMM - Requirement	≈22-Feb-2029
	74 ENG2	Inboard					Mos	17-May-2023				
	35C2353-02						Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
							Enc	3,171				
	Ref:74-20-02-220-801											
74-PW615F-009		Spark Igniter - Visual Inspection (at Engine Overhaul)								RE	LMM - Requirement	≈22-Feb-2029
	74 ENG1	Outboard					Mos	18-May-2023				
	Unknown						Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
	Unknown						Enc	2,711				
	Ref:74-20-02-220-801											
74-PW615F-009		Spark Igniter - Visual Inspection (at Engine Overhaul)								RE	LMM - Requirement	≈22-Feb-2029
	74 ENG2	Outboard					Mos	17-May-2023				
	Unknown						Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
	Unknown						Enc	3,171				
	Ref:74-20-02-220-801											
PW600-74-63056		Replacement of Ignition Exciter								RE (-)	Category 7	
	74 ENG1						Mos	14-Nov-2008				
	Eff: 31-Oct-2008 Complied With	Complied with during Manufacturing					Hrs	0				
							Enc	0				
PW600-74-63056		Replacement of Ignition Exciter								RE (-)	Category 7	
	74 ENG2						Mos	23-Nov-2008				
	Eff: 31-Oct-2008 Complied With	at Manufacture					Hrs	0				
							Enc	0				
▼ 75 - BLEED AIR												
		Bleed Valve Actuator					RE (O/C)					
	75 ENG1						Mos	18-May-2023				
	8100-0028	Tested/Inspected					Hrs	3,898.8				
	16167408						Enc	2,711				
		Bleed Valve Actuator					RE (O/C)					
	75 ENG2						Mos	17-May-2023				
	8100-0028	Tested/Inspected					Hrs	3,581.5				
	16139461						Enc	3,171				
75-PW615F-001		Air System - Bleed Valve Actuator Assembly - Make sure electrical connections of bleed valve actuator are properly attached. Examine them for fraying and corrosion.								RE	EMM - Requirement	≈17-Dec-2023
	75 ENG1	Pkg 450 Hour/12 Month					Mos	07-Jun-2023	12	-/+30d (07-Jun-2024)	6.8 Months (+30 Days)	
	(SOURCE: EMM 05-20-00) (NOTE: A small amount of lubricant leakage from the BVA linkage rod-end bearings is acceptable and may be removed with a clean cloth.)						Hrs	3,898.8	450	-/+10% (4,348.8)	71.3 Hrs (+45)	
							Enc	2,711				

Task No		Description								Categories	Time			
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining			
75-PW615F-001		Air System - Bleed Valve Actuator Assembly - Make sure electrical connections of bleed valve actuator are properly attached. Examine them for fraying and corrosion.								RE	EMM - Requirement	≈17-Dec-2023		
	75 ENG2	Pkg 450 Hour/12 Month					Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)		
	(SOURCE: EMM 05-20-00) (NOTE: A small amount of lubricant leakage from the BVA linkage rod-end bearings is acceptable and may be removed with a clean cloth.)						Hrs	3,581.5	450	-/+10%	(4,031.6)	71.3 Hrs (+45)		
							Enc	3,171						
75-PW615F-002		Bleed Valve Actuator - Inspection / Overhaul (at Engine Overhaul)								RE	EMM - Requirement	≈22-Feb-2029		
	75 ENG1						Mos	18-May-2023						
	8100-0028						Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)		
	16167408						Enc	2,711						
75-PW615F-002		Bleed Valve Actuator - Inspection / Overhaul (at Engine Overhaul)								RE	EMM - Requirement	≈22-Feb-2029		
	75 ENG2						Mos	17-May-2023						
	8100-0028						Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)		
	16139461						Enc	3,171						
PW600-75-63054		Replacement of Bleed Valve Actuator (BVA)								RE (-)	Category 7			
	75 ENG1						Mos	14-Nov-2008						
	Eff: 20-Jun-2008 Complied With	Complied with during Manufacturing					Hrs	0						
							Enc	0						
PW600-75-63054		Replacement of Bleed Valve Actuator (BVA)								RE (-)	Category 7			
	75 ENG2						Mos	23-Nov-2008						
	Eff: 20-Jun-2008 Complied With	at Manufacture					Hrs	0						
							Enc	0						
Reliability-75-001		Adjustment of Bleed Valve								RE (A/R)				
	75 ENG1						Mos	07-Jun-2023						
							Hrs	3,898.8						
							Enc	2,711						
Reliability-75-001		Adjustment of Bleed Valve								RE (A/R)				
	75 ENG2						Mos							
							Hrs							
							Enc							
▼ 76 - ENGINE CONTROLS														
		Throttle Lever Assembly								RE (-)				
	76 A/F						Mos	07-Jun-2021						
	Not Installed						Hrs	8,733						
	Not Installed						Ldg	7,019						
		Engine Electronic Control (EEC)								RE (O/C)				
	76 ENG1						Mos	07-Jun-2023						
	35C4035-03	Tested/Inspected					Hrs	3,898.8						
	08-505						Enc	2,711						
		Engine Electronic Control (EEC)								RE (O/C)				
	76 ENG2						Mos	17-May-2023						
	8237-1217-1	Tested/Inspected					Hrs	3,581.5						
	09-613						Enc	3,171						
B761000		FADEC Time Limited Dispatch (TLD) Fault Operational Check								RE	Inspection Time Limits	≈17-Dec-2023		
	76 A/F	05-12-31					Mos	07-Jun-2023						
							Hrs	9,471.8	450	(9,921.8)	71.3 Hrs			
	Task:76-10-10-710 (ZONE: 224) (SOURCE: Model 510 Maintenance Manual)						Ldg	7,591						

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SB510-76-01	Transmittal of Pratt & Whitney Canada Service Bulletin PW600-72-63087 Revision 1						RE (-)		Mandatory	
 76 A/F					Mos	01-Oct-2012				
Complied With	PERFORMED SB510-76-01				Hrs	3,194.1				
					Ldg	2,679				
SB510-76-01 R01	Transmittal of Pratt & Whitney Canada Service Bulletin PW600-72-63087 Revision 1						RE (-)		Mandatory	
 76 A/F					Mos	01-Oct-2012				
Complied With	PERFORMED SB510-76-01 R1				Hrs	3,194.1				
					Ldg	2,679				
SB510-76-01 R02	Transmittal of Pratt & Whitney Canada Service Bulletin PW600-72-63087 Revision 1						RE (-)		Mandatory	
 76 A/F					Mos	01-Oct-2012				
Eff: 04-Sep-2012 Complied With	PERFORMED SB510-76-01 R2				Hrs	3,194.1				
					Ldg	2,679				
▼ 77 - ENGINE INDICATING										
77-PW615F-001	Engine - T6 Thermocouple Wiring Harness Assembly - Do the functional tests.						RE	EMM - Requirement, Extended TBO		≈06-Apr-2026
 77 ENG1					Mos	18-May-2023				
Task:77-20-02-720-801 (SOURCE: EMM 05-20-00)					Hrs	3,898.8	2,250	+50	6,148.8	1,871.3 Hrs (+50)
					Enc	2,711				
77-PW615F-001	Engine - T6 Thermocouple Wiring Harness Assembly - Do the functional tests.						RE	EMM - Requirement, Extended TBO		≈06-Apr-2026
 77 ENG2					Mos	17-May-2023				
Task:77-20-02-720-801 (SOURCE: EMM 05-20-00) (NOTE: At scheduled HIS interval - Engine following the Extended TBO program)					Hrs	3,581.5	2,250	+50	5,831.5	1,871.2 Hrs (+50)
					Enc	3,171				
77-PW615F-002	T6 Thermocouple Harness Assembly - Visual Inspection and Functional Test (at Engine Overhaul)						RE	LMM - Requirement		≈22-Feb-2029
 77 ENG1					Mos	18-May-2023				
Ref:77-20-02-720-801, Ref:77-20-02-210-801					Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
					Enc	2,711				
77-PW615F-002	T6 Thermocouple Harness Assembly - Visual Inspection and Functional Test (at Engine Overhaul)						RE	LMM - Requirement		≈22-Feb-2029
 77 ENG2					Mos	17-May-2023				
Ref:77-20-02-720-801, Ref:77-20-02-210-801					Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
					Enc	3,171				
PW600-77-63033	Replacement of T6 Thermocouple Wiring Harness						RE (-)		Category 8	
 77 ENG1					Mos	14-Nov-2008				
Eff: 19-Oct-2007 Complied With	Complied with during Manufacturing				Hrs	0				
					Enc	0				
PW600-77-63033	Replacement of T6 Thermocouple Wiring Harness						RE (-)		Category 8	
 77 ENG2					Mos	23-Nov-2008				
Eff: 19-Oct-2007 Complied With	at Manufacture				Hrs					
					Enc					
▼ 79 - OIL										
	Air Cooled Oil Cooler						RE (O/C)			
 79 ENG1					Mos					
Unknown					Hrs					
Unknown					Enc					
	Air Cooled Oil Cooler						RE (O/C)			
 79 ENG2					Mos	17-May-2023				
10941J	Tested/Inspected				Hrs	3,581.5				
WA34447					Enc	3,171				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Chip Collector								RE (O/C)	
	79 ENG1	Unknown Unknown									
		Chip Collector								RE (O/C)	
	79 ENG2	35C0412-01 AB1163									
		Fuel To Oil Heat Exchanger								RE (O/C)	
	79 ENG1	10940J WA34494									
		Fuel To Oil Heat Exchanger								RE (O/C)	
	79 ENG2	10940J WA34522									
		LP Compressor Case Nos. 1,2,3 Bearings Oil Tube								RE (O/C)	
	79 ENG1	Unknown Unknown									
		LP Compressor Case Nos. 1,2,3 Bearings Oil Tube								RE (O/C)	
	79 ENG2	Unknown Unknown									
		Oil Filter Impending Bypass Indicator								RE (O/C)	
	79 ENG1	35C4333-01 WDA01982									
		Oil Filter Impending Bypass Indicator								RE (O/C)	
	79 ENG2	35C4333-01 WDA8119									
		Oil Pressure Transmitter								RE (O/C)	
	79 A/F	APTE-304A-250G 7473-12-820									
		Oil Pressure Transmitter								RE (O/C)	
	79 A/F	APTE-304A-250G 7358-11-220									
		510-79-03 Oil - Oil Pressure Transducer Replacement								T (A/R)	Optional
	79 A/F	Eff: 09-Aug-2017 On Hold (NOTE: 26th March 2019)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-CUS-100		Complete Oil Analysis Technology program (C.O.A.T)						RE		Custom Task	≈23-Dec-2023
	79 ENG1					Mos	07-Jun-2023	6	-/+30d	31-Dec-2023	45 Days (+30)
		(Extension Adjustment: 237.5 Hrs) (NOTE: Pre-requisite for HSI extension)				Hrs	3,898.8	225	-/+10%	4,361.3	83.8 Hrs (+22.5)
						Enc	2,711				
79-CUS-100		Complete Oil Analysis Technology program (C.O.A.T)						RE		Custom Task	≈23-Dec-2023
	79 ENG2					Mos	07-Jun-2023	6	-/+30d	31-Dec-2023	45 Days (+30)
		(Extension Adjustment: 237.5 Hrs) (NOTE: Pre-requisite for HSI extension)				Hrs	3,581.6	225	-/+10%	4,044.1	83.8 Hrs (+22.5)
						Enc	3,171				
79-CUS-200		Check P/N and S/N of the Fuel Oil Heat Exchanger (FOHE)						RE (-)		Customer Convenience	
	79 ENG1					Mos					
						Hrs					
						Enc					
79-CUS-200		Check P/N and S/N of the Fuel Oil Heat Exchanger (FOHE)						RE (-)		Customer Convenience	
	79 ENG2					Mos					
						Hrs					
						Enc					
79-PW615F-001		Oil System - Oil Quantity - Do a visual check of the oil level and fill if required.						RE (Daily)		EMM - Requirement	
	79 ENG1					Mos	18-May-2023				
		Ref.:72-00-00, Task:72-00-00-640-804 (SOURCE: EMM 05-20-00)				Hrs	3,898.8				
						Enc	2,711				
79-PW615F-001		Oil System - Oil Quantity - Do a visual check of the oil level and fill if required.						RE (Daily)		EMM - Requirement	
	79 ENG2					Mos	17-May-2023				
		Ref.:72-00-00, Task:72-00-00-640-804 (SOURCE: EMM 05-20-00) (NOTE: Make sure the oil tank filler cap is properly attached. Examine general condition.)				Hrs	3,581.5				
						Enc	3,171				
79-PW615F-002		Oil System - Engine Oil Change Interval						RE (A/R)		EMM - Requirement	
	79 ENG1					Mos	18-May-2023				
		Ref.:72-00-00, Task:72-00-00-280-801 (SOURCE: EMM 05-20-00) (NOTE: Oil quantity is to be minotored on condition and analyzed.)				Hrs	3,898.8				
						Enc	2,711				
79-PW615F-002		Oil System - Engine Oil Change Interval						RE (A/R)		EMM - Requirement	
	79 ENG2					Mos	17-May-2023				
		Ref.:72-00-00, Task:72-00-00-280-801 (SOURCE: EMM 05-20-00) (NOTE: Oil quantity is to be minotored on condition and analyzed.)				Hrs	3,581.5				
						Enc	3,171				
79-PW615F-003		Oil System - Oil Filter Element - Replace the oil filter element						RE		EMM - Requirement	≈13-Jul-2024
	79 ENG1					Mos	18-May-2023				
		Ref.:79-20-01, Task:79-20-01-400-801, Task:79-20-01-000-801 (SOURCE: EMM 05-20-00)				Hrs	3,898.8	900	-/+10%	4,798.8	521.3 Hrs (+90)
						Enc	2,711				
79-PW615F-003		Oil System - Oil Filter Element - Replace the oil filter element						RE		EMM - Requirement	≈13-Jul-2024
	79 ENG2					Mos	07-Jun-2023				
		Ref.:79-20-01, Task:79-20-01-400-801, Task:79-20-01-000-801 (SOURCE: EMM 05-20-00)				Hrs	3,581.6	900	-/+10%	4,481.6	521.3 Hrs (+90)
						Enc	3,171				
79-PW615F-004		Oil System - Chip Collector - Remove and Examine for Metallic Debris						RE		EMM - Requirement	≈17-Dec-2023
	79 ENG1					Mos	07-Jun-2023	12	-/+30d	07-Jun-2024	6.8 Months (+30 Days)
	Unknown					Hrs	3,898.8	450	-/+10%	4,348.8	71.3 Hrs (+45)
	Unknown	Ref:79-30-01-400-002 , Ref:79-30-01-000-001 (SOURCE: EMM 05-20-00) (NOTE: Post SB 63110:Every 450 flight hours or once a year, whichever occurs first.)				Enc	2,711				
79-PW615F-004		Oil System - Chip Collector - Remove and Examine for Metallic Debris						RE		EMM - Requirement	≈17-Dec-2023
	79 ENG2					Mos	07-Jun-2023	12	-/+30d	07-Jun-2024	6.8 Months (+30 Days)
	35C0412-01					Hrs	3,581.6	450	-/+10%	4,031.6	71.3 Hrs (+45)
	AB1163	Ref:79-30-01-400-002 , Ref:79-30-01-000-001 (SOURCE: EMM 05-20-00) (NOTE: Post SB 63110:Every 450 flight hours or once a year, whichever occurs first.)				Enc	3,171				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-PW615F-005		Oil System - Chip Collector - Examine for General Condition and do a functional check						RE		EMM - Requirement	≈17-Dec-2023
	79 ENG1	Pkg 450 Hour/12 Month				Mos	18-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
	Unknown					Hrs	3,898.8	450	-/+10%	(4,348.8)	71.3 Hrs (+45)
	Unknown					Enc	2,711				
Ref:79-30-01-210-801, Ref:79-30-01-720-801 (SOURCE: EMM 05-20-00)											
79-PW615F-005		Oil System - Chip Collector - Examine for General Condition and do a functional check						RE		EMM - Requirement	≈17-Dec-2023
	79 ENG2	Pkg 450 Hour/12 Month				Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
	35C0412-01					Hrs	3,581.5	450	-/+10%	(4,031.6)	71.3 Hrs (+45)
	AB1163					Enc	3,171				
Ref:79-30-01-210-801, Ref:79-30-01-720-801 (SOURCE: EMM 05-20-00)											
79-PW615F-006		Oil System - Oil Filter Impending Bypass Indicator Popup Button - Do a Visual Inspection.						RE		EMM - Requirement	≈17-Dec-2023
	79 ENG1	Pkg 450 Hour/12 Month,....				Mos	07-Jun-2023	12	-/+30d	≠07-Jun-2024	
						Hrs	3,898.8	450	-/+10%	≠4,348.8	
						Enc	2,711				
Task:79-30-02-210-802 (SOURCE: EMM 05-20-00)											
79-PW615F-006		Oil System - Oil Filter Impending Bypass Indicator Popup Button - Do a Visual Inspection.						RE		EMM - Requirement	≈17-Dec-2023
	79 ENG2	Pkg 450 Hour/12 Month,....				Mos	17-May-2023	12	-/+30d	≠17-May-2024	
						Hrs	3,581.5	450	-/+10%	≠4,031.5	
						Enc	3,171				
Task:79-30-02-210-802 (SOURCE: EMM 05-20-00)											
79-PW615F-007		Oil System - Oil Filter Impending Bypass Indicator - Do a Detail Inspection						RE		EMM - Requirement	≈17-Dec-2023
	79 ENG1	Pkg 450 Hour/12 Month				Mos	07-Jun-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
						Hrs	3,898.8	450	-/+10%	(4,348.8)	71.3 Hrs (+45)
						Enc	2,711				
Task:79-30-02-215-801 (SOURCE: EMM 05-20-00)											
79-PW615F-007		Oil System - Oil Filter Impending Bypass Indicator - Do a Detail Inspection						RE		EMM - Requirement	≈17-Dec-2023
	79 ENG2	Pkg 450 Hour/12 Month				Mos	17-May-2023	12	-/+30d	(07-Jun-2024)	6.8 Months (+30 Days)
						Hrs	3,581.5	450	-/+10%	(4,031.6)	71.3 Hrs (+45)
						Enc	3,171				
Task:79-30-02-215-801 (SOURCE: EMM 05-20-00)											
79-PW615F-008		Oil System - No.4 Bearing Front Carbon Seal - Replace						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
	79 ENG1					Mos	18-May-2023				
						Hrs	3,898.8	2,250	+50	6,148.8	1,871.3 Hrs (+50)
						Enc	2,711				
Task:72-30-04-000-803 (SOURCE: EMM 05-20-00)											
79-PW615F-008		Oil System - No.4 Bearing Front Carbon Seal - Replace						RE		EMM - Requirement, Extended TBO	≈06-Apr-2026
	79 ENG2					Mos	17-May-2023				
						Hrs	3,581.5	2,250	+50	5,831.5	1,871.2 Hrs (+50)
						Enc	3,171				
Task:72-30-04-000-803 (SOURCE: EMM 05-20-00) (NOTE: At scheduled HSI interval - Engine following the Extended TBO program)											
79-PW615F-009		Air Cooled Oil Cooler - Inspection / Overhaul (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	79 ENG1					Mos	18-May-2023				
	Unknown					Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
	Unknown					Enc	2,711				
79-PW615F-009		Air Cooled Oil Cooler - Inspection / Overhaul (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	79 ENG2					Mos	17-May-2023				
	10941J					Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
	WA34447					Enc	3,171				
79-PW615F-010		Fuel-To-Oil Heat Exchanger (F.O.H.E.) - Send To Supplier For Overhaul (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	79 ENG1					Mos	18-May-2023				
	10940J					Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
	WA34494					Enc	2,711				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-PW615F-010		Fuel-To-Oil Heat Exchanger (F.O.H.E.) - Send To Supplier For Overhaul (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	79 ENG2					Mos	17-May-2023				
	10940J					Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
	WA34522					Enc	3,171				
79-PW615F-011		Chip Collector - Do a Visual Inspection and a Functional Test (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	79 ENG1					Mos	18-May-2023				
	Unknown					Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
	Unknown					Enc	2,711				
		Ref:79-30-01-720-801, Ref:79-30-01-210-801									
79-PW615F-011		Chip Collector - Do a Visual Inspection and a Functional Test (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	79 ENG2					Mos	17-May-2023				
	35C0412-01					Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
	AB1163					Enc	3,171				
		Ref:79-30-01-720-801, Ref:79-30-01-210-801									
79-PW615F-012		Oil Filter Impending Bypass Indicator - Do a Visual Inspection and a Functional Test (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	79 ENG1					Mos	18-May-2023				
	35C4333-01					Hrs	3,898.8	4,500	+100	8,398.8	4,121.3 Hrs (+100)
	WDA01982					Enc	2,711				
		Ref:73-30-01-720-801, Ref:79-30-02-215-801									
79-PW615F-012		Oil Filter Impending Bypass Indicator - Do a Visual Inspection and a Functional Test (at Engine Overhaul)						RE		LMM - Requirement	≈22-Feb-2029
	79 ENG2					Mos	17-May-2023				
	35C4333-01					Hrs	3,581.5	4,500	+100	8,081.5	4,121.2 Hrs (+100)
	WDA8119					Enc	3,171				
		Ref:73-30-01-720-801, Ref:79-30-02-215-801									
PW600-72-63076 R1		Replacement/Modification of Oil Filler And Indicator Assembly						RE (-)		Category 7	
	79 ENG2					Mos	17-May-2023				
	Eff: 29-Apr-2016 Complied With					Hrs	3,581.5				
	(AVG MAN HRS: 1.5)					Enc	3,171				
PW600-79-63008		Replacement of Oil Pump Housing And Spur Gears						RE (-)		Category 5	
	79 ENG1					Mos	14-Nov-2008				
	Eff: 16-Feb-2007 Complied With	Complied with during Manufacturing				Hrs	0				
						Enc	0				
PW600-79-63008		Replacement of Oil Pump Housing And Spur Gears						RE (-)		Category 5	
	79 ENG2					Mos	23-Nov-2008				
	Eff: 16-Feb-2007 Complied With	at Manufacture				Hrs	0				
						Enc	0				
PW600-79-63015		Replacement/Modification of Air Cooled Oil Cooler						RE (-)		Category 7	
	79 ENG1					Mos	14-Nov-2008				
	Eff: 08-Aug-2007 Complied With	Complied with during Manufacturing				Hrs	0				
						Enc	0				
PW600-79-63015		Replacement/Modification of Air Cooled Oil Cooler						T (A/R)		Category 7	
	79 ENG2					Mos	23-Nov-2008				
	Eff: 08-Aug-2007 Complied With	at Manufacture				Hrs	0				
						Enc	0				
PW600-79-63046		Replacement of Oil Filter Impending Bypass Switch						RE (-)		Category 7	
	79 ENG1					Mos	14-Nov-2008				
	Eff: 04-Feb-2008 Complied With	Complied with during Manufacturing				Hrs	0				
						Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
PW600-79-63046		Replacement of Oil Filter Impending Bypass Switch								Category 7	
	79 ENG2						Mos	23-Nov-2008	T (A/R)		
	Eff: 04-Feb-2008 Complied	at Manufacture					Hrs	0			
	With						Enc	0			
PW600-79-63047		Replacement of Air-Cooled Oil-Cooler Pressure-Oil-Tube Bolts								Category 3	
	79 ENG1						Mos	14-Nov-2008	RE (-)		
	Eff: 21-Dec-2007 Complied	Complied with during Manufacturing					Hrs	0			
	With						Enc	0			
PW600-79-63047		Replacement of Air-Cooled Oil-Cooler Pressure-Oil-Tube Bolts								Category 3	
	79 ENG2						Mos	23-Nov-2008	RE (-)		
	Eff: 21-Dec-2007 Complied	at Manufacture					Hrs	0			
	With						Enc	0			
PW600-79-63076 R1		Replacement/Modification of Oil Filler And Indicator Assembly								Category 7	
	79 ENG1						Mos	18-May-2023	RE (-)		
	Eff: 29-Apr-2016 Complied	Complied during OH					Hrs	3,898.8			
	With						Enc	2,711			
		(AVG MAN HRS: 1.5)									
Reliability-79-001		LH Engine Clamp P/N: MS21919WDF16 replacement i.a.w. Model 510 Maintenance Manual Ch. 79-30-00. Post replacement make sure that static port on Oil pressure sensor is free and not covered by clamp								RE (-)	
	79 A/F						Mos				
							Hrs				
							Ldg				
Reliability-79-002		RH Engine Clamp P/N: MS21919WDF16 replacement i.a.w. Model 510 Maintenance Manual Ch. 79-30-00. Post replacement make sure that static port on Oil pressure sensor is free and not covered by clamp.								RE (-)	
	79 A/F						Mos				
							Hrs				
							Ldg				
SB510-79-02		Oil Temperature Probe O-Ring Replacement								Recommended	
	79 A/F						Mos		RE (-)		
	Eff: 22-Feb-2008 Not	by S/N					Hrs				
	Applicable						Ldg				
		(NOTE: 26th March 2019)									
SL510-79-01		Oil Pressure Transmitter Inspection								Mandatory	
	79 A/F						Mos	14-Sep-2009	RE (-)		
	Eff: 20-Jul-2009 Complied With						Hrs	725			
							Ldg				
SL510-79-02		Oil Pressure Transmitter Connection Inspection								Mandatory	
	79 A/F						Mos	03-May-2011	RE (-)		
	Eff: 17-Mar-2011 Complied	PERFORMED OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION SERVICE LETTER					Hrs	2,198			
	With						Ldg	1,848			
▼ 80 - STARTING											
		Starter/Generator								Component Time Limits	≈20-Apr-2025
	80 A/F	Left					Mos	07-Jun-2023	RE		
	9912676-1	Overhauled					Hrs	9,471.8	1,500	10,971.8	1,121.3 Hrs
	438D						Ldg	7,591			
		MM:5-11-00 (AVG MAN HRS: 0) (APX COST: 2,625.14) (SOURCE: Model 510 Maintenance Manual)									

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
		Starter/Generator								RE	Component Time Limits	≈20-Apr-2025
	80 A/F	Right					Mos	07-Jun-2023				
	9912676-1	Overhauled	0	0	0	Hrs	9,471.8	1,500	10,971.8		1,121.3 Hrs	
	477D						Ldg	7,591				
MM:5-11-00 (AVG MAN HRS: 0) (APX COST: 2,687.84) (SOURCE: Model 510 Maintenance Manual)												
SL510-80-01		Engine Starting								T (A/R)	Informational	
	80 A/F						Mos					
	Eff: 08-Jun-2009	NOTED					Hrs					
	(NOTE: 26th March 2019)						Ldg					
SL510-80-02		Starting - Starter/Generator Replacement Program								T (A/R)	Recommended	
	80 A/F						Mos					
	Eff: 05-Mar-2019	Complied Starter generator installed: Mode D					Hrs					
	With						Ldg					
(AVG MAN HRS: 3) (NOTE: 26th March 2019)												
▼ 99 - --												
CIL-99-01		Use of Corrosion Inhibiting Compounds								RE (-)	Informational	
	99 A/F						Mos					
	Eff: 12-Jan-2012	Superseded SUPERSEDED BY REVISION 1					Hrs					
	(NOTE: 8th January 2019)						Ldg					
CIL-99-01 R1		Use of Corrosion Inhibiting Compounds								T (-)	Service Letter	
	99 A/F						Mos					
	Eff: 15-Feb-2013	Superseded SUPERSEDED BY REVISION 2					Hrs					
	(NOTE: 8th January 2019)						Ldg					
CIL-99-01 R2		Use of Corrosion Inhibiting Compounds								T (-)	Service Letter	
	99 A/F						Mos					
	Eff: 02-Jul-2015	NOTED					Hrs					
	(NOTE: 26th March 2019)						Ldg					
CIL-99-01 R3		Use of Corrosion Inhibiting Compounds (Cancels this Service Letter)								RE (-)	Service Letter	
	99 A/F						Mos					
	Eff: 14-Aug-2019						Hrs					
CIL-99-02 R1		Avoid Operations on Runways Treated with Runway De-Ice (RDI) Fluids. Aircraft Washing Recommended after Exposure to RDI Fluids - (Cancels this Service Letter)								RE (-)	Service Letter	
	99 A/F						Mos					
	Eff: 14-Aug-2019						Hrs					
CIL-99-03		Corrosion Prevention and Control Program (CPCP)								RE (-)	Recommended	
	99 A/F						Mos					
	Eff: 04-Jan-2013	Superseded SUPERSEDED BY REVISION 1					Hrs					
	(NOTE: 8th January 2019)						Ldg					
CIL-99-03 R2		Miscellaneous - Corrosion Prevention and Control Program (CPCP) (Cancels this Service Letter)								RE (-)	Service Letter	
	99 A/F						Mos					
	Eff: 14-Aug-2019						Hrs					
CIL-99-04 R1		Miscellaneous - Incremental Library Updates For Cesview, Service Letter - (Cancels this Service Letter)								RE (-)	Service Letter	
	99 A/F						Mos					
	Eff: 14-Aug-2019						Hrs					
SL510-99-02		CESCOM Prices - CANCELLED								RE (-)	Informational	
	99 A/F						Mos					
	Superseded	SUPERSEDED BY REVISION 1					Hrs					
	(NOTE: 8th January 2019)						Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL510-99-02 R01	CESCOM Prices - CANCELLED						RE (-)		Informational	
99 A/F										Mos
Superseded	SUPERSEDED BY REVISION 2									Hrs
(NOTE: 8th January 2019)										Ldg
SL510-99-02 R02	CESCOM Prices - CANCELLED						T (A/R)		Informational	
99 A/F										Mos
Eff: 01-Jun-2013 Cancelled										Hrs
										Ldg
SL510-99-03	Tube Assembly Sleeve Inspection						RE (-)		Recommended	
99 A/F										Mos
Eff: 14-Mar-2008 Not Applicable	by S/N									Hrs
(NOTE: 26th March 2019)										Ldg
SL510-99-04	Cessna Part Number Suffixes For Remanufactured Parts						T (A/R)		Informational	
99 A/F										Mos
Eff: 11-Nov-2011	NOTED									Hrs
(NOTE: 26th March 2019)										Ldg
SL510-99-05	Cessna Service Document Change Notification						T (A/R)		Informational	
99 A/F										Mos
Eff: 22-Nov-2011	NOTED									Hrs
(NOTE: 26th March 2019)										Ldg
▼ 100 - GENERAL										
100-CUS-001	Pre-Maintenance Inspection - Acceptance Check						RE (A/R)		Custom Task	
100 A/F										Mos
										Hrs
										Ldg
100-CUS-002	After Maintenance Inspection - Final Check						RE (A/R)		Custom Task	
100 A/F										Mos
										Hrs
										Ldg
CIL-99-02	Avoid Operations on Runways Treated with Runway De-Ice (RDI) Fluids. Aircraft Washing Recommended after Exposure to RDI Fluids						T (-)		Service Letter	
100 A/F										Mos
Eff: 23-May-2012 Not Applicable	IAW no reports from crew									Hrs
(NOTE: 26th March 2019)										Ldg
CIL-99-03 R1	Corrosion Prevention and Control Program (CPCP)						T (-)		Service Letter	
100 A/F										Mos
Eff: 25-Mar-2013 On Hold	Evaluation in progress - refer to AMM									Hrs
(NOTE: 26th March 2019)										Ldg
SIL-PW600-27	PW615F - Recent Field Events						T (A/R)		Service Information Letter	
100 ENG2										Mos
Eff: 24-Nov-2017										Hrs
										Enc