

SiloWrap™ Uni-axial Carbon Fabric (SLW-516-CF)

SiloWrap™ Uni-axial Carbon Fabric SLW-516-CF is a high strength uni-axial carbon fabric used for strengthening concrete and steel structures and is part of the SiloWrap™ Repair System. The fabric is used in conjunction with SiloWrap™ Saturating Polymers.

Benefits

- Restores strength lost due to corrosion
- Increases strength and load capacity of new and long-service life silos
- Reduces coefficient of friction for increased flow
- Abrasion resistant when used in conjunction with ChemSeal™ Protective Coatings & Liners
- FDA compliant per 29 CFR 175.300
- Adds only a 1/16th of an inch to the repaired surface to maximize internal storage space
- High strength per ply = less layers

Typical Data & Physical Properties		
Storage Conditions	Store dry, do not over-stack boxes	
Color	Black	
Tensile Strength - Typical (ASTM D3039)	150,000 psi	1,034 MPa
Tensile Strength - Design (ASTM D3039)	119,400 psi	823 MPa
Modulus of Elasticity - Typical (ASTM D3039)	12,530 ksi	86.3 MPa
Modulus of Elasticity - Design (ASTM D3039)	10,948 ksi	75.5 MPa
Elongation @ Break (ASTM D3039)	1.43%	
Single Ply Thickness	0.051 inches	0.130 cm
Compressive Strength (ASTM D695)	17,200 psi	118.6 MPa
Flexural Strength (ASTM D790)	3,611,000 psi	24,897 MPa
Flexural Modulus (ASTM D790)	3,200,000 psi	22,063 MPa
Shore D Hardness @ 24 hrs (ASTM D2583)	78	



Installation Procedures for SiloWrap™ Uni-axial Carbon (SLW-516-CF)

Design Specifications	
Certified Installer Company Name	
Certified Technician(s)	
HJ3 Design Case #	
Project Name	

Material Handling & Storage						
	Product was stored between 65F and 80F					
	Packing Slip has been verified against order and design calculations					
Record	Primer	Filler	ShapeShift	Saturant	Fabric	Top Coat
ITEM CODE						
QTY						
LOT #'s						
EXP						

Environmental Conditions		
<input type="checkbox"/>	Surface Temperature	Use an infrared thermometer to obtain value and record below: _____(°F) _____(°C)
<input type="checkbox"/>	Ambient Temperature	Use a digital temp gauge to obtain value and record below: _____(°F) _____(°C)
<input type="checkbox"/>	Skin Temperature of Surface > (5F/3C) above Dew Point	
<input type="checkbox"/>	Skin Temp _____(°F) _____(°C) -Dew Point _____(°F) _____(°C)	
<input type="checkbox"/>	= VALUE _____(°F) _____(°C)	



Building Stronger Bonds™

info@hj3.com // 877-303-0453 // hj3.com

Concrete Surface Prep		
<input type="checkbox"/>	Surface Repair Guidelines were followed	Restore the concrete per ICRI 310.1R.
<input type="checkbox"/>	Minimum surface profile was achieved & verified	Confirm surface profile meets ICRI CSP #3 not to exceed #6
<input type="checkbox"/>	Surface is Clean & Dry	Confirm that surface moisture is < 5% Confirm surface is dust free by performing coin dust test
NOTE: Upper Surface Temperature Application Limit = 200°F (93°C). For higher temps consult HJ3.		

Steel Surface Prep		
<input type="checkbox"/>	Surface Repair Guidelines were followed.	Restore the concrete per ICRI 310.1R.
<input type="checkbox"/>	Minimum surface profile was achieved & verified	Confirm surface profile meets ICRI CSP #3 not to exceed #6
<input type="checkbox"/>	Surface is clean & dry	Confirm that surface moisture is < 5% Confirm surface is dust free by performing coin dust test
NOTE: Upper Surface Temperature Application Limit = 200°F (93°C). For higher temps consult HJ3.		

Installation	
<input type="checkbox"/>	Prime the surface with 7-10 mils SiloWrap™ Primer Start by pouring the entire contents of Primer Polymer Part B into the container marked Part A. Mix for 3 minutes using a low-speed drill at 400-600 RPM. Using a brush or roller nap, apply the primer to 100% of repair area. Make sure surface is saturated to rejection; No dry spots shall be visible in the prepared area after priming.
<input type="checkbox"/>	Fill Pits & Smooth Transitions SiloWrap™ Hi-Mod Paste Start by pre-mixing the Part A for 3 mins until completely smooth and consistent. Then pour the entire contents of Filler Part B into the container marked Part A. Mix for 3 minutes using a low-speed drill at 400-600 RPM. Apply hi-mod paste to fill pits, bug holes, and surface irregularities. Use hi-mod paste to make transitions over high spots using a 3:1 transition.

<input type="checkbox"/>	Saturate the SiloWrap™ Fabric using SiloWrap™ Saturant Start by pouring the entire contents of Saturant Polymer Part B into the container marked Part A. Mix for 3 minutes using a low-speed drill at 400-600 RPM. Unwrap the fabric from its packaging. Unroll the fabric and prepare for wet-out and keep foreign matter off of the dry fabric. Use a brush, roller nap, or spatula to fully wet out the fabric on both sides. Roll the wet fabric onto a clean core.	
<input type="checkbox"/>	Apply SiloWrap™ Saturated Fabric to primed & prepared surface After saturating, press the saturated fabric onto the substrate, and using a roller, apply pressure to the surface of the fabric to ensure good bonding. Roll out any trapped air before the polymer sets. Smooth with roller in all directions to remove air pockets. Overhead applications will require Hi-mod paste between layers. All bubbles, voids, and fiber disruptions shall be removed while fiber is still wet.	
<input type="checkbox"/>	Apply SiloWrap™ Compression Film If repair structure can be fully enveloped e.g.(column), then apply 4 layers of compression film in the same direction as the “wet” fabric. Compression film shall be applied to “wet” fabric and can be removed in 12-24hrs depending on ambient temperature.	
<input type="checkbox"/>	Apply ChemSeal™ (or approved) Topcoats After all layers of fabric have been installed, apply designated ChemSeal™ Coating or other pre-approved coating. If Saturated SiloWrap™ fiber has cured for more than 5 days then for all ChemSeal™ Topcoats, sand lightly to remove gloss, then clean with solvent and damp rag, waiting 20 minutes for solvent to flash. Topcoat shall cover 100% of surface area applied at designated minimum thickness.	
Post-Installation Inspection & Repair		
<input type="checkbox"/>	Visual Inspection	A visual inspection shall be performed to detect defects such as but not limited to: dry fiber, voids, bubbles, insufficient overlaps
<input type="checkbox"/>	Acoustic Tap-Test	An acoustic tap test shall be performed to detect voids and delamination between the composite repair and surface
<input type="checkbox"/>	QC Repair	All anomalies requiring repairs shall be performed prior to return to service.
Cure		
<input type="checkbox"/>	Skin Temps < 77°F / 25°C (Shore D of 78 required)	A Minimum 72 hours of Cure Time has been achieved prior to return to service.
<input type="checkbox"/>	For Skin Temps > 77°F / 25°C (Shore D of 78 required)	A Minimum 24 hours of Cure Time has been achieved prior to return to service.

NOTE:

Cure times can be decreased by adding heat to the repair location.
 Consult with HJ3 for specific cure schedules associated with elevated temperatures.