


- I'd start with Begin Analysis (or similar) as the first box, so that all steps stem from there and are consecutive
- Typically, these charts should have no dead ends. So the No circles need errors back into the process.
- In the NaOH part both No and Yes lead to a Re-make. How does one win?!?!? Maybe this diagram should have a happy ending, so that after the user has followed all the steps they arrive at an accurate measurement



# Aeration-Oxidation Troubleshooting Guide