

*issues***SERVICE BULLETIN No. RTC-061a**

**TECHNICAL CONTENT OF THIS DOCUMENT IS APPROVED ON  
THE BASIS OF AUTHORIZATION DOA NO. EASA.21J.057.  
THIS SB COULD BE AFFECTED BY AD.**

- 1. CONCERNING TO:** All airplanes SPORTSTAR RTC, equipped with engine serial number, carburetors part and serial numbers or installed spare parts according to Rotax Service Bulletin SB-912-075UL / SB-914-057UL including spare parts (springs) on the stock to be installed on the SPORTSTAR RTC airplane in the future.
- 2. REASON:** The engine manufacturer (Rotax) has published a Service Bulletin SB-912-075UL / SB-914-057UL concerning exchange of support springs on Rotax Engine Type 912 and 914 (Series). Due to a deviation in the manufacturing process some support springs.
- 3. REQUIRED ACTIONS:**
1. Perform the exchange by the Rotax Service Bulletin SB-912-075UL / SB-914-057UL.
  2. Record the exchange to Engine Log Book.
- 4. LATEST DAY OF THE ACTION:** According to the Rotax Service Bulletin SB-912-075UL / SB-914-057UL.
- 5. CARRIED OUT BY:** Aircraft operator / owner.
- 6. COSTS COVERED BY:** According to the Rotax Service Bulletin SB-912-075UL / SB-914-057UL.
- 7. NECESSARY MATERIAL (RTC060A):**
- | Name                      | P/N    | Nomencl. | Quantity |
|---------------------------|--------|----------|----------|
| Carburetor support spring | 838242 | 766184   | 2 pc     |
- Material shall be supplied by the airplane manufacturer.
- 8. WORK PROCEDURE:** According to the Rotax Service Bulletin SB-912-075UL / SB-914-057UL.
- 9. APPENDICES:** None.

Valid from: 19. 10. 2021