

*issues***SERVICE BULLETIN No.****EV97-040a
SPORTSTAR-041a
Harmony LSA-018a**

- 1. CONCERNING TO:** Airplanes: EV97 – (detected S/N: 20224402, 20224403 a 20224404)
SPORTSTAR
Harmony LSA
and all other airplanes equipped with ROTAX 912 UL/ULS engine according to ROTAX Service Bulletin SB-912-076UL.
- 2. REASON:** The engine manufacturer (ROTAX) has issued Service Bulletin SB-912-076UL ordering the replacement of the fuel pump nipple fittings. The reason for the replacement is the fact that a certain number of fuel pump nipple fittings were installed using a lubricant instead of the prescribed thread sealant LOCTITE 577 Yellow.
This bulletin replaces the cancelled bulletin EV 97-039a SPORTSTAR-040a Harmony LSA-017. This bulletin corrects a numbering error.
- 3. REQUIRED ACTIONS:** 1. Check and perform the exchange according to ROTAX Service Bulletin 912-076UL.
2. Record the replacement into Engine Log Book.
If bulletin EV 97-039a SPORTSTAR-040a Harmony LSA-018a has already been carried out, record the execution of bulletin EV 97-040a SPORTSTAR 041 Harmony LSA 018a into Engine Log Book as well.
- 4. LATEST DAY OF THE ACTION:** According to ROTAX Service Bulletin 912-076UL.
- 5. CARRIED OUT BY:** Aircraft operator / owner.
- 6. COSTS COVERED BY:** According to ROTAX Service Bulletin 912-076UL.
- 7. NECESSARY MATERIAL:**

Name	Marking	ROTAX P/N	Quantity
Nipple	9/5.7	840745	1 pc.
Nipple	7/3.8	840740	1 pc.
Gasket ring	10.2x15x1.5	250425	2 pcs.
Thread sealant	Loctite 577 Yellow	899796	as required

Material shall be supplied by the engine manufacturer.



evektor

Letecká 1008, 686 04 Kunovice, Czech Republic

8. WORK PROCEDURE:

According to ROTAX Service Bulletin 912-076UL.

9. APPENDICES:

None.

Valid from: 10. 02. 2023