



issues

SERVICE BULLETIN No.

**EV97-039a
SPORTSTAR-040a
Harmony LSA-017a**

1. CONCERNING TO: Airplanes: EV97 – (detected S/N: 20224402, 20224403 a 20224404)
SPORTSTAR
Harmony LSA

and all other airplanes equipped with ROTAX 912 UL/ULS engine according to ROTAX Service Bulletin SB-912-076UL.

2. REASON: The engine manufacturer (ROTAX) has issued Service Bulletin SB-912-076UL ordering the replacement of the fuel pump nipple fittings. The reason for the replacement is the fact that a certain number of fuel pump nipple fittings were installed using a lubricant instead of the prescribed thread sealant LOCTITE 577 Yellow.

3. REQUIRED ACTIONS: 1. Check and perform the exchange according to ROTAX Service Bulletin 912-076UL.
2. Record the replacement into Engine Log Book.

4. LATEST DAY OF THE ACTION: According to ROTAX Service Bulletin 912-076UL.

5. CARRIED OUT BY: Aircraft operator / owner.

6. COSTS COVERED BY: According to ROTAX Service Bulletin 912-076UL.

7. NECESSARY MATERIAL:

Name	Marking	Nomencl.	Quantity
Nipple	9/5.7	840745	1 pc.
Nipple	7/3.8	840740	1 pc.
Gasket ring	10.2x15x1.5	250425	2 pcs.
Thread sealant	Loctite 577 Yellow	899796	as required

The material marking and nomenclature is in accordance with the material defined in ROTAX Service Bulletin SB-912-076UL. Material shall be supplied by the airplane manufacturer.

8. WORK PROCEDURE: According to ROTAX Service Bulletin 912-076UL.

9. APPENDICES: None.

Valid from: 21. 10. 2022.