

issues

**SERVICE BULLETIN No. EV97-044a
SPORTSTAR-045a
HARMONY LSA-025a
HARMONY-001a
SAFETY RELATED**

- 1. CONCERNING TO:** All aircraft Eurostar EV97
Harmony / Harmony LSA / Harmony ELSA
SportStar
equipped with ROTAX 912 UL/ULS or engine according to
ROTAX 912 iS Sport according to Service Bulletin Service SB
-SB-912-078UL / SB-914-059UL / SB- 912 i-014iS.
- 2. REASON:** The ROTAX engine manufacturer has issued Service Bulletins
SB-SB-912-078UL / SB-914-059UL / SB-912 i-014iS ordering
the replacement of the propeller shaft and its accessories.
- 3. REQUIRED ACTIONS:**
1. Check and replace if necessary according to ROTAX
Service Bulletins SB-912-078UL / SB-914-059UL / SB-912 i-
014iS.
 2. Record the replacement into Engine Log Book.
- 4. LATEST DAY OF THE ACTION:** According to ROTAX Service Bulletins SB-912-078UL / SB-
914-059UL / SB-912 i-014iS.
- 5. CARRIED OUT BY:** According to ROTAX Service Bulletins SB-912-078UL / SB-
914-059UL / SB-912 i-014iS.
- 6. COSTS COVERED BY:** According to ROTAX Service Bulletins SB-912-078UL / SB-
914-059UL / SB-912 i-014iS.
- 7. NECESSARY MATERIAL:** According to ROTAX Service Bulletins SB-912-078UL / SB-
914-059UL / SB-912 i-014iS.
- 8. WORK PROCEDURE:** According to ROTAX Service Bulletins SB-912-078UL / SB-
914-059UL / SB-912 i-014iS.
- 9. APPENDICES:** None.

Valid from: September 1st, 2023.