

Issues

INFORMATION BULLETIN No. RTC-074b

**TECHNICAL CONTENT OF THIS DOCUMENT IS APPROVED
UNDER THE AUTHORITY OF THE DOA REF. EASA.21J.057.**

- 1. CONCERNING:** SportStar RTC airplane, S/N **2016 1910**.
- 2. REASON:** Required installation of the Rotax 912 S engine in SportStar RTC airplane, S/N 2016 1910.
- 3. REQUIRED ACTIONS:** Replacement of Rotax 912 ULS engine with Rotax 912 S engine.
- 4. LATEST DAY OF ACTION:** As required.
- 5. CARRIED OUT BY:** Organizations authorized for maintenance/repairs of this type of airplane in accordance with Part M, Part ML, Part CAO, Part 145.
- 6. COSTS COVERED BY:** Airplane owner/operator.
- 7. NECESSARY MATERIAL:** The recommended material is listed in the separate document, Doc No. Annex to Bulletin RTC-074b. Contact the airplane manufacturer for Annex to Bulletin RTC-074b.
- 8. WORK PROCEDURE:** The work procedure is specified in the separate Annex to this Bulletin, Doc No. Annex to Bulletin RTC-074b. Contact the airplane manufacturer for Annex to Bulletin RTC-074b.
- 9. APPENDICES:** See Annex to Bulletin No. RTC-074b.

Valid from: November 29th, 2023