

ENGINE OVERHAUL WARRANTY

Work accomplished by Radial Engines, Ltd. ("REL") is covered by an express warranty against faulty workmanship and is subject to the provisions below:

Warranty Period:

For a period of twelve (12) months after date of delivery to customer, REL shall repair or replace, at its option, any aircraft engine, accessory, or part which is found to be defective, to REL's satisfaction, within said warranty period. For engine warranty after twelve (12) months from the date of delivery to customer and prior to the expiration of the manufacturers recommended time between overhaul ("TBO"), the cost of repair or replacement (including the cost of parts and labor), at REL's option, shall be prorated in the following manner. The customer shall pay a prorated amount based upon the engine's TBO and the engine hours (which shall be deemed the greater of logbook hours, recorded tachometer hours, or a minimum of twenty-five (25) hours per month from date of delivery).

General Provisions:

REL warrants its aircraft engines to be free from defects in materials and workmanship only under normal use and service. REL will make corrections or repairs to the engine resulting from defects in materials and faulty workmanship on units delivered to REL located at 11701 W. Forrest Hills Road, Guthrie, OK USA, provided its examination by REL shall disclose to its satisfaction to have been thus defective.

REL assumes no responsibility for bent or broken rods or parts damaged from failure of same due to hydraulic action resulting from improper engine starting procedures, or for any other operational irregularities resulting from, but not limited to: improper fuels and/or lubricants; inadequate lubricants; operating at excessive temperatures; over-speeding; use of excess power; inadequate maintenance; fouled plugs; debris or contamination from oil/fuel filters or tanks, or any other related operational or maintenance deficiency. This warranty is voided if an overhauled or repaired engine is installed without the oil tank being thoroughly cleaned & signed off by a licensed mechanic. The responsibility of REL is specifically restricted to those cases that by mutual inspection and agreement reveal a workmanship default in light of the Manufacturer's specifications and FAA regulations.

REL requires all repairs for defective workmanship to be made in its own shops, and will not be responsible for any costs or expenses of any kind or character incurred by the curing of any defective workmanship in any place other than its own shops, unless such work is specifically authorized in writing by REL <u>prior</u> to its accomplishment. Should an item which is within the warranty period be returned to REL and it is found that the malfunction or failure was not caused by faulty workmanship, the customer must pay for all inspection, repair, or overhaul at established rates.

REL is to be required to accomplish work under this warranty only to the extent of proper correction of the faulty workmanship involved and covered by this warranty. REL is not responsible for any articles or accessories overhauled and certified airworthy by other facilities and installed on engines overhauled by REL. The other certifying facility should be contacted directly for warranty repair work on items overhauled or repaired at their facility.

This warranty does not cover any item unless it is properly installed, operated, and maintained in accordance with FAA and manufacturer's specifications and recommendations. REL will be responsible for proper installations only when such installations are made by REL. Likewise, this warranty shall not apply to any item that has been subject to misuse, neglect or shall have been altered or repaired outside of REL's shops.

Dated:	Engine Type	Serial Number	Bv: