Use 20 / 2 AWG
solid core cable

A C B
COMMON

SPST
(ON-OFF) SWITCH

NOTE:
For this application,
connect to either
A and C
or
B and C
on the Smartsensor
GPIO terminals

**SMARTSENSOR**

Use 20 / 3 AWG
solid core cable

A C B
COMMON

SPDT MOMENTARY CONTACT
(ON - OFF - ON) SWITCH

NOTES:
For this application, connect to
all three GPIO terminals of the
Smartsensor.
The connectivity at the switch
end to be determined by the
project specifier.

**SMARTSENSOR**

smartengine | wtec

| DRAWN BY | RELEASE NO. |
|---|---|
| EJD | 1.1 |
| SCALE | DATE |
| NA | 09/30/20 |

SHEET NO.

SE-SL04