


Anchor Inspection/Safe to Climb Guide

Guy anchors in direct contact with soil have proven to be susceptible to galvanic corrosion. As telecommunications towers come of age the issue has been brought forefront due to tower failures caused by guy anchor corrosion and the inherent life-safety risk to technicians.



*www.Safe2Climb.com and <http://websoilsurvey.sc.egov.usda.gov/App/HomePage.htm> are two resources providing Soil Condition Reports

**Only competent and experienced contractors should be used to perform dig-to-block inspections.