

## **IMPORTANT NOTICE - PRODUCT OBSOLESCENCE**

Dear Valued Customer,

January 8, 2015

Forney has announced the obsolescence of several Legacy flame detectors. The following Forney flame detectors are included under this obsolescence notice:

| Part Number | Description  |  |
|-------------|--|--|
| 7819504     | Enhanced Digital Profile Detector IR front mount       |  |
| 7819505     | Enhanced Digital Profile Detector IR fiber optic mount |  |
| 7819506     | Enhanced Digital Profile Detector UV front mount       |  |
| 7819507     | Enhanced Digital Profile Detector UV fiber optic mount |  |
| 7819574     | Digital Profile Detector IR fiber optic mount          |  |
| 7819585     | Digital Profile Detector UV fiber optic mount          |  |
| 9101645     | Digital Profile Detector IR front mount                |  |
| 9104005     | Digital Profile Detector UV front mount                |  |

The IDD detectors coupled with IDD amplifiers are suitable replacements for the above flame detectors. Consult your local Forney Regional Sales Manager for specifics on the detector replacement.

Our intent is to support these products for a limited time in order to allow for future planning by all of our customers for their product needs, including any requirements for product spares. Forney has identified the following Last Time Buy Dates for these product lines:

| Product Line  | Last Time Buy Date |  |
|---------------|--------------------|--|
| DPD Detectors | June 30, 2015      |  |

Forney Corporation appreciates and values our business relationship and looks forward to your continued interest in our products. We apologize for any inconvenience this announcement may cause and are eager to meet your future product requirements with our world-class quality product lines.

Regards

**Customer Service Manager** 

1