

Tel 800 668 9318 Tel 416 298 5700 Fax 416 298 9535 mail@nienkämper.com www.nienkamper.com



CONFERENCE TABLE AND VOX FORUM® INSTALLATION GUIDE

HARDWARE PARTS LIST



ALLAN KEYS

Small 4 mm

For hex socket assembly, to join rails together. For installing bases to rails. For installing mounting plate to top.

Large 5 mm

For hex socket assembly, to join rail together.



FLAT HEAD HEX SOCKET ASSEMBLY

4 mm and 5 mm - 2" x $^1/_4$ " - 20 and threaded collar. Joins rails together.



FLAT HEAD HEX SOCKET BOLT

4 mm - ⁵/8" x ¹/4" - 20. Joins bases to rail.



FLAT HEAD HEX SOCKET BOLT

4 mm - 1" \times $^{1}/_{4}$ " - 20. Joins mounting plate to top. Joins single leg to top.



TIGHT JOINT FASTENERS

3 piece assembly plus 1 tightening rod.



WOODEN SPLINE

 $^{1}\mbox{/s"}$ x $^{7}\mbox{/s"}$ x (24" - varies). Inserts into the edge of multiple segment tops.



MOUNTING PLATE


¹/4" x 3" x 4". Fixes rail to top.



WIRE MANAGEMENT "U" CLIPS

Grey ABS plastic.

Used to secure wires to support rail.



- Large conference tables incorporate support rails in multiple segments.
- Position and assemble connecting joints as shown.
- Matching joints are number coded (circular labels).
- Required hardware: $2'' \times 1/4'' 20$ flat head hex socket assembly.
- Tighten joint, aligning marks as shown.
- Certain table shapes require rails to be assembled at different angles (as marked).


2



- Place bases on top of rails aligning the holes in the base with factory installed thread locations in the rails.
- Attach and tighten bases to rails.
- Required hardware: 5/8" x 1/4" 20 flat head hex socket bolt.

ATTACHING BASE TO RAILS "ALTERNATE"

FINISHED BASE ASSEMBLY



Assembly for round/square and square wave shaped tables.

- Place bases on top of rails aligning the holes in the base with factory installed thread locations in the rails.
- Attach and tighten bases to rails.
- Required hardware: 5/8" x 1/4" 20 flat head hex bolt.
- Flip base assembly over.
- Place the top on the table and install as described in #5 and #6.
- Position top to align threaded inserts of top with holes in leg (as shown).
- Fix with required hardware: 1" x 1/4" 20 flat head hex bolt.

4



- Flip assembly over to apply top.
- Position and level the base.

JOINING MULTIPLE PIECE TOPS



- Position multiple section tops with matching identification numbers
- Insert wooden spline into the groove at the seam.
- Insert ball fitting, align with tight joint bolt.
- · Start the thread.



- Slide tops together, align the top.
- Insert tight joint collar.
- Tighten ball fitting, hand tight.


ATTACHING BASE TO TOP

INSTALLING VOX FORUMS®



- Insert the mounting plate into the top groove of the rail.
- Slide the plate to align threaded inserts of top with holes in mounting plate.
- Required hardware: 1" x 1/4" 20 flat head hex bolt.

8



- Unpack the Forum box and retrieve the swivel latches.
- Carefully thread plastic thumbscrews into inserts around the square hole in the top.
- Position Forum in opening and carefully ease up into the square hole.
- Rotate the swivel catches and tighten the thumb screw fasteners.

Note: detailed installation instructions are included with all Vox Forums.



- Begin by mounting adhesive wire management strip behind Forum position, or where required.
- Insert cables in 1 of 3 channels.

7 10



• Using wire management "U" clips, store and route cables to bases along the rail.

WIRE MANAGEMENT ACCESSORIES



11

- To bring cabling from the under side of the top to the floor, wire management accessories can also be used.
- A variety of models are available.
- Instructions for installing wire management accessories are packaged with each accessory.