

issues

SERVICE LETTER No. Harmony LSA - 023b R1

- 1. CONCERNING TO:** Harmony LSA aircraft from serial number **S/N 2021 2149, S/N 2021 2150, S/N 2021 2151, S/N 2021 2152, S/N 2022 2155, S/N 2022 2156, S/N 2022 2157, S/N 2022 2158** and all subsequent aircraft from serial number **S/N 2023 2212**.
- 2. REASON:** Release of a new revision of the POH for Harmony LSA aircraft Doc. No. HARMLSAISPOH Revision 4, date of issue August 25th, 2023.
- 3. REQUIRED ACTIONS:** The operator / owner of the aircraft will replace the existing POH.
- 4. LATEST DAY OF THE ACTION:** Upon delivery of POH Doc. No. HARMLSAISPOH Revision 4.
- 5. CARRIED OUT BY:** Operator / owner of the serial numbers of the aircraft referred to para 1.
- 6. COSTS COVERED BY:** Operator / owner of the serial numbers of the aircraft referred to para 1.
- 7. NECESSARY MATERIAL:** POH for Harmony LSA aircraft Doc. No. HARMLSAISPOH, date of issue August 25th, 2023.
- 8. WORK PROCEDURE:** Replace existing POH with POH Doc. No. HARMLSAISPOH Revision 4, date of issue August 25th, 2023.
- 9. APPENDICES:** Contact the aircraft manufacturer for POH Doc. No. HARMLSAISPOH Revision 4, date of issue August 25th, 2023.

Valid from: October 11th, 2023.