

issues

## SERVICE LETTER No. Harmony LSA - 026b R1

1. CONCERNING TO: Harmony LSA aircraft from serial number S/N 2021 2149, S/N

2021 2150, S/N 2021 2151, S/N 2021 2152, S/N 2022 2155, S/N 2022 2156, S/N 2022 2157, S/N 2022 2158 and all subsequent aircraft from serial number S/N 2023 2212.

**2. REASON:** Release of a temporary revision of the Illustrated Parts

Catalogue for Harmony LSA aircraft Doc. No.

HARMLSAIPCUS Temporary Revision No. 1/2023, date of

issue June 2<sup>nd</sup>, 2023.

**3. REQUIRED ACTIONS:** According to the decision of the aircraft operator.

**4. LATEST DAY OF THE ACTION:** As required.

**5. CARRIED OUT BY:** Operator / owner of aircraft with serial numbers referred to para

1.

**6. COSTS COVERED BY:** Operator / owner of aircraft with serial numbers referred to para

1.

**7. NECESSARY MATERIAL:** Illustrated Parts Catalogue for Harmony LSA aircraft Doc. No.

HARMLSAIPCUS Temporary Revision 1/2023, date of issue

June 2<sup>nd</sup>, 2023.

**8. WORK PROCEDURE:** If necessary, supplement the existing Illustrated Parts Catalogue

issued before January 2<sup>nd</sup> with a temporary revision of the

Illustrated Parts Catalogue Doc. No. HARMLSAIPCUS, date of

issue June 2<sup>nd</sup>, 2023.

**9. APPENDICES:** Contact the aircraft manufacturer for the temporary revision of

the Illustrated Parts Catalogue Doc. No. HARMLSAIPCUS Temporary Revision 1/2023, date of issue June 2<sup>nd</sup>, 2023.

Valid from: October 17th, 2023

QS-406/F-09J

tel: + 420 572 537 558 / +420 572 537 605

e-mail: service@evektor.com / evektor@evektor.com

Strana: 1/1