

issues

SERVICE BULLETIN No. RTC-038b R5

TECHNICAL CONTENT OF THIS DOCUMENT IS APPROVED ON THE BASIS OF AUTHORIZATION DOA NO. EASA.21J.057.

1. CONCERNING TO: All airplanes SPORTSTAR RTC

2. REASON: Issue of Revision 5 of Airplane Maintenance Manual for

SportStar RTC Issue 02, Doc. No. ERTC022-10-AS.

3. REQUIRED ACTIONS: Owner / operator of the airplane will download the Airplane

Maintenance Manual for SportStar RTC, Issue 02, Doc No.

ERTC022-10-AS, Revision 5.

4. LATEST DAY OF THE ACTION: Immediately after receiving this bulletin.

5. CARRIED OUT BY: Owner/operator of the airplane.

6. COSTS COVERED BY: Owner/operator of the airplane.

7. NECESSARY MATERIAL: Airplane Maintenance Manual for SportStar RTC Issue 02,

Doc. No. ERTC022-10-AS, Revision 5.

8. WORK PROCEDURE: Send your request to the email address: service@evektor.com.

After receiving the link, download the Airplane Maintenance Manual for SportStar RTC, Issue 02, Doc No. ERTC022-10-

AS, Revision 5.

9. APPENDICES: None.

Valid from: January 22nd, 2024