

Golden Win3





HEAT STRESS MONITOR

FEATURES

TEMP/RH WARNING DEVICE FOR HEAT STRESS & WB MANAGEMENT

- Continuous Temperature & Relative Humidity Measurement
- Instrument calculates Dew Point and Wet Bulb Temperatures
- Data Logging with USB Downloading (25,000 Records)
- Colour Coded Alarm Indication
- Green Safe, Yellow Caution,
 Red Danger, Purple Extreme Danger
- · Audible Alarm for Danger and Extreme Danger
- Internal Coin Cell Battery
- 1 Year Battery Life Exposure Dependant
- Fixes to Cap Lamp Cable (Or Pocket Clip)
- Rugged Design & IS approved
- Low Cost

COLOUR CODED ALARM INDICATION



SAFE

CAUTIO

DANGE

PURPLE: EXTREME DANGER





