



Emnor Mechanical Inc.
20 Depew Street
Hamilton, Ontario
L8L 7H8

Replace Badly Damaged Impeller



Damaged Impeller



New Impeller Side View



New Impeller Top View

Emnor Manufactured a New Impeller for a Pump Installed in 1952