

UNDERWRITERS LABORATORIES INC .**INSPECTION REPORT - Type R Service****E1738531103311328**

Date	03/31/2011	File Number	E17385
Responsible Office	Northbrook	Volume	3
Inspection Center	835	Account / Order Number	
CCN	OANZ2	UL Rep Name	Marc D. Beck
Product Category	[Insulating Devices and Materials - Component] Insulating Tape - Component	UL Representative ID	05828
Subscriber - Factory Number	100558-971	Factory Representative	Mr. Bob Perkins
Manufacturer Name	RSI INC CRI, DIV OF RSI INC	Factory Rep Phone	512-262-3231
Manufacturer Address	1670 KOHLERS CROSSING	Factory Rep Email	bperkins@rsi-cri.com
	KYLE, TX 78640		

Nature of Visit	Initial Production Inspection	Sample Status	Samples not required
Listing/Classification/Recognized (Unlisted) Component Marks Used Since Last Visit	Yes	Listing/Classification/Recognized (Unlisted) Component Marks Removed	No
Variation Notice Issued	No		

VN Corrective Action Follow-up Performed?	No
---	----

PRODUCT DOCUMENTS / PRODUCTION READY VISIT☐ **No Products Examined - Production Ready Visit**

Model	Product	Class	Section/ RNN	Multiple Listed
Super 20	Insulation and Flame Retardant Tape		13	No

SAMPLE DOCUMENTS**If samples are required to be sent to ULI Laboratory, indicate below. If required samples are not sent, explain in the Comments area.**

Type/Style/ Cat/Model	Name	Sample Tag Number	Shipped to Office
No Samples			

Additional Comments:

In addition to the requirements specified in the applicable UL Services agreement and FollowUp Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled, "UL Mark Surveillance Requirements" that can be located at the following web-site: www.ul.com/fus. Manufacturers without Internet access may obtain the current version of this document from their local UL customer service representative or UL field representative.