CERTIFICATION

Safety and fragility of glazed roofing: guidance on specification. CWCT TN67: Safety and fragility of glazed roofing: testing and assessment.





NBS SPECIFICATION


L10 /45 Rooflights L10/460 Rooflights


Uniclass category Pr_30_59_72

84mm Painted border shown as standard to cover glazing frame.









for exact specifications of the glazing and sizes, please refer to the specific line(s) on your quote.

Thermal Stress Note

To provide the highest performance of non fragility and security, the unit incorporates laminated internal panes.

For standard (annealed) laminate inner panes, guidance regarding thermal stress fracture risk is available on Whitesales website or by contacting Whitesales technical team.

To reduce risk it is recommended to keep curb widths under 120mm, avoid partial shading or rapid internal heating or cooling direct of close to the glass.

If higher risks cannot be mitigated then alternative heat strengthened or toughened glass inner panes should be considered.

Curb details shown are indicative only. Detail is designed by others.

It is the responsibility of the curb designer to ensure that the curb is structurally adequate to support the rooflight product.

Whitesales advise an installation with a minimum pitch of 5° for Rooflight units to minimise water pooling. Whilst the product can be installed flat without detriment to the warrantee. Whitesales cannot be held responsible for any excessive pooling of water to the surface of the Rooflight post installation.

CAUTION CDM: Hazard Identification - Handling materials
Manual Handling Operations Regulations (MHOR 1992) sets out a clear ranking of
measures for dealing with risks from manual handling. Ensure measures are considered at all times.
Other measures:

	Δ	
/	W	\
/	U	\
	•	١.

Hand protection (mandatory) to: BS EN 388:1994.
 Wear appropriate PPE required for the task.
 Refer to applicable risk assessment for further details.

NOT BE COPIED OR PASSED TO A THIRD PARTY WITHOUT WRITTEN CONSENT FROM THE MANUFACTURER

THIS DRAWING MUST



Title:		Description			Name	Date
Assembly Drawing	awing Double Glazed Unit		Created	L.Crawford	10/07/2020	
Project No	х	Ref No	х	Drawn	iLogic Auto	12/03/2021
Project		Part Number		Approved		
x		em.glaze		Checked		
Customer Name		Material		Drawing No. Revision:		Revision: 1
x		Varies		ADS12KA15BA1AA.1.CD.1		
Project Address		Finish	RAL7016	Sheet number 1 of 3		
xxx		Quantity	х	Scale DNS	Size: A3	Units: mm



Whitesales Ltd Europa House Cranleigh GU6 8NQ

CERTIFICATION Safety and fragility of glazed roofing: guidance on specification. CWCT TN67: Detail F Safety and fragility of glazed roofing: testing and assessment. Thermally Broken Detail E Aluminium Ring Frame Finished to RAL7016 G Frame Fixings Finished To RAL7016 NBS SPECIFICATION CAWS L10 /45 Rooflights L10/460 Rooflights PVC Upstand Fixings through base of upstand in to roof structure. Uniclass category Pr_30_59_72 Use: M5x100mm CS Woodscrews. Typical 300mm Spacing 84mm Painted border shown as standard to cover glazing frame. Weathering (By Others) D Roof Structure (By Others) Detail G Section D-D Ε

This drawing is for visual purposes only, for exact specifications of the glazing and sizes, please refer to the specific line(s) on your quote.

Thermal Stress Note

To provide the highest performance of non fragility and security, the unit incorporates laminated internal panes.

For standard (annealed) laminate inner panes, guidance regarding thermal stress fracture risk is available on Whitesales website or by contacting Whitesales technical team.

To reduce risk it is recommended to keep curb widths under 120mm, avoid partial shading or rapid internal heating or cooling direct or close to the glass.

 $If \ higher \ risks \ cannot \ be \ mitigated \ then \ alternative \ heat \ strengthened \ or \ toughened \ glass \ inner \ panes \ should \ be \ considered.$

Curb details shown are indicative only. Detail is designed by others.

It is the responsibility of the curb designer to ensure that the curb is structurally adequate to support the rooflight product.

Whitesales advise an installation with a minimum pitch of 5° for Rooflight units to minimise water pooling. Whilst the product can be installed flat without detriment to the warrantee. Whitesales cannot be held responsible for any excessive pooling of water to the surface of the Rooflight post installation.

CAUTION CDM: Hazard Identification - Handling materials
Manual Handling Operations Regulations (MHOR 1992) sets out a clear ranking of
measures for dealing with risks from manual handling. Ensure measures are considered at all times.
Other measures:



Hand protection (mandatory) to: BS EN 388:1994.
 Wear appropriate PPE required for the task.
 Refer to applicable risk assessment for further details.

THIS DRAWING MUS
NOT BE COPIED OR
PASSED TO A THIRD
PARTY WITHOUT
WRITTEN CONSENT
FROM THE
MANUFACTURER





Title:		Description			Name	Date
Assembly Drawing	J	Double Glazed Unit		Created	L.Crawford	10/07/2020
Project No	x	Ref No	x	Drawn	iLogic Auto	12/03/2021
Project		Part Number		Approved		
x		em.glaze		Checked		
Customer Name		Material		Drawing No. Re		Revision: 1
x		Varies		ADS12KA15BA1AA.1.CD.2		
Project Address		Finish RAL7016		Sheet number 2 of 3		
xxx		Quantity	х	Scale DNS	Size: A3	Units: mm



Whitesales Ltd Europa House Cranleigh GU6 8NQ

PVC150V Upstand

Timber wedge to achieve fall (By Others)

Internal Finish (By Others)




Safety and fragility of glazed roofing: guidance on specification. CWCT TN67:

Safety and fragility of glazed roofing: testing and assessment.



Uniclass category



Thermal Stress Note

To provide the highest performance of non fragility and security, the unit incorporates laminated internal panes.

For standard (annealed) laminate inner panes, guidance regarding thermal stress fracture risk is available on Whitesales website or by contacting Whitesales technical team.

To reduce risk it is recommended to keep curb widths under 120mm, avoid partial shading or rapid internal heating or cooling direct or close to the glass.

 $If \ higher \ risks \ cannot \ be \ mitigated \ then \ alternative \ heat \ strengthened \ or \ toughened \ glass \ inner \ panes \ should \ be \ considered.$

Curb details shown are indicative only. Detail is designed by others.

It is the responsibility of the curb designer to ensure that the curb is structurally adequate to support the rooflight product.

Whitesales advise an installation with a minimum pitch of 5° for Rooflight units to minimise water pooling. Whilst the product can be installed flat without detriment to the warrantee. Whitesales cannot be held responsible for any excessive pooling of water to the surface of the Rooflight post installation.

CAUTION CDM: Hazard Identification - Handling materials
Manual Handling Operations Regulations (MHOR 1992) sets out a clear ranking of
measures for dealing with risks from manual handling. Ensure measures are considered at all times.
Other measures:



Hand protection (mandatory) to: BS EN 388:1994.
 Wear appropriate PPE required for the task.
 Refer to applicable risk assessment for further details.

THIS DRAWING MUS
NOT BE COPIED OR
PASSED TO A THIRD
PARTY WITHOUT
WRITTEN CONSENT
FROM THE
MANUFACTURER



Γitle:		Description			Name	Date
Assembly Drawing		Double Glazed Unit		Created	L.Crawford	10/07/2020
Project No	x	Ref No	X	Drawn	iLogic Auto	12/03/2021
Project		Part Number		Approved		
C		em.glaze		Checked		
Customer Name		Material		Drawing No.		Revision: 1
C		Varies		ADS12KA15BA1AA.1.CD.3		
Project Address		Finish RAL7016		Sheet number 3 of 3		
ХХ		Quantity	х	Scale DNS	Size: A3	Units: mm
·	·		·		•	



Whitesales Ltd Europa House Cranleigh GU6 8NQ