



**Emnor Mechanical Inc.**  
20 Depew Street  
Hamilton, Ontario  
L8L 7H8

## Repair of Boiler Feedwater Pump



Pump Received



Rotating Element



Bottom Casing Crack



Casing Inspection



Rotating Element



Finished Repair

Emnor overhauled a 60 year old BFWP. The cast iron casing was weld repaired.