

Report of Thorough Examination

GA1

Customer Information

Date: 2023-07-06

Name: Maveric Contractors Ltd.

Address: IDA Business Park

Plant ID: 2028

Tuam Road

Co. Galway

Equipment Information

Name: CAT 308E2 CR

Serial Number: CAT0308ECFJX13588

Address: Main Street

Equipment Type: Excavator

Kilcolgan

Year: 2019

Co. Galway

Safe Working
Load

Configuration

830Kgs.

As per manufacturers specifications

Examination Information

Date of Test: 2023-07-06

Next Test Date: 2024-07-05

Test Purpose:

Examination Purpose:

Specific Test: ☐

Examination: ☒ 12 months

Particulars of tests carried out:

Parts not available for examination:

Full Visual Examination

All Parts Available

Defect which is a danger to persons:

Repair, Renewal or Alteration
required to remedy this defect:

No apparent defects

None

Defect which could
become a danger to persons:

Timeframe for defect
becoming a danger:

Repair, Renewal or Alteration
required to remedy this defect:

Seat Belt Not Working
Beacon Not Working

0-1 Day
0-1 Day

Repair As Necessary
Repair As Necessary

This item is safe to use: Yes

Signed:

Niall Francis
CITB UK, Lloyds British UK.