

Report of Thorough Examination GA1

Ballybrit, Parkmore, Co. Galway. 091 - 394699info@leeng.ie www.leeng.ie

Customer Information Date: 2023-07-11

Name: Maveric Contractors Ltd. Addres			ress: IDA	ess: IDA Business Park	
Plant ID: 2025			Tuam Road		
	Co. Galway				
Caning out Information					
Equipment Information					
Name: CAT 336FL		Seri	ial Numh	per: CAT0336FCKCS10056	
Address: Trusky West		Equipment Type: Excavator			
Barna	1	Lquip			
Co. Galway	Year: 2017				
Go. Gaima)		Safe Working Load		Configuration	
		3,900Kgs.		As per manufacturers specifications	
		, ,			
Examination Information					
Date of Test: 2023-07-11		N	ext Test	Date: 2024-07-10	
Test Pur	pose:			Examination Purpose:	
Specific Test:		Exa	mination		
Particulars of tests carried out:			Parts not available for examination:		
Full Visual Examination		All Parts Available			
			- <u>-</u> -		
Defect which is a danger to persons:			Repair, Renewal or Alteration required to remedy this defect:		
No apparent defects			None	equired to remedy time defect.	
The apparent acrosse			110110		
Defect which could	Tim	eframe for	defect	Repair, Renewal or Alteration	
become a danger to persons:		oming a da		required to remedy this defect:	
Windscreen Cracked	0-1 Week			Replace As Necessary	
Locking Bolt At Quick Hitch OilQuick Damaged	0-1 Week 0-1 Week			Repair As Necessary Repair As Necessary	
Door Window Missing	0-1 Week			Install Glass	
Boxing Ring Damaged	0-1 Week			Repair As Necessary	
				11 11 1	
This item is safe to use	2: Yes		Signed	. Niall Francis	

Signed:

CITB UK, Lloyds British UK.

This item is safe to use: Yes