

Case Study



Overflow Carpark

CLIENT: BGIS WA

LOCATION: Overflow Carpark – Optus Stadium

PRODUCT: CoverLawn

GRASS TYPE: Kikuyu

APPLICATION: Open Space

DATE: December 2019



KEY CHALLENGES

The overflow carpark area within the precinct of Optus Stadium is used for both events and as an overflow carpark area when required. CoverLawn was used for the entry/exit points for cars and delivery trucks, through the bollard zones. Given the areas are the main entry points for cars/trucks and foot traffic, a suitable solution was required to prevent poor quality turf conditions.

SOLUTION

CoverLawn was installed to protect the natural turf and alleviating bare patches, creating a safe, stable natural grass area. Given the high demand for this Open Space area, CoverLawn was laid over new instant turf, after the areas had been levelled. Bio pins were used to install CoverLawn and degrade naturally overtime. CoverLawn provides the best of both worlds' – Natural grass combined with synthetics.

"Our open space area, adjacent to Optus stadium had become over-used and unsightly. CoverLawn is a great solution for this area, solving our problem and improving our asset."







