



Status Report

PHENOM 300
S/N 50500057 N924LG

OWNER:	RG42, LLC	OPERATOR:	RG42, LLC	
ADDRESS:	2500 N. DALLAS PKWY PLANO TX 75093	ADDRESS:	5960 W. PARKER RD PLANO TX 75093	
PHONE:	214-405-0035	PHONE:	214-405-0035	
FAX:		FAX:		
ANALYST:	ANDREY KORSUKOV	+1-514-636-2016 (DIRECT)	800-787-9749 (EFAX-CARDS)	PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.
EMAIL:	AKORSUKOV@CAMPSYSTEMS.COM	514-636-2020 (OFFICE)	631-980-4222 (EFAX-CARDS)	
		WWW.CAMPSYSTEMS.COM		

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS;

AIRCRAFT	SERIAL/REGNO: 50500057/N924LG	MODEL: PHENOM 300	MANUFACTURER: EMBRAER
DATES		LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 31-JUL-2011		3003:54 A/C HRS as of 25-FEB-2022 _____	A/C HRS as of ____/____/____
		2002 AFL as of 25-FEB-2022 _____	AFL as of ____/____/____
ENGINE NO. 1	SERIAL/PART: PCE-DG0104/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON 07-APR-2011		LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS 0 A/C HRS		3003:54 ENG. HRS as of 25-FEB-2022 _____	ENG. HRS as of ____/____/____
0 ENC		1999 ENC as of 25-FEB-2022 _____	ENC as of ____/____/____
ENGINE NO. 2	SERIAL/PART: PCE-DG0107/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON 06-APR-2011		LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS 0 A/C HRS		3003:54 ENG. HRS as of 25-FEB-2022 _____	ENG. HRS as of ____/____/____
0 ENC		1999 ENC as of 25-FEB-2022 _____	ENC as of ____/____/____



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05-30-01	800 FH MAINTENANCE PACKAGE							
	PKG 1	MOS				13-JUL-2018		
		HRS/MSC	800	+30/-30		2299:30	3099:30	3129:30
	REF: SMR 05-30-01	AFL				1622		
05-30-10	1600 FH MAINTENANCE PACKAGE							
	PKG 10	MOS				22-AUG-2018		
		HRS/MSC	1600	+30/-30		2299:30	3899:30	3929:30
	REF: SMR 05-30-10	AFL				1622		
05-30-20	2400 FH MAINTENANCE PACKAGE							
	PKG 20	MOS				30-DEC-2016		
		HRS/MSC	2400	+30/-30		1790:24	3600 M	3630
	REF: SMR 05-30-20	AFL				1250		
05-30-40	3200 FH MAINTENANCE PACKAGE							
	PKG 40	MOS				31-JUL-2011		
		HRS/MSC	3200	+30/-30		0	3200	3230
	REF: SMR 05-30-40	AFL				0		
05-30-42	3200 FH/60 MO MAINTENANCE PACKAGE							
+	PKG 42	MOS	60	+1m/-1m	-30	30-AUG-2021	31-JUL-2026	31-AUG-2026
		HRS/MSC	3200	+30/-30		2879:18	6079:18	6109:18
	REF: SMR 05-30-42	AFL				2002		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-50	5600 FH MAINTENANCE PACKAGE							
	PKG 50	MOS				31-JUL-2011		
		HRS/MSC	5600	+30/-30		0	5600	5630
	REF: SMR 05-30-50	AFL				0		
05-30-60	6400 FH MAINTENANCE PACKAGE							
	PKG 60	MOS				31-JUL-2011		
		HRS/MSC	6400	+30/-30		0	6400	6430
	REF: SMR 05-30-60	AFL				0		
05-30-80	12 MO MAINTENANCE PACKAGE							
	PKG 80	MOS	12	+1m/-1m	-30	30-AUG-2021	31-JUL-2022	31-AUG-2022
		HRS/MSC				2879:18		
	REF: SMR 05-30-80	AFL				2002		
05-30-81	24 MO MAINTENANCE PACKAGE							
	PKG 81	MOS	24	+1m/-1m	-30	30-AUG-2021	31-JUL-2023	31-AUG-2023
		HRS/MSC				2879:18		
	REF: SMR 05-30-81	AFL				2002		
05-30-82	36 MO MAINTENANCE PACKAGE							
	PKG 82	MOS	36	+1m/-1m	-18	18-AUG-2020	31-JUL-2023	31-AUG-2023
		HRS/MSC				2650:54		
	REF: SMR 05-30-82	AFL				1880		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-83	48 MO MAINTENANCE PACKAGE							
	PKG 83	MOS	48	+1m/-1m	-30	30-AUG-2019 2537:42 1791	31-JUL-2023	31-AUG-2023
	REF: SMR 05-30-83	HRS/MSC AFL						
05-30-84	60 MO MAINTENANCE PACKAGE							
	PKG 84	MOS	60	+1m/-1m	-30	30-AUG-2021 2879:18 2002	31-JUL-2026	31-AUG-2026
	REF: SMR 05-30-84	HRS/MSC AFL						
05-30-87	120 MO MAINTENANCE PACKAGE							
	PKG 87	MOS	120	+1m/-1m	-30	30-AUG-2021 2879:18 2002	31-JUL-2031	31-AUG-2031
	REF: SMR 05-30-87	HRS/MSC AFL						
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE							
	PKG 90	MOS	60	+1m/-1m	-30	30-AUG-2021 2879:18 2002	31-JUL-2026	31-AUG-2026
	REF: SMR 05-30-90	HRS/MSC AFL						
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01								
051254	NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							
	PKG 1	MOS	12	+30d	-30	30-AUG-2021 2879:18 1999	31-JUL-2022 (3679:18) 3679:18	30-AUG-2022 3759:18
	REF: MM 05-20-00	HRS/MSC ENC	800	+10%				
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL		ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051254	NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION								
	PKG 1	MOS	12	+30d			30-AUG-2021	31-JUL-2022	30-AUG-2022
		HRS/MSC	800	+10%	-30		2879:18	(3679:18) 3679:18	3759:18
	REF: MM 05-20-00	ENC					1999		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
EM55-160520	REVIEW EMBRAER PHENOM 300 AMM 2757 TIME LIMITS / MAINTENANCE CHECKS (TLMC) CHAPTER 5 REVISION 40 DATED MAY 20/16								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160520	MOS HRS/MSC - AFL							
EM55-160705	REVIEW EMBRAER PHENOM 300 (EM55) - CHAPTER 4 - AIRWORTHINESS LIMITATIONS REVISION 09 DATED JUL 05/16 FREQUENCY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160705	MOS HRS/MSC - AFL					(EBT)		
EM55-160705-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 41 DATED JUL 05/16 REQUIREMENT CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160705-1	MOS HRS/MSC - AFL					(EBT)		
EM55-160822	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS (TLMC) REVISION 42 DATED AUGUST 22/2016 REQUIREMENT SUMMARY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160822	MOS HRS/MSC - AFL							
EM55-161022	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 43 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161022	MOS HRS/MSC - AFL							



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EM55-161122	REVIEW EMBRAER 505 - PHENOM 300 (EM55) AIR WORTHINESS LIMITATIONS CHAPTER-4 REVISION 10 DATED NOV. 22/2016	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161122	HRS/MSC - AFL					(EBT)		
EM55-161122-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED NOV 22/2016	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161122-1	HRS/MSC - AFL							
EM55-161202	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) / CHAPTER-5 ADVANCE REVISION DATED DECEMBER 02/2016 REQUIREMENT SUMMARY CHANGE FORM	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161202	HRS/MSC - AFL							
EM55-180219	REVIEW EMBRAER PHENOM 300 (EM55) SCHEDULE MAINTENANCE REQUIREMENTS (SMR 2757 - CHAPTER 5) PART III REV 01, DATED FEB 19/18	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL					(EBT)		
EM55-190218A	REVIEW EMBRAER PHENOM 300 (EM55) CHAPTER 04 AIRWORTHINESS LIMITATIONS REVISION 11 DATED FEB 18/2019	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	-------------	------------	---------------------------	--------------

EM55-210514-ALS REVIEW EMBRAER PHENOM 300 - AMM - CHAPTER 04- REV. 14, DATED MAY 14TH, 2021

REQUIREMENT CHANGE
FORMS

REF: RCF 00

MOS
HRS/MSC -
AFL

EM55-211103-SMR REVIEW EMBRAER PHENOM 300 - AMM 2757, SMR REV. 04, DATED NOV 3, 2021

REQUIREMENT CHANGE
FORMS

REF: RCF 00

MOS
HRS/MSC -
AFL

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01

E53E-160530 NO. 1 ENGINE - REVIEW PW535E MM REV 11.0

REQUIREMENT CHANGE
FORMS

REF: RCF E53E

MOS
HRS/MSC -
ENC

(EBT)

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01

E53E-160530 NO. 2 ENGINE - REVIEW PW535E MM REV 11.0

REQUIREMENT CHANGE
FORMS

REF: RCF E53E

MOS
HRS/MSC -
ENC

(EBT)

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

H140-001 (s) EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE

PKG 87

MOS 120 +1m/-1m
HRS/MSC
AFL

REF: AMM 05-42-00

PKG

30-AUG-2021
2879:18
2002

H242-001 (s) INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE

PKG 87

MOS 120 +1m/-1m
HRS/MSC
AFL

REF: AMM 05-42-00

PKG

30-AUG-2021
2879:18
2002



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H430-001	INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS PKG 84 REF: AMM 05-46-00	MOS HRS/MSC AFL	60	+1m/-1m		-30	30-AUG-2021 2879:18 2002	31-JUL-2026	31-AUG-2026
H700-001	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS PKG 84 REF: AMM 05-47-00	MOS HRS/MSC AFL	60	+1m/-1m		-30	30-AUG-2021 2879:18 2002	31-JUL-2026	31-AUG-2026
H700-002	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS PKG 84 REF: AMM 05-47-00	MOS HRS/MSC AFL	60	+1m/-1m		-30	30-AUG-2021 2879:18 2002	31-JUL-2026	31-AUG-2026
H700-003	EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING PKG 84 REF: AMM 05-47-00	MOS HRS/MSC AFL	60	+1m/-1m		-30	30-AUG-2021 2879:18 2002	31-JUL-2026	31-AUG-2026
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01									
+ 05-50-00-210-802	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS REF: MM 05-50-00	MOS HRS/MSC ENC	A/R				23-FEB-2011 0 0		
+ 05-50-00-210-803	NO. 1 ENGINE - ENGINE OVERTEMPERATURE REF: MM 05-50-00	MOS HRS/MSC ENC	A/R				23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-804	NO. 1 ENGINE - ENGINE OVERSPEED	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-805	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	UNSHEDULED MAINTENANCE CHECK	ENC						0	
REF: MM 05-50-00									
+ 05-50-00-210-806	NO. 1 ENGINE - LIGHTNING STRIKE	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-807	NO. 1 ENGINE - DROPPED ENGINE	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-808	NO. 1 ENGINE - HEAVY LANDING	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-809	NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-810	NO. 1 ENGINE - ENGINE IMMERSION IN WATER	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-811	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-812	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-813	NO. 1 ENGINE - LOSS OF OIL	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-815	NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-816	NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-817	NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE	MOS					23-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-818	NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS	MOS					23-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-819	NO. 1 ENGINE - FUEL FILTER CONTAMINATION	MOS					23-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-820	NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN	MOS					23-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-821	NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL	MOS					23-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-822	NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL	MOS					23-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-823	NO. 1 ENGINE - FUEL CONTAMINATION	MOS					23-FEB-2011		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: MM 05-50-00	ENC					0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01									
+ 05-50-00-210-802	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS	MOS					28-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-803	NO. 2 ENGINE - ENGINE OVERTEMPERATURE	MOS					28-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-804	NO. 2 ENGINE - ENGINE OVERSPEED	MOS					28-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-805	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	MOS					28-FEB-2011		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-806	NO. 2 ENGINE - LIGHTNING STRIKE	MOS					28-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-807	NO. 2 ENGINE - DROPPED ENGINE	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-808	NO. 2 ENGINE - HEAVY LANDING	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-809	NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-810	NO. 2 ENGINE - ENGINE IMMERSION IN WATER	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-811	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-812	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-813	NO. 2 ENGINE - LOSS OF OIL	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-815	NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-816	NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-817	NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-818	NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	
+ 05-50-00-210-819	NO. 2 ENGINE - FUEL FILTER CONTAMINATION	MOS						28-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 05-50-00	ENC						0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-820	NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN	MOS					28-FEB-2011		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-821	NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL	MOS					28-FEB-2011		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-822	NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL	MOS					28-FEB-2011		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-823	NO. 2 ENGINE - FUEL CONTAMINATION	MOS					28-FEB-2011		
UNSCHEДУLED MAINTENANCE CHECK	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
CHAPTER 21 AIR CONDITIONING									
21-01-01	RH INSC ILLUM PANEL								
	441-42629-002	MOS		N:0			31-JUL-2011		
	1058	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
21-20-03	NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY								
	1300250-9	MOS					19-JUL-2012		
	425	HRS/MSC	O/C				332:48		
	REF: See Workcard	AFL					217		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-20-03	NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY 1300250-9 939 REF: See Workcard	MOS HRS/MSC AFL	O/C					16-AUG-2019 2529:54 1787	
21-20-05	GROUND COOLING FAN 1133660-3 186 REF: See Workcard	MOS HRS/MSC AFL	O/C					10-APR-2015 1319:18 901	
21-21-02-001 (s)	OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE PKG 60 REF: AMM 21-21-02	MOS HRS/MSC AFL	6400	+30/-30				PKG 31-JUL-2011 0 0	
21-21-02-001 (s)	OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE PKG 60 REF: AMM 21-21-02	MOS HRS/MSC AFL	6400	+30/-30				PKG 31-JUL-2011 0 0	
21-23-01	ELECTROMECHANICAL LINEAR ACTUATOR 100000-77 26056 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			31-JUL-2011 0 0	
21-23-03	RAM AIR VALVE 505-18030-405 0000659768 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			31-JUL-2011 0 0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-23-03-002 (s)	OPERATIONAL CHECK OF RAM AIR VALVE PKG 60 REF: AMM 21-23-03	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
21-23-03-003 (s)	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION PKG 1 REF: AMM 21-23-03	MOS HRS/MSC AFL	800	+30/-30			PKG 06-DEC-2012 597:06 399		
21-23-04-001 (s)	OPERATIONAL CHECK OF RAM AIR CHECK VALVES PKG 60 REF: AMM 21-23-04	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
21-23-05-001 (s)	GENERAL VISUAL INSPECTION OF GROUND COOLING FAN PKG 10 REF: AMM 21-23-05	MOS HRS/MSC AFL	1600	+30/-30			PKG 10-APR-2015 1319:18 901		
+ 21-24-01-001 (s)	OPERATIONAL CHECK OF IFE COOLING FAN PKG 60 REF: AMM 21-24-01	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
21-31-00-002 (s)	OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	800	+30/-30			PKG 13-JUL-2018 2299:30 1622		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-31-00-003 (s)	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE) PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	800	+30/-30			PKG 13-JUL-2018 2299:30 1622		
21-31-00-004 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	5600	+30/-30			PKG 31-JUL-2011 0 0		
21-31-00-005 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	5600	+30/-30			PKG 31-JUL-2011 0 0		
21-31-01	(ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT 2119286-5 2119286-00354 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
21-31-01-001	RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU) 2119286-5 2119286-00354 REF: AMM 21-31-01	MOS HRS/MSC AFL	5600	+30/-30			31-JUL-2011 0 0	6000 M 6030	
21-31-02	OUTFLOW VALVE 103922-1 103922-00064 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-31-02-001	RESTORATION (REPAIR) OF OUTFLOW VALVE 103922-1 103922-00064 REF: AMM 21-31-02	MOS HRS/MSC AFL	7200	+30/-30			31-JUL-2011 0 0	7200	7230
21-31-03	NEGATIVE PRESSURE RELIEF (NPR) VALVE 130664-2 34163-0310 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
21-31-03-001 (s)	OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-03	MOS HRS/MSC AFL	5600	+30/-30			PKG 31-JUL-2011 0 0		
21-31-04	PRESSURE RELIEF (PRV) VALVE 103918-2 103907-00089 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
21-31-04-001 (s)	FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-04	MOS HRS/MSC AFL	5600	+30/-30			PKG 31-JUL-2011 0 0		
21-41-01	BHS SHUT-OFF VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-01	CDM - COMPRESSOR 1134275-12 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				30-DEC-2016 1790:24 1250		
21-52-01-002	DISCARD OF COMPRESSOR DRIVE MODULE BELT REF: AMM 21-52-01	MOS HRS/MSC AFL	2000	+30/-30			30-DEC-2016 1790:24 1250	3790:24	3820:24
21-52-01-003 (s)	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION PKG 1 REF: AMM 21-52-01	MOS HRS/MSC AFL	800	+30/-30			PKG 30-DEC-2016 1790:24 1250		
21-52-01-004	RESTORATION (OVERHAUL) CDM - COMPRESSOR 1134275-12 SN-UNKNOWN REF: AMM 21-52-01	MOS HRS/MSC AFL	2000	+30/-30			30-DEC-2016 1790:24 1250	3790:24	3820:24
21-52-03	SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE 1133860-4 128 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:19 N:720:42 N:447			26-JUL-2012 332:48 217		
21-52-03-001 (s)	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES PKG 1 REF: AMM 21-52-03	MOS HRS/MSC AFL	800	+30/-30			PKG 26-JUL-2012 332:48 217		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-04	FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER 1133850-104 434 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
21-52-06-001 (s)	SERVICING OF VCS REFRIGERANT FLUID PKG 80 REF: AMM 12-17-00	MOS HRS/MSC AFL	12	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
21-52-08	AIR CONDITION CONDENSER ASSEMBLY 1133760-2 163 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
21-52-08-001 (s)	GENERAL VISUAL INSPECTION OF VCS CONDENSER PKG 10 REF: AMM 21-52-08	MOS HRS/MSC AFL	1600	+30/-30			PKG 22-AUG-2018 2299:30 1622		
21-52-09	AIR CONDITION MIX FLOW CONDENSER FAN 1133720-3 181 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
21-52-10	AIR CONDITION BLEED AIR HEAT EXCHANGER 1320260-2 153 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-61-00-001 (s)	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM PKG 1 REF: AMM 21-61-00	MOS HRS/MSC AFL	800	+30/-30			PKG 13-JUL-2018 2299:30 1622		
21-61-01	ECS TEMPERATURE CONTROLLER 1300670-6 00220 REF: See Workcard	MOS HRS/MSC AFL	O/C				10-APR-2015 1319:18 901		
21-61-03	LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 1411 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
21-61-03	RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 1545 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
21-61-04	COCKPIT DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 1407 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
21-61-05	CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 1354 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-61-06-001 (s)	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR PKG 60 REF: AMM 21-61-06	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
CHAPTER 22	AUTO FLIGHT								
22-11-00	GMC 715 GUIDANCE PANEL 011-01430-00 15900473 REF: See Workcard	MOS HRS/MSC AFL	O/C				31-JUL-2011 0 0		
22-11-00-001	FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d		-30	30-AUG-2021 2879:18 2002	31-JUL-2022	30-AUG-2022
AIRWORTHINESS									
22-11-00-001	FUNCTIONAL CHECK ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d		-30	30-AUG-2021 2879:18 2002	31-JUL-2022	30-AUG-2022
AIRWORTHINESS									
22-11-00-001	FUNCTIONAL CHECK RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d		-30	30-AUG-2021 2879:18 2002	31-JUL-2022	30-AUG-2022
AIRWORTHINESS									
22-11-00-001	FUNCTIONAL CHECK TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d		-30	30-AUG-2021 2879:18 2002	31-JUL-2022	30-AUG-2022
AIRWORTHINESS									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-00-002 (s)	LUBRICATION OF SERVO ACTUATORS PKG 80 REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
22-11-00-003 (s)	DETAILED INSPECTION OF AUTOPILOT SERVO CABLE PKG 42 REF: AMM 22-11-00	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			PKG 30-AUG-2021 2879:18 2002		
22-11-01	TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO 011-00877-21 1A0005613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
22-11-02	AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1006419 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
22-11-02	ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1006341 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:109 N:2650:54 N:1880			18-AUG-2020 2650:54 1880		
22-11-02	RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1005595 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:109 N:2650:54 N:1880			18-AUG-2020 2650:54 1880		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-03	AILERON GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK006113 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
22-11-06	ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK005948 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
22-11-09	RUDDER GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK005947 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
22-11-12	TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT 011-01904-00 1GK005944 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
CHAPTER 23 COMMUNICATIONS									
23-10-01	VHF ANTENNA S65-8280-41 322-2580 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
23-12-02	BOTTOM VHF 2 ANTENNA S65-8280-41 322-2579 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-50-01	LEFT GMA 1347D AUDIO PANEL 011-01257-20 17106384 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
23-50-02	COPILLOT HEADSET 026-55-999-0131 00200393 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
23-50-02	PILOT HEADSET 026-55-999-0131 00200392 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
23-50-03	HAND MICROPHONE 85-03-12369-04 244293 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
23-51-00-001 (s)	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE PKG 40 REF: AMM 23-51-00	MOS HRS/MSC AFL	3200	+30/-30			PKG 31-JUL-2011 0 0		
23-51-01	RIGHT GMA 1347D AUDIO PANEL 011-01257-20 17106390 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-51-05	LEFT CONTROL PANEL 441-40943-002 0628 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
23-51-05	RIGHT CONTROL PANEL 441-40943-002 0633 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
23-61-00-001 (s)	FUNCTIONAL CHECK OF STATIC DISCHARGERS PKG 83 REF: AMM 23-61-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
CHAPTER 24 ELECTRICAL POWER									
24-01-01	LEFT CONSOLE CONTROL PANEL 441-40929-002 0311 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
24-31-01	NO. 1 ENGINE STARTER/GENERATOR 400SG180Q S01423XL REF: See Workcard	MOS HRS/MSC AFL	O/C	O:1 O:0 O:0			05-NOV-2020 2687:12 1898		
24-31-01	NO. 2 ENGINE STARTER/GENERATOR 400SG180Q S01122XL REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			04-AUG-2020 2639:12 1869		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-01-001	NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017 400SG180Q S01423XL REF: AMM 24-31-01	MOS HRS/MSC AFL	800	+30/-30			05-NOV-2020 2687:12 1898	3487:12	3517:12
24-31-01-001	NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017 400SG180Q S01122XL REF: AMM 24-31-01	MOS HRS/MSC AFL	800	+30/-30			04-AUG-2020 2639:12 1869	3439:12	3469:12
24-31-01-003	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017) 400SG180Q S01423XL REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A				(EBT)		
24-31-01-003	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017) 400SG180Q S01122XL REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A				(EBT)		
24-31-02	LEFT 28V DC GENERATOR CONTROL UNIT GCSG550-12B 60104 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-JAN-2017 1790:24 1250		
24-31-02	RIGHT 28V DC GENERATOR CONTROL UNIT GCSG550-12B 60284 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-JAN-2017 1790:24 1250		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF LH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF RH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
24-36-01	AFT MAIN BATTERY 7638-48P G03087029 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:1 N:0 N:0			12-FEB-2020 2600:24 1840		
24-36-01	FORWARD MAIN BATTERY 7639-34 G03086867 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:1 N:0 N:0			12-FEB-2020 2600:24 1840		
24-36-01-003	DISCARD AFT MAIN BATTERY 7638-48P G03087029 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+1m/-1m +30/-30			12-FEB-2020 2600:24 1840	12-FEB-2022 2440	12-MAR-2022 2470
24-36-01-003	DISCARD FORWARD MAIN BATTERY 7639-34 G03086867 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+1m/-1m +30/-30			12-FEB-2020 2600:24 1840	12-FEB-2022 2440	12-MAR-2022 2470



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-36-01-004	FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7638-48P G03087029 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						
24-36-01-004	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7639-34 G03086867 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						
24-36-01-005	FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015) 7638-48P G03087029 REF: AMM 24-36-01	MOS HRS/MSC AFL	6	+1m/-1m			30-AUG-2021 2879:18 2002	28-FEB-2022	31-MAR-2022
24-36-01-005	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015) 7639-34 G03086867 REF: AMM 24-36-01	MOS HRS/MSC AFL	6	+1m/-1m			30-AUG-2021 2879:18 2002	28-FEB-2022	31-MAR-2022
24-36-02-001 (s)	OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2) PKG 60 REF: AMM 24-36-02	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
24-54-05	28 VDC / 115 VAC STATIC INVERTER AS-24-0026-001 0329 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-65-01	LEFT POWER DISTRIBUTION BOX SX7EG20-3 0565 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-OCT-2019 2546:24 1795		
24-65-02	RIGHT POWER DISTRIBUTION BOX SX7EG21-1B 0078 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-JUL-2013 776:42 507		
24-65-04	NOSE POWER DISTRIBUTION BOX SX7EG22-1B 0107 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-JUL-2013 776:42 507		
CHAPTER 25	EQUIPMENT/FURNISHINGS								
25-11-01	COPILOT SEAT 1429-621DE 1403-1429 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-11-01	PILOT SEAT 1429-521DE 1401-1429 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-11-01-001 (s)	DETAILED INSPECTION COPILOT SEAT PKG 20 REF: AMM 25-11-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 18-AUG-2020 2650:54 1880		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-01-001 (s)	DETAILED INSPECTION PILOT SEAT PKG 20 REF: AMM 25-11-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 18-AUG-2020 2650:54 1880		
25-11-01-002 (s)	DETAILED INSPECTION OF COCKPIT SEAT BELTS PKG 20 REF: AMM 25-11-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 18-AUG-2020 2650:54 1880		
25-21-01	PAX 1 - RH AFT FACE SEAT 403174-8I2FZ 50443 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-21-01	PAX 2 - LH AFT FACE SEAT 403174-5I2FZ 50438 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-21-01	PAX 3 - RH AFT FACE SEAT 403174-6I2FZ 50440 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-21-01	PAX 6 - LH FWD FACE SEAT 403174-7I2FZ 50441 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-01	PAX 7 - RH FWD FACE SEAT 403174-812FZ 50442 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER SEATS PKG 20 REF: AMM 25-21-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 18-AUG-2020 2650:54 1880		
25-21-01-002 (s)	DETAILED INSPECTION OF PASSENGER SEAT BELTS PKG 20 REF: AMM 25-21-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 18-AUG-2020 2650:54 1880		
25-21-02	DIVAN PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-21-02-001 (s)	DETAILED INSPECTION DIVAN PN PKG 40 SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	N/A				PKG 31-JUL-2011 0 0		
25-21-02-002 (s)	DETAILED INSPECTION DIVAN SEAT BELTS PN PKG 40 SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	N/A				PKG 31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-03	PAX 4 - LH FWD FACE SEAT 403174-512FZ 50437 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-21-03	PAX 5 - RH FWD FACE SEAT 403174-612FZ 50439 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-21-04-001	RESTORATION (REPAIR) OF SEAT BELT AIRBAG ELECTRONIC MODULE ASSEMBLY (EMA) - NOTE: REPLACE THE EMA (ELECTRONIC MODULE ASSEMBLY) INTERNAL BATTERY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
25-43-01-001 (s)	DETAILED VISUAL INSPECTION BELTED TOILET UNIT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3200	+30/-30			PKG 31-JUL-2011 0 0		
25-43-01-002 (s)	DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3200	+30/-30			PKG 31-JUL-2011 0 0		
25-60-01	EMERGENCY LOCATOR TRANSMITTER S1821502-02 AMDT.L RX1000022603 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:94 N:2442:54 N:1729			02-MAY-2019 2442:54 1729		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-60-03	ELT ANTENNA S65-8282-406 401-1848 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
25-60-11	EMERGENCY LOCATOR TRANSMITTER BATTERY S1820506-01 1526-0059 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			05-JAN-2017 1790:24 1250		
25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM S1821502-02 AMDT.L RX1000022603 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				15-JAN-2021 2724:46 1917	15-JAN-2022	
25-61-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER S1821502-02 AMDT.L RX1000022603 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				15-JAN-2021 2724:46 1917	15-JAN-2022	
25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY S1820506-01 1526-0059 REF: AMM 25-61-04	MOS HRS/MSC AFL	DUE				05-JAN-2017 1790:24 1250	30-APR-2022	M
25-61-05	CS144-A ELT/NAV INTERFACE MODULE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-01	FIRST AID KIT 640-151 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			12-JUL-2018 2299:30 1622		
25-62-01-001	VISUAL CHECK FIRST AID KIT 640-151 NSN REF: AMM 25-62-01	MOS HRS/MSC AFL	DUE				30-AUG-2021 2879:18 2002	01-AUG-2022 M	
25-62-02 (s)	COPILLOT LIFE VEST 63600-105 L1610031 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2021 2724:46 1917		
25-62-02 (s)	NO. 1 PASSENGER LIFE VEST 63600-105 L1609475 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2021 2724:46 1917		
25-62-02 (s)	NO. 2 PASSENGER LIFE VEST 63600-105 L1610032 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2021 2724:46 1917		
25-62-02 (s)	NO. 3 PASSENGER LIFE VEST 63600-105 L1609476 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2021 2724:46 1917		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02 (s)	NO. 4 PASSENGER LIFE VEST 63600-105 L1610033 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2021 2724:46 1917		
25-62-02 (s)	NO. 5 PASSENGER LIFE VEST 63600-105 L1609477 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2021 2724:46 1917		
25-62-02 (s)	NO. 6 PASSENGER LIFE VEST 63600-105 L1610034 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2021 2724:46 1917		
25-62-02 (s)	NO. 7 PASSENGER LIFE VEST 63600-105 L1609478 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2021 2724:46 1917		
25-62-02 (s)	PILOT LIFE VEST 63600-105 L1610030 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-JAN-2021 2724:46 1917		
+ 25-62-02-001	RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST 63600-105 L1610031 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				15-JAN-2021	15-JAN-2031	
OVERHAUL									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-62-02-001	RESTORATION (OVERHAUL) OF DIVAN NO. 1 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-001	RESTORATION (OVERHAUL) OF DIVAN NO. 2 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST 63600-105 L1609475 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				15-JAN-2021	15-JAN-2031	
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST 63600-105 L1610032 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				15-JAN-2021	15-JAN-2031	
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST 63600-105 L1609476 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				15-JAN-2021	15-JAN-2031	
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST 63600-105 L1610033 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				15-JAN-2021	15-JAN-2031	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 5 LIFE VEST 63600-105 L1609477 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				15-JAN-2021	15-JAN-2031	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST 63600-105 L1610034 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				15-JAN-2021	15-JAN-2031	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 7 LIFE VEST 63600-105 L1609478 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				15-JAN-2021	15-JAN-2031	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF PILOT LIFE VEST 63600-105 L1610030 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				15-JAN-2021	15-JAN-2031	
OVERHAUL									
25-62-04-001 (s)	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER PKG 81 REF: AMM 25-62-04	MOS HRS/MSC AFL	24	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
25-66-01	LIFE RAFT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-AUG-2018 2299:30 1622		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-66-01-001	RESTORATION LIFE RAFT (OVERHAUL) PN NOT INSTALLED REF: AMM 25-66-01	MOS HRS/MSC AFL	N/A					20-AUG-2018 2299:30 1622	
CHAPTER 26 FIRE PROTECTION									
26-11-01	LEFT ENGINE FIRE DETECTOR 3951-51-565/215C-5.1M 44546 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	
26-11-01	RIGHT ENGINE FIRE DETECTOR 3951-51-565/215C-5.1M 44512 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	
26-11-01-001 (s)	DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1600	+30/-30				PKG 22-AUG-2018 2299:30 1622	
26-11-01-001 (s)	DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1600	+30/-30				PKG 22-AUG-2018 2299:30 1622	
26-11-01-002 (s)	OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR PKG 1 REF: AMM 26-11-01	MOS HRS/MSC AFL	800	+30/-30				PKG 22-AUG-2018 2299:30 1622	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-11-01-002 (s)	OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR PKG 1 REF: AMM 26-11-01	MOS HRS/MSC AFL	800	+30/-30			PKG 22-AUG-2018 2299:30 1622		
26-15-01	MODEL 602 SMOKE DETECTOR 8930-223B60L014 20400 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
26-21-01	ENGINE FIRE EXTINGUISHER BOTTLE 33000073-1 93319A1 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:8 N:0 N:0			18-AUG-2020 2650:54 1880		
26-21-01-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL REF: AMM 26-21-00	MOS HRS/MSC AFL	2400	+30/-30			11-JUL-2018 2299:30 1622	4699:30	4729:30
AIRWORTHINESS									
26-21-01A	FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL 441-42702-002 0403 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
26-21-03-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHER BOTTLE 33000073-1 93319A1 REF: AMM 26-21-03	MOS HRS/MSC AFL	120				18-AUG-2020 2650:54 1880	04-DEC-2029 M	
AIRWORTHINESS									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-05-001 (s)	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS) PKG 20 REF: AMM 26-21-05	MOS HRS/MSC AFL	2400	+30/-30			PKG 30-DEC-2016 1790:24 1250		
26-21-07	NO. 1 CARTRIDGE PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	N:8 N:0 N:0			18-AUG-2020 2650:54 1880		
26-21-07	NO. 2 CARTRIDGE PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	N:8 N:0 N:0			18-AUG-2020 2650:54 1880		
26-21-07-001 LIFE LIMIT	DISCARD NO. 1 CARTRIDGE PN-UNKNOWN SN-UNKNOWN REF: AMM 26-21-07	MOS HRS/MSC AFL	120				01-DEC-2019	01-DEC-2029	
26-21-07-001 LIFE LIMIT	DISCARD NO. 2 CARTRIDGE PN-UNKNOWN SN-UNKNOWN REF: AMM 26-21-07	MOS HRS/MSC AFL	120				01-DEC-2019	01-DEC-2029	
26-21-09-001 (s)	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING PKG 20 REF: AMM 26-21-09	MOS HRS/MSC AFL	2400	+30/-30			PKG 30-DEC-2016 1790:24 1250		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-24-01	CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 X-725092 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0				31-JUL-2011 0 0	
26-24-01	COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-725100 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0				31-JUL-2011 0 0	
26-24-01-001	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 X-725092 REF: AMM 26-24-01	MOS HRS/MSC AFL	12		-12		30-AUG-2021	18-AUG-2022	
26-24-01-001	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-725100 REF: AMM 26-24-01	MOS HRS/MSC AFL	12		-12		30-AUG-2021	18-AUG-2022	
26-24-01-002	DISCARD CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 X-725092 REF: AMM 26-24-01	MOS HRS/MSC AFL	144				01-APR-2011	01-APR-2023	
LIFE LIMIT									
26-24-01-002	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-725100 REF: AMM 26-24-01	MOS HRS/MSC AFL	144				01-APR-2011	01-APR-2023	
LIFE LIMIT									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-24-01-003	DISCARD CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 X-725092 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
26-24-01-003	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-725100 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-004	WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 X-725092 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-004	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-725100 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
CHAPTER 27 FLIGHT CONTROLS									
+ 27-001	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1013 0428 REF: See Workcard	MOS HRS/MSC AFL	N/A					31-JUL-2011 0 0	
+ 27-001	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1013 0456 REF: See Workcard	MOS HRS/MSC AFL	N/A					31-JUL-2011 0 0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-002	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2013 0240 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
+ 27-002	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2013 0243 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
+ 27-003	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR 475000-1013 0282 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
+ 27-003	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR 475000-1013 0711 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
27-004	ROLL TRIM ACTUATOR 470500-1005 0069 REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			31-JUL-2011 0 0	12000	
LIFE LIMIT									
27-005	YAW TRIM ACTUATOR 470600-1005 0088 REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			31-JUL-2011 0 0	12000	
LIFE LIMIT									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-006	PITCH TRIM ACTUATOR 467500-1003 0123 REF: See Workcard	MOS HRS/MSC AFL	35000	N:4025 N:2680			17-APR-2017 1897:06 1324	32872:06	
LIFE LIMIT									
27-007	LEFT SPOILER ACTUATOR 456800-1003 0151 REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			31-JUL-2011 0 0	35000	
LIFE LIMIT									
27-007	RIGHT SPOILER ACTUATOR 456800-1003 0152 REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			31-JUL-2011 0 0	35000	
LIFE LIMIT									
27-008	ELECTRO - RUDDER GUST LOCK ACTUATOR SYLC-53058 1690 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-MAR-2016 1530:36 1057		
27-009	RUDDER BOOSTER ACTUATOR 9125-3 0071T REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			31-JUL-2011 0 0	35000	
LIFE LIMIT									
27-01-01	LEFT CONTROL WHEEL 83912139 00511 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-01-01	RIGHT CONTROL WHEEL 83912140 00521 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
27-01-03-001 (s)	LUBRICATION OF ROTARY BALL SPLINE PKG 81 REF: AMM 12-21-00	MOS HRS/MSC AFL	24	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
27-010 LIFE LIMIT	LEFT TOGGLE LINK 456870-1001 0130 REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			31-JUL-2011 0 0	35000	
27-010 LIFE LIMIT	RIGHT TOGGLE LINK 456870-1001 0131 REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			31-JUL-2011 0 0	35000	
27-011 LIFE LIMIT	STICK PUSHER ACTUATOR 9124-1 0112T REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			31-JUL-2011 0 0	35000	
27-012 LIFE LIMIT	POWER DRIVE UNIT 467700-1003 0085 REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			31-JUL-2011 0 0	35000	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-013	LEFT FLAP POSITION SENSOR UNIT								
	457310-1001	MOS		N:0			31-JUL-2011		
	0164	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		N:0			0		
27-013	RIGHT FLAP POSITION SENSOR UNIT								
	457310-1001	MOS		N:0			31-JUL-2011		
	0166	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF: See Workcard	AFL		N:0			0		
+ 27-014	DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT								
	457360-1007	MOS					31-JUL-2011		
	SSW0118	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		
+ 27-014	DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT								
	457360-1005	MOS					31-JUL-2011		
	SSW0229	HRS/MSC	35000				0		35000
LIFE LIMIT	REF: See Workcard	AFL					0		
+ 27-014	DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT								
	457360-1005	MOS					31-JUL-2011		
	SSW0231	HRS/MSC	35000				0		35000
LIFE LIMIT	REF: See Workcard	AFL					0		
+ 27-014	DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT								
	457360-1007	MOS					31-JUL-2011		
	SSW0117	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-014	DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0232 REF: See Workcard	MOS HRS/MSC AFL	35000				31-JUL-2011 0 0	35000	
LIFE LIMIT									
+ 27-014	DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0230 REF: See Workcard	MOS HRS/MSC AFL	35000				31-JUL-2011 0 0	35000	
LIFE LIMIT									
+ 27-015	DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0118 REF: See Workcard	MOS HRS/MSC AFL	35000				31-JUL-2011 0 0	35000	
LIFE LIMIT									
+ 27-015	DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0229 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
+ 27-015	DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0231 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
+ 27-015	DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0117 REF: See Workcard	MOS HRS/MSC AFL	35000				31-JUL-2011 0 0	35000	
LIFE LIMIT									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-015	DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0232 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
+ 27-015	DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0230 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
+ 27-016	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1013 0428 REF: See Workcard	MOS HRS/MSC AFL	7200	I:1779 I:1345			30-DEC-2016 1790:24 1250	7211:24	
+ 27-016	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1013 0456 REF: See Workcard	MOS HRS/MSC AFL	7200	I:1779 I:1345			30-DEC-2016 1790:24 1250	7211:24	
+ 27-017	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2013 0240 REF: See Workcard	MOS HRS/MSC AFL	7200	I:3474 I:2346			30-DEC-2016 1790:24 1250	5516:24	
+ 27-017	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2013 0243 REF: See Workcard	MOS HRS/MSC AFL	7200	I:3476:12 I:2351			30-DEC-2016 1790:24 1250	5514:12	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-018	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR 475000-1013 0282 REF: See Workcard	MOS HRS/MSC AFL	7200	I:1533 I:1105			30-DEC-2016 1790:24 1250	7457:24	
LIFE LIMIT									
+ 27-018	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR 475000-1013 0711 REF: See Workcard	MOS HRS/MSC AFL	7200	I:1776 I:1152			30-DEC-2016 1790:24 1250	7214:24	
LIFE LIMIT									
27-03-01	NO. 1 ELECTRONICS FLIGHT CONTROL 462900-1017 0582 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-APR-2017 1897:06 1324		
27-03-01	NO. 2 ELECTRONICS FLIGHT CONTROL 462900-1017 0604 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JUN-2020 2626:12 1855		
27-03-01-002 (s)	FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP PKG 50 REF: AMM 27-03-01	MOS HRS/MSC AFL	5600	+30/-30			PKG 31-JUL-2011 0 0		
27-03-01-003 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER PKG 50 REF: AMM 27-03-01	MOS HRS/MSC AFL	5600	+30/-30			PKG 31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-03-01-004	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR	MOS					31-JUL-2011		
AIRWORTHINESS	REF: AMM 27-03-01	HRS/MSC	6000	+30/-30			0	6000	6030
		AFL					0		
27-04-01	TRIM ACTUATOR CONTROLLER	MOS							
	475200-1005	HRS/MSC	O/C						
	0146	AFL							
	REF: See Workcard								
27-04-01-001 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER	MOS					PKG		
	PKG 50	HRS/MSC	5600	+30/-30			31-JUL-2011		
	REF: AMM 27-04-01	AFL					0		
							0		
27-04-01-002 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP	MOS					PKG		
	PKG 50	HRS/MSC	5600	+30/-30			31-JUL-2011		
	REF: AMM 27-04-01	AFL					0		
							0		
27-11-00	AILERON CABLES ASSY.	MOS					30-AUG-2021		
	PN	HRS/MSC	O/C				2879:18		
	SN-UNKNOWN	AFL					2002		
	REF: See Workcard								
27-11-00-001 (s)	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS	MOS	60	+1m/-1m			PKG		
	PKG 42	HRS/MSC	3200	+30/-30			30-AUG-2021		
	REF: AMM 27-11-00	AFL					2879:18		
							2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-11-01	LEFT AILERON 505-14735-635 0000658191 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-JUL-2020 2630:24 1861		
27-11-01	RIGHT AILERON 505-14696-603 0000657854 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-JUL-2020 2630:24 1861		
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			30-AUG-2021 2879:18 2002	30-AUG-2026 6079:18	30-SEP-2026 6109:18
27-11-02-001(INITIAL)	FUNCTION CHECK OF AILERON CONTROL CABLES TENSION - INITIAL 12 MOS CHECK REF: AMM 27-11-02	MOS HRS/MSC AFL	12	+1m/-1m			30-AUG-2021 2879:18 2002	30-AUG-2022	30-SEP-2022
27-11-02-002 (s)	DETAILED INSPECTION OF AILERON CONTROL CABLES PKG 42 REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			PKG 30-AUG-2021 2879:18 2002		
27-14-02-001	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY REF: AMM 27-14-03	MOS HRS/MSC AFL	6000	+30/-30			31-JUL-2011 0 0	6000	6030
AIRWORTHINESS									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-14-02-002	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM	MOS					31-JUL-2011		
AIRWORTHINESS	REF: AMM 27-14-02	HRS/MSC	6000	+30/-30			0	6000	6030
		AFL					0		
27-14-03	LEFT AILERON TAB	MOS					31-JUL-2011		
	505-14679-4003	HRS/MSC	O/C	N:0			0		
	0000657024	AFL		N:0			0		
	REF: See Workcard			N:0					
27-21-00	RUDDER CABLES ASSY.	MOS					31-JUL-2011		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	REF: See Workcard			N:0					
27-21-00-001 (s)	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS						PKG		
	PKG 42	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC	3200	+30/-30			2879:18		
	REF: AMM 27-21-00	AFL					2002		
27-21-01	RUDDER ASSEMBLY	MOS					16-JUL-2020		
	505-39061-611	HRS/MSC	O/C				2630:24		
	0000660023	AFL					1861		
	REF: See Workcard								
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION	MOS	60	+1m/-1m			12-JUL-2017	12-JUL-2022	12-AUG-2022
		HRS/MSC	3200	+30/-30			1987:12	5187:12	5217:12
	REF: AMM 27-21-02	AFL					1393		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-21-02-001(INITIAL)	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION - INITIAL 12 MOS CHECK	MOS						31-JUL-2011	
	REF: AMM 27-21-02	HRS/MSC -						0	
		AFL						0	
27-21-02-002 (s)	DETAILED INSPECTION OF RUDDER CONTROL CABLES							PKG	
	PKG 42	MOS	60	+1m/-1m				30-AUG-2021	
	REF: AMM 27-21-02	HRS/MSC	3200	+30/-30				2879:18	
		AFL						2002	
27-23-00-001 (s)	OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM							PKG	
	PKG 10	MOS						13-JUL-2018	
	REF: AMM 27-23-00	HRS/MSC	1600	+30/-30				2299:30	
		AFL						1622	
27-24-02-001	FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH								
		MOS						31-JUL-2011	
AIRWORTHINESS	REF: AMM 27-24-03	HRS/MSC	6000	+30/-30				0	6000 6030
		AFL						0	
27-24-02-002	DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM								
		MOS						31-JUL-2011	
AIRWORTHINESS	REF: AMM 27-24-02	HRS/MSC	6000	+30/-30				0	6000 6030
		AFL						0	
27-24-03	RUDDER TRIM TAB								
	505-10450-401	MOS		N:0				31-JUL-2011	
	0000656893	HRS/MSC	O/C	N:0				0	
	REF: See Workcard	AFL		N:0				0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-26-01	VENTRAL RUDDER 505-07540-417 0000671429 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
27-31-00	ELEVATOR CABLES ASSY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
27-31-00-001 (s)	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 REF: AMM 27-31-00	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			PKG 30-AUG-2021 2879:18 2002		
27-31-01	LEFT ELEVATOR 505-11101-603 0000660010 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-JUL-2020 2630:24 1861		
27-31-01	RIGHT ELEVATOR 505-11101-604 0000660012 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-JUL-2020 2630:24 1861		
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION REF: AMM 27-31-02	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			12-JUL-2017 1987:12 1393	12-JUL-2022 5187:12	12-AUG-2022 5217:12



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-31-02-001(INITIAL)	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION - INITIAL 12 MOS CHECK REF: AMM 27-31-02	MOS HRS/MSC - AFL						31-JUL-2011 0 0	
27-31-02-002 (s)	DETAILED INSPECTION OF ELEVATOR CONTROL CABLES PKG 42 REF: AMM 27-31-02	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30				PKG 30-AUG-2021 2879:18 2002	
27-31-03	LEFT ELEVATOR TAB 505-39086-4003 0000657033 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	
27-31-03	RIGHT ELEVATOR TAB 505-39086-4004 0000657026 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	
27-31-03-001 (s)	FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH PKG 50 REF: AMM 27-31-03	MOS HRS/MSC AFL	5600	+30/-30				PKG 31-JUL-2011 0 0	
27-31-03-002 (s)	DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM PKG 50 REF: AMM 27-31-03	MOS HRS/MSC AFL	5600	+30/-30				PKG 31-JUL-2011 0 0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-36-03-001 (s)	OPERATIONAL CHECK OF PUSHER CUTOUT SWITCH PKG 10 REF: AMM 27-36-03	MOS HRS/MSC AFL	1600	+30/-30			PKG 30-AUG-2019 2537:42 1791		
27-41-01-001	DETAILED INSPECTION OF PITCH TRIM ACTUATOR REF: AMM 27-41-01	MOS HRS/MSC AFL	6000	+30/-30			31-JUL-2011 0 0	6000	6030
AIRWORTHINESS									
27-41-01-002	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH REF: AMM 27-40-00	MOS HRS/MSC AFL	6000	+30/-30			31-JUL-2011 0 0	6000	6030
AIRWORTHINESS									
27-41-01-003 (s)	LUBRICATION OF PITCH TRIM ACTUATOR PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-41-01-004	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK REF: AMM 27-41-01	MOS HRS/MSC AFL	6000	+30/-30			31-JUL-2011 0 0	6000	6030
AIRWORTHINESS									
27-41-01-005 (s)	SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES PKG 83 REF: AMM 12-18-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-41-01-006 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP PKG 50 REF: AMM 27-41-01	MOS HRS/MSC AFL	5600	+30/-30			PKG 31-JUL-2011 0 0		
27-50-01-01-901	DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL REF: NDT PART 5 27-51-00	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
27-51-01-001 (s)	LUBRICATION OF FLAP ACTUATORS BALL SCREWS PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-01-002	DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR REF: AMM 27-51-01	MOS HRS/MSC AFL	6000	+30/-30			30-DEC-2016 1790:24 1250	7790:24	7820:24
27-51-01-002	DETAILED INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR REF: AMM 27-51-01	MOS HRS/MSC AFL	6000	+30/-30	I:3474		30-DEC-2016 1790:24 1250	4316:24	4346:24
27-51-01-002	DETAILED INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR REF: AMM 27-51-01	MOS HRS/MSC AFL	6000	+30/-30	I:1779		30-DEC-2016 1790:24 1250	6011:24	6041:24



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-01-002	DETAILED INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR	MOS					30-DEC-2016		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			1790:24 1250	7790:24	7820:24
27-51-01-002	DETAILED INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					30-DEC-2016		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30	I:3476:12		1790:24 1250	4314:12	4344:12
27-51-01-002	DETAILED INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					30-DEC-2016		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30	I:1779		1790:24 1250	6011:24	6041:24
27-51-01-004	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER	MOS					30-DEC-2016		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			1790:24 1250	7790:24	7820:24
27-51-01-005 (s)	SERVICING OF FLAP ACTUATOR GEAR BOXES						PKG		
	PKG 83	MOS	48	+1m/-1m			30-AUG-2019		
	REF: AMM 12-18-00	HRS/MSC AFL					2537:42 1791		
27-51-01-900-801-01	LEFT NO. 3 OUTBOARD FLAP ACTUATOR								
	475100-1013	MOS					30-DEC-2016		
	0428	HRS/MSC	H/T		N:1779		1790:24		
	REF: See Workcard	AFL			N:1345		1250		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-01-900-801-02	RIGHT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1013 0456 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:1779 N:1345			30-DEC-2016 1790:24 1250		
27-51-01-900-801-03	LEFT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2013 0240 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:3474 N:2346			30-DEC-2016 1790:24 1250		
27-51-01-900-801-04	RIGHT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2013 0243 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:3476:12 N:2351			30-DEC-2016 1790:24 1250		
27-51-01-900-801-05	LEFT NO. 1 INBOARD FLAP ACTUATOR 475000-1013 0282 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:1533 N:1105			30-DEC-2016 1790:24 1250		
27-51-01-900-801-06	RIGHT NO. 1 INBOARD FLAP ACTUATOR 475000-1013 0711 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:1776 N:1152			30-DEC-2016 1790:24 1250		
27-51-05	LEFT INBOARD FLAP 505-14401-4003 0000656903 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-05	LEFT OUTBOARD FLAP 505-14361-4003 0000649362 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
27-51-05	RIGHT INBOARD FLAP 505-14401-4004 0000656407 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
27-51-05	RIGHT OUTBOARD FLAP 505-14361-4004 0000655853 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
27-51-06-001 (s)	LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-001 (s)	LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-001 (s)	LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-001 (s)	LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-001 (s)	LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-001 (s)	LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+1m/-1m			PKG 30-AUG-2019 2537:42 1791		
27-51-06-900-801-01	RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0230 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			31-JUL-2011 0 0		
27-51-06-900-801-02	RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0232 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			31-JUL-2011 0 0		
27-51-06-900-801-03	LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0231 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-900-801-04	LEFT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0229 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			31-JUL-2011 0 0		
27-51-06-900-801-05	LEFT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0118 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			31-JUL-2011 0 0		
27-51-06-900-801-06	RIGHT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0117 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			31-JUL-2011 0 0		
27-53-01	FLAP SELECTOR, PRODUCTION, LEVER 780501-9 1132 REF: See Workcard	MOS HRS/MSC AFL	O/C						
27-64-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 6 27-64-00								
27-64-01-01-902	DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 27-64-00								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-64-01-02-901	SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 7 27-64-00	AFL	14000				0		14000
27-65-00-001 (s)	FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM	MOS					PKG		
	PKG 60	HRS/MSC	6400	+30/-30			31-JUL-2011		
	REF: AMM 27-60-00	AFL					0		
27-65-01-001 (s)	GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU)	MOS					PKG		
	PKG 60	HRS/MSC	6400	+30/-30			31-JUL-2011		
	REF: AMM 27-65-00	AFL					0		
27-66-01	NO. 1 CONTROL WHEEL POSITION SENSOR	MOS					31-JUL-2011		
	456896-1001	HRS/MSC	O/C	N:0			0		
	023187	AFL		N:0			0		
	REF: See Workcard			N:0			0		
27-66-01	NO. 2 CONTROL WHEEL POSITION SENSOR	MOS					31-JUL-2011		
	456896-1001	HRS/MSC	O/C	N:0			0		
	865991	AFL		N:0			0		
	REF: See Workcard			N:0			0		
27-66-02	LEFT SPOILER SURFACE POSITION SENSOR	MOS					31-JUL-2011		
	456897-1001	HRS/MSC	O/C	N:0			0		
	008573	AFL		N:0			0		
	REF: See Workcard			N:0			0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-66-02	RIGHT SPOILER SURFACE POSITION SENSOR 456897-1001 864225 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-SEP-2015 1406:48 966		
CHAPTER 28 FUEL									
28-11-00-001 (s)	FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS PKG 80 REF: AMM 28-11-00	MOS HRS/MSC AFL	12	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
28-11-05	LEFT WING WATER DRAIN VALVE L83A13-628 E61905 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-11-05	RIGHT WING WATER DRAIN VALVE L83A13-628 E54596 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-11-07	LEFT WING DUMP VALVE V98A32-001 E72275 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-11-07	RIGHT WING DUMP VALVE V98A32-001 E72268 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-12-01-001 (s)	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA PKG 1 REF: AMM 28-12-01	MOS HRS/MSC AFL	800	+30/-30			PKG 30-AUG-2019 2537:42 1791		
28-12-03	LEFT FUEL TANK FLOAT VENT VALVE L87-19-001P2 E63037 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-12-03	RIGHT FUEL TANK FLOAT VENT VALVE L87-19-001P2 E63043 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-12-03-001 (s)	OPERATIONAL CHECK LEFT FLOAT VENT VALVE PKG 60 REF: AMM 28-12-03	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
28-12-03-001 (s)	OPERATIONAL CHECK RIGHT FLOAT VENT VALVE PKG 60 REF: AMM 28-12-03	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
28-21-02	LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 E82130 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-02	RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 E82138 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-03	LEFT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 E83865 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-03	RIGHT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 E83869 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-05	LEFT WING JET PUMP FEED LINE T99A19-602 E83491 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-05	RIGHT WING JET PUMP FEED LINE T99A19-602 E76092 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-07	LEFT 0.75 SHUTOFF VALVE B97-15-601 E64993 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-07	RIGHT 0.75 SHUTOFF VALVE B97-15-601 E64998 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-07-001	OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM REF: AMM 28-21-07	MOS HRS/MSC AFL	600	+30/-30		20:12	30-AUG-2021 2879:18 2002	3499:30	3529:30
AIRWORTHINESS									
28-21-07-001	OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM REF: AMM 28-21-07	MOS HRS/MSC AFL	600	+30/-30		20:12	30-AUG-2021 2879:18 2002	3499:30	3529:30
AIRWORTHINESS									
28-21-08	FORWARD LEFT 28 VDC SOV ACTUATOR D97C00-644P2 C70967 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-08	LEFT WING 28 VDC SOV ACTUATOR D97C00-644P2 C70987 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-08	REAR RIGHT 28 VDC SOV ACTUATOR D97C00-644P2 C70988 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-09	LEFT WING SCAVENGER JET PUMP T99A19-603 E77408 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-09	RIGHT WING SCAVENGER JET PUMP T99A19-603 E77410 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-10	3/4" (CROSSFEED) SHUT OFF VALVE B97H19-608P2 E75972 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-10-001	OPERATIONAL CHECK OF FUEL XFEED VALVE REF: AMM 28-21-10	MOS HRS/MSC AFL	12000	+30/-30			31-JUL-2011 0 0	12000	12030
28-21-11	LEFT WING 1/2 INCH CHECK VALVE VALVE L96-13-001 E74661 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-21-11	RIGHT WING 1/2 INCH CHECK VALVE VALVE L96-13-001 E74666 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-13	INSC ILLUM PANEL 441-42621-002 1061 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-23-01	REFUEL CONTROL PANEL 742388-1-2 742388IN00165 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-23-03	LEFT WING PRESSURE REFUELING SOLENOID VALVE L94E31-653P2 E88620 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-23-03	RIGHT WING PRESSURE REFUELING SOLENOID VALVE L94E31-653P2 E88618 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-23-04-001 (s)	GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER PKG 40 REF: AMM 28-23-05	MOS HRS/MSC AFL	3200	+30/-30			PKG 31-JUL-2011 0 0		
28-23-07	LEFT HIGH LEVEL SENSOR 722860-2-0 0246 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-23-07	RIGHT HIGH LEVEL SENSOR 722860-2-0 0251 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-23-09	FUEL PORT AND CAP K97-63-613 E74372 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-41-01	NO. 1 LEFT PROBE 765896-1-0 765896IN00251 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-41-01	NO. 1 RIGHT PROBE 765896-1-0 765896IN00260 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-41-01	NO. 2 LEFT PROBE 765873-1-0 765873IN00216 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-41-01	NO. 2 RIGHT PROBE 765873-1-0 765873IN00211 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-01	NO. 3 LEFT PROBE 765874-1-0 765874IN00216 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-41-01	NO. 3 RIGHT PROBE 765874-1-0 765874IN00254 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-41-01	NO. 4 LEFT PROBE 765875-1-0 765875IN00218 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-41-01	NO. 4 RIGHT PROBE 765875-1-0 765875IN00219 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-41-05	EFCU ELECTRICAL FUEL CONTROL UNIT 738742-1-4 738790IN00442 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-43-01	TEMPERATURE SENSOR 798840-1-0 02332 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-43-01-001 (s)	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR PKG 60 REF: AMM 28-43-01	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
28-45-01	LEFT PRESSURE SWITCH D98C07-611 0629 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
28-45-01	RIGHT PRESSURE SWITCH D98C07-611 0630 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
CHAPTER 29	HYDRAULIC POWER								
29-12-02	CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR 3032763-003 MX744013 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-AUG-2014 1096 738		
29-12-02	LEFT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX745314 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
29-12-02	RIGHT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX745808 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-12-02-001 (s)	VISUAL CHECK OF MANIFOLD/ RESERVOIR PKG 80 REF: AMM 29-12-02	MOS HRS/MSC AFL	12	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
29-12-02-002 (s)	OPERATIONAL CHECK LEFT EDP CHECK VALVE PKG 50 REF: AMM 29-10-00	MOS HRS/MSC AFL	5600	+30/-30			PKG 17-SEP-2019 2546:24 1795		
29-12-02-002 (s)	OPERATIONAL CHECK RIGHT EDP CHECK VALVE PKG 50 REF: AMM 29-10-00	MOS HRS/MSC AFL	5600	+30/-30			PKG 17-SEP-2019 2546:24 1795		
29-15-03	CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 25 CU.IN ACCUMULATOR 0860231003 60231-2334 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
29-15-03-001 (s)	SERVICING CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 25 CU.IN ACCUMULATOR 0860231003 PKG 80 60231-2334 REF: AMM 12-13-00	MOS HRS/MSC AFL	12	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
29-15-04	NO. 1 FSOV FIRE SHUT OFF VALVE 3032428-001 AA238535 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-15-04	NO. 2 FSOV FIRE SHUT OFF VALVE 3032428-001 AA238536 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
29-15-04-001	OPERATIONAL CHECK LEFT ENGINE HYDRAULIC SHUT-OFF VALVE REF: AMM 29-15-04	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30		-30	30-AUG-2019 2537:42 1791	31-JUL-2023 5537:42	30-AUG-2023 5567:42
AIRWORTHINESS									
29-15-04-001	OPERATIONAL CHECK RIGHT ENGINE HYDRAULIC SHUT-OFF VALVE REF: AMM 29-15-04	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30		-30	30-AUG-2019 2537:42 1791	31-JUL-2023 5537:42	30-AUG-2023 5567:42
AIRWORTHINESS									
29-15-05	PRIORITY VALVE 2217-0001-401 00061 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
29-31-02-001 (s)	FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE PKG 50 REF: AMM 29-31-02	MOS HRS/MSC AFL	5600	+30/-30			17-SEP-2019 2546:24 1795		
CHAPTER 30	ICE AND RAIN PROTECTION								
30-01-01	MD INSC ILLUM PANEL 441-43234-002 1037 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-00-001 (s)	OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM PKG 60 REF: AMM 30-10-00	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
30-12-01-001 (s)	FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS PKG 60 REF: AMM 30-12-01	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
30-12-02	LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-3 0014 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
30-12-02	RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-4 0069 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
30-12-05	LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7623-4-30 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
30-12-05	LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7723-1-556 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-05	RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7623-4-37 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
30-12-05	RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7723-1-549 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
30-12-05-001 (s)	FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 60 REF: AMM 30-12-05	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
30-12-05-001 (s)	FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 60 REF: AMM 30-12-05	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
30-12-05-002 (s)	FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER PKG 60 REF: AMM 30-12-05	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
30-12-05-002 (s)	FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER PKG 60 REF: AMM 30-12-05	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-21-01	LEFT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0000130 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
30-21-01	RIGHT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0000119 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
30-21-02	LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 7717-11-57 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
30-21-02	RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 7717-11-17 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
30-21-02-001	FUNCTIONAL CHECK OF LEFT ENGINE ANTI-ICING PRESSURE TRANSDUCER REF: AMM 30-21-02	MOS HRS/MSC AFL	12000	+30/-30			31-JUL-2011 0 0	12000	12030
30-21-02-001	FUNCTIONAL CHECK OF RIGHT ENGINE ANTI-ICING PRESSURE TRANSDUCER REF: AMM 30-21-02	MOS HRS/MSC AFL	12000	+30/-30			31-JUL-2011 0 0	12000	12030



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-21-02-720-801-A	TROUBLE SHOOTING ENGINE OPERATING PROBLEMS - ENGINE ANTI-ICING PRESSURE TRANSDUCER FUNCTIONAL CHECK								
		MOS					31-JUL-2011		
		HRS/MSC	A/R				0		
		AFL					0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 30-21-02								
30-21-03-001 (s)	BORESCOPE INSPECTION OF PICCOLO TUBE						PKG		
	PKG 50	MOS					31-JUL-2011		
		HRS/MSC	5600	+30/-30			0		
	REF: AMM 30-21-03	AFL					0		
30-21-04-001 (s)	DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS						PKG		
	PKG 20	MOS					30-DEC-2016		
		HRS/MSC	2400	+30/-30			1790:24		
	REF: AMM 30-21-00	AFL					1250		
30-31-00-002	OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING								
	PKG 81	MOS	24	+1m/-1m			30-AUG-2021	30-AUG-2023	30-SEP-2023
		HRS/MSC					2879:18		
	REF: AMM 30-30-00	AFL					2002		
+ 30-41-01-002 (s)	DISCARD OF WINDSHIELD RAIN REPELLENT COATING						PKG		
	PKG 80	MOS	12	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: AMM 30-41-01	AFL					2002		
30-41-01-003 (s)	FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE						PKG		
	PKG 80	MOS	12	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: AMM 30-41-01	AFL					2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-42-00-001 (s)	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM PKG 1 REF: AMM 30-42-00	MOS HRS/MSC AFL	800	+30/-30			PKG 13-JUL-2018 2299:30 1622		
30-42-01	LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-1124-4 02034 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-APR-2013 669 434		
30-42-01	RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-112-4 02033 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-APR-2013 669 434		
CHAPTER 31	INDICATING/RECORDING SYSTEMS								
31-30-02	CVDR ACCELEROMETER 3001-01-111 1210-DTF4835 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
31-30-03	REAR CVDR IMPACT SWITCH 5930-4-000 5128 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
31-31-00-002	OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER) PKG 80 REF: AMM 31-31-00	MOS HRS/MSC AFL	12	+1m/-1m	-30		30-AUG-2021 2879:18 2002	31-JUL-2022	31-AUG-2022



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-01	(CVR / CVDR) COCKPIT VOICE RECORDER 2100-3083-50 000694819 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
31-31-03	CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON DK120/90 AT54068 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			16-MAR-2017 1854:12 1297		
31-31-03-001	DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY DK120/90 AT54068 REF: AMM 31-31-03	MOS HRS/MSC AFL	DUE				16-MAR-2017 1854:12 1297	31-OCT-2023 M	
LIFE LIMIT									
31-31-09	CVDR CONTROL PANEL 441-42635-003 0317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
31-33-05	ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
31-33-05	RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-33-05-001	FUNCTIONAL CHECK OF RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A					31-JUL-2011 0 0	
31-33-05-002	FUNCTIONAL CHECK OF ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A					31-JUL-2011 0 0	
31-40-01	LH DCU UNIT 011-01457-00 16905358 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	
31-40-01	RH DCU UNIT 011-01457-00 16905368 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	
31-40-02	LEFT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-01 15W013447 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	
31-40-02	RIGHT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-01 15W013442 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-41-01	LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL 441-42627-001 1059 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
31-42-00-001 (s)	OPERATIONAL CHECK OF HSDB SWITCH REVERSION PKG 60 REF: AMM 31-42-00	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
31-50-01	1 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46712761 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
31-50-01	2 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46712939 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
31-50-01	3 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46712774 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
31-61-00	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) MFD AMLCD DISPLAY 011-01440-10 18T005756 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-61-00-001 (s)	OPERATIONAL CHECK MFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3200	+30/-30			PKG 31-JUL-2011 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK MFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3200	+30/-30			PKG 31-JUL-2011 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3200	+30/-30			PKG 31-JUL-2011 0 0		
31-61-01	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01440-10 18T006057 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			02-MAY-2019 2442:54 1729		
31-61-01	NO. 2 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01440-10 18T005755 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
CHAPTER 32 LANDING GEAR									
32-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF MAIN LANDING GEAR POLYURETHANE FILMS PKG 1 REF: AMM 32-00-20	MOS HRS/MSC AFL	800	+30/-30			PKG 13-JUL-2018 2299:30 1622		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-001	LEFT MLG SHOCK STRUT LEFT MAIN FITTING								
	2317-1201-503	MOS		N:0			31-JUL-2011		
	1358278/001	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0		16800
32-002	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING								
	2317-1201-504	MOS		N:0			31-JUL-2011		
	1360627/001	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0		16800
32-003	LEFT PINTLE PIN								
	2317-1101-003	MOS		N:0			31-JUL-2011		
	1360625/006	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0		16800
32-003	RIGHT PINTLE PIN								
	2317-1101-003	MOS		N:0			31-JUL-2011		
	1360625/002	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0		16800
32-004	LEFT PINTLE PIN								
	2317-1102-001	MOS		N:0			31-JUL-2011		
	1367836/005	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0		16800
32-004	RIGHT PINTLE PIN								
	2317-1102-001	MOS		N:0			31-JUL-2011		
	1367836/006	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0		16800



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-005	LEFT MLG SHOCK STRUT (MF - AS) AXLE								
	2317-1103-003	MOS		N:0			31-JUL-2011		
	1368537/003	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-005	RIGHT MLG SHOCK STRUT (MF - AS) AXLE								
	2317-1103-003	MOS		N:0			31-JUL-2011		
	1368537/004	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-006	LEFT MLG SHOCK STRUT (TR - AS) AXLE								
	2317-1107-005	MOS		N:0			31-JUL-2011		
	1365835/009	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	15300	N:0			0	15300	
32-006	RIGHT MLG SHOCK STRUT (TR - AS) AXLE								
	2317-1107-005	MOS		N:0			31-JUL-2011		
	1365835/002	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	15300	N:0			0	15300	
32-007	LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN								
	2317-1109-003	MOS		N:0			31-JUL-2011		
	1356004/006	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-007	RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN								
	2317-1109-003	MOS		N:0			31-JUL-2011		
	1356004/001	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-008	LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT								
	2317-1126-003	MOS		N:0			31-JUL-2011		
	1366894/001	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-008	RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT								
	2317-1126-003	MOS		N:0			31-JUL-2011		
	1366894/004	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-10-00	LEFT MAIN LANDING GEAR								
	PN	MOS		N:0			31-JUL-2011		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-11-00	AFL		N:0			0		
32-10-00	RIGHT MAIN LANDING GEAR								
	PN	MOS		N:0			31-JUL-2011		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-11-00	AFL		N:0			0		
32-10-01	LEFT MAIN LANDING GEAR LEG STRUT ASSY								
	2317-1100-405	MOS		N:0			15-JAN-2021		
	00550	HRS/MSC	O/C	N:0			2724:48		
	REF: See Workcard	AFL		N:0			1917		
32-10-01	RIGHT MAIN LANDING GEAR LEG STRUT ASSY								
	2317-1100-406	MOS		N:0			15-JAN-2021		
	00554	HRS/MSC	O/C	N:0			2724:48		
	REF: See Workcard	AFL		N:0			1917		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-100	LEFT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-405 00567 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JAN-2021 2724:48 1917		
32-100	RIGHT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-406 00563 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JAN-2021 2724:48 1917		
32-101	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 1361249/006 REF: See Workcard	MOS HRS/MSC AFL	15300	N:0 N:0 N:0			31-JUL-2011 0 0		15300
32-101	RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 1362317/005 REF: See Workcard	MOS HRS/MSC AFL	15300	N:0 N:0 N:0			31-JUL-2011 0 0		15300
32-102	LEFT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-005 1361247/002 REF: See Workcard	MOS HRS/MSC AFL	16800	N:0 N:0 N:0			31-JUL-2011 0 0		16800
32-102	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-004 1361247/004 REF: See Workcard	MOS HRS/MSC AFL	16800	N:0 N:0 N:0			31-JUL-2011 0 0		16800



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-103	LEFT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 1358155/003	MOS HRS/MSC		N:0 N:0			31-JUL-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-103	RIGHT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 1359952/002	MOS HRS/MSC		N:0 N:0			31-JUL-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-104	LEFT MAIN LANDING GEAR TRAILING ARM 2317-1501-001 1363545/003	MOS HRS/MSC		N:0 N:0			31-JUL-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-105	RIGHT MAIN LANDING GEAR TRAILING ARM 2317-1501-002 1357922/003	MOS HRS/MSC		N:0 N:0			31-JUL-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-106	LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1505-001 1362301/003	MOS HRS/MSC		N:0 N:0			31-JUL-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-106	RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1505-001 1362301/002	MOS HRS/MSC		N:0 N:0			31-JUL-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-00-001 (s)	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR PKG 80 REF: AMM 32-11-00	MOS HRS/MSC AFL	12	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
32-11-00-003	LUBRICATION OF MAIN LANDING GEAR REF: AMM 12-21-00	MOS HRS/MSC AFL	12 650	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2022 2567	15-FEB-2022 2597
32-11-01-001 OVERHAUL	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH) REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2031 13917	15-FEB-2031 13947
32-11-01-002 OVERHAUL	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH) REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2031 13917	15-FEB-2031 13947
32-11-02-001 OVERHAUL	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH) REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2031 13917	15-FEB-2031 13947
32-11-02-002 OVERHAUL	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH) REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2031 13917	15-FEB-2031 13947



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-02-900-801-05	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-003 1558047/009 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0				18-SEP-2015 1406:48 966	
32-11-02-900-801-06	LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-003 1562835/017 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0				18-SEP-2015 1406:48 966	
32-11-02-900-801-07	LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1366065/001 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:50 N:1406:48 N:966				18-SEP-2015 1406:48 966	
32-11-02-900-801-08	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3027-901 14022 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0				18-SEP-2015 1406:48 966	
32-11-02-900-801-13	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-003 1562335/005 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0				18-SEP-2015 1406:48 966	
32-11-02-900-801-14	LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1368524/003 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:50 N:1406:48 N:966				18-SEP-2015 1406:48 966	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-02-900-801-15	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1551229/003 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			18-SEP-2015 1406:48 966		
32-11-02-900-801-16	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1553991/015 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			18-SEP-2015 1406:48 966		
32-11-03-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH)	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2031 13917	15-FEB-2031 13947
OVERHAUL	REF: GENERIC NO REF								
32-11-03-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH)	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2031 13917	15-FEB-2031 13947
OVERHAUL	REF: GENERIC NO REF								
32-11-03-004	SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER REF: AMM 12-14-02	MOS HRS/MSC AFL	12 650	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2022 2567	15-FEB-2022 2597
32-11-04-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH)	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2031 13917	15-FEB-2031 13947
OVERHAUL	REF: GENERIC NO REF								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-04-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH)	MOS	120	+1m/-1m			15-JAN-2021 2724:46	15-JAN-2031	15-FEB-2031
OVERHAUL	REF: GENERIC NO REF	HRS/MSC AFL	12000	+30/-30			1917	13917	13947
32-20-01	NOSE LANDING GEAR	MOS					31-JUL-2011		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	REF: AMM 32-21-00								
32-200	LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER	MOS					15-JAN-2021		
	2317-3000-409	HRS/MSC	O/C	N:0			2724:48		
	01255	AFL		N:0			1917		
	REF: See Workcard								
32-200	RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER	MOS					15-JAN-2021		
	2317-3000-405	HRS/MSC	O/C	N:0			2724:48		
	01263	AFL		N:0			1917		
	REF: See Workcard								
32-201	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER	MOS					31-JUL-2011		
	2317-3011-001	HRS/MSC		N:0			0		
	1360612/002	AFL	16800	N:0			0	16800	
LIFE LIMIT	REF: See Workcard								
32-201	RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER	MOS					31-JUL-2011		
	2317-3011-001	HRS/MSC		N:0			0		
	1360612/009	AFL	16800	N:0			0	16800	
LIFE LIMIT	REF: See Workcard								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-202	LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE								
	2317-3021-001	MOS		N:0			31-JUL-2011		
	1360615/001	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-202	RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE								
	2317-3021-001	MOS		N:0			31-JUL-2011		
	1360615/002	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-203	LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING								
	2317-3001-003	MOS		N:0			31-JUL-2011		
	1365834/003	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-203	RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING								
	2317-3001-003	MOS		N:0			31-JUL-2011		
	1365834/004	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-204	LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT								
	2317-3004-001	MOS		N:0			31-JUL-2011		
	1361873/006	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	
32-204	RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT								
	2317-3004-001	MOS		N:0			31-JUL-2011		
	1361873/003	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	16800	N:0			0	16800	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-00-001 (s)	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR PKG 80 REF: AMM 32-21-00	MOS HRS/MSC AFL	12	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
32-21-00-003	LUBRICATION OF NOSE LANDING GEAR REF: AMM 12-21-00	MOS HRS/MSC AFL	12 650	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2022 2567	15-FEB-2022 2597
32-21-01-001 OVERHAUL	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2031 13917	15-FEB-2031 13947
32-21-02	NLG RETRACTION ACTUATOR 2117-1000-401 00069 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-21-03	NLG DOWNLOCK ACTUATOR 2117-2000-401 00066 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-21-04-001 OVERHAUL	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			15-JAN-2021 2724:46 1917	15-JAN-2031 13917	15-FEB-2031 13947



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-05-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER								
		MOS	120	+1m/-1m			15-JAN-2021	15-JAN-2031	15-FEB-2031
		HRS/MSC					2724:46		
OVERHAUL	REF: GENERIC NO REF	AFL	12000	+30/-30			1917	13917	13947
32-21-05-004	SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER								
		MOS	12	+1m/-1m			15-JAN-2021	15-JAN-2022	15-FEB-2022
		HRS/MSC					2724:46		
	REF: AMM 12-14-03	AFL	650	+30/-30			1917	2567	2597
32-21-06-005 (s)	VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER						PKG		
	PKG 80	MOS	12	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: AMM 32-21-06	AFL					2002		
32-21-09-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY								
		MOS	120	+1m/-1m			15-JAN-2021	15-JAN-2031	15-FEB-2031
		HRS/MSC					2724:46		
OVERHAUL	REF: GENERIC NO REF	AFL	12000	+30/-30			1917	13917	13947
32-300	LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR								
	2117-3000-409	MOS		N:0			15-JAN-2021		
	00979	HRS/MSC	O/C	N:0			2724:48		
	REF: See Workcard	AFL		N:0			1917		
32-300	RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR								
	2117-3000-409	MOS		N:0			15-JAN-2021		
	01070	HRS/MSC	O/C	N:0			2724:48		
	REF: See Workcard	AFL		N:0			1917		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-301	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER								
	2117-3031-001	MOS		N:50			18-SEP-2015		
	1354529/001	HRS/MSC		N:1406:48			1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000	N:966			966		12000
32-301	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER								
	2117-3034-501	MOS		N:0			18-SEP-2015		
	1559578/004	HRS/MSC		N:0			1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000	N:0			966		12966
+ 32-302	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON								
	2117-3001-003	MOS					31-JUL-2011		
	1562835/017	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		
+ 32-302	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON								
	2117-3001-003	MOS					31-JUL-2011		
	1558047/009	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		
+ 32-303	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER								
	2117-3010-001	MOS		I:50			18-SEP-2015		
	1366065/001	HRS/MSC		I:1406:48			1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000	I:966			966		12000
+ 32-303	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER								
	2117-3027-901	MOS					31-JUL-2011		
	14022	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-304	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD								
	2117-3008-901	MOS		N:50			18-SEP-2015		
	61651S1/008	HRS/MSC		N:1406:48			1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000	N:966			966		12000
32-304	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD								
	2117-3008-901	MOS		N:0			18-SEP-2015		
	76537-0027	HRS/MSC		N:0			1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000	N:0			966		12966
32-305	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON								
	2117-3009-007	MOS		N:50			18-SEP-2015		
	1322471/002	HRS/MSC		N:1406:48			1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000	N:966			966		12000
32-305	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON								
	2117-3009-007	MOS		N:0			18-SEP-2015		
	1562899/003	HRS/MSC		N:0			1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000	N:0			966		12966
+ 32-306	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN								
	2117-3019-001	MOS		I:50			18-SEP-2015		
	1368524/003	HRS/MSC		I:1406:48			1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000	I:966			966		12000
+ 32-306	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN								
	2117-3019-003	MOS					31-JUL-2011		
	1562335/005	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-307	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1551229/003 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
+ 32-307	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1553991/015 REF: See Workcard	MOS HRS/MSC AFL	N/A				31-JUL-2011 0 0		
32-308	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 1358151/004 REF: See Workcard	MOS HRS/MSC AFL	12000	N:50 N:1406:48 N:966			18-SEP-2015 1406:48 966	12000	
32-308	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 1553979-042 REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			18-SEP-2015 1406:48 966	12966	
32-309	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 1370969/005 REF: See Workcard	MOS HRS/MSC AFL	12000	N:50 N:1406:48 N:966			18-SEP-2015 1406:48 966	12000	
32-309	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 1561659/008 REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			18-SEP-2015 1406:48 966	12966	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-31-01	LANDING GEAR CONTROL LEVER 827101-7 1068 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-31-04	CENTER FUSELAGE LANDING GEAR SELECTOR VALVE 7342-1 0082T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-31-05	LH MLG UPLOCK BOX ASSY 2617-1000-401 00120 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-31-05	NLG UPLOCK BOX ASSY 2617-1000-401 00121 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-31-05	RH MLG UPLOCK BOX ASSY 2617-1000-402 00062 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-310	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT 2117-3015-001 1365816/006 REF: See Workcard	MOS HRS/MSC AFL		N:50 N:1406:48 N:966			18-SEP-2015 1406:48 966		12000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-310	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT 2117-3015-001 1365816/003	MOS HRS/MSC		N:0 N:0			18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000	N:0			966	12966	
32-311	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA1 00030	MOS HRS/MSC		N:50 N:1406:48			18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	10500	N:966			966	10500	
32-311	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA1 00584	MOS HRS/MSC		N:0 N:0			18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	10500	N:0			966	11466	
+ 32-312	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1366065/001	MOS HRS/MSC	N/A				31-JUL-2011 0		
	REF: See Workcard	AFL					0		
+ 32-312	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3027-901 14022	MOS HRS/MSC					18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000				966	12966	
+ 32-313	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT 2117-3029-001 00324	MOS HRS/MSC		N:0 N:0			18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	28000	N:0			966	28966	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-313	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT 2117-3029-001 00477	MOS HRS/MSC		N:0 N:0			18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	28000	N:0			966	28966	
+ 32-314	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1368524/003	MOS HRS/MSC	N/A				31-JUL-2011 0		
	REF: See Workcard	AFL					0		
+ 32-314	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-003 1562335/005	MOS HRS/MSC					18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000				966	12966	
+ 32-315	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1551229/003	MOS HRS/MSC					18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000				966	12966	
+ 32-315	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1553991/015	MOS HRS/MSC					18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000				966	12966	
+ 32-316	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-003 1562835/017	MOS HRS/MSC					18-SEP-2015 1406:48		
LIFE LIMIT	REF: See Workcard	AFL	12000				966	12966	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-316	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-003 1558047/009 REF: See Workcard	MOS HRS/MSC AFL	12000				18-SEP-2015 1406:48 966	12966	
LIFE LIMIT									
32-35-00-001	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM REF: AMM 32-35-00	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			23-JUN-2021 2847:34 1986	23-JUN-2023 4047:34	23-JUL-2023 4077:34
AIRWORTHINESS									
32-35-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES REF: AMM 32-35-00	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30		-30	30-AUG-2021 2879:18 2002	31-JUL-2023 4079:18	30-AUG-2023 4109:18
AIRWORTHINESS									
32-35-02	CENTER FUSELAGE FREE FALL VALVE 7343-2 0020T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-400	NOSE LANDING GEAR SHOCK STRUT 2317-5100-403 00018 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 N:1606 O:0			15-JAN-2021 2724:48 1917		
32-401	NOSE LANDING GEAR SHOCK STRUT AXLE BOLT 2310-1144-005 1371225/010 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			31-JUL-2011 0 0	11200	
LIFE LIMIT									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-402	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT								
	2310-1173-001	MOS		N:0			31-JUL-2011		
	1371218/003	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-403	LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN								
	2317-5105-001	MOS		N:0			31-JUL-2011		
	1363516/003	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-403	RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN								
	2317-5105-001	MOS		N:0			31-JUL-2011		
	1363516/009	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-404	NOSE LANDING GEAR SHOCK STRUT MAIN FITTING								
	2317-5301-503	MOS		N:0			31-JUL-2011		
	1365838/001	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-405	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER								
	2117-4000-403	MOS		N:0			31-JUL-2011		
	00067	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-406	NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE								
	2317-5101-001	MOS		N:0			31-JUL-2011		
	1360618/013	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-407	LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK								
	2317-5201-001	MOS		N:0			31-JUL-2011		
	1367851/009	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-407	UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK								
	2317-5201-001	MOS		N:0			31-JUL-2011		
	1367851/008	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-408	NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN								
	2317-6003-001	MOS		N:0			31-JUL-2011		
	1362490/006	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-409	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE								
	2310-1165-001	MOS		N:0			31-JUL-2011		
	1371211/003	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-41-00	BRAKE CONTROL UNIT								
	DAP00100-06	MOS		N:0			31-JUL-2011		
	229950115	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
32-41-00-001 (s)	FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM						PKG		
	PKG 50	MOS					31-JUL-2011		
		HRS/MSC	5600	+30/-30			0		
	REF: AMM 32-41-00	AFL					0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-01	BRAKE CONTROL UNIT TRAY DAP00100-100 353010527 REF: See Workcard	MOS HRS/MSC AFL	O/C					20-JUL-2017 1987:12 1393	
32-41-02	LH BRAKE PEDAL TRANSDUCER 441-42631-003 1429 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:4 R:0 R:0				02-MAY-2019 2442:54 1729	
32-41-02	RH BRAKE PEDAL TRANSDUCER 441-43246-001 1047 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	
32-41-02-001 (s)	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 60 REF: AMM 32-41-02	MOS HRS/MSC AFL	6400	+30/-30				PKG 31-JUL-2011 0 0	
32-41-02-001 (s)	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 60 REF: AMM 32-41-02	MOS HRS/MSC AFL	6400	+30/-30				PKG 31-JUL-2011 0 0	
32-41-02-002 (s)	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 10 REF: AMM 32-41-02	MOS HRS/MSC AFL	1600	+30/-30				PKG 30-AUG-2019 2537:42 1791	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-02-002 (s)	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 10 REF: AMM 32-41-02	MOS HRS/MSC AFL	1600	+30/-30			PKG 30-AUG-2019 2537:42 1791		
32-41-06	LH MLG WHEEL SPEED TRANSDUCER DAP00103-01 6JQ REF: See Workcard	MOS HRS/MSC AFL	O/C				01-FEB-2012 53:12 41		
32-41-06	RH MLG WHEEL SPEED TRANSDUCER DAP00103-01 128JT REF: See Workcard	MOS HRS/MSC AFL	O/C						
32-41-07	BRAKE CONTROL MODULE DAP00101-02 54JK REF: See Workcard	MOS HRS/MSC AFL	O/C				01-FEB-2012 53:12 41		
32-410	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN 57675-1 00326 REF: See Workcard	MOS HRS/MSC AFL		N:0 N:0 N:0			31-JUL-2011 0 0		11200
32-411	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT 2310-1183-001 1366528/002 REF: See Workcard	MOS HRS/MSC AFL		N:0 N:0 N:0			31-JUL-2011 0 0		11200



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-412	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK								
	2317-5191-001	MOS		N:0			31-JUL-2011		
	1373124/006	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-43-00-001 (s)	FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM						PKG		
	PKG 50	MOS					31-JUL-2011		
		HRS/MSC	5600	+30/-30			0		
	REF: AMM 32-43-00	AFL					0		
32-43-01-001 (s)	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM						PKG		
	PKG 50	MOS					31-JUL-2011		
		HRS/MSC	5600	+30/-30			0		
	REF: AMM 32-43-00	AFL					0		
32-43-02	PRESSURE SWITCH								
	DAP00108-01	MOS		N:0			31-JUL-2011		
	123JN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR								
	DAP00106-01	MOS		N:0			31-JUL-2011		
	058	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
32-43-05	EMERGENCY/PARKING BRAKE VALVE								
	DAP00107-01	MOS		N:0			31-JUL-2011		
	76JV	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-43-02	AFL		N:0			0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-43-06	PRESSURE TRANSDUCER DAP00109-01 7653-2-348 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-43-08	THERMAL RELIEF VALVE DAP00110-01 048 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-43-10	EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE DAP00202-01 072 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-43-11	FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE 2216-0001-401 00289 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-43-11-001	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE REF: AMM 32-43-11	MOS HRS/MSC AFL	600	+30/-30	20:12		30-AUG-2021 2879:18 2002	3499:30	3529:30
AIRWORTHINESS									
32-45-00	LH MAIN WHEEL AND TIRE ASSY 505-19517-611 5101TM REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-JUN-2021 2847:34 1986		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-00	NOSE WHEEL AND TIRE ASSY 505-19601-605 5092MK REF: See Workcard	MOS HRS/MSC AFL	O/C	O:6 O:0 O:0			30-MAR-2019 2423:18 1719		
32-45-00	RH MAIN WHEEL AND TIRE ASSY 505-19517-611 5047U REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-JUN-2021 2847:34 1986		
32-45-01	LEFT MAIN WHEEL DAP00098-02 5101TM REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-JUN-2021 2847:34 1986		
32-45-01	RIGHT MAIN WHEEL DAP00098-02 5047U REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-JUN-2021 2847:34 1986		
+ 32-45-01-003	RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY DAP00098-02 5101TM REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C 1500	+30/-30			23-JUN-2021 2847:34 1986	3486	3516
32-45-01-003	RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY DAP00098-02 5047U REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C 1500	+30/-30			23-JUN-2021 2847:34 1986	3486	3516



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-02	LEFT MAIN WHEEL TIRE 258K63-2 10570646 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-JUN-2021 2847:34 1986		
32-45-02	RIGHT MAIN WHEEL TIRE 258K63-2 10560656 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-JUN-2021 2847:34 1986		
32-45-03	LH MLG HUB CAP DAP00131-02 43JR REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-45-03	RH MLG HUB CAP DAP00131-02 42JR REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-45-11	NOSE WHEEL DAP00099-02 5092MK REF: See Workcard	MOS HRS/MSC AFL	O/C	O:6 O:0 O:0			30-MAR-2019 2423:18 1719		
+ 32-45-11-003	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY DAP00099-02 5092MK REF: AMM 32-45-00	MOS HRS/MSC AFL	1500	+30/-30			30-MAR-2019 2423:18 1719	3219	3249



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-12	NOSE TIRE 156K23B1 72852812 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-MAR-2019 2423:18 1719		
32-45-21	LH MLG CARBON BRAKE ASSY DAP00097-04 5036NN REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			11-MAY-2016 1613:48 1117		
32-45-21	RH MLG CARBON BRAKE ASSY DAP00097-04 5006MF REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			14-MAY-2016 1619 1121		
32-500	NOSE LANDING GEAR SHOCK ABSORBER 2317-5170-403 00068 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:114 N:2724:48 N:1917			15-JAN-2021 2724:48 1917		
32-501	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK 2317-5227-501 1367868/001 REF: GENERIC NO REF	MOS HRS/MSC AFL		N:0 N:0 N:0			31-JUL-2011 0 0		
LIFE LIMIT			11200					11200	
32-502	NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING 2317-5113-005 1367862/004 REF: GENERIC NO REF	MOS HRS/MSC AFL		N:0 N:0 N:0			31-JUL-2011 0 0		
LIFE LIMIT			11200					11200	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-503	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER								
	2317-5231-503	MOS		N:0			31-JUL-2011		
	1369321/002	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	11200	N:0			0	11200	
32-600	NOSE LANDING GEAR DRAG BRACE								
	2317-6000-403	MOS		R:0			15-JAN-2021		
	00616	HRS/MSC	O/C	N:0 R:0			2724:48		
	REF: See Workcard	AFL		N:0 R:0			1917		
32-601	NOSE LANDING GEAR UPPER DRAG BRACE								
	2317-6101-501	MOS		N:0			31-JUL-2011		
	1369888/001	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-602	NOSE LANDING GEAR LOWER DRAG BRACE								
	2317-6201-001	MOS		N:0			31-JUL-2011		
	1357916/008	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-603	LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN								
	2317-6001-001	MOS		N:0			31-JUL-2011		
	1358153/002	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	
32-603	RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN								
	2317-6001-001	MOS		N:0			31-JUL-2011		
	1358153/003	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	11200	N:0			0	11200	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-604	NOSE LANDING GEAR DRAG BRACE PIN 2317-6003-001 1355999/005	MOS HRS/MSC AFL		N:0 N:0 N:0			31-JUL-2011 0 0		
LIFE LIMIT	REF: See Workcard		11200					11200	
32-61-01	LH WING PROXIMITY SWITCH 80-057-01 26991	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
	REF: GENERIC NO REF								
32-61-01	NO. 1 LEFT MLG PROXIMITY SWITCH 80-057-01 26513	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
	REF: GENERIC NO REF								
32-61-01	NO. 1 NLG PROXIMITY SWITCH 80-057-01 26516	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
	REF: GENERIC NO REF								
32-61-01	NO. 1 RIGHT MLG PROXIMITY SWITCH 80-057-01 26535	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
	REF: GENERIC NO REF								
32-61-01	NO. 2 LEFT MLG PROXIMITY SWITCH 80-057-01 26979	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
	REF: GENERIC NO REF								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-01	NO. 2 NLG PROXIMITY SWITCH 80-057-01 26518 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-61-01	NO. 2 RIGHT MLG PROXIMITY SWITCH 80-057-01 26992 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-61-01	NO. 3 LEFT MLG PROXIMITY SWITCH 80-057-01 26981 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-61-01	NO. 3 RIGHT MLG PROXIMITY SWITCH 80-057-01 27030 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-61-01	RH WING PROXIMITY SWITCH 80-057-01 27031 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
32-700	NOSE LANDING GEAR LOCKING STAY 2317-6500-403 00446 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JAN-2021 2724:48 1917		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-701	NOSE LANDING GEAR UPPER LOCKING STAY 2317-6521-003 1350666/004	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			31-JUL-2011 0 0		11200
LIFE LIMIT	REF: See Workcard								
32-702	NOSE LANDING GEAR LOWER LOCKING STAY 2317-6531-001 1353055/008	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			31-JUL-2011 0 0		11200
LIFE LIMIT	REF: See Workcard								
32-703	LOWER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 1364735/006	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			31-JUL-2011 0 0		11200
LIFE LIMIT	REF: See Workcard								
32-703	UPPER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 1364735/003	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			31-JUL-2011 0 0		11200
LIFE LIMIT	REF: See Workcard								
CHAPTER 33 LIGHTS									
33-12-01	COCKPIT DIMMER 81-01760-002 0368	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
	REF: See Workcard								
33-42-01	LH LWR FWD TAXI LIGHT ASSY 81017-3 000097	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
	REF: See Workcard								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-42-01	RH LWR FWD TAXI LIGHT ASSY 81017-4 000093 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
33-47-01	LEFT LANDING LIGHT ASSY 81017-5 000080 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
33-47-01	RIGHT LANDING LIGHT ASSY 81017-6 000083 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
33-48-00	LEFT NO. 1 NAVIGATION LIGHT 84004-7 000145 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
33-48-00	LEFT NO. 2 NAVIGATION LIGHT 84015-1 000099 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
33-48-00	RIGHT NO. 1 NAVIGATION LIGHT 84004-7 000144 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-48-00	RIGHT NO. 2 NAVIGATION LIGHT 84015-2 000090 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
33-48-00-001	DISCARD LEFT NO. 1 NAVIGATION LIGHT 84004-7 000145 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			31-JUL-2011 0 0	12000	12030
33-48-00-001	DISCARD LEFT NO. 2 NAVIGATION LIGHT 84015-1 000099 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			31-JUL-2011 0 0	12000	12030
33-48-00-001	DISCARD RIGHT NO. 1 NAVIGATION LIGHT 84004-7 000144 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			31-JUL-2011 0 0	12000	12030
33-48-00-001	DISCARD RIGHT NO. 2 NAVIGATION LIGHT 84015-2 000090 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			31-JUL-2011 0 0	12000	12030
33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 30-DEC-2016 1790:24 1250		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 30-DEC-2016 1790:24 1250		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 30-DEC-2016 1790:24 1250		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 2 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 30-DEC-2016 1790:24 1250		
33-49-00	NO. 1 STROBE LIGHT 84036-3 000100 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
33-49-00	NO. 2 STROBE LIGHT 84036-4 000093 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
33-49-00-001	DISCARD NO. 1 STROBE LIGHT 84036-3 000100 REF: AMM 33-49-00	MOS HRS/MSC AFL	8000	+30/-30			31-JUL-2011 0 0	8000	8030



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-49-00-001	DISCARD NO. 2 STROBE LIGHT 84036-4 000093 REF: AMM 33-49-00	MOS HRS/MSC AFL	8000	+30/-30			31-JUL-2011 0 0	8000	8030
33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 30-DEC-2016 1790:24 1250		
33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 30-DEC-2016 1790:24 1250		
33-52-01	LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 001585 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:3 R:0 R:0			11-MAY-2021 2788 1952		
33-52-01	RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 002136 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			11-MAY-2021 2788 1952		
33-52-01-001	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 001585 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+1m/-1m			11-MAY-2021 2788 1952	11-MAY-2022	11-JUN-2022



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-52-01-001	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 002136 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+1m/-1m			11-MAY-2021 2788 1952	11-MAY-2022	11-JUN-2022
33-52-01-002	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 001585 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A				11-MAY-2021 2788 1952		
33-52-01-002	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 002136 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A				11-MAY-2021 2788 1952		
33-52-01-003	DISCARD OF LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 001585 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-01-003	DISCARD OF RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 002136 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-05	SELF-ILLUMINATED UNIT 1225006 NSN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-52-17-001 (s)	OPERATIONAL CHECK OF INERTIAL SWITCH (AIRCRAFT WITH INERTIAL SWITCH INSTALLED) PKG 10 REF: AMM 33-52-17	MOS HRS/MSC AFL	1600	+30/-30			PKG 30-AUG-2019 2537:42 1791		
CHAPTER 34 NAVIGATION									
34-00-03	NO.1 IASP SMART PROBE 2015L-4B 0015 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2301 R:1423			06-JAN-2017 1790:24 1250		
34-00-03	NO.2 IASP SMART PROBE 2015L-4B 0083 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:710 R:548			06-JAN-2017 1790:24 1250		
34-10-01	RADIO ALTIMETER 066-01153-0101 KRA405B-11027 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-10-02	LEFT RADIO ALTIMETER TRANSMIT ANTENNA S67-2002-45 553-3781 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-10-02	RIGHT RADIO ALTIMETER RECEIVE ANTENNA S67-2002-45 553-3789 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-00	IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT C16786DA01 C16786000840 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-11-00-001	FUNCTIONAL CHECK OF (IESI) INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001) C16786DA01 C16786000840 REF: AMM 34-11-00	MOS HRS/MSC AFL	24	+1m/-1m			05-NOV-2020 2687:12 1898	05-NOV-2022	05-DEC-2022
34-11-02	PITOT/STATIC PROBE 0856UT4 267064 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:121 N:2879:18 N:2002			30-AUG-2021 2879:18 2002		
34-11-02-001	RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001) 0856UT4 267064 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+1m/-1m		18	30-AUG-2021 2879:18 2002	17-SEP-2023	17-OCT-2023
34-15-00-001	FUNCTIONAL CHECK OF AIR DATA SYSTEM PKG 81 REF: AMM 34-15-00	MOS HRS/MSC AFL	24	+1m/-1m		-30	30-AUG-2021 2879:18 2002	31-JUL-2023	31-AUG-2023
34-15-00-002	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS PKG 84 REF: AMM 34-15-00	MOS HRS/MSC AFL	60	+1m/-1m			30-AUG-2021 2879:18 2002	30-AUG-2026	30-SEP-2026



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-15-00-003	DETAILED INSPECTION OF IASP PKG 81 REF: AMM 34-15-07	MOS HRS/MSC AFL	24	+1m/-1m		-30	30-AUG-2021 2879:18 2002	31-JUL-2023	31-AUG-2023
34-20-01	LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM 011-00868-10 42016512 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-20-01	RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM 011-00868-10 42016524 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-20-02	LEFT MAGNETOMETER 011-00870-10 1CM005851 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-20-02	RIGHT MAGNETOMETER 011-00870-10 1CM005858 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-21-00-001 (s)	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE LH WING MAGNETOMETER 011-00870-10 PKG 82 1CM005851 REF: AMM 34-21-02	MOS HRS/MSC AFL	36				PKG 31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-21-00-001 (s)	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE RH WING MAGNETOMETER 011-00870-10 PKG 82 1CM005858 REF: AMM 34-21-02	MOS HRS/MSC AFL	36				PKG 31-JUL-2011 0 0		
34-23-00	MAGNETIC COMPASS KCA0120W BE9290910 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-23-00-001 (s)	FUNCTIONAL CHECK MAGNETIC COMPASS OF STANDBY COMPASS KCA0120W PKG 82 BE9290910 REF: AMM 34-23-00	MOS HRS/MSC AFL	36	+1m/-1m	-30		PKG 30-AUG-2021 2879:18 2002		
34-30-01	LEFT VOR/LOC 2 & 3 BLADE ANTENNA S65-247170 173-2591 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-30-01	RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE S65-247170 173-2592 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-40-01	GDL-69A SATELLITE WEATHER AND RADIO RECEIVER 011-00987-00 47763857 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-40-02	AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 8549 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-40-02	FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 8508 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-40-03	WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA 011-00883-20 47202958 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			21-AUG-2018 2299:30 1622		
34-40-04	TCAS II UNIT 9003500-55905 TSE01439 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JUL-2012 332:48 217		
34-40-05	TCAS II TOP ANTENNA 7514060-902 ANE34447 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-JAN-2012 41:18 33		
34-43-02	LOWER TCAS L BAND ANTENNA S65-5366-7L 261-103535 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-50-02	BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA S65-5366-7L 261-103465 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-50-02	TOP XPDR L BAND ANTENNA S65-5366-7L 261-103525 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-50-03	KN 63 DISTANCE MEASURING UNIT 066-01070-0001 34417 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-50-05	PHASING COUPLER SSPD-113-10 6625 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-50-06	MARKER BEACON ANTENNA S35-1000-2 102-8939 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-50-14	ADF ANTENNA 622-7383-001 463HD REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-50-15	ADF UNIT 622-7382-101 4519F REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-51-02	NO. 1 DME L BAND ANTENNA S65-5366-7L 261-103714 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-52-00	NO. 1 TRANSPONDER 9006000-55000 NXE08269 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			21-JUN-2019 2475:36 1753		
34-52-00	NO. 2 TRANSPONDER 9006000-55000 NXE06057 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-AUG-2018 2299:30 1622		
34-52-00-001	FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM 9006000-55000 NXE08269 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				30-AUG-2021	30-AUG-2023	
34-52-00-001	FUNCTIONAL CHECK OF NO. 2 TRANSPONDER SYSTEM 9006000-55000 NXE06057 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				30-AUG-2021	30-AUG-2023	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-52-04	LOWER COAXIAL UNIT D2-729B005 566113 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-52-04	UPPER COAXIAL UNIT D2-729B005 566107 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-53-01	ADF MOUNTING TRAY 622-5212-001 45C3J REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
34-60-03	FLIGHT MANAGEMENT SYSTEM PANEL 011-01428-00 194005797 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-SEP-2014 1119:48 754		
CHAPTER 35 OXYGEN									
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30	-18		18-AUG-2020 2650:54 1880	31-JUL-2023 4450:54	30-AUG-2023 4480:54
AIRWORTHINESS	REF: AMM 35-00-00								
35-01-00-001 (s)	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION PKG 84 REF: AMM 35-01-02	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-01-02	OXYGEN CYLINDER TRANSDUCER 4441125-000 7743-9-28 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
35-01-05	CREW OXYGEN SYSTEM LOW PRESSURE SWITCH P24151 0042 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
35-01-06	OXYGEN SYSTEM CONTROL PANEL 441-40945-002 0421 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:43 N:0 N:0			02-MAY-2019 2442:54 1729		
35-01-07	COCKPIT SENSOR P24099 0248 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
35-01-09	ALTITUDE COMPENSATING REGULATOR 4421135-001 00140M REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			19-NOV-2016 1738:12 1207		
35-01-10	LOW PRESSURE OXYGEN VALVE 4421132-109 00307 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-02-01	OXYGEN CYLINDER 4441122-050 409760802 REF: See Workcard	MOS HRS/MSC AFL	H/T	R:2 N:762 R:0 R:0			18-AUG-2020 2650:54 1880		
35-02-01-001	FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR 4441122-050 409760802 REF: AMM 35-02-01	MOS HRS/MSC AFL	60				29-JUN-2020	29-JUN-2025	
35-02-01-003	DISCARD OF OXYGEN CYLINDER 4441122-050 409760802 REF: AMM 35-02-01	MOS HRS/MSC AFL	180				01-JUL-2010	01-MAY-2025	M
LIFE LIMIT									
35-02-05	OXYGEN PRESSURE REGULATOR 172421-14 0851 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			04-SEP-2015 1406:48 966		
35-11-00-001	OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX REF: AMM 35-11-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30	-30		30-AUG-2021 2879:18 2002	31-JUL-2022 3479:18	30-AUG-2022 3509:18
AIRWORTHINESS									
35-11-01	COPILLOT OXYGEN MASK STOWAGE BOX 1186F6-23 00622 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-11-01	PILOT OXYGEN MASK STOWAGE BOX 1186F6-23 00626 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
35-11-02	LEFT CREW OXYGEN MASK 174232-93 39406 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 N:1674 R:0 N:2271 R:0			30-MAR-2020 2618 1847		
35-11-02	RIGHT CREW OXYGEN MASK 174232-93 33118 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:9 N:2586 O:0 O:0			30-MAR-2020 2618 1847		
35-11-02-001	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK 174232-93 39406 REF: AMM 35-11-02	MOS HRS/MSC AFL	24	+1m/-1m			20-MAR-2020 2618 1847	20-MAR-2022	20-APR-2022
35-11-02-001	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK 174232-93 33118 REF: AMM 35-11-02	MOS HRS/MSC AFL	24	+1m/-1m			20-MAR-2020 2618 1847	20-MAR-2022	20-APR-2022
35-11-02-002	RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK 174232-93 39406 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+1m/-1m +30/-30	I:1674		20-MAR-2020 2618 1847	01-JAN-2022 4544	M 01-FEB-2022 4574



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-11-02-002	RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK 174232-93 33118 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+1m/-1m +30/-30			20-MAR-2020 2618 1847	01-JUN-2025 M 6218	01-JUL-2025 6248
35-11-02-003	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK 174232-93 39406 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A						
35-11-02-003	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK 174232-93 33118 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A						
35-11-04-001 (s)	DETAILED INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED) PKG 82 REF: AMM 35-11-04	MOS HRS/MSC AFL	36	+1m/-1m			PKG 18-AUG-2020 2650:54 1880		
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE REF: AMM 35-21-00	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30	-18		18-AUG-2020 2650:54 1880	31-JUL-2023 4450:54	30-AUG-2023 4480:54
AIRWORTHINESS									
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE REF: AMM 35-21-00	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30	-18		18-AUG-2020 2650:54 1880	31-JUL-2023 4450:54	30-AUG-2023 4480:54
AIRWORTHINESS									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-21-01	FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER								
	4411071-002	MOS		N:0			31-JUL-2011		
	4411071-002-00017	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
35-21-01	NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER								
	4411072-002	MOS		N:0			31-JUL-2011		
	4411072-002-00030	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
35-21-01	NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER								
	4411072-002	MOS		N:0			31-JUL-2011		
	4411072-002-00047	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
35-21-01	NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER								
	4411072-002	MOS		N:0			31-JUL-2011		
	4411072-002-00089	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
35-21-01	NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER								
	4411072-002	MOS		N:0			31-JUL-2011		
	4411072-002-00090	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
35-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER OXYGEN MASKS						PKG		
	PKG 82	MOS	36	+1m/-1m			18-AUG-2020		
		HRS/MSC					2650:54		
	REF: AMM 35-21-01	AFL					1880		

CHAPTER 36 PNEUMATIC



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 36-00-00-710-801-A	TROUBLE SHOOT ENGINE OPERATING PROBLEMS - PNEUMATIC SYSTEM OPERATIONAL CHECK	MOS						31-JUL-2011	
	REF: AMM 36-00-00	HRS/MSC	A/R					0	
		AFL						0	
36-01-01	PNEUMATIC INSC ILLUM PANEL								
	441-42633-002	MOS		N:0				31-JUL-2011	
	1057	HRS/MSC	O/C	N:0				0	
	REF: See Workcard	AFL		N:0				0	
36-11-01	LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE								
	RYLB-53505-5	MOS						03-JAN-2019	
	0045	HRS/MSC	O/C	N:685				2388:06	
	REF: See Workcard	AFL		N:555				1693	
36-11-01	RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE								
	RYLB-53505-6	MOS						10-APR-2019	
	0415	HRS/MSC	O/C	N:1858				2442:06	
	REF: See Workcard	AFL		N:1464				1726	
36-11-01-001 (s)	RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER							PKG	
	PKG 20	MOS						18-AUG-2020	
		HRS/MSC	2400	+30/-30				2650:54	
	REF: AMM 36-11-01	AFL						1880	
36-11-01-002 (s)	OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION							PKG	
	PKG 1	MOS						13-JUL-2018	
		HRS/MSC	800	+30/-30				2299:30	
	REF: AMM 36-11-00	AFL						1622	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-02-001 (s)	DETAILED INSPECTION OF BLEED LINE WATER DRAINS PKG 81 REF: AMM 36-11-02	MOS HRS/MSC AFL	24	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
36-11-03	AMS CONTROLLER SYLZ-53632-203 0098 REF: See Workcard	MOS HRS/MSC AFL	O/C						
36-11-04	NO. 1 ENGINE FAN AIR VALVE RYLB-53527-1 0169 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
36-11-04	NO. 2 ENGINE FAN AIR VALVE RYLB-53527-1 0166 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
36-11-04-001 (s)	RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER PKG 20 REF: AMM 36-11-04	MOS HRS/MSC AFL	2400	+30/-30			PKG 18-AUG-2020 2650:54 1880		
36-11-05	LH INCONEL 625 BLEED PRE-COOLER 10965000-105 T0058 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-05	RH INCONEL 625 BLEED PRE-COOLER 10964000-105 T0052 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
36-11-06	CROSS BLEED VALVE RYLB-53506-1 0021 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
36-11-06-001 (s)	OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION PKG 1 REF: AMM 36-11-06	MOS HRS/MSC AFL	800	+30/-30			PKG 13-JUL-2018 2299:30 1622		
36-11-06-002 (s)	RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER PKG 60 REF: AMM 36-11-06	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
36-11-07	NO. 1 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 7738-5-166 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
36-11-07	NO. 2 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 7738-5-348 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-08	NO. 1 BLEED TEMPERATURE SENSOR 103-00264 00930 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:1 N:0 N:0			10-APR-2019 2442:06 1726		
36-11-08	NO. 2 BLEED TEMPERATURE SENSOR 103-00264 01229 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:1 N:0 N:0			10-APR-2019 2442:06 1726		
36-11-08	NO. 3 BLEED TEMPERATURE SENSOR 103-00264 01224 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:1 N:0 N:0			10-APR-2019 2442:06 1726		
36-11-08	NO. 4 BLEED TEMPERATURE SENSOR 103-00264 01228 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:1 N:0 N:0			10-APR-2019 2442:06 1726		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR PKG 60 REF: AMM 36-11-08	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR PKG 60 REF: AMM 36-11-08	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR PKG 60 REF: AMM 36-11-08	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR PKG 60 REF: AMM 36-11-08	MOS HRS/MSC AFL	6400	+30/-30			PKG 31-JUL-2011 0 0		
36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS	MOS HRS/MSC AFL	6000	+30/-30			31-JUL-2011 0 0	6000	6030
AIRWORTHINESS	REF: AMM 36-21-01								
CHAPTER 38	WATER/WASTE								
38-33-07	WASTE DRAIN VALVE 0218-0032-1 145213 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
CHAPTER 44	CABIN SYSTEMS								
44-21-03	DC-DC CONVERTER 35-192-00 218 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
44-21-09	IFE INSC ILLUM PANEL 441-42725-001 0121 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
44-22-01	CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER 0604-001 12100102 REF: See Workcard	MOS HRS/MSC AFL	O/C					26-NOV-2012 596:42 398	
44-32-01	ATG5000 TRANSCEIVER P13989 1398915070 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0				25-FEB-2022 3003:54 2002	
44-32-05	AIRCELL AXCESS (CTR) CABIN TELECOMMUNICATIONS ROUTER P12083-001 P1208373453 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0				20-JUL-2017 1987:12 1393	
CHAPTER 52	DOORS								
52-00-00	KEY LOCK KIT 505-38956-901 000083-00083 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				31-JUL-2011 0 0	
52-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 84 REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+1m/-1m				PKG 30-AUG-2021 2879:18 2002	
52-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 84 REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+1m/-1m				PKG 30-AUG-2021 2879:18 2002	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-01-01-901	GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 52-10-00	AFL	14000				0		14000
52-10-01-02-901	GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 52-10-00	AFL	14000				0		14000
52-10-01-02-902	DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 52-10-00	AFL	14000				0		14000
52-10-02-01-901	GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 52-10-00	AFL	14000				0		14000
52-10-20-001 (s)	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL						PKG		
	PKG 80	MOS	12	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: AMM 52-10-20	AFL					2002		
52-11-00-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM						PKG		
	PKG 83	MOS	48	+1m/-1m			30-AUG-2019		
		HRS/MSC					2537:42		
	REF: AMM 52-11-00	AFL					1791		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-11-00-003 (s)	FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH PKG 1 REF: AMM 52-11-23	MOS HRS/MSC AFL	800	+30/-30			PKG 30-AUG-2019 2537:42 1791		
52-13-00	MAIN DOOR BALANCE ASSY. GEAR SECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			31-JUL-2011 0 0		
52-13-01	MAIN DOOR BALANCE ASSY. PINION SHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			31-JUL-2011 0 0		
52-13-21-001 (s)	DISCARD OF SECTOR GEAR SECTOR (ACFT WITH GEAR SECTOR P/N 500-09892-005 INSTALLED) PN PKG 50 SN-UNKNOWN REF: AMM 52-13-21	MOS HRS/MSC AFL	5600	+30/-30			PKG 31-JUL-2011 0 0		
52-13-22	MAIN DOOR BALANCING MECHANISM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
52-13-22-001 (s)	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE PN PKG 1 SN-UNKNOWN REF: AMM 52-13-22	MOS HRS/MSC AFL	O/C				PKG 13-JUL-2018 2299:30 1622		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-13-22-004 (s)	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES PKG 40 REF: AMM 52-13-22	MOS HRS/MSC AFL	3200	+30/-30			PKG 31-JUL-2011 0 0		
52-13-23-001 (s)	DISCARD OF SHAFT PINION SHAFT (ACFT WITH PINION SHAFT P/N 500-09890-001 INSTALLED) PN PKG 50 SN-UNKNOWN REF: AMM 52-13-23	MOS HRS/MSC AFL	5600	+30/-30			PKG 31-JUL-2011 0 0		
52-20-00	EMERGENCY DOOR 500-09700-433 0000654487 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
52-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR STRUCTURE PKG 90 REF: NDT PART 5 52-20-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
52-20-01-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE PKG 90 REF: See Workcard	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
52-20-01-01-901	GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 52-20-00								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20-01-01-902	DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 52-20-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
52-20-20-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM						PKG		
	PKG 83	MOS	48	+1m/-1m			30-AUG-2019		
	REF: AMM 52-20-20	HRS/MSC					2537:42		
		AFL					1791		
52-20-21-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR RUBBER SEAL						PKG		
	PKG 81	MOS	24	+1m/-1m			30-AUG-2021		
	REF: AMM 52-20-21	HRS/MSC					2879:18		
		AFL					2002		
52-31-20-001 (s)	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM						PKG		
	PKG 83	MOS	48	+1m/-1m			30-AUG-2019		
	REF: AMM 52-31-20	HRS/MSC					2537:42		
		AFL					1791		
52-32-20-001 (s)	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM						PKG		
	PKG 83	MOS	48	+1m/-1m			30-AUG-2019		
	REF: AMM 52-32-20	HRS/MSC					2537:42		
		AFL					1791		
CHAPTER 53 FUSELAGE									
53-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF FUSELAGE POLYURETHANE FILMS						PKG		
	PKG 1	MOS					13-JUL-2018		
	REF: AMM 53-00-20	HRS/MSC	800	+30/-30			2299:30		
		AFL					1622		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-05-00-001 (s)	DETAILED INSPECTION OF FUSELAGE DRAINS PKG 84 REF: AMM 53-05-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
53-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES PKG 90 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
53-10-00-002 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES PKG 87 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
53-10-00-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 87 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
53-10-01-01-901	DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-10-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-02-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	AFL	14000				0		14000
53-10-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	AFL	14000				0		14000
53-10-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	AFL	14000				0		14000
53-10-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	AFL	14000				0		14000
53-10-04-01-901	DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	AFL	14000				0		14000
53-10-04-01-902	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-10-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD PKG 90 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
53-10-05-01-901	DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
53-10-07-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 84 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
53-10-07-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TRUNNIONS,DRAW LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	15000 12000				31-JUL-2011 0 0	15000 12000	
53-10-07-02-901	DETAILED INSPECTION OF WHEEL WHEEL STRUCTURE. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - EXTERNAL REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	15000 12000				31-JUL-2011 0 0	15000 12000	
53-10-07-02-902	DETAILED INSPECTION NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WHEEL STRUCTURE. REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	15000 12000				31-JUL-2011 0 0	15000 12000	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-14-00	NOSE RADOME 5190-102-1 313 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
53-20-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
53-20-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
53-20-01-01-901	DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 53-20-00								
53-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 53-20-00								
53-20-02-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 53-20-00								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
53-20-03-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
53-20-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
53-20-04-01-901	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
53-20-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
53-20-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 6 53-20-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-04-02-902	GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE						PKG		
	PKG 90	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 53-20-00	AFL					2002		
53-20-05-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE						PKG		
	PKG 90	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 53-20-00	AFL					2002		
53-20-05-01-901	GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-05-02-901	DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-05-03-901	DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-05-04-901	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-05-05-901	GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-06-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF MAIN DOOR CUTOUT STRUCTURE						PKG		
	PKG 84	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 53-20-00	AFL					2002		
53-20-06-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE						PKG		
	PKG 84,90	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 53-20-00	AFL					2002		
53-20-06-01-901	DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-06-01-902	DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	8750				0		8750
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	7000				0		7000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-07-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-07-01-902	DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-08-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE PKG 84,90	MOS	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
	REF: NDT PART 5 53-20-00	HRS/MSC							
		AFL							
53-20-08-01-901	GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-08-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-10-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS PKG 90	MOS	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
	REF: NDT PART 5 53-20-00	HRS/MSC							
		AFL							



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-10-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-10-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-20-10-02-901	GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	AFL	14000				0		14000
53-30-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE	MOS	60	+1m/-1m			30-AUG-2021		
	PKG 90	HRS/MSC					2879:18		
	REF: NDT PART 5 53-30-00	AFL					2002		
53-30-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES	MOS	60	+1m/-1m			30-AUG-2021		
	PKG 90	HRS/MSC					2879:18		
	REF: NDT PART 5 53-30-00	AFL					2002		
53-30-01-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL	MOS						31-JUL-2011	
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	14000				0		14000
53-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL	MOS	60	+1m/-1m				PKG	
	PKG 90	HRS/MSC					30-AUG-2021		
	REF: NDT PART 5 53-30-00	AFL					2879:18		
							2002		
53-30-02-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS						31-JUL-2011	
		HRS/MSC	12500				0		12500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	10000				0		10000
53-30-02-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS						31-JUL-2011	
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	14000				0		14000
53-30-02-01-903	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL	MOS						31-JUL-2011	
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	14000				0		14000
53-30-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS						31-JUL-2011	
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
53-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES						PKG		
	PKG 90	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 53-30-00	AFL					2002		
53-30-04-01-901	DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
		AFL	14000				0		14000
53-30-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
		AFL	14000				0		14000
53-30-05-02-901	DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS					31-JUL-2011		
		HRS/MSC	10000				0		10000
		AFL	8000				0		8000
53-30-06-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS					31-JUL-2011		
		HRS/MSC	12500				0		12500
		AFL	10000				0		10000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-06-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	14000				0		14000
53-30-06-01-903	DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	14000				0		14000
53-30-07-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION						PKG		
	PKG 90	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 53-30-00	AFL					2002		
53-30-07-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION						PKG		
	PKG 90	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 53-30-00	AFL					2002		
53-30-07-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	14000				0		14000
53-30-07-01-902	DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-08-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 87 REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
53-30-08-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 90 REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
CHAPTER 54 NACELLES/PYLONS									
54-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF PYLON POLYURETHANE FILMS PKG 1 REF: AMM 54-51-20	MOS HRS/MSC AFL	800	+30/-30			PKG 13-JUL-2018 2299:30 1622		
54-50-00-001 (s)	INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE PKG 90 REF: NDT PART 5 54-50-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
54-50-00-002 (s)	INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX PKG 90 REF: See Workcard	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
54-50-01-01-901	GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 54-50-00								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-50-02-01-901	GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 54-50-00	AFL	14000				0		14000
54-50-03-001 (s)	EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE.	MOS	60	+1m/-1m			PKG		
	PKG 84	HRS/MSC					30-AUG-2021		
	REF: NDT PART 5 54-52-00	AFL					2879:18		
							2002		
54-50-03-01-901	GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 54-52-00	AFL	14000				0		14000
54-50-03-01-902	DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 54-52-00	AFL	14000				0		14000
54-50-04-01-901	GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 54-52-00	AFL	14000				0		14000
54-50-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES	MOS	120	+1m/-1m			PKG		
	PKG 87	HRS/MSC					30-AUG-2021		
	REF: NDT PART 5 54-55-00	AFL					2879:18		
							2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-50-05-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 6 54-55-00	HRS/MSC AFL	15000 12000				0 0	15000 12000	
54-50-05-02-901	DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 54-55-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
54-50-06-01-901	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 54-55-00	HRS/MSC AFL	15000 12000				0 0	15000 12000	
54-50-06-01-902	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 54-55-00	HRS/MSC AFL	15000 12000				0 0	15000 12000	
CHAPTER 55	STABILIZERS								
55-00-00-001 (s)	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS						PKG		
	PKG 1	MOS					13-JUL-2018		
	REF: AMM 55-00-20	HRS/MSC AFL	800 +30/-30				2299:30 1622		
55-10-00	HORIZONTAL STABILIZER (COMPLETION)								
	505-10700-413	MOS		N:0			31-JUL-2011		
	0000656233	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
55-10-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
55-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
55-10-01-01-901	DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-10-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-10-02-01-902	DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN PKG 87 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
55-10-03-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
55-10-03-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
55-10-03-01-902	DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
55-10-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
55-10-05-001 (s)	INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS PKG 90 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-05-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00	AFL	14000				0		14000
55-10-05-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 55-10-00	AFL	14000				0		14000
55-10-05-02-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00	AFL	14000				0		14000
55-10-05-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00	AFL	14000				0		14000
55-10-05-04-901	DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00	AFL	14000				0		14000
55-10-05-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 55-10-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-07-01-901	GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
55-10-08-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS	MOS	60	+1m/-1m			30-AUG-2021		
	PKG 84	HRS/MSC					2879:18		
	REF: NDT PART 5 55-10-00	AFL					2002		
55-10-08-01-901	DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
55-10-09-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT	MOS	120	+1m/-1m			30-AUG-2021		
	PKG 87	HRS/MSC					2879:18		
	REF: NDT PART 5 55-10-00	AFL					2002		
55-10-09-01-901	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
55-10-09-01-902	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-10-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF ELEVATOR TRIM-TAB FITTINGS						PKG		
	PKG 90	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 55-10-00	AFL					2002		
55-10-10-01-901	DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00	AFL	14000				0		14000
55-20-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX						PKG		
	PKG 87	MOS	120	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: See Workcard	AFL					2002		
55-20-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-20-00	AFL	14000				0		14000
55-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-20-00	AFL	14000				0		14000
55-20-02-01-901	DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-20-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-02-02-901	GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-20-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY PKG 87	MOS HRS/MSC AFL	120 +1m/-1m				30-AUG-2021 2879:18 2002		
55-20-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 6 55-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-20-03-02-901	SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 8 55-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-20-04-001	INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS	MOS	60				16-JUL-2020	16-JUL-2025	
ALI	REF: See Workcard	HRS/MSC AFL					2630:24 1861		
55-20-04-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS	MOS	60				16-JUL-2020	16-JUL-2025	
ALI	REF: NDT PART 5 55-20-00	HRS/MSC AFL					2630:24 1861		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-22-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB PKG 87 REF: NDT PART 5 55-22-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
55-30-00	VERTICAL STABILIZER 505-10100-413 0000655831 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
55-30-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER PKG 84 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
55-30-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER PKG 84 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
55-30-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 6 55-30-00								
55-30-01-02-901	DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 55-30-00								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-01-03-901	DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-30-01-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 55-30-00	AFL	14000				0		14000
55-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER						PKG		
	PKG 84	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 55-30-00	AFL					2002		
55-30-02-01-901	DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-30-02-03-901	DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-30-02-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 55-30-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-02-05-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-30-02-06-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-30-02-07-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-30-03-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS						PKG		
	PKG 87	MOS	120	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 55-30-00	AFL					2002		
55-30-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX						PKG		
	PKG 87	MOS	120	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: See Workcard	AFL					2002		
55-30-03-01-901	DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-03-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING PKG 84	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 55-30-00	AFL					2002		
55-30-04-01-901	GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-30-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER PKG 84	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 55-30-00	AFL					2002		
55-30-05-01-901	DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-30-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING PKG 90	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 55-30-00	AFL					2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-06-01-901	DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-30-00	AFL	14000				0		14000
55-40-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX PKG 87	MOS	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
	REF: NDT PART 5 55-40-00	HRS/MSC							
		AFL							
55-40-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-40-00	AFL	14000				0		14000
55-40-01-01-902	DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-40-00	AFL	14000				0		14000
55-40-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS PKG 87	MOS	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
	REF: NDT PART 5 55-40-00	HRS/MSC							
		AFL							
55-40-02-01-901	DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 55-40-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40-02-02-901	GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-40-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY PKG 87	MOS HRS/MSC AFL	120 +1m/-1m				PKG 30-AUG-2021 2879:18 2002		
55-40-03-01-901	GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-40-04-002	INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS	MOS	60				16-JUL-2020	16-JUL-2025	
ALI	REF: NDT PART 5 55-40-00	HRS/MSC AFL					2630:24 1861		
55-40-04-003	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS	MOS	60				16-JUL-2020	16-JUL-2025	
ALI	REF: NDT PART 5 55-40-00	HRS/MSC AFL					2630:24 1861		
55-42-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB PKG 90	MOS HRS/MSC AFL	60 +1m/-1m				PKG 30-AUG-2021 2879:18 2002		

CHAPTER 56 WINDOWS



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-00	LEFT GLASS, HEATED WINDSHIELD ASSY, (LH) NP-195301-3 11021H5091 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-10-00	RIGHT GLASS, HEATED WINDSHIELD ASSY, (LH) NP-195301-4 10326H8865 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF SIDE WINDOW PKG 84 REF: NDT PART 5 56-12-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
56-10-01-002	FUNCTIONAL CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS REF: AMM 56-10-00	MOS HRS/MSC AFL	1600	+30/-30			13-JUL-2017 1987:12 1393	3587:12	3617:12
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
56-10-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 6 56-10-00								
56-12-00	LEFT ACRYLIC SIDE WINDOW NP-195302-3 10325H5758 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-12-00	RIGHT ACRYLIC SIDE WINDOW NP-195302-4 10350H2083 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-00	NO. 1 WINDOW TRANSPARENCY 14024 02791 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-00	NO. 10 WINDOW TRANSPARENCY 14024 1491177 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-00	NO. 11 WINDOW TRANSPARENCY 14024 1491181 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-00	NO. 2 WINDOW TRANSPARENCY 14024 02859 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-00	NO. 3 WINDOW TRANSPARENCY 14024 02861 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-00	NO. 4 WINDOW TRANSPARENCY 14024 02875 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-00	NO. 5 WINDOW TRANSPARENCY 14024 02877 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-00	NO. 6 WINDOW TRANSPARENCY 14024 02878 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-00	NO. 7 WINDOW TRANSPARENCY 14024 02879 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-00	NO. 8 WINDOW TRANSPARENCY 14024 02880 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-00	NO. 9 WINDOW TRANSPARENCY 14024 1491176 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
56-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PASSENGER WINDOW PANELS PKG 84 REF: NDT PART 5 56-20-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
CHAPTER 57	WINGS								
57-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF WINGLET POLYURETHANE FILMS PKG 1 REF: AMM 57-35-21	MOS HRS/MSC AFL	800	+30/-30			PKG 13-JUL-2018 2299:30 1622		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX PKG 90 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
57-10-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN PKG 87 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
57-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS PKG 87 REF: NDT PART 5 57-00-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
57-10-01-01-901	DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-10-02-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR PKG 90 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
57-10-02-01-901	DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR PKG 90 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
57-10-03-01-901	DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-10-00								
57-10-04-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR PKG 84 REF: NDT PART 5 57-20-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
57-10-04-01-901	DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-10-00								
57-10-05-01-901	GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-10-00								
57-10-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL PKG 87 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-07-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL PKG 84 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
57-10-07-01-901	GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-10-00								
57-10-07-01-902	DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-10-00								
57-10-08-01-901	DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-10-00								
57-10-08-02-901	DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-10-00								
57-10-11-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE PKG 84 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-11-01-901	DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-10-00	AFL	14000				0		14000
57-10-11-01-902	SPECIAL DETAILED INSPECTION (BOREScope) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-10-00	AFL	14000				0		14000
57-10-12-01-901	DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	12500				0		12500
AIRWORTHINESS	REF: NDT PART 5 57-10-00	AFL	10000				0		10000
57-50-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS						PKG		
	PKG 84	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 57-50-00	AFL					2002		
57-50-01-01-901	DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-50-00	AFL	14000				0		14000
57-50-01-01-902	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL								
		MOS					31-JUL-2011		
		HRS/MSC	11250				0		11250
AIRWORTHINESS	REF: NDT PART 6 57-50-00	AFL	9000				0		9000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-01-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 57-50-00	AFL	14000				0		14000
57-50-01-03-901	DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-50-00	AFL	14000				0		14000
57-50-01-04-901	DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-50-00	AFL	14000				0		14000
57-50-01-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 57-50-00	AFL	14000				0		14000
57-50-01-05-902	DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-50-00	AFL	14000				0		14000
57-50-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK						PKG		
	PKG 84	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 57-20-00	AFL					2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-02-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 57-50-00	AFL	14000				0		14000
57-50-02-01-902	DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-50-00	AFL	14000				0		14000
57-50-02-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 57-50-00	AFL	14000				0		14000
57-50-02-02-902	DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-50-00	AFL	14000				0		14000
57-52-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP						PKG		
	PKG 90	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 57-52-00	AFL					2002		
57-52-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP						PKG		
	PKG 84	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 57-52-00	AFL					2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-52-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-52-00	AFL	14000				0		14000
57-52-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-52-00	AFL	14000				0		14000
57-52-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-52-00	AFL	14000				0		14000
57-52-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	11250				0		11250
AIRWORTHINESS	REF: NDT PART 6 57-52-00	AFL	9000				0		9000
57-52-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-52-00	AFL	14000				0		14000
57-52-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 57-52-00	AFL	14000				0		14000



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-53-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE OUTBOARD FLAP PKG 90 REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
57-53-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP PKG 84 REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
57-53-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-53-00								
57-53-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-53-00								
57-53-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL	MOS HRS/MSC AFL	17500 14000				31-JUL-2011 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 57-53-00								
57-53-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL	MOS HRS/MSC AFL	11250 9000				31-JUL-2011 0 0	11250 9000	
AIRWORTHINESS	REF: NDT PART 6 57-53-00								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-53-04-01-901	DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-53-00	AFL	14000				0		14000
57-53-04-02-901	DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-53-00	AFL	14000				0		14000
57-53-04-03-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 5 57-53-00	AFL	14000				0		14000
57-53-04-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					31-JUL-2011		
		HRS/MSC	17500				0		17500
AIRWORTHINESS	REF: NDT PART 6 57-53-00	AFL	14000				0		14000
57-60-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON	MOS	60				16-JUL-2020	16-JUL-2025	
		HRS/MSC					2630:24		
ALI	REF: NDT PART 5 57-60-00	AFL					1861		
57-60-00-002 (s)	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF AILERON AND TAB						PKG		
	PKG 84	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 57-60-00	AFL					2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
57-60-01-01-902	DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
57-60-01-02-901	DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
57-60-02-01-901	DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
57-60-02-02-901	DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL	MOS					31-JUL-2011		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC	17500				0		17500
		AFL	14000				0		14000
57-60-04-001	INTERNAL DETAILED VISUAL INSPECTION OF AILERON MASS-BALANCE WEIGHTS AND ATTACHMENTS	MOS					30-AUG-2021		
	REF: NDT PART 5 57-60-00	HRS/MSC	O/C				2879:18		
		AFL					2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-70-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS						PKG		
	PKG 84	MOS	60	+1m/-1m			30-AUG-2021		
		HRS/MSC					2879:18		
	REF: NDT PART 5 57-70-00	AFL					2002		

CHAPTER 70 STANDARD PRACTICES - ENGINES

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01

700010	NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION								
		MOS					23-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 70-00-00	ENC					0		

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01

700010	NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION								
		MOS					28-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 70-00-00	ENC					0		

CHAPTER 71 POWER PLANT

71-11-00-001 (s)	GENERAL VISUAL INSPECTION OF UPPER MID COWL						PKG		
	PKG 50	MOS					31-JUL-2011		
		HRS/MSC	5600	+30/-30			0		
	REF: AMM 71-11-00	AFL					0		

71-20-00	LEFT AFT ENGINE MOUNT ISOLATOR								
	LM-475-SA4	MOS			N:0		31-JUL-2011		
	LK0286	HRS/MSC	O/C		N:0		0		
	REF: See Workcard	AFL			N:0		0		

71-20-00	LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR								
	LM-475-SA3	MOS			N:0		31-JUL-2011		
	LK0498	HRS/MSC	O/C		N:0		0		
	REF: See Workcard	AFL			N:0		0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-00	LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK0459 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
71-20-00	RIGHT AFT ENGINE MOUNT ISOLATOR LM-475-SA4 LK0290 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
71-20-00	RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK0457 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
71-20-00	RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK0476 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JUL-2011 0 0		
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT AFT MOUNT ASSEMBLY AND ATTACHMENTS LM-475-SA4 LK0286 REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+30/-30			31-JUL-2011 0 0	6000	6030
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS LM-475-SA3 LK0498 REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+30/-30			31-JUL-2011 0 0	6000	6030



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS								
	LM-475-SA3	MOS					31-JUL-2011		
	LK0459	HRS/MSC	6000	+30/-30			0	6000	6030
OVERHAUL	REF: AMM 71-20-00	AFL					0		
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT AFT MOUNT ASSEMBLY AND ATTACHMENTS								
	LM-475-SA4	MOS					31-JUL-2011		
	LK0290	HRS/MSC	6000	+30/-30			0	6000	6030
OVERHAUL	REF: AMM 71-20-00	AFL					0		
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS								
	LM-475-SA3	MOS					31-JUL-2011		
	LK0457	HRS/MSC	6000	+30/-30			0	6000	6030
OVERHAUL	REF: AMM 71-20-00	AFL					0		
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS								
	LM-475-SA3	MOS					31-JUL-2011		
	LK0476	HRS/MSC	6000	+30/-30			0	6000	6030
OVERHAUL	REF: AMM 71-20-00	AFL					0		
71-21-01-01-901	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY								
		MOS					31-JUL-2011		
		HRS/MSC	7500				0	7500	
AIRWORTHINESS	REF: AMM 71-20-00	AFL	6000				0	6000	
71-22-01-01-901	DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL								
		MOS					31-JUL-2011		
		HRS/MSC	4500				0	4500	
AIRWORTHINESS	REF: See Workcard	AFL	3600				0	3600	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-22-01-01-902	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY							31-JUL-2011	
AIRWORTHINESS	REF: AMM 71-20-00	MOS						0	7500
		HRS/MSC	7500					0	
		AFL	6000					0	6000
71-31-00-001 (s)	DETAILED INSPECTION OF PYLON FIREWALL SEAL							PKG	
	PKG 20	MOS						30-DEC-2016	
		HRS/MSC	2400	+30/-30				1790:24	
	REF: AMM 71-31-00	AFL						1250	
71-60-01	LEFT ENGINE AIR INLET								
	505-36920-403	MOS						31-JUL-2011	
	032	HRS/MSC	O/C					0	
	REF: See Workcard	AFL						0	
71-60-01	RIGHT ENGINE AIR INLET								
	505-36930-403	MOS						31-JUL-2011	
	041	HRS/MSC	O/C					0	
	REF: See Workcard	AFL						0	
71EN1	NO. 1 ENGINE								
	A3072913-01	MOS							
71.EN1	PCE-DG0104	HRS/MSC	E/C						
	REF: See Workcard	AFL							
71EN2	NO. 2 ENGINE								
	A3072913-01	MOS							
71.EN2	PCE-DG0107	HRS/MSC	E/C						
	REF: See Workcard	AFL							

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
70-00-00-200-801	NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	MOS						23-FEB-2011	
	REF: MM 70-00-00	HRS/MSC	A/R					0	
		ENC						0	
71-00-00-160-805	NO. 1 ENGINE - COMPRESSOR WASH	DAYS						10-JUL-2018	
	REF: MM 71-00-00	HRS/MSC	A/R					2299:30	
		ENC						1622	
+ 71-00-00-160-806	NO. 1 ENGINE - PERFORMANCE RECOVERY WASH	MOS						24-SEP-2017	
	REF: MM 71-00-00	HRS/MSC	A/R					2059:06	
		ENC						1444	
71-00-00-760-810	NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN	MOS						23-FEB-2011	
	REF: MM 71-00-00	HRS/MSC	A/R					0	
		ENC						0	
+ 71-00-00-760-814	NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK	MOS						23-FEB-2011	
	REF: MM 71-00-00	HRS/MSC	A/R					0	
		ENC						0	
71-00-00-760-817	NO. 1 ENGINE - DOWNLOAD ENGINE DCU DATA	MOS						23-FEB-2011	
	REF: MM 71-00-00	HRS/MSC	A/R					0	
	UNSCHEDULED MAINTENANCE CHECK	ENC						0	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00-00-760-823	NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	MOS	12	+30d			30-AUG-2021	30-AUG-2022	29-SEP-2022
		HRS/MSC	630	+10%			2879:18	(3509:18) 3509:18	3572:18
	REF: MM 71-00-00	ENC					1999		
72-00-02-810-801	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	MOS	12				30-AUG-2021	30-AUG-2022	
		HRS/MSC	630				2879:18	(3509:18) 3509:18	
	REF: MM 72-00-02	ENC					1999		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01									
70-00-00-200-801	NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	MOS					28-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 70-00-00	ENC					0		
71-00-00-160-805	NO. 2 ENGINE - COMPRESSOR WASH	DAYS					10-JUL-2018		
		HRS/MSC	A/R				2299:30		
	REF: MM 71-00-00	ENC					1622		
+ 71-00-00-160-806	NO. 2 ENGINE - PERFORMANCE RECOVERY WASH	MOS					24-SEP-2017		
		HRS/MSC	A/R				2059:06		
	REF: MM 71-00-00	ENC					1444		
71-00-00-760-810	NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN	MOS					28-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 71-00-00	ENC					0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00-00-760-814	NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK	MOS					28-FEB-2011		
	REF: MM 71-00-00	HRS/MSC	A/R				0		
		ENC					0		
71-00-00-760-817	NO. 2 ENGINE - DOWNLOAD ENGINE DCU DATA	MOS					28-FEB-2011		
UNSCHEDULED MAINTENANCE CHECK	REF: MM 71-00-00	HRS/MSC	A/R				0		
		ENC					0		
71-00-00-760-823	NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	MOS	12	+30d			30-AUG-2021	30-AUG-2022	29-SEP-2022
	REF: MM 71-00-00	HRS/MSC	630	+10%			2879:18	(3509:18) 3509:18	3572:18
		ENC					1999		
72-00-02-810-801	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	MOS	12				30-AUG-2021	30-AUG-2022	
	REF: MM 72-00-02	HRS/MSC	630				2879:18	(3509:18) 3509:18	
		ENC					1999		
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01									
+ 72-00-00-000-802	NO. 1 ENGINE - DISCARD GAS GENERATOR CASE	MOS							
	3075417-01	HRS/MSC							
	RWA25D354	ENC	8200				(EBT)	(8200) 8203	
	REF: GENERIC NO REF								
72-00-00-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA	MOS	12	+30d			PKG		
	PKG 1	HRS/MSC	800	+10%			30-AUG-2021		
	REF: MM 72-00-00	ENC					2879:18		
							1999		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-802 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-212-803 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-212-804 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-212-805 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-212-806 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-212-807 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-808 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-212-809 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-280-802	NO. 1 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR REF: MM 72-00-00	MOS HRS/MSC ENC	A/R				23-FEB-2011 0 0		
72-00-00-280-818	NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES) REF: MM 72-00-00	MOS HRS/MSC ENC	24	+1m	-30		30-AUG-2021 2879:18 1999	31-JUL-2023	31-AUG-2023
72-00-00-280-820 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-640-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL REF: MM 72-00-00	MOS HRS/MSC ENC	BF/F				31-JUL-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-640-806	NO. 1 ENGINE - OIL ANALYSIS	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
	REF: MM 72-00-00	ENC						0	
72-00-01-810-822	NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115)	MOS						23-FEB-2011	
		HRS/MSC	A/R					0	
UNSCCHEDULED MAINTENANCE CHECK	REF: MM 72-00-01	ENC						0	
+ 72-00-51-030-002	NO. 1 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER	MOS							
		HRS/MSC	5000	+100			(EBT)		
LIFE LIMIT	REF:	ENC						(5000) 5000	5100
+ 72-60-01-212-801	NO. 1 ENGINE - INSPECT THE HYDRAULIC PUMP DRIVESHAFT SPLINES	MOS						23-FEB-2011	
		HRS/MSC	1200	+100				0	
	REF: GENERIC NO REF	ENC						0	(3819:30) 3819:30 M 3919:30
720010	NO. 1 ENGINE - OVERHAUL	MOS						23-FEB-2011	
		HRS/MSC	5000	+100				0	
	REF: GENERIC NO REF	ENC						0	(5000) 5000 5100
720060	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS						23-AUG-2019	
		HRS/MSC	2500	+50				2537:42	
	REF: MM 72-00-00	ENC			-37:42			1787	(5000) 5000 5050



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722001	NO. 1 ENGINE - OIL PUMP 3073477-02 EC01A003A127 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723004	NO. 1 ENGINE - LP SHAFT ASSEMBLY 3073356-01 A002X5YT REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	30000	N:0 N:0 N:0 N:0			23-FEB-2011 0 0		
723010	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR 3073311-01 A002Y7F1 REF: See Workcard	MOS HRS/MSC ENC ACCCYC	15000	N:0 N:0 N:0 N:0			23-FEB-2011 0 0		
723020	NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR 3073292-01 TXA1C4221 REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	15000	N:0 N:0 N:0 N:0			23-FEB-2011 0 0		
723030	NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR 3072981-01 A002X4FT REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	13500	N:0 N:0 N:0 N:0			23-FEB-2011 0 0		
723040	NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR 3056210-01 A002XKTT REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	13500	N:0 N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY 3074676-01 EDA01039M REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723070	NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY 3075850-01 A002XTEA REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723080	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY 3075417-01 RWA25D354 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723090	NO. 1 ENGINE - GAS GENERATOR DIFFUSER 3073236-01 A002Y1XP REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723095	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3052673-01 PKAAA351856 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723110	NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER 3052668-01 AFD00D842 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723120	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 3072571-01 AWE013979 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723130	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 3072572-01 AWE014205 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723140	NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING 3052737-01 LPA09608 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723150	NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR 3072574-01 EAAC000E885 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723160	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING 3052670-02 FCN327877 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
723170	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3072280-01 PKAAA220594 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723705	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK								
	3053812-01	MOS		N:0			23-FEB-2011		
	A002XR7B	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
		ACCCYC	13500	N:0					
723706	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK								
	3053743-01	MOS		N:0			23-FEB-2011		
	A002Y2X4	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
		ACCCYC	13500	N:0					
724001	NO. 1 ENGINE - INNER COMBUSTION LINER								
	3079976-01	MOS		N:1			23-AUG-2019		
	A004HMKF	HRS/MSC	O/C	N:0			2537:42		
	REF: See Workcard	ENC		N:0			1787		
724002	NO. 1 ENGINE - OUTER COMBUSTION LINER								
	3123695-01	MOS		N:1			23-AUG-2019		
	A004HAC5	HRS/MSC	O/C	N:0			2537:42		
	REF: See Workcard	ENC		N:0			1787		
724010	NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY								
	3075468-01	MOS		N:0			23-FEB-2011		
	ACM221823146	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
724706	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK								
	3053331-01	MOS		N:0			23-FEB-2011		
	A002XWLT	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	ENC		N:0			0		
		ACCCYC	10000	N:0					



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER								
	3052661-01	MOS		N:0			23-FEB-2011		
	A002X6H9	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
		ACCCYC	13500	N:0					
725010	NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE								
	3074951-01	MOS		N:0			23-FEB-2011		
	HWEF3294	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
725010	NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE								
	3074951-01	MOS		N:0			23-FEB-2011		
	HWEL7562	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
725010	NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE								
	3074951-01	MOS		N:0			23-FEB-2011		
	HWEL7569	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
725010	NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE								
	3074951-01	MOS		N:0			23-FEB-2011		
	HWEL7575	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
725010	NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE								
	3074951-01	MOS		N:0			23-FEB-2011		
	HWEL7580	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7582 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7585 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7596 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7603 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7606 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8557 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3297 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8561 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8565 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8566 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8568 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8574 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8575 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8580 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8583 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8584 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8587 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3333 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8594 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8597 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8602 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8604 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8608 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8610 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8612 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8617 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8619 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8626 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7539 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8630 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8634 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8636 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8644 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8647 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8648 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8650 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8653 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8661 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8664 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7545 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8666 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8671 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL8673 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1189 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1193 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1199 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1200 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1208 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1215 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1218 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7548 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1223 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7550 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7553 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7561 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1224 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1230 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1233 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1234 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1244 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1262 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1269 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1274 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1275 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725010	NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEN1277 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725015	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING 3073355-01 FCN325121 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725020	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 3076552-01 RWA19D865 REF: MM 72-50-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725025	NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER 3073353-01 MDAA000A728 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725030	NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING 3052263CL01 PDAHTY2N01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725035	NO. 1 ENGINE - TURBINE (CASTING) VANE RING 3052361CL01 PDAHUREB01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
725040	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY 3073262CL02 BHERAHD01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
726010	NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING 3052549-01 FCN318948 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726020	NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING								
	3073908-01	MOS		N:0			23-FEB-2011		
	AEB0100819	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
726030	NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING								
	3073908-01	MOS		N:0			23-FEB-2011		
	AEB0100820	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
726040	NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING								
	3073908-01	MOS		N:0			23-FEB-2011		
	AEB0100821	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
726050	NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING								
	3073908-01	MOS		N:0			23-FEB-2011		
	AEB0100824	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
726070	NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY								
	3072949-01	MOS		N:0			23-FEB-2011		
	PKAAA337792	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
726080	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT								
	3072279-01	MOS		N:0			23-FEB-2011		
	RWA15D633	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726090	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING 3072235-01 FAA1021102 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
726110	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING 3052605-01 FAA1023340 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
726120	NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING 3052550-01 BB0101135 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
726130	NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT 3072282-01 PKAAA352273 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
727010	NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY 3075013-01 KYAA008A054 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
727020	NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY 3074835-01 KYAA007A857 REF: MM 72-70-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793010	NO. 1 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR 3052535-02 HA1329 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C						
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01									
+ 72-00-00-000-802	NO. 2 ENGINE - DISCARD GAS GENERATOR CASE 3075417-01 RWA23D765 REF: GENERIC NO REF	MOS HRS/MSC ENC	8200				(EBT)	(8200) 8203	
72-00-00-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-212-802 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-212-803 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
72-00-00-212-804 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-805 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM						PKG		
	PKG 1	MOS	12	+30d			30-AUG-2021		
		HRS/MSC	800	+10%			2879:18		
	REF: MM 72-00-00	ENC					1999		
72-00-00-212-806 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM						PKG		
	PKG 1	MOS	12	+30d			30-AUG-2021		
		HRS/MSC	800	+10%			2879:18		
	REF: MM 72-00-00	ENC					1999		
72-00-00-212-807 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS						PKG		
	PKG 1	MOS	12	+30d			30-AUG-2021		
		HRS/MSC	800	+10%			2879:18		
	REF: MM 72-00-00	ENC					1999		
72-00-00-212-808 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM						PKG		
	PKG 1	MOS	12	+30d			30-AUG-2021		
		HRS/MSC	800	+10%			2879:18		
	REF: MM 72-00-00	ENC					1999		
72-00-00-212-809 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP						PKG		
	PKG 1	MOS	12	+30d			30-AUG-2021		
		HRS/MSC	800	+10%			2879:18		
	REF: MM 72-00-00	ENC					1999		
72-00-00-280-802	NO. 2 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR								
		MOS					28-FEB-2011		
		HRS/MSC	A/R				0		
	REF: MM 72-00-00	ENC					0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-280-818	NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)	MOS HRS/MSC ENC	24	+1m		-30	30-AUG-2021 2879:18 1999	31-JUL-2023	31-AUG-2023
	REF: MM 72-00-00								
72-00-00-280-820 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES	MOS HRS/MSC ENC	12	+30d			PKG 30-AUG-2021 2879:18 1999		
	PKG 1		800	+10%					
	REF: MM 72-00-00								
72-00-00-640-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS HRS/MSC ENC	BF/F				31-JUL-2011 0 0		
	REF: MM 72-00-00								
+ 72-00-00-640-806	NO. 2 ENGINE - OIL ANALYSIS	MOS HRS/MSC ENC	A/R				28-FEB-2011 0 0		
	REF: MM 72-00-00								
72-00-01-810-822	NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115)	MOS HRS/MSC ENC	A/R				28-FEB-2011 0 0		
UNSCHEDULED MAINTENANCE CHECK	REF: MM 72-00-01								
+ 72-00-51-030-002	NO. 2 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	5100
LIFE LIMIT	REF:								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-60-01-212-801	NO. 2 ENGINE - INSPECT THE HYDRAULIC PUMP DRIVESHAFT SPLINES	MOS					28-FEB-2011		
	REF: GENERIC NO REF	HRS/MSC ENC	1200	+100			0 0	(3819:30) 3819:30 M	3919:30
720010	NO. 2 ENGINE - OVERHAUL	MOS					28-FEB-2011		
	REF: GENERIC NO REF	HRS/MSC ENC	5000	+100			0 0	(5000) 5000	5100
720060	NO. 2 ENGINE - HOT SECTION INSPECTION	MOS					23-AUG-2019		
	REF: MM 72-00-00	HRS/MSC ENC	2500	+50		-37:42	2537:42 1787	(5000) 5000	5050
722001	NO. 2 ENGINE - OIL PUMP	MOS					28-FEB-2011		
	3073477-02	HRS/MSC	O/C	N:0			0		
	EC01A003A154	ENC		N:0			0		
	REF: See Workcard			N:0					
723004	NO. 2 ENGINE - LP SHAFT ASSEMBLY	MOS					28-FEB-2011		
	3073356-01	HRS/MSC		N:0			0		
	A002XHX6	ENC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ACCCYC	30000	N:0					
723010	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR	MOS					28-FEB-2011		
	3073311-01	HRS/MSC		N:0			0		
	A002Y19H	ENC		N:0			0		
LIFE LIMIT	REF: See Workcard	ACCCYC	15000	N:0					



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723020	NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR								
	3073292-01	MOS		N:0			28-FEB-2011		
	TXA1C3241	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
		ACCCYC	15000	N:0					
723030	NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR								
	3072981-01	MOS		N:0			28-FEB-2011		
	A002X8L4	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
		ACCCYC	13500	N:0					
723040	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR								
	3056210-01	MOS		N:0			28-FEB-2011		
	A002XRDX	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
		ACCCYC	13500	N:0					
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY								
	3074676-01	MOS		N:0			28-FEB-2011		
	EDA01036B	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		
723070	NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY								
	3075850-01	MOS		N:0			28-FEB-2011		
	A002Y7FE	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
723080	NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY								
	3075417-01	MOS		N:0			28-FEB-2011		
	RWA23D765	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723090	NO. 2 ENGINE - GAS GENERATOR DIFFUSER 3073236-01 A002YB6W REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
723095	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3052673-01 PKAAA351861 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
723110	NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER 3052668-01 AFD00E175 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
723120	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 3072571-01 AWE013974 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
723130	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 3072572-01 AUAA0315 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
723140	NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING 3052737-01 LPA09601 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723150	NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR 3072574-01 EAAC000E889 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
723160	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING 3052670-02 FCN327882 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
723170	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3072280-01 PKAAA220593 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
723180	NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING 3052616-01 FCN324037 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
723705	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK 3053812-01 A002XR77 REF: GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			28-FEB-2011 0 0		
LIFE LIMIT		ACCCYC	13500	N:0					
723706	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK 3053743-01 A002Y2X2 REF: GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			28-FEB-2011 0 0		
LIFE LIMIT		ACCCYC	13500	N:0					



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724001	NO. 2 ENGINE - INNER COMBUSTION LINER 3079976-01 A004HMKK REF: See Workcard	MOS HRS/MSC ENC	O/C	N:1 N:0 N:0			23-AUG-2019 2537:42 1787		
724002	NO. 2 ENGINE - OUTER COMBUSTION LINER 3123695-01 A004HAPT REF: See Workcard	MOS HRS/MSC ENC	O/C	N:1 N:0 N:0			23-AUG-2019 2537:42 1787		
724010	NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY 3075468-01 ACM221823276 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
724706	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK 3053331-01 A002XWLW REF: See Workcard	MOS HRS/MSC ENC ACCCYC	10000	N:0 N:0 N:0 N:0			28-FEB-2011 0 0		
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 3052661-01 A002XKTK REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC	13500	N:0 N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3275 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3330 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3331 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3347 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3349 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEH1390 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEH1395 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEH1403 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEH1431 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEH1438 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEH1479 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3278 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7357 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7259 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7360 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7362 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7364 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7368 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7369 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7372 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7376 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7392 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3283 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7395 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7399 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7402 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7407 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7413 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7414 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7415 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7416 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7425 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7426 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3289 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7428 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7430 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7431 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7435 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7438 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7442 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7443 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7447 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7450 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7451 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3292 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7455 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7459 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7462 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7469 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7470 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7471 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7485 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7487 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7489 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7491 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3293 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7492 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3302 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3321 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEF3326 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7500 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7508 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7509 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7510 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7511 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7519 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7526 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7532 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7533 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725010	NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE 3074951-01 HWEL7535 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725015	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING 3073355-01 FCN325123 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725020	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 3076552-01 RWA21D097 REF: MM 72-50-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725025	NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER 3073353-01 MDAA000A732 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725030	NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING 3052263CL01 PDAHT49H01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725035	NO. 2 ENGINE - TURBINE (CASTING) VANE RING 3052361CL01 PDAHUMEK01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
725040	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY 3073262CL02 BHERAHN01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
726020	NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3112368-01 FAA1022893 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
726030	NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3112368-01 FAA1022894 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
726040	NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3112368-01 FAA1022895 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726050	NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3112368-01 FAA1022896 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
726060	NO. 2 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING 3112368-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
726070	NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY 3072949-01 PKAAA337787 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
726080	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT 3072279-01 RWA15D625 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
726090	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING 3072235-01 FAA1009800 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
726110	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING 3052605-01 FAA1025076 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726130	NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT 3072282-01 PKAAA352262 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
727010	NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY 3075013-01 KYAA008A056 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
727020	NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY 3074835-01 KYAA007A854 REF: MM 72-70-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
793010	NO. 2 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR 3052535-02 HA1315 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C						
CHAPTER 73 ENGINE FUEL AND CONTROL									
73-21-01	LEFT FADEC 1012300-3-003 2011050010 REF: See Workcard	MOS HRS/MSC AFL	O/C				19-MAY-2014 1051:30 695		
73-21-01	RIGHT FADEC 1012300-3-003 2011030033 REF: See Workcard	MOS HRS/MSC AFL	O/C				19-MAY-2014 1051:30 695		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-33-01	LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER 8TJ300AAB2 25337 REF: See Workcard	MOS HRS/MSC AFL	O/C						
73-33-01	RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER 8TJ300AAB2 25542 REF: See Workcard	MOS HRS/MSC AFL	O/C						
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01									
72-00-00-280-819 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
73-10-01-212-801	NO. 1 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
+ 73-10-04-000-801	NO. 1 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES REF: MM 73-10-04	MOS HRS/MSC ENC	9900				(EBT)	(9900) 9903	
73-10-05-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT REF: MM 73-10-05	MOS HRS/MSC ENC	12	+30d	-30		30-AUG-2021 2879:18 1999	31-JUL-2022	30-AUG-2022



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-05-960-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	800	+10%			11-JUL-2018 2299:30 1622	(3099:30) 3099:30	3179:30
73-10-07-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: MM 73-10-07	MOS HRS/MSC ENC	12 800	+30d +10%			30-AUG-2021 2879:18 1999		
+ 73-20-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT 3071682-05 F71916 REF: MM 73-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
73-20-02-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: MM 73-20-02	MOS HRS/MSC ENC	12 800	+30d +10%			30-AUG-2021 2879:18 1999		
73-20-10-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS 3073237-03 ADXBA000309 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
73-20-20-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			23-AUG-2019 2537:42 1787	(7537:42) 7537:42	7637:42



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-20-30-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100				(5000) 5000 M	5100
73-30-02-212-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR PKG 1 REF: MM 73-30-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
731005	NO. 1 ENGINE - FUEL FILTER PN SN-UNKNOWN REF: MM 73-10-05	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		11-JUL-2018 2299:30 1622		
731010	NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAB39052 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:3 N:0 N:0		23-AUG-2019 2537:42 1787		
731010	NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAB39352 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:3 N:0 N:0		23-AUG-2019 2537:42 1787		
731010	NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA76580 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		O:2 O:0 O:0		23-AUG-2019 2537:42 1787		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAB39351 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:3 N:0 N:0			23-AUG-2019 2537:42 1787		
731010	NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA76583 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
731010	NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA56988 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
731010	NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA56980 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
731010	NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAB39361 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:2 N:0 N:0			23-AUG-2019 2537:42 1787		
731010	NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA76579 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAB39362 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:2 N:0 N:0			23-AUG-2019 2537:42 1787		
731010	NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA76573 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
732001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT 3073593-06 2011040053 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-JUN-2011 2:06 2		
732002	NO. 1 ENGINE - FUEL METERING UNIT (FMU) 3071682-05 F71916 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
732010	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS 3073237-03 ADXBAA000309 REF: See Workcard	MOS HRS/MSC ENC	O/C						
732030	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732040	NO. 1 ENGINE - FUEL SHUT-OFF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01									
72-00-00-280-819 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			30-AUG-2021 2879:18 1999		
73-10-01-212-801	NO. 2 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
+ 73-10-04-000-801	NO. 2 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES REF: MM 73-10-04	MOS HRS/MSC ENC	9900				(EBT)	(9900) 9903	
73-10-05-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT REF: MM 73-10-05	MOS HRS/MSC ENC	12	+30d	-30		30-AUG-2021 2879:18 1999	31-JUL-2022	30-AUG-2022
73-10-05-960-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	800	+10%			11-JUL-2018 2299:30 1622	(3099:30) 3099:30	3179:30



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-07-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: MM 73-10-07	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
+ 73-20-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT 3071682-05 F72063 REF: MM 73-20-01	MOS HRS/MSC ENC	5000	+100			(EBT) (5000) 5000 M 5100		
73-20-02-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: MM 73-20-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
73-20-10-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS 3073237-03 ADXBA000300 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) (5000) 5000 M 5100		
73-20-20-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			23-AUG-2019 2537:42 1787 (7537:42) 7537:42	7637:42	
73-20-30-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(5000) 5000 M 5100		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-30-02-212-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR PKG 1 REF: MM 73-30-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
731005	NO. 2 ENGINE - FUEL FILTER PN SN-UNKNOWN REF: MM 73-10-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			11-JUL-2018 2299:30 1622		
731010	NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA76588 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
731010	NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAB39353 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:3 N:0 N:0			23-AUG-2019 2537:42 1787		
731010	NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA64970 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
731010	NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BPB0553 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA64967 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
731010	NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA76594 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
731010	NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA76587 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
731010	NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAB39354 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:3 N:0 N:0			23-AUG-2019 2537:42 1787		
731010	NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA57007 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
731010	NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA64965 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY 3057135-01 DE1APN1589 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			23-AUG-2019 2537:42 1787		
732001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT 3073593-06 2011040077 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			24-JUN-2011 2:06 2		
732002	NO. 2 ENGINE - FUEL METERING UNIT (FMU) 3071682-05 F72063 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
732010	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS 3073237-03 ADXBA000300 REF: See Workcard	MOS HRS/MSC ENC	O/C						
732030	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
732040	NO. 2 ENGINE - FUEL SHUT-OFF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		

CHAPTER 74 IGNITION

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-00-01-750-801 (s)	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-10-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER 31J2807-07 PKG 1 NNA10520376 REF: MM 74-10-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-20-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-20-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR 502600-1 PKG 1 NNA17350151 REF: MM 74-20-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-20-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR 502600-1 PKG 1 NNA17350126 REF: MM 74-20-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-20-02-960-801	NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER 502600-1 NNA17350151 REF: See Workcard	MOS HRS/MSC ENC	O/C				22-AUG-2018 2299:30 1622		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 74-20-02-960-801	NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER 502600-1 NNA17350126 REF: See Workcard	MOS HRS/MSC ENC	O/C				22-AUG-2018 2299:30 1622		
741001	NO. 1 ENGINE - EXCITER IGNITION 31J2807-07 NNA10520376 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
742000	NO. 1 ENGINE - 5 O'CLOCK IGNITER 502600-1 NNA17350151 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			22-AUG-2018 2299:30 1622		
742001	NO. 1 ENGINE - 7 O'CLOCK IGNITER 502600-1 NNA17350126 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			22-AUG-2018 2299:30 1622		
742002	NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD 3127408-02 NNA15510221 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			11-MAR-2016 1530:36 1057		
742003	NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD 3127408-01 NNA15520094 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			11-MAR-2016 1530:36 1057		

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-00-01-750-801 (s)	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-10-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER 31J2807-07 PKG 1 NNA11060135 REF: MM 74-10-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-20-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR 502600-1 PKG 1 NNA17350112 REF: MM 74-20-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR 502600-1 PKG 1 NNA17350174 REF: MM 74-20-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
74-20-02-960-801	NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER 502600-1 NNA17350112 REF: See Workcard	MOS HRS/MSC ENC	O/C				22-AUG-2018 2299:30 1622		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 74-20-02-960-801	NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER 502600-1 NNA17350174 REF: See Workcard	MOS HRS/MSC ENC	O/C				22-AUG-2018 2299:30 1622		
741001	NO. 2 ENGINE - EXCITER IGNITION 31J2807-07 NNA11060135 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
742000	NO. 2 ENGINE - 5 O'CLOCK IGNITER 502600-1 NNA17350112 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			22-AUG-2018 2299:30 1622		
742001	NO. 2 ENGINE - 7 O'CLOCK IGNITER 502600-1 NNA17350174 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			22-AUG-2018 2299:30 1622		
742002	NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD 3127408-01 NNA15520098 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			11-MAR-2016 1530:36 1057		
742003	NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD 3127408-02 NNA15520126 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			11-MAR-2016 1530:36 1057		

CHAPTER 75 AIR

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75-30-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE PKG 1 REF: MM 75-30-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
+ 75-30-01-212-802	NO. 1 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: MM 75-30-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
75-30-01-212-803	NO. 1 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE 3053367-01 AHX017753 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
75-30-01-900-802	NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE 3075987-01 TR4883 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
75-30-01-900-803	NO. 1 ENGINE - LINEAR TRANSFORMER 3071811-01 1354 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
+ 75-30-01-960-801	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES REF: See Workcard	MOS HRS/MSC ENC	A/R				23-FEB-2011 0 0		
UNSCHEDULED MAINTENANCE CHECK									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 75-30-01-960-802	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE 3075987-01 TR4883 REF: See Workcard	MOS HRS/MSC ENC	A/R				23-FEB-2011 0 0		
UNSCHEDULED MAINTENANCE CHECK									
+ 75-30-01-960-803	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER 3071811-01 1354 REF: See Workcard	MOS HRS/MSC ENC	A/R				23-FEB-2011 0 0		
UNSCHEDULED MAINTENANCE CHECK									
+ 75-30-02-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER 3071811-01 1354 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 75-30-20-212-801	NO. 1 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
750010	NO. 1 ENGINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: MM 75-00-00	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-FEB-2011 0 0		
753010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY 3053367-01 AHX017753 REF: MM 75-30-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753020	NO. 1 ENGINE - BOV TORQUE MOTOR								
	PN	MOS		N:0			23-FEB-2011		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01									
75-30-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE						PKG		
	PKG 1	MOS	12	+30d			30-AUG-2021		
		HRS/MSC	800	+10%			2879:18		
	REF: MM 75-30-01	ENC					1999		
+ 75-30-01-212-802	NO. 2 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	5000	+100			(EBT)	(5000) 5000	M 5100
	REF: MM 75-30-01	ENC							
75-30-01-212-803	NO. 2 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE								
	3053367-01	MOS							
	AHX017621	HRS/MSC	5000	+100			(EBT)	(5000) 5000	M 5100
	REF: GENERIC NO REF	ENC							
75-30-01-900-802	NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE								
	3075987-01	MOS		N:0			28-FEB-2011		
	TR4982	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		
75-30-01-900-803	NO. 2 ENGINE - LINEAR TRANSFORMER								
	3071811-01	MOS		N:0			28-FEB-2011		
	1364	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 75-30-01-960-801	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES	MOS HRS/MSC ENC	A/R					28-FEB-2011 0 0	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard								
+ 75-30-01-960-802	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE 3075987-01 TR4982	MOS HRS/MSC ENC	A/R					28-FEB-2011 0 0	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard								
+ 75-30-01-960-803	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER 3071811-01 1364	MOS HRS/MSC ENC	A/R					28-FEB-2011 0 0	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard								
+ 75-30-02-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER 3071811-01 1364	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
	REF: GENERIC NO REF								
+ 75-30-20-212-801	NO. 2 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR PN SN-UNKNOWN	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
	REF: GENERIC NO REF								
750010	NO. 2 ENGINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0			28-FEB-2011 0 0	
	REF: MM 75-00-00								



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753010	NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY 3053367-01 AHX017621 REF: MM 75-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
753020	NO. 2 ENGINE - BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
CHAPTER 76 ENGINE CONTROLS									
76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY 6990010-11 1624 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:161:18 N:105			18-SEP-2015 1406:48 966		
CHAPTER 77 ENGINE INDICATING									
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01									
77-20-02-750-801	NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM REF: MM 77-20-02	MOS HRS/MSC ENC	36 1800	+30d +100		-18	18-AUG-2020 2650:54 1880	31-JUL-2023 (4450:54) 4450:54	30-AUG-2023 4550:54
+ 77-40-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT 3075394-01 DP10-1943 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
774001	NO. 1 ENGINE - DATA COLLECTION UNIT 3075394-01 DP10-1943 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01									



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
77-20-02-750-801	NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM REF: MM 77-20-02	MOS HRS/MSC ENC	36 1800	+30d +100		-18	18-AUG-2020 2650:54 1880	31-JUL-2023 (4450:54) 4450:54	30-AUG-2023 4550:54
+ 77-40-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT 3075394-01 DP10-1826 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
774001	NO. 2 ENGINE - DATA COLLECTION UNIT 3075394-01 DP10-1826 REF: See Workcard	MOS HRS/MSC ENC	O/C		N:5 N:4		17-APR-2012 175:36 109		
CHAPTER 79	OIL								
79-31-05	LEFT ENGINE MAIN OIL PRESSURE SENSOR APTE-478A-1000-270D 00103 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0				
79-31-05	RIGHT ENGINE MAIN OIL PRESSURE SENSOR APTE-478A-1000-270D 00105 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0				
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0104 Part # A3072913-01									
+ 79-10-02-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) 3052640-01 06123306 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-20-00-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
79-20-01-210-801	NO. 1 ENGINE - EXAMINE AND REPLACE - OIL FILTER REF: MM 79-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
79-20-01-960-801 DISCARD	NO. 1 ENGINE - DISCARD THE OIL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	800	+10%			11-JUL-2018 2299:30 1622	(3099:30) 3099:30	3179:30
+ 79-30-01-210-801	NO. 1 ENGINE - EXAMINE - CHIP DETECTOR PN SN-UNKNOWN REF: MM 79-30-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
79-30-01-770-801 (s)	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
79-30-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-30-03-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
+ 79-30-20-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
790000	NO. 1 ENGINE - OIL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
790020	NO. 1 ENGINE - CHANGE OIL REF: See Workcard	MOS HRS/MSC ENC	A/R				23-FEB-2011 0 0		
792010	NO. 1 ENGINE - TEMPERATURE SENSOR ATS-9-800 5-18-10-64 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
793003	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER 3052640-01 06123306 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793010	NO. 1 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR 3052535-02 HA1324 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C						
793020	NO. 1 ENGINE - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
793025	NO. 1 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-FEB-2011 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0107 Part # A3072913-01									
+ 79-10-02-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) 3052640-01 06108555 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 79-20-00-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
79-20-01-210-801	NO. 2 ENGINE - EXAMINE AND REPLACE - OIL FILTER REF: MM 79-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-20-01-960-801	NO. 2 ENGINE - DISCARD THE OIL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	800	+10%			11-JUL-2018 2299:30 1622	(3099:30) 3099:30	3179:30
DISCARD									
+ 79-30-01-210-801	NO. 2 ENGINE - EXAMINE - CHIP DETECTOR PN SN-UNKNOWN REF: MM 79-30-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
79-30-01-770-801 (s)	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
79-30-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 30-AUG-2021 2879:18 1999		
79-30-03-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
+ 79-30-20-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790000	NO. 2 ENGINE - OIL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
790020	NO. 2 ENGINE - CHANGE OIL REF: See Workcard	MOS HRS/MSC ENC	A/R				28-FEB-2011 0 0		
792010	NO. 2 ENGINE - TEMPERATURE SENSOR ATS-9-800 5-18-10-78 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
793003	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER 3052640-01 06108555 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		
793010	NO. 2 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR 3052535-02 HA1313 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C						
793020	NO. 2 ENGINE - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-FEB-2011 0 0		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793025	NO. 2 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				28-FEB-2011 0 0	
CHAPTER --	GENERAL								
Z210-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE NOSE SECTION PKG 87 REF: AMM 05-41-00	MOS HRS/MSC AFL	120	+1m/-1m				PKG 30-AUG-2021 2879:18 2002	
Z210-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION PKG 87 REF: AMM 05-41-00	MOS HRS/MSC AFL	120	+1m/-1m				PKG 30-AUG-2021 2879:18 2002	
Z220-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 84 REF: AMM 05-41-00	MOS HRS/MSC AFL	60	+1m/-1m				PKG 30-AUG-2021 2879:18 2002	
Z220-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 87 REF: AMM 05-41-00	MOS HRS/MSC AFL	120	+1m/-1m				PKG 30-AUG-2021 2879:18 2002	
Z230-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE FRONT SECTION PKG 84 REF: AMM 05-42-00	MOS HRS/MSC AFL	60	+1m/-1m				PKG 30-AUG-2021 2879:18 2002	



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z230-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION PKG 87 REF: AMM 05-42-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z240-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE REAR SECTION PKG 87 REF: AMM 05-42-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z240-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION PKG 84 REF: AMM 05-42-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z310-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE FRONT SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z310-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z320-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE REAR SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z320-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z330-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE VERTICAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z330-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z340-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE HORIZONTAL STABILIZER PKG 84 REF: AMM 05-44-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z340-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z410-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PYLON PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		



Status Report

PHENOM 300 S/N 50500057 (N924LG): 3003:54 HRS, 2002 AFL as of 25-Feb-2022

Owner/Operator: RG42, LLC

Report Date: 17-MAR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z410-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z430-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE NACELLE PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z430-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z500-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE WINGS PKG 84 REF: AMM 05-45-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z500-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS PKG 84 REF: AMM 05-45-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		
Z700-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE MAIN LANDING GEAR BAY PKG 84 REF: AMM 05-47-00	MOS HRS/MSC AFL	60	+1m/-1m			PKG 30-AUG-2021 2879:18 2002		