

Inspection Complete!

Inspection is being reviewed, but you may still make changes!

View Field Notes

Email Service Team

Vehicle Report

AUTOMOBILE-0000012655



Adjusters Name	Requester's Phone Number	Requester's Email
John Smith	555-123-4567	here@there.com
VIN for Tracking	Vehicles VIN	Year
3VV4B7AX3KM015786	3VV4B7AX3KM015786	2003
Make	Model	Milage
Nissan	Rouge	56447
Repair Facility Name	Repair Facility Address	Repair Facility Phone Number
ABC Auto	123 Fake St, Dallas, TX, 12345	555-765-4321
Repair Facility Contact		
Bob Ross		

Problems as described by repair facility

Check to see if the frame is damaged. Facility claims 10000 heat melted the subframe and we need to get clear pictures of melting frame.

Inspectors Report

Step 1 Vehicle Info

Date of Inspection

06.27.2023

Verified Vehicle Milage

56447

Verified VIN

3VV4B7AX3KM015786

Verified Year/Make/Model

2003 Nissan Rogue